Storm Damage Report (updated on 24.05.2023 till 9:00 P.M.)																		
Date of occurrence	District	Rev. Circle	Name of Village affected	No. of Village affected	Total Population affected	Houses Damaged					Human life lost	Crop Damage (In Hect)	Other loss (Livestock, Road Communication	Ex-Gratia distributed	Time	GPS Co- ordinates		Remarks
						Partially Damaged		Fully Damaged		Any other Institutions affected								
						Kutcha	Pucca	Kutcha	Pucca									
23-05-2023	South Salmara	Mankachar	**Mankachar R.C:** Pipulbari Pt-1, Margaonjanta, Sadullabari, Tangaon Pt.II, Chirakhawa, Pathuria, Kanyamoti, Bengarvita, Bhurakata, Darua Khwahagi, Pipulbari Pt- III, Fulercha Pt-IV, Kakripara PI-1	13	0	0	0	0	0	0	0	-	-	-	-	**Latitude** 25.621474 25.631524 25.629642 25.6471003 25.614556 25.61111 25.608303 25.610299 25.630842 25.623756 25.64169 25.745908 25.49360095	**Longitude** 89.945911 89.964907 89.963934 89 9561159 89.921741 89.88744 89.888054 89.933736 89.915004 89.8892 89.95516 89.888903 89.863987	Pole-14 Conductor-4.92 KM As per report received from APDCL, Mankachar Yesterday due to storm several villages of mentioned under Mankachar Rev. Circle got damaged Poles and Conductors.
23-05-2023	Barpeta	Barpeta, Barnagar	**Barpeta R.C:** Banbahar, Bhakuamari, Bhakuamari(Madhya), Banbahar (2 No Banbahar), Bhaakuamari, Fularguri, Maricha, Chakirbhitha, Ata. **Barnagar R.C:** Roha Khatakuchi Ghilajari	12	0	0	0	0	0	0	0	-	-	-	-	-	-	HT Pole-0 LT-Pole-2 Conductor Damaged (In Km)-0.4 HT Pole-0 LT Pole-1 Conductor Damaged (In Km)-0.2 HT Pole-1 LT Pole-0 Conductor Damaged (In Km)-0.1 HT Pole-0 LT Pole-0 Conductor Damaged (In Km)-0.3 HT Pole-0 LT Pole-0 Conductor Damaged (In Km)-0.2 HT Pole-0 LT Pole-1 Conductor Damaged (In Km)-0.5 HT Pole-0 LT Pole-0 Conductor Damaged (In Km)-0.12 HT Pole-0 LT Pole-0 Conductor Damaged (In Km)-0.16 HT Pole-0 LT Pole-0 Conductor Damaged (In Km)-0.2 LT Pole-2 LT Pole-1 LT Pole-1 HT Pole-1 LT Pole-8 Conductor Damaged (In Km)-2.18
23-05-2023	Goalpara	Lakhipur	**Lakhipur R.C:** Cholakura, Rajmita	2	0	0	0	0	0	0	0	-	-	-	-	-	-	APDCL LAKHIPUR ESD NOS. OF LT POLE DAMAGED: 1 No. HT POLE DAMAGED 2 Nos. Conductor Snapping 2.5
Total				**27**	**0**	**0**	**0**	**0**	**0**	**0**	**0**	**-**	**-**	**-**	**-**			