

Assam Daily Flood Report as on 17-06-2022 at 4:00 PM

Assam Daily Flood Report as on 17-06-2022 at 4:00 PM			
Particulars	Situation as on 17-06-2022 (in last 24 hours)		
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above danger level	Beki (Road Bridge), Manas (Nh Road Crossing), Pagladiya (Nt Road Crossing), Puthimari (Nh Road Crossing), Jia-Bharali (Nt Road Crossing), Brahmaputra (Dhubri; Neamatighat)	
	Rivers flowing above highest flood level	Kopili (Kampur)	
District Affected	<b>No. of Districts Affected</b>	<b>Name of Flood Affected Districts</b>	<b>Name of Urban Flood Districts</b>
	28	Bajali, Baksa, Barpeta, Biswanath, Bongaigaon, Chirang, Darrang, Dhemaji, Dhubri, Dibrugarh, Dima-Hasao, Goalpara, Hojai, Kamrup, Kamrup (M), Karbi Anglong West, Kokrajhar, Lakhimpur, Majuli, Morigaon, Nagaon, Nalbari, Sivasagar, Sonitpur, South Salmara, Tamulpur, Tinsukia, Udalguri	Bajali, Barpeta, Darrang, Goalpara, Kamrup (M), Kokrajhar, Nalbari, Udalguri
No. Of Revenue Circles Affected	96		
Name Of Revenue Circles Affected	<b>District</b>	<b>Total</b>	<b>Revenue Circle</b>
	Bajali	2	Sarupeta, Bajali
	Baksa	5	Baska, Baganpara, Barnagar RC part, Barama, Jalah
	Barpeta	6	Barpeta, Baghbar, Sarthebari, Kalgachia, Barnagar, Chenga
	Biswanath	1	Halem
	Bongaigaon	5	Manikpur, Bongaigaon, Boitamari, Dangtol, Srijangram
	Chirang	3	Sidli, Bijni, Bengtal
	Darrang	4	Patharighat, Dalgaon, Mangaldoi, Sipajhar
	Dhemaji	4	Jonai, Gogamukh, Sissiborgaon, Dhemaji
	Dhubri	5	Chapar, South Salmara Part, Athani, Bilasipara, Agamoni
	Dibrugarh	1	Chabua
	Dima-Hasao	1	Haflong
	Goalpara	5	Balijana, Matia, Dudhnoi, Rongjuli, Lakhipur
	Hojai	3	Lanka, Hojai, Doboka
	Kamrup	9	Rangia, Kayan, Goroimari, Palashbari, Chaygaon, Kamalpur, Boko, North Ghy, Hajo
	Kamrup (M)	2	Guwahati, Dispur
	Karbi Anglong West	1	Donkamokam
	Kokrajhar	5	Bagribari, Kokrajhar, Bhawraguri, Gossaigaon, Dotma
	Lakhimpur	5	North Lakhimpur, Subansiri, Kadam, Bihpuria, Nowboicha
	Majuli	2	Majuli, Ujani Majuli
	Morigaon	1	Mayong
	Nagaon	2	Kampur, Raha
	Nalbari	7	Banekuchi, Barkhetri, Paschim Nalbari, Ghograpar, Barbhag, Nalbari, Tihu
Sivasagar	1	Demow	
Sonitpur	5	Dhekiajuli, Thelamara, Naduar, Chariduar, Tezpur	
South Salmara	2	South Salmara, Mankachar	
Tamulpur	2	Tamulpur, Goreswar	
Tinsukia	2	Tinsukia, Doomdooma	

	Udalguri	5	Khairabari, Udalguri, Mazbat, Kalaigaon, Harisinga					
	Total	96						
Villages Affected	<b>District</b>	<b>Total</b>	<b>Revenue Circle</b>					
	Bajali	172	( Sarupeta   78 ), ( Bajali   94 )					
	Baksa	70	( Baska   19 ), ( Baganpara   7 ), ( Barnagar RC part   20 ), ( Barama   16 ), ( Jalah   8 )					
	Barpeta	464	( Barpeta   77 ), ( Baghbar   67 ), ( Sarthebari   135 ), ( Kalgachia   99 ), ( Barnagar   50 ), ( Chenga   36 )					
	Biswanath	3	( Halem   3 )					
	Bongaigaon	110	( Manikpur   79 ), ( Bongaigaon   3 ), ( Boitamari   3 ), ( Dangtol   6 ), ( Srijangram   19 )					
	Chirang	50	( Sidli   10 ), ( Bijni   33 ), ( Bengtal   7 )					
	Darrang	260	( Patharighat   59 ), ( Dalgaon   82 ), ( Mangaldoi   67 ), ( Sipajhar   52 )					
	Dhemaji	53	( Jonai   12 ), ( Gogamukh   27 ), ( Sissiborgaon   11 ), ( Dhemaji   3 )					
	Dhubri	181	( Chapar   4 ), ( South Salmara Part   32 ), ( Athani   55 ), ( Bilasipara   68 ), ( Agamoni   22 )					
	Dibrugarh	4	( Chabua   4 )					
	Dima-Hasao	1	( Haflong   1 )					
	Goalpara	258	( Balijana   87 ), ( Matia   71 ), ( Dudhnoi   1 ), ( Rongjuli   16 ), ( Lakhipur   83 )					
	Hojai	87	( Lanka   11 ), ( Hojai   56 ), ( Doboka   20 )					
	Kamrup	230	( Rangia   77 ), ( Kayan   28 ), ( Goroimari   6 ), ( Palashbari   3 ), ( Chaygaon   3 ), ( Kamalpur   65 ), ( Boko   17 ), ( North Ghy   2 ), ( Hajo   29 )					
	Kamrup (M)	20	( Guwahati   9 ), ( Dispur   11 )					
	Karbi Anglong West	8	( Donkamokam   8 )					
	Kokrajhar	271	( Bagribari   106 ), ( Kokrajhar   54 ), ( Bhawraguri   28 ), ( Gossaigaon   51 ), ( Dotma   32 )					
	Lakhimpur	66	( North Lakhimpur   5 ), ( Subansiri   2 ), ( Kadam   7 ), ( Bihpuria   14 ), ( Nowboicha   38 )					
	Majuli	24	( Majuli   21 ), ( Ujani Majuli   3 )					
	Morigaon	34	( Mayong   34 )					
	Nagaon	54	( Kampur   39 ), ( Raha   15 )					
	Nalbari	203	( Banekuchi   19 ), ( Barkhetri   7 ), ( Paschim Nalbari   19 ), ( Ghograpar   55 ), ( Barbhag   36 ), ( Nalbari   39 ), ( Tihu   28 )					
	Sivasagar	1	( Demow   1 )					
	Sonitpur	92	( Dhekiajuli   23 ), ( Thelamara   18 ), ( Naduar   1 ), ( Chariduar   28 ), ( Tezpur   22 )					
	South Salmara	45	( South Salmara   14 ), ( Mankachar   31 )					
Tamulpur	37	( Tamulpur   13 ), ( Goreswar   24 )						
Tinsukia	7	( Tinsukia   3 ), ( Doomdooma   4 )						
Udalguri	125	( Khairabari   24 ), ( Udalguri   36 ), ( Mazbat   19 ), ( Kalaigaon   36 ), ( Harisinga   10 )						
	Total	2930						
Population And Crop Area Affected	<b>District</b>	<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Total Population</b>	<b>Population Details</b>	<b>Crop Area ( in Hect. )</b>	<b>Crop Area Details</b>
	Bajali	180000	140000	35000	355000	( Sarupeta   195000 ), ( Bajali   160000 )	20.00	( Sarupeta   20.00 ), ( Bajali   0.00 )
	Baksa	27497	19609	18814	65920	( Barnagar RC part   51222 ), ( Baska   1780 ), ( Baganpara   3583 ), ( Barama   1359 ), ( Jalah   7976 )	1081.72	( Barnagar RC part   830.00 ), ( Baska   32.72 ), ( Baganpara   43.00 ), ( Barama   30.00 ), ( Jalah   146.00 )
	Barpeta	68997	61214	38759	168970	( Barpeta   45088 ), ( Sarthebari   122952 ), ( Kalgachia   0 ), ( Barnagar   0 ), ( Chenga   930 ), ( Baghbar   0 )	7592.30	( Barpeta   178.00 ), ( Sarthebari   37.00 ), ( Kalgachia   1666.50 ), ( Barnagar   901.50 ), ( Chenga   724.00 ), ( Baghbar   4085.30 )
	Biswanath	367	298	526	1191	( Halem   1191 )	27.00	( Halem   27.00 )
	Bongaigaon	33068	27703	19815	80586	( Manikpur   75850 ), ( Bongaigaon   925 ), ( Srijangram   1569 ), ( Boitamari   585 ), ( Dangtol   1657 )	2908.50	( Manikpur   2712.00 ), ( Bongaigaon   196.50 ), ( Srijangram   0.00 ), ( Boitamari   0.00 ), ( Dangtol   0.00 )
	Chirang	5115	3809	5788	14712	( Sidli   1786 ), (	365.60	( Sidli   22.10 ), (

						Bengtal   846 ), ( Bijni   12080 )		Bengtal   65.00 ), ( Bijni   278.50 )
Darrang	114434	103598	72373	290405		( Patharighat   75294 ), ( Dalgaon   120340 ), ( Mangaldoi   81207 ), ( Sipajhar   13564 )	7058.70	( Patharighat   1181.20 ), ( Dalgaon   3795.50 ), ( Mangaldoi   1572.00 ), ( Sipajhar   510.00 )
Dhemaji	12391	11765	6049	30205		( Jonai   4716 ), ( Gogamukh   15759 ), ( Sissiborgaon   8131 ), ( Dhemaji   1599 )	2525.00	( Jonai   1728.00 ), ( Gogamukh   457.00 ), ( Sissiborgaon   310.00 ), ( Dhemaji   30.00 )
Dhubri	9701	8777	3803	22281		( Chapar   900 ), ( South Salmara Part   11805 ), ( Athani   318 ), ( Bilasipara   9258 ), ( Agamoni   0 )	5192.80	( Chapar   1018.20 ), ( South Salmara Part   0.00 ), ( Athani   1040.20 ), ( Bilasipara   2919.40 ), ( Agamoni   215.00 )
Dibrugarh	2870	2204	1593	6667		( Chabua   6667 )	3.50	( Chabua   3.50 )
Goalpara	100465	73131	10906	184502		( Balijana   63643 ), ( Lakhipur   117215 ), ( Matia   3644 ), ( Dudhnoi   0 ), ( Rongjuli   0 )	1062.00	( Balijana   762.50 ), ( Lakhipur   0.00 ), ( Matia   272.00 ), ( Dudhnoi   0.50 ), ( Rongjuli   27.00 )
Hojai	55150	39535	10656	105341		( Lanka   9047 ), ( Hojai   73499 ), ( Doboka   22795 )	3757.00	( Lanka   532.00 ), ( Hojai   3026.00 ), ( Doboka   199.00 )
Kamrup	52965	42906	23068	118939		( Kayan   38122 ), ( Chaygaon   0 ), ( North Ghy   221 ), ( Rangia   50253 ), ( Goroimari   0 ), ( Palashbari   0 ), ( Kamalpur   14071 ), ( Boko   0 ), ( Hajo   16272 )	2625.65	( Kayan   358.00 ), ( Chaygaon   123.00 ), ( North Ghy   0.00 ), ( Rangia   593.00 ), ( Goroimari   69.00 ), ( Palashbari   198.00 ), ( Kamalpur   208.20 ), ( Boko   10.45 ), ( Hajo   1066.00 )
Kamrup (M)	17775	14589	1965	34329		( Chandrapur   0 ), ( Guwahati   12879 ), ( Dispur   21450 )	0.00	( Chandrapur   0.00 ), ( Guwahati   0.00 ), ( Dispur   0.00 )
Karbi Anglong West	1575	1476	2102	5153		( Donkamokam   5153 )	244.00	( Donkamokam   244.00 )
Kokrajhar	34300	33351	24764	92415		( Bagribari   20212 ), ( Kokrajhar   22186 ), ( Bhawraguri   17767 ), ( Gossaigaon   1989 ), ( Dotma   30261 )	1583.74	( Bagribari   284.49 ), ( Kokrajhar   460.40 ), ( Bhawraguri   0.00 ), ( Gossaigaon   141.10 ), ( Dotma   697.75 )
Lakhimpur	16337	12987	11641	40965		( North Lakhimpur   7853 ), ( Nowboicha   27412 ), ( Subansiri   257 ), ( Kadam   2926 ), ( Bihpuria   2517 )	549.30	( North Lakhimpur   97.00 ), ( Nowboicha   360.30 ), ( Subansiri   75.00 ), ( Kadam   7.00 ), ( Bihpuria   10.00 )
Majuli	0	0	0	0		( Majuli   0 ), ( Ujani Majuli   0 )	361.00	( Majuli   309.00 ), ( Ujani Majuli   52.00 )
Morigaon	0	0	0	0		( Mayong   0 )	320.00	( Mayong   320.00 )
Nagaon	21164	20546	15416	57126		( Kampur   57126 ), ( Raha   0 )	1631.74	( Kampur   1437.00 ), ( Raha   194.74 )
Nalbari	52613	43534	26888	123035		( Paschim Nalbari   25102 ), ( Ghograpar   35610 ), ( Barbhag   8551 ), ( Nalbari   9460 ), ( Tihu   11500 ), ( Banekuchi   22196 ), ( Barkhetri   10616 )	1891.80	( Paschim Nalbari   449.00 ), ( Ghograpar   606.00 ), ( Barbhag   178.00 ), ( Nalbari   252.80 ), ( Tihu   367.00 ), ( Banekuchi   39.00 ), ( Barkhetri   0.00 )
Sivasagar	0	0	0	0		( Demow   0 )	19.14	( Demow   19.14 )
Sonitpur	8142	7310	6102	21554		( Naduar   0 ), (	799.50	( Naduar   6.00 ), (

						Dhekiajuli   3703 ), ( Thelamara   4840 ), ( Chariduar   12947 ), ( Tezpur   64 )		Dhekiajuli   250.90 ), ( Thelamara   127.00 ), ( Chariduar   262.00 ), ( Tezpur   153.60 )
South Salmara	2615	2512	1105	6232		( South Salmara   6232 ), ( Mankachar   0 )	405.00	( South Salmara   0.00 ), ( Mankachar   405.00 )
Tamulpur	3769	12314	3115	19198		( Tamulpur   6070 ), ( Goreswar   13128 )	524.00	( Tamulpur   300.00 ), ( Goreswar   224.00 )
Tinsukia	1848	1625	1248	4721		( Tinsukia   2666 ), ( Doomdooma   2055 )	494.30	( Tinsukia   238.00 ), ( Doomdooma   256.30 )
Udalguri	20273	14351	10302	44926		( Khairabari   4850 ), ( Udalguri   10393 ), ( Mazbat   4010 ), ( Kalaigaon   24903 ), ( Harisinga   770 )	295.10	( Khairabari   55.00 ), ( Udalguri   0.00 ), ( Mazbat   0.00 ), ( Kalaigaon   240.10 ), ( Harisinga   0.00 )
<b>Total</b>	<b>843431</b>	<b>699144</b>	<b>351798</b>	<b>1894373</b>			<b>43338.39</b>	

Relief Camps / Centres Opened	District	Total	Relief Camp		Relief Distribution Centres			
	Bajali	30	29(Bajali   29, Sarupeta   0)		1(Bajali   0, Sarupeta   1)			
Baksa	13	10(Baska   6, Barama   3, Jalah   1, Baganpara   0)		3(Baska   0, Barama   1, Jalah   0, Baganpara   2)				
Barpeta	35	35(Barpeta   29, Sarthebari   3, Chenga   3)		0(Barpeta   0, Sarthebari   0, Chenga   0)				
Bongaigaon	55	18(Manikpur   1, Bongaigaon   1, Boitamari   3, Dangtol   8, Srijangram   5)		37(Manikpur   35, Bongaigaon   2, Boitamari   0, Dangtol   0, Srijangram   0)				
Chirang	19	1(Bijni   1, Sidli   0, Bengtal   0)		18(Bijni   7, Sidli   10, Bengtal   1)				
Darrang	13	13(Patharighat   2, Mangaldoi   9, Sipajhar   2)		0(Patharighat   0, Mangaldoi   0, Sipajhar   0)				
Dhemaji	4	0(Jonai   0, Dhemaji   0)		4(Jonai   2, Dhemaji   2)				
Dhubri	25	25(Chapar   3, Athani   4, Bilasipara   18)		0(Chapar   0, Athani   0, Bilasipara   0)				
Dima-Hasao	20	20(Haflong   20)		0(Haflong   0)				
Goalpara	35	23(Balijana   10, Matia   3, Lakhipur   10)		12(Balijana   2, Matia   0, Lakhipur   10)				
Hojai	47	36(Hojai   25, Doboka   11, Lanka   0)		11(Hojai   0, Doboka   6, Lanka   5)				
Kamrup	16	16(Rangia   5, Kayan   3, North Ghy   2, Hajo   6)		0(Rangia   0, Kayan   0, North Ghy   0, Hajo   0)				
Kamrup (M)	24	5(Guwahati   2, Dispur   3)		19(Guwahati   12, Dispur   7)				
Karbi Anglong West	4	0(Donkamokam   0)		4(Donkamokam   4)				
Kokrajhar	128	56(Bagribari   7, Kokrajhar   24, Bhawraguri   6, Gossaigaon   11, Dotma   8)		72(Bagribari   0, Kokrajhar   27, Bhawraguri   16, Gossaigaon   0, Dotma   29)				
Lakhimpur	7	0(North Lakhimpur   0, Subansiri   0, Kadam   0)		7(North Lakhimpur   2, Subansiri   3, Kadam   2)				
Nagaon	3	3(Kampur   3)		0(Kampur   0)				
Nalbari	54	54(Banekuchi   12, Paschim Nalbari   10, Ghograpar   2, Barbhag   3, Nalbari   11, Tihu   16)		0(Banekuchi   0, Paschim Nalbari   0, Ghograpar   0, Barbhag   0, Nalbari   0, Tihu   0)				
Sonitpur	9	1(Chariduar   1, Dhekiajuli   0)		8(Chariduar   3, Dhekiajuli   5)				
Tamulpur	24	10(Tamulpur   5, Goreswar   5)		14(Tamulpur   7, Goreswar   7)				
Tinsukia	7	4(Doomdooma   4, Tinsukia   0)		3(Doomdooma   0, Tinsukia   3)				
Udalguri	33	14(Udalguri   8, Mazbat   2, Kalaigaon   4, Khairabari   0, Harisinga   0)		19(Udalguri   0, Mazbat   0, Kalaigaon   9, Khairabari   3, Harisinga   7)				
<b>Total</b>	<b>605</b>	<b>373</b>		<b>232</b>				

Inmates In Relief Camps	District	Total	Revenue Circlewise	Male	Female	Children	Pregnant / Lactating Mother	Person with Disability
	Bajali	2990	(Sarupeta   0), (Bajali   2990)		1251	1392	325	22
Baksa	1853	(Baganpara   0), (Barnagar RC part   0), (Baska   1469), (Barama   314), (Jalah   70)		642	753	442	8	8
Barpeta	6112	(Baghbar   0), (Kalgachia   0), (Barnagar   0), (Chenga   280), (Barpeta   5294), (Sarthebari   538)		2185	2144	1772	11	0

	Bongaigaon	4441	(Srijangram   1569), (Manikpur   582), (Bongaigaon   153), (Boitamari   480), (Dangtol   1657)			2039	1593	699	110	0
	Chirang	96	(Sidli   0), (Bengtal   0), (Bijni   96)			33	31	29	3	0
	Darrang	5085	(Dalgaon   0), (Sipajhar   377), (Patharighat   234), (Mangaldoi   4474)			2043	1713	1327	1	1
	Dhubri	4050	(South Salmara Part   0), (Athani   318), (Bilasipara   3509), (Agamoni   0), (Chapar   223)			1207	1756	1086	1	0
	Dima-Hasao	1476	(Haflong   1476)			527	566	333	49	1
	Goalpara	5118	(Balijana   2563), (Dudhnoi   0), (Rongjuli   0), (Lakhipur   1971), (Matia   584)			2132	1635	1233	103	15
	Hojai	29745	(Lanka   0), (Hojai   27730), (Doboka   2015)			16014	12297	1426	6	2
	Kamrup	5301	(Kayan   4332), (Goroimari   0), (Palashbari   0), (Chaygaon   0), (Kamalpur   0), (Boko   0), (North Ghy   221), (Hajo   0), (Rangia   748)			2405	1774	1097	25	0
	Kamrup (M)	697	(Chandrapur   0), (Guwahati   77), (Dispur   620)			171	341	185	0	0
	Kokrajhar	19579	(Bagribari   1516), (Kokrajhar   5880), (Bhawraguri   1692), (Gossaigaon   2179), (Dotma   8312)			7093	6625	5803	57	1
	Nagaon	924	(Raha   0), (Kampur   924)			345	310	261	6	2
	Nalbari	15103	(Banekuchi   2329), (Barkhetri   0), (Paschim Nalbari   2815), (Nalbari   3247), (Tihu   6065), (Ghograpar   281), (Barbhag   366)			8284	4675	2059	69	16
	Sonitpur	66	(Dhekiajuli   0), (Naduar   0), (Tezpur   0), (Chariduar   66)			30	21	15	0	0
	Tamulpur	1427	(Tamulpur   440), (Goeswar   987)			402	400	625	0	0
	Tinsukia	2165	(Tinsukia   0), (Doomdooma   2165)			863	777	415	110	0
	Udalguri	1876	(Khairabari   0), (Harisinga   0), (Udalguri   1025), (Mazbat   310), (Kalaigaon   541)			776	573	503	24	0
	<b>Total</b>	<b>108104</b>				<b>48442</b>	<b>39376</b>	<b>19635</b>	<b>605</b>	<b>46</b>
Human Lives Lost - Confirmed	<b>District</b>	<b>Total</b>	<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Revenue Circlewise</b>				
	Bajali	1	1	0	0	(Bajali   1), (Sarupeta   0)				
	Dhubri	1	0	0	1	(Agamoni   0), (Athani   0), (Bilasipara   1), (Chapar   0), (South Salmara Part   0)				
	Hojai	2	0	1	1	(Doboka   0), (Hojai   2), (Lanka   0)				
	Kamrup	1	1	0	0	(Boko   0), (Chaygaon   0), (Goroimari   0), (Hajo   0), (Kamalpur   0), (Kayan   0), (North Ghy   0), (Palashbari   0), (Rangia   1)				
	Kokrajhar	1	1	0	0	(Bagribari   0), (Bhawraguri   0), (Dotma   0), (Gossaigaon   0), (Kokrajhar   1)				
	Nalbari	2	2	0	0	(Banekuchi   1), (Barbhag   0), (Barkhetri   0), (Ghograpar   0), (Nalbari   0), (Paschim Nalbari   1), (Tihu   0)				
	Sonitpur	1	1	0	0	(Chariduar   1), (Dhekiajuli   0), (Naduar   0), (Tezpur   0), (Thelamara   0)				
<b>Total</b>	<b>9</b>	<b>6</b>	<b>1</b>	<b>2</b>						
Human Lives Lost Confirmed - Death Type	<b>District</b>	<b>Total</b>	<b>Flood Death</b>	<b>General Drowning (Non Flood)</b>	<b>Landslide</b>					

	Bajali	1	1	0	0					
	Dhubri	1	1	0	0					
	Hojai	2	2	0	0					
	Kamrup	1	1	0	0					
	Kokrajhar	1	1	0	0					
	Nalbari	2	2	0	0					
	Sonitpur	1	1	0	0					
	<b>Total</b>	<b>9</b>	<b>9</b>	<b>0</b>	<b>0</b>					
Human Lives Lost - Missing	<b>District</b>	<b>Total</b>	<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Details</b>				
	Hojai	1	1	0	0	(Doboka   0), (Hojai   1), (Lanka   0)				
	<b>Total</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>0</b>					
Human Lives Lost Missing - Type	<b>District</b>	<b>Total</b>	<b>Flood</b>	<b>Non Flood</b>						
	Hojai	1	1	0						
	<b>Total</b>	<b>1</b>	<b>1</b>	<b>0</b>						
Animals Affected	<b>District</b>	<b>Total</b>	<b>Big</b>	<b>Small</b>	<b>Poultry</b>					
	Bajali	92922	51773	26649	14500					
	Baksa	19962	11064	7098	1800					
	Barpeta	316996	123519	60795	132682					
	Bongaigaon	202817	59150	23732	119935					
	Darrang	171979	102638	46841	22500					
	Dhemaji	46193	14021	9395	22777					
	Dhubri	71735	39378	32357	0					
	Goalpara	80106	41806	29918	8382					
	Hojai	47210	22460	13330	11420					
	Kamrup	335459	187791	28873	118795					
	Kokrajhar	55374	26179	8495	20700					
	Lakhimpur	15994	9092	4204	2698					
	Nagaon	14410	8930	3230	2250					
	Nalbari	160846	83140	64766	12940					
	Sonitpur	498	280	218	0					
	South Salmara	103645	19414	13219	71012					
Tamulpur	21643	7288	5016	9339						
Udalguri	11220	5846	4622	752						
<b>Total</b>	<b>1769009</b>	<b>813769</b>	<b>382758</b>	<b>572482</b>						
Animals Washed Away	<b>District</b>	<b>Total</b>	<b>Big</b>	<b>Small</b>	<b>Poultry</b>					
	Kokrajhar	410	0	10	400					
	<b>Total</b>	<b>410</b>	<b>0</b>	<b>10</b>	<b>400</b>					
Houses Damaged	<b>District</b>	<b>Fully Kuccha</b>	<b>Fully Pukka</b>	<b>Fully Total</b>	<b>Partially Kuccha</b>	<b>Partially Pukka</b>	<b>Partially Total</b>	<b>Others Huts</b>	<b>Others Cattle Shed</b>	<b>Others Total</b>
	Darrang	10	0	10	0	0	0	0	0	0
	Goalpara	0	0	0	9	21	30	0	0	0
	Kamrup	6	2	8	193	8	201	0	132	132
	Kamrup (M)	0	0	0	0	7	7	0	0	0
	Lakhimpur	5	0	5	20	0	20	0	0	0
	Udalguri	2	0	2	0	0	0	0	0	0
<b>Total</b>	<b>23</b>	<b>2</b>	<b>25</b>	<b>222</b>	<b>36</b>	<b>258</b>	<b>0</b>	<b>132</b>	<b>132</b>	
Rescue Operation	<b>District</b>	<b>Agency</b>			<b>Boats Deployed</b>	<b>Person Evacuated By Boats</b>	<b>Animal Evacuated By Boats</b>	<b>Helicopters Deployed</b>	<b>Person Evacuated By Helicopters</b>	<b>Medical Team Deployed</b>
	Bajali	Army/Paramilitary force, NDRF, SDRF			7	280	0	0	0	0
	Baksa	Army/Paramilitary force, Fire & Emergency Services (F&ES), SDRF			5	255	0	0	0	1
	Barpeta	NDRF, Circle Office/Local Administration, SDRF			4	102	0	0	0	2

	Bongaigao n	Local People, SDRF, Country Boat, Engine Boat, Circle Office/Local Administration, NDRF			31	377	678	0	0	0
	Chirang				0	0	0	0	0	1
	Darrang	NDRF, SDRF, Fire & Emergency Services (F&ES)			10	680	250	0	0	4
	Dhemaji	Fire & Emergency Services (F&ES)			1	0	0	0	0	0
	Dhubri	Fire & Emergency Services (F&ES), Circle Office/Local Administration, Police, SDRF			5	383	586	0	0	1
	Dima-Hasao	Circle Office/Local Administration, Fire & Emergency Services (F&ES), Police, SDRF, Water Resources Department			1	44	23	0	0	15
	Goalpara	Fire & Emergency Services (F&ES), SDRF			4	68	41	0	0	14
	Hojai	SDRF, Local country Boat, Local People, NDRF, Country Boats			47	2506	127	0	0	0
	Kamrup	Circle Office/Local Administration, Fire & Emergency Services (F&ES), NDRF, SDRF			7	103	0	0	0	7
	Kamrup (M)	Circle Office/Local Administration, Fire & Emergency Services (F&ES), Local People, NDRF, Police, SDRF, GMC			1	0	0	0	0	3
	Karbi Anglong West	SDRF			2	0	0	0	0	0
	Kokrajhar	Fire & Emergency Services (F&ES), SDRF			3	135	6	0	0	19
	Lakhimpur				0	0	0	0	0	4
	Nagaon	Fire & Emergency Services (F&ES), SDRF			1	120	0	0	0	0
	Nalbari	Fire & Emergency Services (F&ES), NDRF, SDRF, Army/Paramilitary force			10	557	107	0	0	24
	Sonitpur	SDRF, NDRF			8	294	0	0	0	2
	South Salmara				0	0	0	0	0	1
	Tamulpur	NDRF, NGO, Fire & Emergency Services (F&ES), SDRF			7	112	0	0	0	1
	Udalguri	Fire & Emergency Services (F&ES)			2	25	0	0	0	0
	<b>Total</b>				<b>156</b>	<b>6041</b>	<b>1818</b>	<b>0</b>	<b>0</b>	<b>99</b>
Relief Distributed	<b>District</b>	<b>Rice (in Q)</b>	<b>Dal (in Q)</b>	<b>Salt (in Q)</b>	<b>M. Oil (in L)</b>	<b>Cattle Feed - Green Fooder (in Q)</b>	<b>Cattle Feed - Wheat Bran (in Q)</b>	<b>Cattle Feed - Rice Bran (in Q)</b>		
	Bajali	33.28	5.78	131.95	102.03	0.00	100.00	0.00		
	Baksa	88.75	610.37	4.90	490.44	0.00	30.69	0.00		
	Barpeta	6.84	1.23	0.37	0.00	0.00	0.00	0.00		
	Biswanath	11.22	2.27	0.00	0.00	0.00	0.00	0.00		
	Bongaigao n	1303.43	236.70	71.16	373.14	0.00	4437.28	0.00		
	Chirang	142.59	27.67	8.12	811.06	0.00	0.00	0.00		
	Dhemaji	39.16	7.24	2.16	143.91	0.00	0.00	0.00		
	Dhubri	11.17	2.07	0.62	62.43	0.00	0.00	0.00		

	Goalpara	49.54	9.12	2.74	273.60	0.00	0.00	0.00
	Hojai	0.00	11.40	4.75	228.00	0.00	0.00	0.00
	Kamrup	317.57	59.11	18.79	1879.09	0.00	939.00	0.00
	Kamrup (M)	64.32	10.60	3.18	319.00	0.00	0.00	0.00
	Karbi Anglong West	110.33	20.58	6.17	617.49	0.00	0.00	0.00
	Kokrajhar	613.11	113.95	33.75	3375.63	0.00	0.00	0.00
	Lakhimpur	56.30	10.93	3.28	242.99	0.00	0.00	0.00
	Nalbari	895.61	182.69	48.23	4824.00	0.00	3850.00	0.00
	Sonitpur	60.62	11.54	3.46	0.00	0.00	0.00	0.00
	Tamulpur	504.19	83.80	31.65	1535.66	0.00	611.94	0.00
	Tinsukia	77.49	11.40	4.25	188.19	0.00	0.00	0.00
	Udalguri	190.56	34.30	10.31	123.00	0.00	0.00	0.00
	<b>Total</b>	<b>4576.08</b>	<b>1452.75</b>	<b>389.84</b>	<b>15589.66</b>	<b>0.00</b>	<b>9968.91</b>	<b>0.00</b>
Relief Distributed Others	<b>District</b>	<b>Baby Food Liquid</b>		<b>Baby Food Solid</b>		<b>Others</b>		
	Bajali	0.00-Q		0.00-Q				
	Baksa	0.00-Q, 0.00-Pkt		0.00-Q, 30.00-Pkt		Nil-0.00-Q; Biscuit-1269.00-Pkt; Candle -30.00-Pkt; Biscuit -100.00-Pkt; Mosquito coil -30.00-Pkt		
	Barpeta	0.00-Q		20.00-Pkt		candles-1013.00-Pkt; mosquito repellent coli-15.00-Pkt; Sanitary Napkin-50.00-Pkt; Chira-5155.60-Kg; Jeggary-942.70-Kg		
	Biswanath	0.00-Q		0.00-Q				
	Bongaigaon	0.00-Q, 1102.00-Pkt		0.00-Q, 6630.00-Pkt		Tarpaulin-7303.00-Pieces; Sanitary Pad-60.00-Pkt; Sanitary pad-175.00-Pkt; Candle-91.00-Pkt; Match box-91.00-Pkt; Coil-91.00-Pkt; Sanitary Pad-488.00-Pkt; chira-0.84-Q; gur-0.15-Q		
	Chirang	0.00-Q		0.00-Q		Tarpaulin-89.00-Pieces		
	Darrang	0.00-Q		0.00-Q		Tarpaulin-200.00-Pieces; candle-10.00-Pkt; mosquito coil-10.00-Pkt		
	Dhemaji	0.00-Q		0.00-Q		Tarpaulin-40.00-Pieces		
	Dhubri	0.00-Q, 45.00-Pkt		0.00-Q, 0.00-Pkt		Tarpauline-250.00-Pieces; chira-236.00-Kg; gur-43.00-Kg; M. Coil-46.00-Pkt; M.Box-46.00-Pkt; Candle-46.00-Pkt; Tarpaulin-30.00-Pieces		
	Goalpara	0.00-Q		0.00-Q		candle-570.00-Pkt; Mosquito Coil-570.00-Pkt; Match box-288.00-Pieces; Tarpaulin-242.00-Pieces; Bleaching Powder-5.00-Kg; Phenyl-5.00-Kg; 0-0.00-Q		
	Hojai	0.00-Q, 0.00-L		0.00-Q		Water Bottle 40 Carton ( 12 Pc per cartone) -480.00-L; Amul Taza-228.00-L; Sanitary pads-20.00-Pkt; Water Bottles-600.00-L; Sanitary Pad-75.00-Pkt; Water Bottle-1200.00-L		
	Kamrup	71.00-Pkt, 0.00-Q		71.00-Pkt, 0.00-Q		Candle-315.00-Pkt; Mosquito Coil-70.00-Pkt; Sanitary Napkin-17.00-Pkt; Tarpaulin-350.00-Pieces; Tarpaulin-2000.00-Pieces		
	Kamrup (M)	0.00-Q		0.00-Q		Water -3144.00-L; Bread-1960.00-Pkt; Biscuit-3920.00-Pkt; Candle-240.00-Pkt; Tarpauline-530.00-Pieces; Water Bottle-15000.00-L; Tarpaulin-340.00-Pieces		
	Karbi Anglong West	0.00-Q		0.00-Q				
	Kokrajhar	0.00-Q		6.00-Pkt, 0.00-Q		Chira-75.00-Kg; Gur-12.00-Kg; Match Box-20.00-Pkt; Water Bottle-120.00-Pieces; Candle-536.00-Pkt; Biscuit-168.00-Pkt; CANDLE-3893.00-Pkt; MATCHBOX-306.00-Pkt; GOODDAY BISCUIT-14548.00-Pkt; Match Box-138.00-Q; Match Box-71.00-Pieces; Chemical Packets-200.00-Pkt; Halogen Tablets-800.00-Pieces; M COIL-853.00-Pkt; SOAP-853.00-Pieces		
	Lakhimpur	0.00-Q		0.00-Q, 31.00-Kg		Tarpaulin-463.00-Pkt; Tarpaulin-63.00-Pieces		
	Nalbari	0.00-Q		0.00-Q		Phenyl-50.00-L; Candle-110.00-Pkt; Mosquito Coil-110.00-Pkt		
	Sonitpur	0.00-Q		0.00-Q				
	Tamulpur	0.00-Q		0.00-Q		chira-14676.00-Kg; Gur-2621.00-Kg		
Tinsukia	0.00-Q		0.00-Q					
Udalguri	0.00-Q, 0.00-Pkt		0.00-Q, 20.00-Pkt		Sanitary Pad -40.00-Pkt; Candles & Match Sticks-40.00-Pkt; Mosquito Coil-40.00-Pkt; Mosquito Net-40.00-Pieces; Disposal Plates & Glass-40.00-Pkt; Soap-80.00-Pieces; Water Bottle-40.00-Pkt; Phenyl-20.00-Pieces; Mask & Sanitizer-600.00-			



			Pieces; 0-0.00-Q
Infrastructure Damaged - Embankment Breached	District	Number	Details
	Bajali	1	<b>Sarupeta</b> - Right bank Embankment of Pahumara river at medhikuchi   Medhikuchi   Embankment breached report received from concerned LM on 17th June,2022   (Long - 91.155941, Lat - 26.536503)
	Darrang	5	<b>Patharighat</b> - Nonoi R/B embankment   Kalitapara   breach at Nonoi R/B embankment at ch 10500 m time 10.30 pm on 16.5.2022 as reported by W/R Deptt   (Long - 0.000000, Lat - 0.000000), Nonoi R/B embankment   Kocharidol   breach at Nonoi R/B embankment at kacharidol time 11.00 pm on 16.5.2022 as reported by W/R Deptt   (Long - 0.000000, Lat - 0.000000), Nonoi R/B embankment   Kaikiapara   breach at Nonoi R/B embankment at Ch 8500 mt time 11.30 pm on 16.5.2022 as reported by W/R Deptt   (Long - 0.000000, Lat - 0.000000), <b>Sipajhar</b> - Nonoi Embankment R/B from MPK road to NH15   Chengelajhar at Ch.16800m   ..   (Long - 0.000000, Lat - 0.000000), Nonoi Embankment R/B from MPK road to NH15   Kacharidol at Ch. 20900m   ..   (Long - 0.000000, Lat - 0.000000)
	Hojai	1	<b>Lanka</b> - Kopili river dyke.   Dakhin Laskar pather Village   Breach at 10800m of Kharikhana to Jugijan Kopili Dyke. Breach width 20m.Work done by WRD. Dated: 17-06-2022.   (Long - 25.913653, Lat - 92.870593)
	Kamrup	1	<b>Kayan</b> - Baralia L/B embankment breach on 16/06/2022.   At two villages namely Dhuhi No.1 (chamukha) and Lormagurhati under Kayan Rev. Circle. Reported by WR, Rangia.   GPS co-ordinates could'nt be provided at the moment.   (Long - 0.000000, Lat - 0.000000)
	Lakhimpur	1	<b>Nowboicha</b> - Singra River side Bund   Fulbari Basti   Singra River Side Bund breached (approx 20 Mtr) at Fulbari Basti on 17.06.2022. Report received from Nowboicha Block Development Office   (Long - 0.000000, Lat - 0.000000)
	Nalbari	4	<b>Paschim Nalbari</b> - LB Buradia near Amoni Baba Than Area   Amoni   As per information received from LM & GB on 16/06/2022   (Long - 0.000000, Lat - 0.000000), LB of River Buradia near Pukhura village   Pokhura   As per information received from LM & GB on 16/06/2022   (Long - 0.000000, Lat - 0.000000), <b>Tihu</b> - Niz Khana Agril Bundh Tihu Nadi   Niz Khana   As per report GB as on 16-06-2022 length 15m approx   (Long - 26.460668, Lat - 91.248111), Bali Agril Bandh Mora Pagaldia   Dakhin Bali   As per report GB as on 16-06-2022 length 30m approx   (Long - 26.449363, Lat - 91.318202)
	Tamulpur	4	<b>Goreswar</b> - Bagaribari Right Bank   Bagaribari   17/06/2022 breach occurred at two points approximately damage 50 m each   (Long - 0.000000, Lat - 0.000000), Dhulabari Right bank   Dhulabari   Dated 17/06/2022 breach occurred at Village Dhulabari approximately width damage 50 m   (Long - 0.000000, Lat - 0.000000), Bholajhar Panchayat Bandh   Village Bholajhar   Dated 17/06/2022 right bank breached approximately damage 20 m.   (Long - 0.000000, Lat - 0.000000)
Total	17		
Infrastructure Damaged - Embankment Affected	District	Number	Details
	Baksa	1	<b>Barama</b> - R/B embankment of Mora Pagladia   At village Niz Juluki near Gopal than   Crack observed at a reach of length 10 m. Date of occurrence: 16/06/22   (Long - 91.349799, Lat - 26.519949)
	Barpeta	2	<b>Barnagar</b> - PWD Road cum Embankment from Barpeta Road to Bashbari   Village- Uttar safakamar   As per report received from JE, WR Dept on 16/06/2022 Embankment damaged due to heavy rain fall.   (Long - 26.550013, Lat - 90.974620), <b>Chenga</b> - B/dyke on R/B of river Brahmaputra from Adabari to Kukarjan from Ch.5.80km to 33.232 km   Roumari Pathar, Balartari, Chenimari, Roumari Bazar   B/dyke on R/B of river Brahmaputra from Adabari to Kukarjan from Ch.5.80km to 33.232 km,casue of damage erosion, report by W.R division, Mukalmua on 16.6.22   (Long - 91.232474, Lat - 26.257979)
	Charaideo	1	<b>Mahmora</b> - Gorja gaon embankment of Desang River   Village Deodhai , Mouza - Khaloighugura, Mahmora Revenue Circle   Embankment is damaged on 17/06/2022 , Name of the river - desang, damaged length 200 m approximate as reported by Water Resource Department , Demow   (Long - 27.038333, Lat - 94.879722)
	Darrang	1	<b>Patharighat</b> - Nonoi R/B embankment   Khatara Kaikiapara   Overtopping on embankment as reported on 16.6.2022 midnight by W.R.D   (Long - 0.000000, Lat - 0.000000)
	Kamrup	2	<b>Rangia</b> - Uttar Bardol Puthimari R/B   Vill- Uttar Bardol   Rain water had damaged the CS slope at uttar Bardol, Puthimari R/B as per report of JE, WR Dept, Rangia on 16.06.2022. Temporary measures undertaken   (Long - 91.687718, Lat - 26.465089), <b>Kayan</b> - Baralia L/B embankment. Date: 16/06/2022   Dhuhi No.1 (Chamukha) and Lormagurhati under Kayan Rev. Circle. Reported by WR, Rangia.   GPS co-ordinates couldn't be provided at the moment.   (Long - 0.000000, Lat - 0.000000)
Karimganj	2	<b>Nilambazar</b> - Embankment along both bank of River Longai   From Patherkandi to Nilambazar Ph-II R/B   On 16-06-2022, the EE, Karimganj W.R. Division Karimganj reported that on 21-05-2022,	

			sloughing is observed at Cherrabazar, Teoghor, Issaganj and Bahadurpur and presently due to incessant rainfall, the embankment at the said locations is affected   (Long - 24.715558, Lat - 92.333643), Embankment along both bank of River Longai   Nilambazar to Krishnanagar Ph-I L/B   On 16-06-2022, the EE, Karimganj W.R. Division Karimganj reported that on 21-05-2022, sloughing is observed at Krishnanagar, Gandhai and Medha and presently due to incessant rainfall, the embankment at the said locations is affected   (Long - 24.759522, Lat - 92.340291)
	Lakhimpur	1	<b>Bihpuria</b> - Dikrong L/B Embankment   Chichapathar village near Trinayan Mandir   Seepage/Boiling of the embankment at CH. 13000 observed on 17th June 2022 as reported by WRD, Bihpuria   (Long - 93.937442, Lat - 27.031229)
	South Salmara	1	<b>South Salmara</b> - South Salmara Collage to Tumni bandh cum road   Tumni Laokhowa   As per Field visit by field Officer and LM the bandh has been damaged several locations due to heavy rainfall on 17/6/22 lenth 1.5 km   (Long - 90.000000, Lat - 25.870000)
	Total	<b>11</b>	
	<b>District</b>	<b>Number</b>	<b>Details</b>
Infrastructure Damaged - Road	Barpeta	46	<b>Baghbar</b> - 1.Baghbar Satra to Baghbar Thana   Baghbar gaon   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-450 m Reported by PWD deptt.   (Long - 90.995278, Lat - 26.265878), 2 Mondia Rowmari road to Dapnasing road   1 no Bardoloni   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-(450m,500m,650m,700m)= 450m Reported by PWD deptt.   (Long - 90.932119, Lat - 26.259443), 3 Bamundongra tiniali to Baksabanda road Pkg no As-01-339   Baskabanda   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-(300.00 m to 1000m)=300m Reported by PWD deptt.   (Long - 90.965756, Lat - 26.267875), 4. Kalpana azar to Satrakanara 5 no seat Pkg no As-01-341   Satrakanara 5 no seat   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-Ch.300m,450m,550m,600m)=150m Reported by PWD deptt.   (Long - 90.964757, Lat - 26.267576), 5. Saalimpur Jadavpur Kanchanpur Road   Salimpur, Jadavpur Kanchanpu   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-2050 m Reported by PWD deptt.   (Long - 90.994767, Lat - 26.268566), 6. Mondia GP Office to 2 no Bordoloni Chariali PKG no As-01-281   2 no bardoloni   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-Ch.(0m to 40m,350m,550m,600m)=450m Reported by PWD deptt.   (Long - 90.984768, Lat - 26.267546), 7. Agmondia Chariali to Mondia gaon via E&D . Pkg no As-01-241   Mandia gaon   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-ch.(550,600,850,1050,1160m)=450m Reported by PWD deptt.   (Long - 90.995786, Lat - 26.267978), 8. Mouripam to Bhairarpam chariali rd. Pkg no As-01-258   Mouripam,Bhairarpam   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-Ch.(300m,450m,650m,950m,1100m)=650m Reported by PWD deptt.   (Long - 90.997685, Lat - 26.268679), 9 Satrakanara Bazar to Manikpur HS Road   Satrakanara   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-Ch.( 450m,600m,850)=600m, Reported by PWD deptt.   (Long - 90.997865, Lat - 26.267678), 10. Jadavpur HS to Salimpur MPNA Road . Pkg no As-01-332   Jadavpur   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-Ch.750m,860m,980m)=250m Reported by PWD deptt.   (Long - 90.987875, Lat - 26.257878), 11 Chasra no 2 to Tedhera Pathar Pkg no As-01-77   Tedherapathar   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-Ch( 350m,450m,600,730,860,1050,1250m,1000m,1560m) =2000m Reported by PWD deptt.   (Long - 90.997865, Lat - 26.267676), 12 Pachim Chaysimana Madrassa to Sukhowarjhar Road Pkg no As-01-358   Dharmapur, Pachimchaysimana   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length-ch.(350m to 550m,750m to 1250m, 1650m to 3500m, 4850m to 13500m)= 8500.00m Reported by PWD deptt.   (Long - 90.987875, Lat - 26.257578), 13 Majorchar to Khatiamari Road Pkg no As-01-201   Majorchar, Khatiamari   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-Ch.450m,550m,1150m,1560m,1850m)=1050m Reported by PWD deptt.   (Long - 90.997654, Lat - 26.267898), 14 1653 no satrakanara Barakata LPS to new E&D PKG no 247   Satrakanara 5 no seat   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-Ch.300m to 700m=400m Reported by PWD deptt.   (Long - 90.998764, Lat - 26.257698), 15.Baghbor PWD Sub-Division road to Mandia Rowmari road.   Mandia   Date of damage-16-06-2022 Type of damage-shoulder & H/C damage Damage length(m)-0.00m to 50m=50m Reported by PWD deptt.   (Long - 90.989865, Lat - 26.267875), 16 Mandia-Dighirpam Road on SPT Bridge No. 10/1( Sub structure& Super Str) and RCC Br no 11/1& 12/1 apprhoach   Dighirpam   Date of damage-16-06-2022 Type of damage-App, Sub Str.&

		<p>Super str. Damage length(m)-80m Reported by PWD deptt.   (Long - 90.989756, Lat - 26.265786),  17. Mandia-Dongra road   Mandia   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage Damage length(m)-150m Reported by PWD deptt.   (Long - 90.996746, Lat - 26.267586),  18. Mandia-Dongra road on RCC Slab-culvert and RCC br app of br No. 1/1 &amp; 1/2 approach   Dongra   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-300m Reported by PWD deptt.   (Long - 90.007865, Lat - 26.267676),  19. Mandia-Palhaji road on RCC Bridge No. 3/1 approach   Agmandia   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-250m Reported by PWD deptt.   (Long - 90.997754, Lat - 26.268578),  20. Mandia Digharpam road to Mourigaon road via Dr. Atower Rahman house.   Mourigaon   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-200m Reported by PWD deptt.   (Long - 90.998756, Lat - 26.267576),  21. Satrakanara 9 No. Seat to 15 No. Seat road   Satrakanara 9 no seat   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-350m Reported by PWD deptt.   (Long - 90.998655, Lat - 26.268656),  22. Mandia Dighirpam road 1st KM   Dighirpam   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-550m Reported by PWD deptt.   (Long - 90.989675, Lat - 26.265458),  23. Kapoha SCSP road to Kapoha PMGSY road.   Kapoha   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-250m Reported by PWD deptt.   (Long - 90.997676, Lat - 26.264758),  24. Barpeta Mandia PWD road to Kapoha SCSP road.   Kapoha   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-300 m to 450 m Reported by PWD deptt.   (Long - 90.997586, Lat - 26.265869),  25. Barpeta-Baghar road.   Baghar Gaon   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-2040m Reported by PWD deptt.   (Long - 90.997687, Lat - 26.267689),  26. Milijuli Bazar to Rajiv Nagar via Social forest road, Pkg no As-01-200   Rajiv nagar   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)- ch.400m, 600m, 780m, 1120m, 1390m Reported by PWD deptt.   (Long - 90.996787, Lat - 26.259689),  27. 1254 no Paharpur LPS to Bhairarpam Chariali road. Pkg no As-01-350   Bhairarpam   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-ch. 400m, 700m, 1050m, 1260m= 950m Reported by PWD deptt.   (Long - 90.986797, Lat - 26.269789),  28. Paharpur to Bamundongra Kabarsthan Pkg no As-01-260   Paharpur   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-350m to 800m= 450m Reported by PWD deptt.   (Long - 90.997697, Lat - 26.266878),  29. Allengipathar LPS to Satrakanara 12 no seat road Pkg no As-01-256   Allengipathar   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-ch 1200m to 1265m= 65m Reported by PWD deptt.   (Long - 90.995695, Lat - 26.265778),  30. Sokhowarjhar to Bhatnapaity Moishkhuti MEM Pkg No AS-01-273   Bhatnapaity   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-ch. 250m to 8000m = 7500m Reported by PWD deptt.   (Long - 90.987785, Lat - 26.259767),  31. kalairdia to 1 no Baghmar char via Nichanar Char road Pkg no AS-01-272   Nichanarchar   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-ch. 1200m to 8500m = 5070m Reported by PWD deptt.   (Long - 90.949740, Lat - 26.111654),  32. Satrakanara 5 no. seat to satrakanara 12 no seat road Pkg no As-01-228   Satrakanara 12 no. seat   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-ch. 350m to 6500m= 1430m Reported by PWD deptt.   (Long - 90.966779, Lat - 26.267664),  33. Chasra no 1 to Mandia Bordoloni road   Chasra no. 1   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-ch. 560m to 1800m = 250m Reported by PWD deptt.   (Long - 90941575.000000, Lat - 26.245594),  34. Kapoha to Medhertary road Pkg no As-01-213   medhertary   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-650m to 1100m = 450 m Reported by PWD deptt.   (Long - 90.996788, Lat - 26.267865),  35. 4 no. Bordoloni to Kapoha via Dapnasing road Pkg no as-01-267   4 no. Bardoloni   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-2450m to 3400m = 950m Reported by PWD deptt.   (Long - 90.986778, Lat - 26.267765),  36. Mandia Dighirpam (Br no 9/1) to Tedhera Pathar Road Pkg no As- 01-276   Therapathar   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-650.00m to 900m= 350m Reported by PWD deptt.   (Long - 90.996776, Lat - 26.267668),  37. Sikatary MES to Pub Tarakandi Road Pkg no As-01-228   Tarakandi   Date of damage-16-06-2022 Type of damage-shoulder &amp; H/C damage. Damage length(m)-Ch 500m to 1130m = 250m Reported by PWD deptt.   (Long - 90.996786, Lat - 26.257867),  <b>Sarthebari</b> - Baisha to Barmara PWD Road   Brmara   Reported By Gaon Pradhan on 17.06.2022   (Long - 0.000000, Lat - 0.000000),  <b>Kalgachia</b> - Kalgachia to Sorbhog via Tengagaon road   At various points between kalgachia and Tengagaon chowk   As per report received from PWD department on 17/06/22, due to continuous</p>
--	--	--

			<p>heavy rainfall kalgachia to sorbhog via Tengagaon road (PMGSY pkg No. AS-01-475) road submerged at 1st km, 6th km, 7th km (Avg submerged height=30.00 cm, length= 400.00 m, coordinates- 26.361239, 90.873642/ 26.393726, 90.87884/ 26.404086, 90.896633) and also damaged road shoulder at ch. 3rd km, 5th km and 6th km (total length=300.00 m, width=1.50 m, avg. height= 1.80 m, coordinates- 26.375572, 90.883649/ 26.386749, 90.886467/ 26.394358, 90.888473).   (Long - 0.000000, Lat - 0.000000),</p> <p>Monakacha to chakla HS school road   At various point Monakacha to Haldhia Gaon   As per report received from PWD department on 17/06/22, due to continuous heavy rainfall Monakacha to chakla H S school road has submerged from ch 100.00 m to ch. 700.00 m (length=600.00 m, height= 60.00 cm and coordinates- 26.393619, 90.847863.   (Long - 0.000000, Lat - 0.000000),</p> <p>Khatakuchi to Chakla PMGSY road   various points at khatakuchi to Haldhia pathar   As per report received from PWD department on 17/06/22, due to continuous heavy rainfall Khatakuchi to Chakla PMGSY road (pkg No.AS-01-59) has submerged from ch. 1500.00 m to 1700.00 m (submerged length=200.00 m, height= 30.00 cm, coordinates- 26.409430, 90.857905   (Long - 0.000000, Lat - 0.000000),</p> <p><b>Barnagar</b> - Const of rd from abdul halim house to Akbar ali   Ghugubari   As per report received from Rupshi dev Block office on 17/06/2022 the MGNREGA road from abdul halim house to Akbar ali damaged due to heavy rain L= 180m, B= 1.5m, H= 0.6m   (Long - 0.000000, Lat - 0.000000),</p> <p>Const of rd with Haldhia HP culvertfrom Joynal Abdin house to abed ali house   Dharmapur   As per report received from Rupshi dev Block office on 17/06/2022 the due to heavy rain L= 300m, B= 1.5m, H= 0.5m   (Long - 90.863857, Lat - 26.417019),</p> <p>Beki Par to Balabhitha Road   Jashihati   as per WT message received from Ex Engineer, PWD, Sorbhog &amp; Jania Terr. Road Divn, Barpeta Road on 17/06/2022bthe mentioned road is breached of 25 m occurred due to heavy rain.   (Long - 0.000000, Lat - 0.000000),</p> <p>NH 31 to kalahbhanga vidyapara road   Kalahbhanga &amp; Satboinir tup   as per WT message received from Ex Engineer, PWD, Sorbhog &amp; Jania Terr. Road Divn, Barpeta Road on 17/06/2022 the mentioned road is damaged due to heavy rain at CH 1000m   (Long - 0.000000, Lat - 0.000000),</p> <p>Sanosh Karmakar house to 1933 No west Nisuka LP school road   Nisuka &amp; Barpeta Road   as per WT message received from Ex Engineer, PWD, Sorbhog &amp; Jania Terr. Road Divn, Barpeta Road on 17/06/2022 the mentioned road is damaged due to heavy rain at CH 0.4 m, 0.500m, and 0.600m   (Long - 0.000000, Lat - 0.000000)</p>
Bongaigaon	43		<p><b>Manikpur</b> - Manasghat Sakisali Road   Manasghat Sakisali Road   Road embankment , surface damaged and road submerged at 5th to 10th km. Average. Submergence depth 20 cm reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.790815, Lat - 26.431621),</p> <p>Gerukabari Jamdoha PMGSY Road   Gerukabari Jamdoha PMGSY Road   Side shoulder &amp; hard crust damaged &amp; approach of RCC Culvert No 1/3 damaged at Ch. 300.00 m reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.704158, Lat - 26.453926),</p> <p>Manikpur Sakisali Road   Manikpur Sakisali Road   Approach of RCC Bridge no 4/1, 4/2 &amp; 5/1 damaged at 4th &amp; 5th km reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.825423, Lat - 26.436146),</p> <p>Old NT road   Old NT road   Approach of RCC Br. No 2/1 damaged and eroded at 2nd km reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.795583, Lat - 26.465989),</p> <p>Hapachara Borbila to Silghagri road   Hapachara Borbila to Silghagri road   Hard crust and Shoulder damage at ch 1350.00m Ch. 2300.00m Road submerged at 2nd km to 4th km. Average submergence depth 60cm. Approach of Culvert No. ¼ damage reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.744685, Lat - 26.438632),</p> <p>Samukamari to Salabila Bazar road   Samukamari to Salabila Bazar road   Hard crust and shoulder damaged at 1st km &amp; 2nd km reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.764577, Lat - 26.437360),</p> <p>Manikpur to Bashbari road   Manikpur to Bashbari road   Water logging at ch. 1st km, shoulder damage at 1st, 2nd, 3rd, 4th ,5th &amp; 6th km reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.783444, Lat - 26.421127),</p> <p>NH31 to Darkinamari road   NH31 to Darkinamari road   Road submerged at 3rd &amp; 4th .km average submergence depth 30 cm reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.641673, Lat - 26.494025),</p> <p>Roha Chakla Kokila road   Roha Chakla Kokila road   Approach of RCC Br. No 7/1 damaged at 7th km reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.840268, Lat - 26.409399),</p> <p>Sialmari Solmara road   Sialmari Solmara road   Road submerged by flood water of river Dulani from Ch. 3500.00m to Ch. 4100.00m &amp; damaged road surface etc. Submergence depth 40 cm reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.759074, Lat - 26.491594),</p> <p>NH-31 to Darkinamari road   NH-31 to Darkinamari road   Breached occurred at Ch 850.00 m to Ch 855.00m and road submerged at ch 500.00m to Ch 850.00m .Submergencedepth 30cm reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.638112, Lat - 26.492040),</p> <p>NH-31 to Daokijhar road   NH-31 to Daokijhar road   Road submerged and road surface damaged at ch 400.00m to ch 650.00m reported by PWRD, Bongaigaon date of incident 16.06.2022   (Long - 90.646538, Lat - 26.498191),</p>

		<p><b>Bongaigaon</b> - NH 31C Popragaon PMGSY road to Korebari road   Korebari   A length of 10 m road portion washed away at Ch 200 m depth of erosion=0.08 m. Road submerged depth 20 cm. Erosion of side slops, edge restrain. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.619676, Lat - 26.489413),</p> <p>Majgaon Ghondol Road   Majgaon   Shoulder and approach of RCC brider no 2/1 damaged at 2nd km. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.368000, Lat - 26.485800),</p> <p>Siponsila Monakocha Road   Monakocha   Nature of Damage- Approach of RCC Bridge No 1/1 damaged at ch 250.00 m. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.364600, Lat - 26.243600),</p> <p>Siponsila Kahipara Road   Siponsila   Approach of RCC Bridge No 1/1damaged at Ch 700.00 m. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.371500, Lat - 26.244400),</p> <p>Siponsila Kashibari Road   Siponsila   Approach of RCC Bridge No. 1/1 washed away by the flood water of river Kujia at Ch 950.00m Shulder eroded at ch 1100.00m. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.375000, Lat - 26.252700),</p> <p>Kathilguri to SH-2 via Sipansila Pt.III Road   Kathilguri   Nature of Damage- Shoulder with hard crust damaged by flood water of river Kujia at Ch. 5450.00m. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.371900, Lat - 26.253700),</p> <p>Kashidoba Kakojana Road   Kashidoba   Embankment eroded by flood water of river Kujia at Ch 4500.00 m. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.372700, Lat - 26.244300),</p> <p>Hatimutura Bakhrapara Road   Hatimutura   Nature of Damage-Culvert approach settled down at ch 450.00.as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.343400, Lat - 26.262000),</p> <p>Bageswari Temple to Bakharapara Pt.II Road   B.T Road   Nature of Damage- Hard crust and road shoulder eroded at ch 1100.00m. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.569043, Lat - 26.466978),</p> <p>Bageswari Temple to Deuripara road   B.T Road   Nature of Damage- Hard crust and shoulder damaged at Ch 100.00m to Ch 250.00m.as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.563631, Lat - 26.468217),</p> <p>B.Ed. College approach road   B.Ed. College   Nature of Damage- Hard crust damaged at Ch.0.00m to Ch.400.00m. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.564221, Lat - 26.470926),</p> <p>New Bongaigaon Dolaigaon road   New Bongaigaon   Nature of Damage- Road damaged by occurring big depression surface become muddy, water logged in carriage way at ch. 0.00 m to Ch. 500.00m. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.523272, Lat - 26.490535),</p> <p>Saonagaon Fakir Bazar road   Saonagaon   Nature of damage- Bridge approach of Bridge No ½ at 1st km. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.499993, Lat - 26.424939),</p> <p>Jelkajhar to Gang Quarter Road   jelkajhar   Approach of culvet No No. 2/1 damaged at Ch. 1300.00 m. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.531066, Lat - 26.473781),</p> <p><b>Boitamari</b> - Jogighopa Salbari Road   Jogighopa   RoadNature of Damage- Road submerged at 17th &amp; 20th km. Average submergence depth 20 cm as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.496243, Lat - 26.309038),</p> <p>Balapara Hokodoba Road   Balapara   Nature of Damage- Road submerged at 2nd km. Average submergence depth 15 cm. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.531847, Lat - 26.255282),</p> <p>Jogighopa Salbari Road   Jogighopa   Nature of Damage- Embankment partially damaged at 11th km. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.708796, Lat - 26.282422),</p> <p>Kabaitari I to Kabaitari IV Road   Kabaitari I   Rain cut occurred at 1st km. as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.708796, Lat - 26.282422),</p> <p><b>Dangtol</b> - Dhontola Nankargaon road   Dhontola   Water stegnent at various stretches of the road from 1st to 2nd km. as per report received PWRD, Bongaigaon date-16.06.2022   (Long - 90.467782, Lat - 26.365693),</p> <p>Paltan Bazar Hollaguri Road   Hollaguri   Bridge approach of Br. No 1/1 damaged at 1st km and hard crust damaged, side shoulder erroded at Ch. 2000.00 m to 2200.00m as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.414727, Lat - 26.379137),</p> <p>Mulagaon Chengmari Road   Chengmari   Hard crust &amp; side shoulder erroded at 10th km as per report received from 16.06.2022   (Long - 90.475685, Lat - 26.382423),</p> <p><b>Srijangram</b> - Kuchbari Dubachari Road   Kuchbari Dubachari Road   Road is in endangered position from river Manas at 1st km as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.710795, Lat - 26.276578),</p> <p>Kerkhabari I to kerkhabari II Road   Kerkhabari I to kerkhabari II Road   Road submerged at 1st km. Average submergence depth 20 cm as per report received from PWRD, Bongaigaon date-16.06.2022  </p>
--	--	--

		<p>(Long - 90.619791, Lat - 26.298001),  Borigaon Mererchar Road   Borigaon Mererchar Road   Rain cut occurred at 2nd, 4th &amp; 5th km    (Long - 90.708796, Lat - 26.282422),  Rangapani State Highway to Mulbari Parghat Raod   Rangapani State Highway to Mulbari Parghat  Raod   Approaches of RCC Br. No. 3/1 damage and eroded at 3rd km as per report received from  PWRD, Bongaigaon date-16.06.2022   (Long - 90.781091, Lat - 26.327249),  Kirtanpara to Narabhita road   Kirtanpara to Narabhita road   Shoulder &amp; hard crust damaged at 1st &amp;  2nd km as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.716861, Lat -  26.384381),  Ujanpara Ambari road   Ujanpara Ambari road   Water logging at 1st km approach of RCC bridge No  1/1 damaged as per report received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.716861,  Lat - 26.384381),  Nowagaon Rangapani road to Numberpara Bazar road   Nowagaon Rangapani road to Numberpara  Bazar road   Road embankment damaged at 1st km, STP Bridge approach damaged.as per report  received from PWRD, Bongaigaon date-16.06.2022   (Long - 90.813805, Lat - 26.400069),  Chakla Amtola to Kokila road   Chakla Amtola to Kokila road   Road embankment and road surface  damage at 1st, 2nd &amp; 3rd km as per report received from PWRD, Bongaigaon date-16.06.2022    (Long - 90.844374, Lat - 26.386435),  Nowagaon Rangapani road   Nowagaon Rangapani road   Road embankment and road surface eroded  at 7th,8th &amp; 9th km as per report received from PWRD, Bongaigaon date-16.06.2022   (Long -  90.818442, Lat - 26.378880),  Kirtanpara Nararvita road   Kirtanpara Nararvita road   Erosion of side berm and damage occurred on  hard crust at 2nd km as per report received from PWRD, Bongaigaon date-16.06.2022   (Long -  90.716861, Lat - 26.384381)</p>
Chirang	1	<p><b>Bijni</b> - Boupara Village Road   At Boupara   Boupara village road damaged On 15-06-2022 at  Baupara village. Damage Details:: Length=5 mtr, Breadth=5 mtr, Depth=2 mtr.   (Long - 90.806101,  Lat - 26.565533)</p>
Darrang	6	<p><b>Dalgaon</b> - No.2 Kheteswar to No.1 Arimari road   No.2 Kheteswar to No.1 Arimari road at CH. 5450    No.2 Kheteswar to No.1 Arimari road has been partially damaged and raincut occurred at ch 5450  about 1.5m x 1.8m date of occurrence -16/06/2022   (Long - 0.000000, Lat - 0.000000),  Nadirkash to Bechimari road   Nadirkash to Bechimari road at CH-1700m to CH-2100   Nadirkash to  Bechimari road has been submerged at CH-1700m to CH-2100m about height .45m and raincut  occured at various location date of occurrence -16/06/2022   (Long - 0.000000, Lat - 0.000000),  No.2 Mazgaon to madhupur   date of occurrence -16/06/2022 at ch.1800m to 2100m has been  submerged on 16/06/2022   No.2 Mazgaon to madhupur road has been submerged at ch.1800m to  2100m on 16/06/2022   (Long - 0.000000, Lat - 0.000000),  No.1 Kheteswar to NH-52   No.1 Kheteswar to NH-52 at CH- 2100m to CH- 2200m   No.1  Kheteswar to NH-52 road has been submerged at CH- 2100m to CH- 2200m on 16/06/2022   (Long -  0.000000, Lat - 0.000000),  kachomari chapori habi to NH-52 road   kachomari chapori habi to NH-52 road at CH-5400 to 5580m  and CH- 6450m to 7100m and 9300 to 9400   kachomari chapori habi to NH-52 road has been  submerged at CH-5400 to 5580m and CH- 6450m to 7100m and 9300 to 9400 on 16/06/2022   (Long  - 0.000000, Lat - 0.000000)</p>
Dhemaji	5	<p><b>Jonai</b> - PWD territorial road embankment 10.00 meter partially damaged at NH-52 to Naharani  Mohanpur Road under package no. As-04-170 on 16/07/2022 by River Mopi   From Ch.920.00M to  Ch.930.00M   As per report received from PWRD, Jonai Territorial Road Sub-Division-II, Jonai a  PWD territorial road embankment 10.00 meter partially damaged at NH-52 to Naharani Mohanpur  Road under package no. As-04-170 on 16/07/2022 by River Mopi.   (Long - 94.926977, Lat -  27.732597),  PWD territorial road embankment 100.00 meter (right side) partially damaged at Junekareng Rest  Camp Tiniali to Mainapur Chariali via Nahar Detak Road on 16/06/2022 by Nahar Detak River.    From Ch.290.00M to Ch.390.00M   As per report received from PWRD, Jonai Territorial Road Sub-  Division-II, Jonai a PWD territorial road embankment 100.00 meter (right side) partially damaged at  Junekareng Rest Camp Tiniali to Mainapur Chariali via Nahar Detak Road on 16/06/2022 by Nahar  Detak River.   (Long - 95.158261, Lat - 27.791467),  PWD territorial road embankment toe(both sides) 100 meter(right) &amp; partially damaged on 100  meter(left) Jonai Nepali Basti College Tiniali to Deepi Bridge via Upendra Barmah high School on  17/06/2022 by Sansuri Nallah.   From Ch.1250.00M to Ch.1350.00M &amp; From Ch.1370.00M to  Ch.1470.00M   As per report received from PWRD, Jonai Territorial Road Sub-Division-II, Jonai a  PWD territorial road embankment toe(both sides) 100 meter(right) &amp; partially damaged on 100  meter(left) Jonai Nepali Basti College Tiniali to Deepi Bridge via Upendra Barmah high School on  17/06/2022 by Sansuri Nallah. For immediate restoration contractor Jitu Pegu has been engaged.    (Long - 0.000000, Lat - 0.000000),  PWD territorial road embankment 20.00meter partially damaged at PHC to Railway Station Masjid  road under Package No. As-04-85 on 17/06/2022 by Koke Nallah Water Channel.   From Ch.810.00M  to Ch.830.00M   As per report received from PWRD, Jonai Territorial Road Sub-Division-II, Jonai a  PWD territorial road embankment 20.00meter partially damaged at PHC to Railway Station Masjid</p>

		road under Package No. As-04-85 on 17/06/2022 by Koke Nallah Water Channel.   (Long - 95.005558, Lat - 27.765608), <b>Sissiborgaon</b> - Bhairabpur PWD road via Kulajan Pam to Ashirghar   Bhairabpur via Kulajan to Ashighar   300 m of road under submergence at Ch 3000.00 m as on 17/06/2022   (Long - 27.579203, Lat - 94.776616)
Dhubri	46	<p><b>Gauripur</b> - SIDE BERM AND HARD CRUST DAMAGED ALOMGANJ-FULKATARI ROAD AT 2ND AND 3RD KM Dated (13/06/2022 to 17/06/2022)   ALOMGANJ-FULKATARI    (Long - 0.000000, Lat - 0.000000), SIDE BERM AND HARD CRUST DAMAGED MATIA BAGH TO CHARALDANGA ROAD AT 2ND KM Dated (13/06/2022 to 17/06/2022)   MATIA BAGH TO CHARALDANGA    (Long - 0.000000, Lat - 0.000000), SIDE BERM AND HARD CRUST DAMAGED SAHEBGANJ BAZAR TO RUPSHI BAZAR 1ST AND 3RD KM Dated (13/06/2022 to 17/06/2022)   SAHEBGANJ BAZAR TO RUPSHI BAZAR    (Long - 0.000000, Lat - 0.000000), SIDE BERM AND HARD CRUST DAMAGED GHAGERALGA ROAD BUG BR. TO BORAIBARI ROAD Dated (13/06/2022 to 17/06/2022)   GHAGERALGA    (Long - 0.000000, Lat - 0.000000), SIDE BERM AND HARD CRUST DAMAGED KHUDIMARI-DUMURDOHA –KALAHAT-BINNACHARA ROAD AT 7TH AND 8TH KM Dated (13/06/2022 to 17/06/2022)   KHUDIMARI-DUMURDOHA –KALAHAT    (Long - 0.000000, Lat - 0.000000), SIDE BERM DAMAGED 1ST KM AND 2ND KM OF KHUDIMARI TO GAURIPUR BASHBARI ROAD Dated (13/06/2022 to 17/06/2022)   KHUDIMARI    (Long - 0.000000, Lat - 0.000000), SIDE BERM DAMAGED 1ST KM OF 3RD KM OF ALOMGANG TO SILAIPAR ROAD TSHYAMSARENER KUTI ROAD Dated (13/06/2022 to 17/06/2022)   ALOMGANG TO SILAIPAR    (Long - 0.000000, Lat - 0.000000), . SIDE BERM DAMAGED NH-31 AT MURALIGHAT TO TARGHAT VIA GOALER GAON ROAD CH.2000M TO 3400M Dated (13/06/2022 to 17/06/2022)   MURALIGHAT TO TARGHAT   DHORARGHAT   (Long - 0.000000, Lat - 0.000000), . SIDE BERM AND HARD CRUST DAMAGED BALAJAN SAHEBGANJ PWD ROAD TO DHORARGHAT AT 1ST KM Dated (13/06/2022 to 17/06/2022)   DHORARGHAT    (Long - 0.000000, Lat - 0.000000),</p> <p><b>Dhubri</b> - ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF .D.K ROAD AT 10TH &amp; 11TH KM IN STRETCHES BY FLOOD WATER OF RIVER GANGADHAR Dated (13/06/2022 to 17/06/2022)   D.K ROAD    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DMAGED OF DHUBRI PATAMARI ROAD AT 9TH KM TO 12TH KM IN STRETCHES BY FLOOD WATER OF RIVER BRAHMAPUTRA Dated (13/06/2022 to 17/06/2022)   PATAMARI    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF TISTARPAR PMGSY ROAD TO TISTARPAR BSF CAMP ROAD AT 1ST KM IN STRETCHES Dated (13/06/2022 to 17/06/2022)   TISTARPAR    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF GHEWMARI BAZAR TO GHEWMARI BSF CAMP AT 1ST KM IN STRETCHES Dated (13/06/2022 to 17/06/2022)   GHEWMARI    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF GHEWMARI BSF CAMP TO IBB FENCHING ROAD AT 1ST KM IN STRETCHES INCLUDING RCC BRIDGE APPROACH OF BR. NO. 1/1 Dated (13/06/2022 to 17/06/2022)   GHEWMARI    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF GASPARA SLUICE GATE TO PURANPARA VILLAGE ROAD AT 1ST &amp; 2ND KM IN STRETCHES Dated (13/06/2022 to 17/06/2022)   GASPARA    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF GASPARA PANCHAYAT OFFICE TO BSF TENT POST ROAD AT 1ST KM IN STRETCHES Dated (13/06/2022 to 17/06/2022)   GASPARA    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF ROAD FROM DHARMASLA DURAHATI ROAD TO GHEWMARI VIA TISTARPAR ROAD AT 1ST TO 6TH KM IN STRETCHES Dated (13/06/2022 to 17/06/2022)   DHARMASLA DURAHATI    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF DHUBRI GAURIPUR ROAD AT 6TH KM IN STRETCHES Dated (13/06/2022 to 17/06/2022)   DHUBRI GAURIPUR ROAD    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE DAMAGED OF FALIMARI PMGSY ROAD TO FALIMARI PT-II VILLAGE (ARATI VILLAGE) ROAD AT 1ST &amp; 2ND KM INSTRETCHES Dated (13/06/2022 to 17/06/2022)   FALIMARI    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF FALIMARI PMGSY ROAD TO FALIMARI PT-I VILLAGE (GAONJOLA BRIDGE) AT 2ND KM TO 4TH KM IN STRETCHES Dated (13/06/2022 to 17/06/2022)   FALIMARI    (Long - 0.000000, Lat - 0.000000), ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF FALIMARI PT-I VILLAGE</p>

(MARKET) TO FALIMARI PT-II VILLAGE ROAD AT 1ST TO 3RD KM IN STRETCHES Dated (13/06/2022 to 17/06/2022) | FALIMARI || (Long - 0.000000, Lat - 0.000000),  
ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF FALIMARI PT-II VILLAGE (GHORAMAR) AT 1ST KM IN NSTRETCHES Dated (13/06/2022 to 17/06/2022) | FALIMARI || (Long - 0.000000, Lat - 0.000000),  
ROAD FORMATION AND SIDE SLOPE BADLY DAMAGED OF DHUBRI PATAMARI ROAD AT 3RD KM TYO 7TH KM IN STRETCHES Dated (13/06/2022 to 17/06/2022) | PATAMARI || (Long - 0.000000, Lat - 0.000000),  
SIDE SLOPE DAMAGED OF KALAHAT CHARIALI TO GASPARA ROAD FROM 4TH TO 6TH KM IN STRETCHES Dated (13/06/2022 to 17/06/2022) | KALAHAT CHARIALI TO GASPARA || (Long - 0.000000, Lat - 0.000000),  
ROAD FORMATION DMAGED OF VELAKOBA SINGIMARI ROAD AT 2ND KM IN STRETCHES Dated (13/06/2022 to 17/06/2022) | VELAKOBA SINGIMARI ROAD || (Long - 0.000000, Lat - 0.000000),  
SIDE SLOPE & SIDE BERM DAMAGED ON KISMAT HASDAHA SINGIMARI ROAD TO TISTARPAR ROAD AT 3RD KM IN STRETCHES Dated (13/06/2022 to 17/06/2022) | KISMAT HASDAHA SINGIMARI ROAD TO TISTARPAR || (Long - 0.000000, Lat - 0.000000),  
SIDE SLOPE & SIDE BERM DAMAGED ON DHARMASLA DURAHATI ROAD VIA SINGIMARI AT 1ST KM Dated (13/06/2022 to 17/06/2022) | DHARMASLA DURAHATI || (Long - 0.000000, Lat - 0.000000),  
SIDE SLOPE & SIDE BERM DAMAGED ON DHARMASALA MOTIRCHAR TO DHARMASALA GIRLS LP SCHOOL AT 1ST KM Dated (13/06/2022 to 17/06/2022) | DHARMASALA MOTIRCHAR || (Long - 0.000000, Lat - 0.000000),  
SIDE SLOPE & SIDE BERM DAMAGED ON KACHUARKHASH PT-I PWD ROAD NEAR UMAR UDDIN MEMORIAL HIGH SCHOOL TO CHANDAKHOLA BILL AR 1ST & 2ND KM Dated (13/06/2022 to 17/06/2022) | KACHUARKHASH || (Long - 0.000000, Lat - 0.000000),  
SIDE SLOPE & SIDE BERM DAMAGED ON GORENGAON BRIDGE TO KACHUARKHASH PT-I IDDGAMATH AT 1ST & 2ND KM Dated (13/06/2022 to 17/06/2022) | KACHUARKHASH || (Long - 0.000000, Lat - 0.000000),  
SIDE SLOPE & SIDE BERM DAMAGED OF DURAHATI RCC BRIDGE TO CHARBALADOBA BAZAR AT 1ST & 2ND KM Dated (13/06/2022 to 17/06/2022) | DURAHATI || (Long - 0.000000, Lat - 0.000000),  
ROAD FORMATION DAMAGED OF DURAHATI TISTARPAR ROAD TO CHAR DURAHATI LP SCHOOL AT 1ST KM (.) Dated (13/06/2022 to 17/06/2022) | DURAHATI TISTARPAR ROAD || (Long - 0.000000, Lat - 0.000000),  
ROAD FORMATION DAMAGED ON DHUBRI BINNACHARA ROAD TO AIRANJONGLA L.P. SCHOOL AT 1ST KM Dated (13/06/2022 to 17/06/2022) | BINNACHARA ROAD TO AIRANJONGLA L.P. SCHOOL || (Long - 0.000000, Lat - 0.000000),  
SIDE SLOPE & SIDE BERM DAMAGED ON DURAHATI SINGIMARI PMGSY ROAD TO ARFA MEMORIAL LP SCHOOL AT 1ST KM Dated (13/06/2022 to 17/06/2022) | DURAHATI SINGIMARI || (Long - 0.000000, Lat - 0.000000),  
IB SUB WAY ROAD AT (COLLEGE ROAD) SUBMERGED AND DAMAGED BADLY FROM CH. 0.00 M TO 200.00 M (.) Dated (13/06/2022 to 17/06/2022) | COLLEGE ROAD || (Long - 0.000000, Lat - 0.000000),  
ROAD FORMATION DAMAGED & SUBMERGED ON N.S. ROAD FROM CH. 0.00 M TO 500.00 M Dated (13/06/2022 to 17/06/2022) | N.S. ROAD || (Long - 0.000000, Lat - 0.000000),  
ROAD FORMATION DAMAGED ON CHARMAIN ROAD FROM CH. 0.00 M TO 1000.00 M IN STRETCHES Dated (13/06/2022 to 17/06/2022) | CHARMAIN ROAD || (Long - 0.000000, Lat - 0.000000),  
SIDE BERM & SIDE SLOPE DAMAGED AT 1ST KM ON DHUBRI BINNACHARA ROAD TO R.K. MISSION ROAD Dated (13/06/2022 to 17/06/2022) | R.K. MISSION ROAD || (Long - 0.000000, Lat - 0.000000),  
SIDE BERM DAMAGED KANURI(DIMAKURI) TO BINNACHARA PWD ROAD CH.5KM TO 9KM Dated (13/06/2022 to 17/06/2022) | BINNACHARA || (Long - 0.000000, Lat - 0.000000),  
**South Salmara Part** - Naskara to Namashershow road | Naskara | As per information received from PWRD and Field enquiry made by LM on 16/6/22 Said road has been submerged and damage due to flood water /rainfall at several stretches. | (Long - 0.000000, Lat - 0.000000),  
Chatla to Surjomoni road | Surjomoni | As per information received from PWRD and Field enquiry made by LM on 16/6/22 Said road has been submerged and damage due to flood water /rainfall at several stretches. | (Long - 0.000000, Lat - 0.000000),  
Matifata Salkatata Road | Salkatata | As per information received from PWRD and Field enquiry made by LM on 16/6/22 Said road has been submerged and damage due to flood water /rainfall at several stretches. | (Long - 0.000000, Lat - 0.000000),  
RM Road to Chandipara | B K Naskara | As per information received from PWRD and Field enquiry made by LM on 16/6/22 Said road has been submerged and damage due to flood water /rainfall at several stretches. | (Long - 0.000000, Lat - 0.000000),  
Fakirganj Nidanpur Road | Fakirganj | As per information received from PWRD and Field enquiry



		made by LM on 16/6/22 Said road has been submerged and damage due to flood water /rainfall at several stretches.   (Long - 0.000000, Lat - 0.000000), Salkata Surjomoni via Ambari Road   Salkata   As per information received from PWRD and Field enquiry made by LM on 16/6/22 Said road has been submerged and damage due to flood water /rainfall at several stretches.   (Long - 0.000000, Lat - 0.000000), Radhuram to Namashershow   Radhuram   As per information received from PWRD and Field enquiry made by LM on 16/6/22 Said road has been submerged and damage due to flood water /rainfall at several stretches.   (Long - 0.000000, Lat - 0.000000)
Dibrugarh	2	<b>Tingkhong</b> - 1)Sisumara Betoni borchuk bornamghar road 2)2 no. chapatoli Galaki Maz Ali   1)Sisumara Betoni borchuk bornamghar road Length:2.50 km Lat:27.207736N Long:95.211554E (Date of occurrence:13/06/22 Reported by PwD on 16/06/22) 2)2 no. chapatoli Galaki Maz Ali Length:2.00km Lat:27.155146N Long:95.164397E (Date of occurrence:13/06/22 Reported by PwD on 16/06/22)   (Long - 95.164397, Lat - 27.155146)
Goalpara	5	<b>Balijana</b> - SH46 Near Kaushalya Das LP School to Kankai Madani Hafizia Madrasa   Near Kaushalya Das LP School   Date of occurrence- 16.06.2022 Length/dimension- Length affected 0.05 KM Average depth of submergence- 0.3 M Traffic have not been disrupted Road Embankment, GSB Layer is damaged Report received from Department- Dudhnoi & Goalpara East Territorial Road Division, Goalpara   (Long - 90.635522, Lat - 26.142341), Bolbola to Bodahpur Hatigaon Road   Bolbola   Date of occurrence- 16.06.2022 Length/dimension- Length affected 0.2 KM Average depth of submergence- 0.4M Traffic disrupted from 16.06.2022 to Till now Road Submerged till now Report received from Department- Dudhnoi & Goalpara East Territorial Road Division, Goalpara   (Long - 90.554910, Lat - 26.009543), Durgamandir Milonagar PWD Road to Chandaria Pathar PWD Road   Chandaria Pathar PWD Road   Date of occurrence- 16.06.2022 Length/dimension- Length affected 0.03 KM Average depth of submergence- 0.3 M Traffic have not been disrupted 15.00 M length of Road Breached Report received from Department- Dudhnoi & Goalpara East Territorial Road Division, Goalpara   (Long - 90.635522, Lat - 26.142341), <b>Matia</b> - Baladmari Pt-IV to Netaji Club Road (PMGSY)   Baladmari Char Pt-IV   Affected length = 1.5 Km and average depth of submergence = 0.300 m (as on 16/06/2022) as reported by PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara   (Long - 90.665775, Lat - 26.951535), <b>Dudhnoi</b> - Kachadol Kacharipara Road   Kachadol   The road of length 0.100 km got affected with a submergence depth of 0.500 m. 4 Nos. of Culvert Approach of the road got damaged dated 16.06.2022-Information received from PWRD, Dudhnoi & Goalpara East Territorial Road Division, Goalpara   (Long - 90.782448, Lat - 25.982956)
Kamrup	9	<b>Rangia</b> - Gurkuchi village road   vill- Gurkuchi   Gurkuchi Village Road is submerged in flood water and is partially damaged as per report of AEE, PWD NKT, Roads, Rangia on 16.05.2022   (Long - 0.000000, Lat - 0.000000), N.T Road   vill- Rangia Town   N.T Road is submerged in flood water and is partially damaged as per report of AEE, PWD NKT, Roads, Rangia on 16.05.2022   (Long - 0.000000, Lat - 0.000000), Rangia Baralia West Embankment to Noona Embankment via Barkukuria village Road   Vill- Barkukuria   Rangia Baralia West Embankment to Noona Embankment is submerged (1 KM) in flood water and is partially damaged as per report of AEE, PWD NKT, Roads, Rangia on 16.05.2022   (Long - 0.000000, Lat - 0.000000), Udiana Gurkuchi Road   Vill- Udiana   Udiana Village Road is submerged in flood water and is partially damaged as per report of AEE, PWD NKT, Roads, Rangia on 16.05.2022   (Long - 0.000000, Lat - 0.000000), <b>Kayan</b> - Bagals Road near choumukha bazar chowk, Dhuhi Balisatra Road near Bathan, Garamsung Gorput Road, Kamalpur Morowa road at Baranghati Bokultol, Kayan Kampith road side berm and one culvert damaged.   Kayan Revenue Circle. Date: 16/06/2022. Reported by PWRD, Hajo Division.   GPS co-ordinates couldn't be provided at the moment.   (Long - 0.000000, Lat - 0.000000)
Karimganj	7	<b>Karimganj</b> - NH 151 TO BARSHILLA VIA AKBARPUR GP OFFICE   AKBARPUR   DUE TO INCESSANT HEAVY RAINFALL FROM LAST FEW DAYS ABOVE ROAD IS DAMAGED/ERODED PARTIALLY AT VARIOUS STRETCHES (CH-200M TO 300M.) THE WT MESSAGE WAS SUBMITTED BY ASST.EXECUTIVE ENGINEER,PWRD. KARIMGANJ ON 16/06/2022   (Long - 92.306734, Lat - 24.865132), RAILWAY LINE TO BETAIL   BETAIL   DUE TO INCESSANT HEAVY RAINFALL FROM LAST FEW DAYS ABOVE ROAD IS DAMAGED/ERODED PARTIALLY AT VARIOUS STRETCHES (CH 650M TO 110M.) THE WT MESSAGE WAS SUBMITTED BY ASST.EXECUTIVE ENGINEER,PWRD. KARIMGANJ ON 16/06/2022   (Long - 92.357224, Lat - 24.859385), BONOMALI ROAD   BANAMALI   DUE TO INCESSANT HEAVY RAINFALL FROM LAST FEW DAYS ABOVE ROAD IS DAMAGED/ERODED PARTIALLY AT VARIOUS STRETCHES (CH 450M TO 460M. & 1500M TO 1510M) THE WT MESSAGE WAS SUBMITTED BY ASST.EXECUTIVE ENGINEER,PWRD. KARIMGANJ ON 16/06/2022   (Long - 92.358564, Lat - 24.865812), HOSPITAL ROAD   KARIMGANJ Part III, BLOCK 5   DUE TO INCESSANT HEAVY RAINFALL FROM LAST FEW DAYS ABOVE ROAD IS DAMAGED/ERODED PARTIALLY

			<p>AT VARIOUS STRETCHES (CH 200M TO 460M) THE WT MESSAGE WAS SUBMITTED BY ASST.EXECUTIVE ENGINEER,PWRD. KARIMGANJ ON 16/06/2022   (Long - 92.362227, Lat - 24.867349),</p> <p>THANA ROAD   KARIMGANJ Part III, BLOCK 5   DUE TO INCESSANT HEAVY RAINFALL FROM LAST FEW DAYS ABOVE ROAD IS DAMAGED/ERODED PARTIALLY AT VARIOUS STRETCHES (CH 550M TO 555M) THE WT MESSAGE WAS SUBMITTED BY ASST.EXECUTIVE ENGINEER, PWRD. KARIMGANJ ON 16/06/2022   (Long - 92.358441, Lat - 24.866600),</p> <p>LONGAI ROAD   KARIMGANJ Part III, BLOCK 3   DUE TO INCESSANT HEAVY RAINFALL FROM LAST FEW DAYS ABOVE ROAD IS DAMAGED/ERODED PARTIALLY AT VARIOUS STRETCHES (CH 700 M TO 750 M &amp; 850 M TO 900 M) THE WT MESSAGE WAS SUBMITTED BY ASST.EXECUTIVE ENGINEER, PWRD. KARIMGANJ ON 16/06/2022   (Long - 92.356955, Lat - 24.865903),</p> <p>SUBASH ROAD   KARIMGANJ Part IV, BLOCK 4   DUE TO INCESSANT HEAVY RAINFALL FROM LAST FEW DAYS ABOVE ROAD IS DAMAGED/ERODED PARTIALLY AT VARIOUS STRETCHES (CH 30M TO 40M &amp; 45M TO 60 M) THE WT MESSAGE WAS SUBMITTED BY ASST.EXECUTIVE ENGINEER,PWRD. KARIMGANJ ON 16/06/2022   (Long - 92.362147, Lat - 24.866993)</p>
Kokrajhar	5		<p><b>Bagribari</b> - Bhalukjhora to Marshuljhora CC Block village Road   Marshuljhora   As reported by LR staff, the road has been damaged due to to the incessant rainfall w.e.f.11/06/2022   (Long - 89.889044, Lat - 26.293139),</p> <p>Kuarpar to Silbari PWD Road   Balubari   As reported by LR staff, the road has been submerged due to to the incessant rainfall w.e.f.11/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Jalabila to Ghugujhora Village Road   Hajipara   As reported by LR staff, the road has been damaged due to to the incessant rainfall w.e.f.11/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Dampur to Khutabagra Raod   Dampur   As reported by PWD, RR Div. Gossaigaon, Ch. 700M to 1200M eroded in stretches   (Long - 0.000000, Lat - 0.000000),</p> <p>Mahamaya Mandir to Sngahat Mandir Road   Mahamaya   As reported by PWD, RR Div. Gossaigaon, road has been damaged and closed   (Long - 0.000000, Lat - 0.000000)</p>
Lakhimpur	7		<p><b>Bihpuria</b> - Panchayat road at Torajuli   Torajuli village   Overtopping of about 10 meters of the panchayat road due to rising of Gabharu river on 16th June 2022 under Karunabari Development Block   (Long - 93.911595, Lat - 27.137257),</p> <p>Road from 65/68 Grant to Meneha   RCC Culvert no. 1/2 and roadside embankment from Ch 2020m to Ch. 2100m   The said road damaged badly due to flood water spillover of Dikrong river on 17th June 2022 as reported by AEE, PWD R, Bihpuria TRSD   (Long - 93.916872, Lat - 27.092335),</p> <p>Karunabari Kehutoli to Dharmapur block road   Ch. 5500.00m to Ch.5840.00m   Road overtopped and submerged for about 0.05m depth due to flood water spillway on 17th June 2022 as reported by AEE, PWD R, Bihpuria TRSD   (Long - 93.974709, Lat - 27.119500),</p> <p><b>Nowboicha</b> - 333st KM of NH 15 Dolohat to Laluk Kachajuli Road   Dolohat   Road embankment and shoulder erosion in the CH:2500.00m to CH:2800.00m due to flood water of Singra River and spilway of flood water in CH:2180.00m to CH:2200.00m and CH:2250.00m to CH:2300.00m. The site is in danger and temporary restoration works are going on. Report received from PWRD Nowboicha Territorial Road Sub-Division on 17/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Phulbari Naharani Road   Phulbari   HP Culvert no 2/1 approaches are damaged. Road embankment and shoulder erosion in the CH:1500.00m to CH:1515.00m due to spilway of flood water. Report received from PWRD Nowboicha Territorial Road Sub-Division on 17/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Ahmedpur Kutubpur to Gorchiga PWD Road   Gorchiga   Road overtopped and submerged in CH:9400.00m to CH:9700.00m for about 0.50m depth damaged hard crust, shoulder and road embankment. Embankment damaged due to flood water spilover. Report received from PWRD Nowboicha Territorial Road Sub-Division on 17/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Sagarpur Bhitoripam Road   Bhitoripam   Salb culvert no.1/1 and approaches are damaged due to spilway of flood water. Report received from PWRD Nowboicha Territorial Road Sub-Division on 17/06/2022   (Long - 0.000000, Lat - 0.000000)</p>
Majuli	1		<p><b>Ujani Majuli</b> - Bongaon to Meragarh colony road   Meragarh colony   Bongaon to Meragarh colony road ch. 80.00 m to ch. 380.00m got submerged (approx 50 cm depth on top of road level) and road communication got disrupted on 16.06.2022   (Long - 94.292538, Lat - 26.962534)</p>
Morigaon	2		<p><b>Mayong</b> - Sildubi-Gagalmar part II road   2nd and 6th km   Submerged at 2nd and 6th km as reported by PWD Morigaon District Territorial Road Division on 17/06/22   (Long - 92.129000, Lat - 26.267000),</p> <p>Karatipam Bazar to Chotogarjan   Road Submerged at 2nd Km   Road Submerged at 2nd km as reported by PWD Morigaon district territorial road division on 17/06/22   (Long - 92.178000, Lat - 26.278000)</p>
Nagaon	2		<p><b>Kampur</b> - Kampur to Changchaki via Shaibuk to Bakulaguri Road   Shaibuk, Garukhunda, Kumbhirdubi, Bakulaguri   Due to rising water level of River Kopili submerged Kampur to Changchaki via Shaibuk to Bakulaguri Road at various points on dated 17.06.2022. The road belongs to Batadrava, Dhing and Raha Territorial Road Division.   (Long - 0.000000, Lat - 0.000000),</p>

			Kampur Jamunamukh Road   Railway Gate No 3 near Petrol Pump   Kampus Jamunamukh Road submerged at Railway Gate No 3 around 500 metres. The road belongs to Barhampur Territorial Road Division on dated 16.06.2022   (Long - 0.000000, Lat - 0.000000)
Nalbari	36		<p><b>Banekuchi</b> - Makrapar Chowk to Sahpur road   Barbara   Ae per report of Gaon Pradhan this road is submerged due to flood on 16/06/2022   (Long - 26.436323, Lat - 91.311548),  Makrapar Chowk to via Majkuchi Kaithalkuchi road   Barsanara   Ae per report of Gaon Pradhan this road is submerged due to flood on 16/06/2022   (Long - 0.000000, Lat - 0.000000),  Makrapar Chowk to Barpit road   Makrapar Kalitapara, Near Mora Pagladia river   Ae per report of Gaon Pradhan this road is submerged due to flood on 16/06/2022   (Long - 0.000000, Lat - 0.000000),  Bali to Nalbari road   Kaithalkuchi   Ae per report of Gaon Pradhan this road is submerged due to flood on 16/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p><b>Barkhetri</b> - kakaya naptipara road   naptipara   due to incessant rain the road is submerged and partially breached at naptipara, length 10 m and overtopped length 100m as reported by AEE, PWRD, Barkhetri teritorial sub div. on 17/06/2022.   (Long - 0.000000, Lat - 0.000000),  laupara shyamraimandir to narikalbari road   laupara   due to incessant rain side berm damaged. length 120m, as reported by AEE, PWRD, Barkhetri teritorial sub div. on 17/06/2022.   (Long - 0.000000, Lat - 0.000000),  loharkatha arikuchi road   balikuchi   due to incessant rain the road is submrged at balikuchi, length 120m, as reported by AEE, PWRD, Barkhetri teritorial sub div. on 17/06/2022.   (Long - 0.000000, Lat - 0.000000),  naptipara gopalthan to darmon road   naptipara   submerged and damaged due to overflowing water current of incessant rainwater, length 400m as reported by AEE, PWRD, Barkhetri teritorial sub div. on 17/06/2022.   (Long - 0.000000, Lat - 0.000000),</p> <p><b>Paschim Nalbari</b> - Amoni to Pokhura Via Jokmari   Amoni   As per report of PWRD this road is submerged due to flood on 16/06/2022   (Long - 0.000000, Lat - 0.000000),  Solmara to Pokhora   Solmara   As per report of PWRD this road is submerged due to flood on 16/06/2022   (Long - 0.000000, Lat - 0.000000),  Solmara Sarabari road   Solmara   As per report of PWRD this road is submerged due to flood on 16/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p><b>Ghograpar</b> - Gohain Kamal Ali road   Gohain Kamal   As per WT msg from PWRD Gohain Kamal Ali road submerged on 16/06/2022, length 2500m   (Long - 0.000000, Lat - 0.000000),  Rangia Dhamdhama road   Dhamdhama   As per WT msg from PWRD Rangia Dhamdhama road submerged on 16/06/2022, length 1000m, Bridge No 20/1 approachs damages, Bridge No 20/2 approachs damages   (Long - 0.000000, Lat - 0.000000),  Bhelamari to Chataimari road   Bhelamari, Chataimari   As per WT msg from PWRD Bhelamari to Chataimari road has been submerged on 16/06/2022, length 1.5km   (Long - 0.000000, Lat - 0.000000),  Rangmili to Majusiral road   Majusiral   As per WT msg from PWRD Rangmili to Majusiral road has been submerged on 16/06/2022, length 2000m   (Long - 0.000000, Lat - 0.000000),  Gohain Kamal to Chataibari Barsiral road   Chataibari, Barsiral   As per WT msg from PWRD Gohain Kamal to Chataibari Barsiralroad has been submerged on 16/06/2022, length 500m   (Long - 0.000000, Lat - 0.000000),  Kallopap road to Barsiral road   Barsiral   As per WT msg from PWRD Kallopap to Barsiral road has been submerged on 16/06/2022, length 500m   (Long - 0.000000, Lat - 0.000000),  Gohain Kamal to Kallopap PHC Uttar Barsiral road   Barsiral   As per WT msg from PWRD Gohain Kamal to Kallopap PHC Uttar Barsiral road has been submerged on 16/06/2022, length 1500m   (Long - 0.000000, Lat - 0.000000),  Rangia Dhamdhama at Barsiral to Kolloipar road   Barsiral   As per WT msg from PWRD Rangia Dhamdhama at Barsiral Kolloipar road has been submerged on 16/06/2022, length 1000m   (Long - 0.000000, Lat - 0.000000),  Dhamdhama Fulguri road (PMGSY)   Dhamdhama   As per WT msg from PWRD Dhamdhama Fulguri, Br No 1/1 approach damage road has been submerged on 16/06/2022, length 1500m   (Long - 0.000000, Lat - 0.000000),  Dhamdhama Higher Secondary to Fulguri via Sankardev School   Dhamdhama   As per WT msg from PWRD Dhamdhama Higher Secondary to Fulguri via Sankardev School road has been submerged on 16/06/2022, length 500m   (Long - 0.000000, Lat - 0.000000),  Hibidimba school to Mohina road   Mohina   As per WT msg from PWRD the above road has been submerged on 16/06/2022, length 1500m   (Long - 0.000000, Lat - 0.000000),  Nalbari Dhamdhama road   Dhamdhama   As per WT msg from PWRD the above road has been submerged on 16/06/2022, length 150m   (Long - 0.000000, Lat - 0.000000),  3No Balitara to 4No Balitara   Balitara   As per WT msg from PWRD the above road has been submerged ,on 16/06/2022, Br Now/1 approach demages length 2km   (Long - 0.000000, Lat - 0.000000),  Dhamdhama PWD IB   Dhamdhama   As per WT msg from PWRD the above road has been submerged on 16/06/2022, length 500m   (Long - 0.000000, Lat - 0.000000),  Post office Chowk to Naherbari road   Naherbari   As per WT msg from PWRD the above road has been submerged on 16/06/2022, length 200m   (Long - 0.000000, Lat - 0.000000),</p>

			<p>Rangia Dhamdhama road   Dhamdhama   As per WT msg from PWRD the above road has been submerged , Br No 18/1 approach damages on 16/06/2022, length 500m   (Long - 0.000000, Lat - 0.000000),</p> <p>Uttar Barsiral to Chatabari road   Uttar Barsiral, Chatabari   As per WT msg from PWRD the above road has been submerged on 16/06/2022, length 1200m   (Long - 0.000000, Lat - 0.000000),</p> <p><b>Barbhag</b> - Bargasha Sanekuchi Road   Bargasa   As per report of PWRD this road is submerged due to flood on 17/06/2022 length -2.50km   (Long - 0.000000, Lat - 0.000000),</p> <p>Sonkani Saru Barara vill road   Sonkani Saru Barara   As per report of PWRD this road is submerged due to flood on 17/06/2022 length -1 km   (Long - 0.000000, Lat - 0.000000),</p> <p>Barkulhati Kalarchar vill road   Barkulhati   As per report of PWRD this road is submerged due to flood on 17/06/2022 length -2. km   (Long - 0.000000, Lat - 0.000000),</p> <p>Sonkani vill road   Sonkani   As per report of PWRD this road is submerged due to flood on 17/06/2022 length -1 km   (Long - 0.000000, Lat - 0.000000),</p> <p><b>Nalbari</b> - Nalbari Bahjani Road   Bahjani   as per the report of PWRD this road is submerged due to heavy rain water on 16/06/2022 length 1 km   (Long - 0.000000, Lat - 0.000000),</p> <p>Namati Samrai Mandir Road   Namati   as per the report of PWRD this road is submerged due to flood on 16/06/2022 length- 0.7 km   (Long - 0.000000, Lat - 0.000000),</p> <p><b>Tihu</b> - Tihu Akhara Road   Tihu   As per Report JE PWD Roads Barama Ana Patacharkuchi Divn has been submerged as 16-06-2022 length 7KM   (Long - 0.000000, Lat - 0.000000),</p> <p>Bali Haribhanga Kaithalkuchi Road   Bali   As per Report GB Bali Haribhanga Kaithalkuchi Road Breach as on 17-06-2022 length 100m approx   (Long - 0.000000, Lat - 0.000000)</p>
	Sonitpur	5	<p><b>Dhekiajuli</b> - 3 No Rangagora village road   one village road severely affected due to rising water of the Belsiri river at 3No Rangagora village. dated 17.06.2022    (Long - 92.538929, Lat - 26.697914),</p> <p><b>Chariduar</b> - UHANI PATHAR BATABARI ROAD DTD 17/06/2022   CHARIDUAR    (Long - 26.756770, Lat - 92.789090),</p> <p>BAMUNGULA MANSIRI ROAD CUL 2/1 DTD 17/06/2022   CHARIDUAR    (Long - 26.749183, Lat - 92.792482),</p> <p>UROHILOGA TO MAINAOSHRI ROAD   CHARIDUAR    (Long - 26.897557, Lat - 92.620087),</p> <p><b>Tezpur</b> - Balughat Road (Bhalukjarani Village)   Bhalukjarani village   dated: 17/06/2022. As reported by PWD Roads Balughat road in Bhalukjarani village is affected upto the extent of 150 m i.e from ch 560 m ti ch 710 m.   (Long - 92.821845, Lat - 26.706153)</p>
	South Salmara	3	<p><b>South Salmara</b> - Monirchar Daspara PMGSY road   Monirchar   As per information received from PWRD and Field inquiry made by LM on 15/6/22 the said road has been several stretches due to flood water /rainfall. Length Aprox. 2 km   (Long - 89.970000, Lat - 25.850000),</p> <p>Dhenarkuti to Baladoba road   Baladoba   As per information received from PWRD and Field inquiry made by LM on 15/6/22 the said road has been several stretches due to flood water /rainfall. Length Aprox 3.5 km   (Long - 90.020000, Lat - 25.890000),</p> <p>Tumni Fershertary road   Tumni   As per information received from PWRD and Field inquiry made by LM on 15/6/22 the said road has been several stretches due to flood water /rainfall. Length Aprox 1.5 km   (Long - 89.990000, Lat - 25.850000)</p>
	Udalguri	3	<p><b>Harisinga</b> - No.2 Alikakh village road   Chabari to No2 Alikakh Village road   Chabari to No2 Alikakh Village road damaged on 17th June 2022   (Long - 91.913200, Lat - 26.672100),</p> <p>Chenipara village road   Chenipara village   Chenipara village road damaged due to over topping of River kulshi. on 17th July 2022   (Long - 91.913200, Lat - 26.672100),</p> <p>MB Road   Banseria Village   the Mangaldai Bhootiachang road eroded due to heavy rainfall on 17th July 2022   (Long - 91.545700, Lat - 26.405300)</p>
	Total	<b>234</b>	
Infrastructure Damaged - Bridge	<b>District</b>	<b>Number</b>	<b>Details</b>
	Barpeta	1	<b>Barpeta</b> - SPT Br. No. 4/1   on Nagaon Khardhara Road to Panichila road   SPT bridge badly effected by water hyacinth PWRD 16.06.2022   (Long - 91.090553, Lat - 26.359592)
	Dhubri	5	<p><b>Gauripur</b> - BRIDGE APPROACHES OF BRIDGE NO 1 BY 1 ON 6TH KM D K ROAD TO DUKHISUKHI PMGSY ROAD Dated (13/06/2022 to 17/06/2022)   DUKHISUKHI    (Long - 0.000000, Lat - 0.000000),</p> <p><b>Dhubri</b> - RCC BRIDGE APPROACHES DMAGED OF BR. NO. 17/1 ON BANDIHANA MAJERCHAR ROAD Dated (13/06/2022 to 17/06/2022)   MAJERCHAR    (Long - 0.000000, Lat - 0.000000),</p> <p>BRIDE APPROACHES OF RCC BR. NO. 3/1 ON MOTIRCHAR DHARMASALA ROAD Dated (13/06/2022 to 17/06/2022)   MOTIRCHAR DHARMASALA    (Long - 0.000000, Lat - 0.000000),</p> <p>RCC BRIDGE APPROACHES DAMAGED OF RCC BR, NO. 1/1 ON KACHARIHAT PWD ROAD TO SINGIMARI ROAD Dated (13/06/2022 to 17/06/2022)   KACHARIHAT    (Long - 0.000000, Lat - 0.000000),</p> <p>RCC BRIDGE APPROACHES DAMAGED OF RCC BR, NO. 6/1 ON DHUBRI JHAGRARPUR GAURIPUR (D.J.G.) ROAD Dated (13/06/2022 to 17/06/2022)   JHAGRARPUR    (Long - 0.000000, Lat - 0.000000)</p>
	Kokrajhar	3	<b>Bagribari</b> - Bridge No.4/1, 4/2 and 4/3   Chechapani to Monglajhora Road   Damaged   (Long - 0.000000, Lat - 0.000000)

	Lakhimpur	1	<b>Nowboicha</b> - 1 No. Panchnoi Bamboo Bridge   1 No. Panchnoi   1 No. Panchnoi Bamboo Bridge over Ranganadi River washed away (30 Mtr approx) on 17.06.2022. Report received from PWRD Nowboicha Territorial Road Sub-Division   (Long - 0.000000, Lat - 0.000000)
	Morigaon	2	<b>Mayong</b> - Dhekiphala Karatipam RCC bridge   RCC Br No 2/1   Bridge Approaches of RCC Bridge on Dhekiphala Karatipam Road damaged and eroded as reported by PWD Morigaon District Territorial Road Division on 17/06/22/   (Long - 92.156000, Lat - 26.286000), <b>RCC Bridge No.3/1   Sidhaguri   Bridge Approach of RCC Bridge No.3/1 at Pavakati on Sidhaguri Garubandha road eroded. Temporary protection work is in progress.   (Long - 92.097000, Lat - 26.274000)</b>
	Sonitpur	2	<b>Dhekiajuli</b> - One RCC Bridge at the main entrance of Monabag Tea Estate washed away by the rising water of Sopai river. dated 17.6.22   Monabag TE     (Long - 92.466587, Lat - 26.778572), <b>Chariduar</b> - Due to Flood on 16/06/2022 Bridge approach of chariduar side on Chariduar to Mansiri Road badly eroded and threat to vehicular traffic.   chariduar     (Long - 26.846259, Lat - 92.797666)
	Udalguri	2	<b>Harisinga</b> - Huduma bridge   tangla Collage   Huduma bridge damaged due to rising current of river Huduma on 17th June 2022   (Long - 91.559800, Lat - 26.394400), <b>santipur Bridge   Santipur (Corramore)   Huduma bridge damaged due to rising current of river Huduma on 17th June 2022   (Long - 91.951200, Lat - 26.843100)</b>
	Total	<b>16</b>	
Infrastructure Damaged - Wildlife	Nil		
Infrastructure Damaged - Others	<b>District</b>	<b>Other Details</b>	
	Baksa	<b>Barama</b> - Culvert Approach Road Damaged   Culvert approach damaged at village Bhalukdonga. Date of occurrence: 16/06/22. Lat: 26.580914 Lon: 91.328001	
	Barpeta	<b>Baghbar</b> - Anganwadi Centres Affected   4 nos of Anganwadi centres are submerged (17-6-2022), <b>Sarthebari</b> - Anganwadi Centres Affected   74 no angwanwadi Centre (17-6-2022), Fisheries/Pond   12 (17-6-2022), <b>Kalgachia</b> - Health Sub-Centre   As per report received from Health department on 17/06/22, total 6(six) nos of health Sub-centre and HWC are submerged. They are as follows- 1.Dimapur HWC, Dimapur, 2.Garalipam HWC, Garalipam, 3.Isabpur SC, Isabpur, 4.Bardanga SC, Bardanga, 5.Bartary HWC, Bartary and 6.Gunialguri HWC, Gunialguri., <b>Chenga</b> - Elementary Schools Damaged   37 nos. school partially affected on 16.6.22 report by BEE0	
	Chirang	<b>Sidli</b> - Power Dept. Poles   As reported by SDE, Basugaon ESD, 3 nos poles washed away on 16.06.2022 at Deulguri and 1 pole uprooted on 16.06.2022 at Mozabari, Power Dept. Conductors   As reported by SDE, Basugaon ESD 1.5 km Conductors damaged on 16.06.2022 at Deulguri, <b>Bengtal</b> - Agri Bundh Damaged   Mwinaguri Bundh broken at village Dorogaon on 17-06-2022. Damage Details: Length:4M, Breath:2.5M, Depth:2M, Long:90.392627, Lat:26.606085, Power Dept. Poles   As reported by SDE, BESD-II, APDCL, 2 nos. of pole uprooted at Khoirabari FV and 4 nos. of HT pole washed away at Khagrabarion on 15-06-2022., Power Dept. Conductors   As reported by SDE, BESD-II, APDCL, 1.2 km conductor damaged at Khagrabari FV on 15-06-2022, Power Dept. Transformers   As reported by SDE, BESD-II, APDCL, 5 nos. of transformer namely (63kVA at Bengtal, 63kVA at Kumguri, 25kVA at Thuribari, 16kVA at Madarpur and 25kVA at Khagrabari ) damaged on 15-06-2022.	
	Darrang	<b>Patharighat</b> - Power Dept. Poles   19 nos as reported by SDE on 17.6.2022, Power Dept. Conductors   approx. 11 km conductor snapped as reported by SDE, APDCL on 16.6.2022 & 17.6.2022, Fisheries/Pond   3070 nos of pond submerged as reported by FDO on 16.6.2022, Anganwadi Centres Affected   12 nos AWC submerged partially as reported by CDPO on 17.6.2022, <b>Dalgaon</b> - Washed away Culverts   single HPC was away at nadirkash to bechimari road on 16/06/2022, <b>Mangaldoi</b> - Power Dept. Poles   As reported by APDCL approx 15 poles are damaged as of now. Dated 17-06-2022, <b>Sipajhar</b> - Anganwadi Centres Affected   Uttar Kalitapara AWC, worker name: Anjali Deka dated 17.06.2022, Power Dept. Poles   7 nos of power dept poles damaged dated 17.06.2022, Power Dept. Conductors   11.8 KM dated 17.06.2022, Fisheries/Pond   Daily flooTotal number of fish farmer affected (approximately) - 277 nosTotal water area affected (approximately) - 18 Hac.Regards	
Dhemaji	<b>Jonai</b> - Culvert Approach Road Damaged   PWD territorial road RCC Culvert 6.00M Span Slab Foundation, Substructure & Superstructure damaged on 16/06/2022 by the River Depi., Sericulture Deptt. Damaged   At No.1 Jamuguri under Uluwani Jamuguri, 5 hectares of plantation (5000nos. of Som Plants) damaged on 17/06/2022 by flood water affecting approx. 150 Sericulture farmers., Power Dept. Poles   1 nos. of HT Poles & 1nos. of LT Pole uprooted At Gali Nabang ,Komonselek, Gali Migang,Torajan, Amarpur, Bijoypur on 17/06/2022 by flood water from fields , Power Dept. Conductors   6.5 Kilometer conductor Snapped damage due to At Gali Nabang ,Komonselek, Gali Migang,Torajan, Amarpur, Bijoypur on 17/06/2022 by flood water from fields,		

		<b>Sissiborgaon</b> - Bridge Approach Road Damaged   Bridge approach road damaged at Ch 3000.00 m on PWD Amguri road to No.2 Bangalmari on 16/06/2022
Dhubri		<b>Gauripur</b> - Culvert Approach Road Damaged   CULVERT DAMAGED AND SIDE BERM DAMAGED ON PANBARI IDGAH TO NOVODOY VIDYALAYA Dated (13/06/2022 to 17/06/2022) ROAD AT 1ST KM
Dibrugarh		<b>Chabua</b> - Health Sub-Centre   DODHIA KULIGAON HEALTH SUB-CENTRE SUBMERGED AS PER INFORMATION RECEIVED FROM HEALTH DEPT. ON 17/6/2022 Coordinates-N27 35.835 E95 13.266, Elementary Schools Damaged   DODHIA ME SCHOOL SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 17/6/2022 N27 36.390 E95 13.651, Elementary Schools Damaged   DODHIA KULIGAON LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 17/6/2022 N27 35.845 E95 13.227, Elementary Schools Damaged   DODHIA KARMI LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 17/6/2022 N 27 36.032 E95 14.787, Elementary Schools Damaged   DODHIA TENGABARI LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 17/6/2022 N27 36.652 E95 14.237, Elementary Schools Damaged   DODHIA CHALBIL LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT ON 17/6/2022 N27 36.462 E95 14.673, Anganwadi Centres Affected   DODHIA KULIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 17/6/2022 N27 35.845 E 95 13.227, Anganwadi Centres Affected   DODHIA TENGABARI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 17/6/2022 N27 36.652 E95 14.237, Anganwadi Centres Affected   DODHIA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 17/6/2022 N27 36.390 E95 13.651, Elementary Schools Damaged   MOHMORA HINDI LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 17/06/2022. N27 34'5.0514" E95 10'23.7144", Elementary Schools Damaged   MIRIGAON LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 17/06/2022. N27 30'44.51" E95 12'49.41"
Dima-Hasao		<b>Haflong</b> - Road Breaches   Landslide at Dolaichunga (Jatinga to Harangajao Section) as per information received from NHAI, Haflong dated 17/06/2022, Road Breaches   Damage Restoration ongoing at Doliachunga culvert location as per information received from NHAI, Haflong dated 17/06/2022, Road Breaches   Damage of road at S-Curve, NH-27 (( Nrimbanglo to Jatinga Section) as per information received from NHAI, Haflong dated 17/06/2022, Road Breaches   Landslide in between Kalachand-Koladisa Road as per information received from local public dated 17/06/2022
Hojai		<b>Lanka</b> - PWSS Damaged   Kapilipar PWSS Submarged on 16/06/2022, <b>Hojai</b> - PWSS Damaged   Int Hatimura Dakhin Kenduguri PWSS Submarged on 16/06/2022, PWSS Damaged   Baruphoti PWSS Submarged ob 17/06/2022, PWSS Damaged   Pub Jugijan PWSS Submarged on 17/06/2022, PWSS Damaged   Radhanagar PWSS Submarged on 16/06/2022, PWSS Damaged   Hayang Basti PWSS (SVS) Submarged ob 16/06/2022, PWSS Damaged   Hayang Gaon PWSS Submarged on 16/06/2022, PWSS Damaged   Saotal Basti PWSS Submarged on 17/06/2022, PWSS Damaged   Donky Gaon PWSS Submarged on 17/06/2022, PWSS Damaged   Kendulimari PWSS Submarged on 17/06/2022, PWSS Damaged   Taradubi PWSS Submarged on 16/06/2022, PWSS Damaged   Kumurakata PWSS Submarged on 16/06/2022, PWSS Damaged   Mainapather PWSS Submarged on 17/06/2022, PWSS Damaged   Nandapur Togia PWSS Submarged on 17/06/2022, <b>Doboka</b> - PWSS Damaged   Beduwati Sarlok PWSS Submarged on 17/06/2022, PWSS Damaged   Jugijan Baliram pathar PWSS Submarged on 17/06/2022, PWSS Damaged   Kapili Kathkatia PWSS Submarged on 17/06/2022
Kamrup		<b>Rangia</b> - Power Dept. Poles   20 Nos. of LT poles damaged in villages Tulsibari, Balagaon, Ischapur and Chirakhundi under Rangia rev. Circle as per report of SDE, APDCL, Sub Div-II, Rangia on 16.06.2022, Power Dept. Conductors   5.4 KM conductor damaged in villages Tulsibari, Balagaon, Ischapur and Chirakhundi under Rangia Rev. Circle as per report of SDE, APDCL, Sub Div-II, Rangia on 16.06.2022, Fisheries/Pond   16 Nos. of Ponds amounting to water area of 17.7 Ha affected by flood on 16.06.2022 as per report of FDO, Rangia, <b>Kayan</b> - Fisheries/Pond   103 Nos. Ponds covering water area of 11.33 Hactre. Date: 16/06/2022. Reported by FDO, Rangia Dev. Block, Power Dept. Poles   29 nos. Date: 16/06/2022. Reported by Rangia Electrical Sub-Division 2, APDCL, Rangia., Power Dept. Transformers   1 no. 63 KVA and 1 no. 16 KVA. Date: 16/06/2022. Reported by Rangia Electrical Sub-Division 2, APDCL, Rangia, Power Dept. Conductors   6.4 km. Date: 16/06/2022. Reported by Rangia Electrical Sub-Division 2, APDCL, Rangia
Karimganj		<b>Nilambazar</b> - Protection Bundh Damaged   On 16-06-2022, the EE, Karimganj W.R. Division Karimganj reported damage to the Protection Bundh at Ratanpur, Halghat, Bharibond where sloughing is observed due to incessant rainfall and rise of water Level of River Longai. The GPS Coordinates of the sites are Lat-24.752716,

		Long-92.349521, Lat-24.763620, Long-92.341708 and Lat-24.757558, Long-92.343926
	Kokrajhar	<p><b>Bagribari</b> - Damaged SPT Bridge   As reported by PWD RR, Gossaigaon Div, SPT Bridge No.5/1 on Modati Bazar to Bashbari Kazigaon Road has been damaged due to incessant heavy rainfall, Washed away Culverts   As reported by PWD RR, Gossaigaon Div, Culvert has been washout on Modati Bazar to Bashbari Kazigaon Road due to incessant heavy rainfall, Washed away Culverts   As reported by PWD RR, Gossaigaon Div, HPC Culvert has been damaged on Chechapani to Monglajhora Road due to incessant heavy rainfall, Damaged SPT Bridge   As reported by PWD RR, Gossaigaon Div, SPT Bridge No.2/1 has been damaged on Bongshijhora to Harjhora Road. due to incessant heavy rainfall, <b>Gossaigaon</b> - Bridge Approach Road Damaged   A wooden bridge damaged at Chengmari Rabha Village near Jambguri High School Over Modati River</p>
	Lakhimpur	<p><b>North Lakhimpur</b> - Elementary Schools Damaged   Kathal pukhori L P shool under BEEO Nowboicha on 17/06/2022, Culvert Approach Road Damaged   Location of the culvert: Amtola Nagargaon to Parghat, Amtola, Pachim Telahi GP. Only partial damage has been observed. Headwalls at both sides of the HP culvert along with earthwork portion of the river side have been damaged. on 17/06/2022, <b>Subansiri</b> - Bamboo Foot Bridge   As reported by Dhakuakhana Teritorial Road division, Ghilamara, the existing Bamboo Bridge No. 3/1 is damaged on Balideori to Majdeori Road. (Length=60.00M) on 17/06/2022, Bridge Approach Road Damaged   As reported by Dhakuakhana Teritorial Road division, Ghilamara, the approach of RCC Bridge No. 8/1 on Sonari Chapori to Sapekhati Charikoria Road is eroded (Length=40.00M) on 17/06/2022, <b>Kadam</b> - Bamboo Foot Bridge   Bamboo bridge connecting from NH-15 Seajuli Road to Kadam Bagan Gaon washed away by the river Kakoi, date 17/06/2022, Agri Bundh Damaged   CONST OF EARTHEN PERIPHERIAL BUNDH FOR COMMUNITY AT KHURACHUK DOLEY PATHAR(0410010/LD/9010285087), damage 200 mtrs, informed by BDO Boginadi, date 17/06/2022, <b>Bihpuria</b> - Damaged SPT Bridge   Some wooden piles and other components of SPT Br no. 1/1 has been damaged and bridge approaches eroded on 17th June 2022 of No.2 Karunabari to Ahomgaon road( Jadumoni Muslim TiniAli to SH 43 at Kahipara, Power Dept. Transformers   2 nos. of Distribution transformers, 11kV line approx. 1km and Lt. Line approximately 0.8 km to be shifted due to flood at No.2 Sonapur as reported by SDE,APDCL Bihpuria ESD , <b>Nowboicha</b> - Fisheries/Pond   Approximate Fish pond Area affected in Nowboicha Circle 95 Hact. Report received from FDO, Nowboicha, Fishery Department, Lakhimpur on 17/06/2022</p>
	Nagaon	<b>Kampur</b> - Secondary Schools Damaged   Bakulaguri High School submerged on dated 16.06.2022
	Nalbari	<b>Ghograpar</b> - Culvert Approach Road Damaged   As per PWRD WT msg 12 No of Culvert has been damaged / Washed away on 16/06/2022 at various villages under Ghograpar Revenue Circle
	Sonitpur	<p><b>Dhekiajuli</b> - Culvert Approach Road Damaged   PWD village road partially damaged due to rising agricultural water at Bhairaguri village, Borsola. Dated 17.06.22, <b>Tezpur</b> - Damaged RCC Bridge   Dated: 17/06/2022. yesterday i.e 16/06/2022 at about 5:00 P.M Heavy road erosion is observed at half constructed RCC box culvert point at B.P Tinali to Rangapara road (via Bindukuri) at Dihingia &amp; Dekachuburi kundarbari village. length : 5 m (approx)</p>
	South Salmara	<b>Mankachar</b> - Fisheries/Pond   As per reported fishery department, 28 nos fishery/pond damaged due to heavy rainfall on 17/06/22 under Mankachar Revenue Circle
	Udalguri	<p><b>Khairabari</b> - Washed away Culverts   One HPC of Length :10M (approx.) was washed away creating breach on Panisali to Ranganadi road on 16.06.2022. GPS-Coordinates: Lat- 26.678132 Long: 91.770944, Power Dept. Conductors   Due to continious rarin and flood occured on 16/06/2022, conductors were snapped at various places namely, Jhargaon, Barakhat, Patala &amp; Bartangla. As a result the power supply have been hampered. , Fisheries/Pond   As per reported by the department approximately 180 farmers were affected and approximately 22.55 Ha. of area is affected in 12 nos. Of villages , Gully Control Damaged   One GCP cracked at Malmura Village (near Bistiram Boro paddy field) by Kacharidong during flood on 16.05.2022. GPS Coordinates- Lat: 26.3729 Long: 91.4512 Length: 10 M (approx.). <b>Kalaigaon</b> - Bridge Approach Road Damaged   The bridge approach of Rupatal bridge o Makenjee road eroded due to heavy pressure of flood water from river Noa and communication disrupted for all kinds of vehicle at village Rupatal covering a length of around 20 meters and breadth of 10 meters on 17-06-2022 Longitude: 92.021256, Latitude: 26.564562, <b>Harisinga</b> - Power Dept. Poles   LT and HT pole damaged at village Botabari, Teliapara, Nonke sukla, Polahgarh, Majgaon, Niz Ghagra,, Teliapara Corramore, sagalijhar, Sastrapara, Dui nodirmukh, Kristianpara, on 15/06/2022, 16/06/2022 &amp; 17/06/2022 under Tangla electrical sub-division, Power Dept. Conductors   Conductors were snapped at various places like Village Nonke Suklai, Batabari, Teliapara, Badlapara, Majgaon, Batabari amguri, Teliapara,Patala, Borjalah, Bartangla, Sastrapara, Pukhuripara, on 16/06/2022 under Tangla electrical sub-division</p>
Erosion	<b>District</b>	<b>Details</b>
	Baksa	<p><b>Barama</b> - 1. Agchia 2. Dolbari   1. Erosion observed at riverine L/B of Mora Pagladia river at a stretch of 100 m approx. Date of occurrence: 17/06/22. Lat: 26.591495 Lon: 91.392614 2. Erosion occurred on L/B embankment of Mora Pagladia river at Dolbari Gaibari supa at a length of 400 m. Date of occurrence: 17/06/22. Lat:</p>

		26.582945 Lon: 91.391315   13, <b>Jalah</b> - Khagrabari   On 17 June 2022, approximately 600 meter of left bank of river beki eroded .   14
	Biswanath	<b>Biswanath</b> - Diring Tiniali to Diring T.E Road   Side erosion of the village road from Diring Tiniali to Diring T.E by Diring river on 16.06.2022 at ch.120 m for a length of about 80 m, average Depth of erosion is 1.95 m for an average width of 2 m as per WT message from PWD(roads), Biswanath Territorial Road Division.   0, <b>Naduar RC part</b> - Soraijonia   As per report received from Ex. Engineer PWD BSN, Side erosion of the road is observed from sootea to Soraijonia Hospital by the river Mornoi at Ch. 500.00m for a length of about 50 m. The average width & depth of side erosion are 2m & 1.95m. 17.06.2022   0, <b>Halem</b> - Borani Pathar   As reported by Water Resources, Gohpur, Bank erosion is observed at downstream of Railway bridge on the R/B embankment of river Brahmajon from 17/06/2022. Legth 22m   0
	Bongaigaon	<b>Manikpur</b> - Nowapara no 2   one nos house was damge due to erosion at Nowapara. date- 17.06.2022   5, <b>Srijangram</b> - Madhufal and Dubachuri part I   Madhufal: erosion occurred on 17.06.2022 in length of 450 m of river bank of Manas .Dubachuri Part I(90.711696 26.277567): erosion occurred due to flood water   330
	Charaideo	<b>Mahmora</b> - Japidhara Gaon, Hingrijan Near Khoomtai, Kokoramora Gaon, Bholukaguri Gaon, Jonghal Block gaon, Tiphuk Kachari Gaon, Doomor Dollong Habi   1. Erosion occurred on 17/06/2022 Hingrijan Gaon at right bank of Desang river under Mahmora Revenue Circle. Temporary restoration work immediately required at the present location. Lat-27.07000, Long-95.0291667 as reported by Water Resource Department Demow . 2. Erosion occurred on 17/06/2022 Pub Japidhara Nepali Gaon at right bank of Desang river under Mahmora Revenue Circle. Temporary restoration work immediately required at the present location. Lat-27.141388, Long-94.9511111 , as reported by WR dept. Demow. 3. Erosion occurred on 17/06/2022 Kokoramora Gaon at right bank of Deroi river under Mahmora Revenue Circle. Temporary restoration work immediately required at the present location. Lat-27.1344444, Long-94.8716666 , as reported by WR Dept. Demow 4. Erosion occurred on 17/06/2022 Bholukaguri Gaon at right bank of Desang river under Mahmora Revenue Circle. Temporary restoration work immediately required at the present location. Lat-27.125000, Long-95.0983250 , as reported by WR Dept. Demow 5. Erosion occurred on 17/06/2022 Jonghal Block Sundarpur Gaon at right bank of Deroi river under Mahmora Revenue Circle. Temporary restoration work immediately required at the present location. Lat-27.1144444, Long-94.9122222 , as reported by WR Dept. Demow 6. Erosion occurred on 17/06/2022 Tiphuk Kachari Gaon at right bank of Deroi river under Mahmora Revenue Circle. Temporary restoration work immediately required at the present location. Lat-27.0961111, Long-94.868333 , as reported by WR Dept. Demow. 7. Erosion occurred on 17/06/2022 Doomor Dollong Habi Gaon at right bank of Deroi river under Mahmora Revenue Circle. Temporary restoration work immediately required at the present location. Lat-27.1011111, Long-94.8616667 , as reported by WR Dept. Demow.   0
	Chirang	<b>Sidli</b> - Betagaon (Fulguri), South Deolguri, Dakshin Nangdarbari (Nepalpara)   As reported by WRD 3 nos. of Erosion Occurred:: 1. As reported by WRD, due to rise in water level severe erosion occurred on 16-06-2022 on L/B of River Suthi. Damage Details: Length: 400 M Apprx., Breadth:10M Apprx., Depth: 3.50M, Long:90.405501, Lat:26.512358. 2. As reported by WRD, due to rise in water level severe erosion occurred on 16-06-2022 on R/B of river Suthi. Damage Details: 275 M Apprx., Breadth:3.50 M Apprx. Depth: 2.50M Apprx. Long:90.408815 Lat:26.524044. 3. As reported by WRD, due to rise in water level severe erosion occurred on 17-06-2022 on L/B of River Champamati. Damage Details: 430M Apprx. Breadth:6.50M Apprx. Depth: 3.70 M Apprx. Long:90.36862, Lat: 26.581571   0, <b>Bijni</b> - Bagargaon, Gundamara   As reported by Chirang WR Division, Kajalgaon, 1. Erosion occurred on 16-06-2022 at Bagargaon on R/B of river Daranga. Length=300.00 mtr, Breadth=5.50 mtr, Depth=6.60 mtr. Longitude=90.744616 Latitude=26.54269 2. Erosion occurred on 16-06-2022 at Gundamara on R/b of river Daranga. Length=350.00 mtr, Breadth=6.00 mtr, Depth=8.00 mtr. Longitude=90.62325 Latitude=26.42359   0
	Dhubri	<b>Chapar</b> - Jamduar Pt-I   Erosion occurred at Jamduar Pt-I Village in the river Gaurang under Chapar Revenue Circle. Around 0B-2K-10L of land has been eroded so far on dated 16-06-2022.   0, <b>Agamoni</b> - Village Bholarkhas under Chotoguma GP under Agomani Rev. Circle.   Riverine area of River Gangadhar at vill Bholarkhas under Chotoguma GP is getting eroded. The river embankment of that village has been eroded at several points. Village : Bholarkhas River: Gangadhar GP : Chotoguma Incident date : 15/06/2022 to 17/06/2022 Time : 4.00pm Land : 0 bigha 2 khata 10 Lessa Population affected : Nil GPS Coordinate : Lat. 26.3078053. Long. 89.8036509   0
	Hailakandi	<b>Katlicherra</b> - kukicherra Pt. I, under Katlicherra Revenue Circle dtd. 16-06-2022   Severe erosion occurred at Kukicherra Pt. I, under Katlicherra Revenue circle. Area of erosion - Length- 60 meter and Breadth- 20 meter   0, <b>Lala</b> - Nimaichandpur pt-2 under Lala Revenue Circle, Hailakandi. Date- 13/06/2022   Severly damaged due to vertical settlement and sloughening during the last wave of flood and at the time of draw -down stage of river Katakhal on its right bank. Reach lenght-100m   3000
	Kamrup	<b>Chaygaon</b> - Garjanpara, Chhaygaon revenue Circle   After Field visit by Field Officer (DM), LM along with water resource Asst Eng. An erosion was seen at the bank of river Kulsi at Garjanpara area about 15 m approx on 16/6/2022 at 10:30 AM.   0
	Lakhimpur	<b>Kadam</b> - 1. Errosion occured on NH.15 to Moinapara Jorhatia Akarabosti rd at Ch.75 m to 460 m, 2. Boginadi Khurachuk erosion occured due to increasing water level of the river Boginadi approximately 100 feet   Errosion occured on NH.15 due to heavy rain to Moinapara Jorhatia Akarabosti rd at Ch.75 m to 460 m informed by PWD Road Boginadi Khurachuk erosion occured due to increasing water level of the river Boginadi approximately 100 feet informed by concerned Gaon Pradhan on 17/06/2022   0, <b>Bihpuria</b> - Pava embankment at No. 2 Sonapur   About 15 meters of the embankment has been eroded due to flood water of Pava river on 16th June 2022 under WRD, North Lakhimpur   0, <b>Dhakuakhana</b> - Gurkhali Nepali (Revenue Village: Nemitengani)   Erosion occurred at Gurkhali Nepali. One



		temporary bamboo structured Temple (Ram Mandir) was damaged on 17/06/2022 due to rising water level of River Laipulia. Report submitted by Dhakuakhana Revenue Circle.   0
	Morigaon	<b>Mayong</b> - Bhakatgaon   Erosion is going on Kollong river on 17/06/2022 as reported by concerned LM and Gaonpradhan. appx 15 mtr eroded   6, <b>Laharighat</b> - Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori   As per report received from the Water Resources depr on 17-06-2022, erosion is observed in areas like Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori, with max maximum erosion of 1 m in Leruamukh, 0 m in Goroimari , 3 m in Bhajaikhati gaon & 3 m in Barchapori respectively.   0
	Sonitpur	<b>Thelamara</b> - Village- Goruduba   As reported by Water Resource Department, Tezpur on 17/06/2022, Severe bank erosion is occurred at Garuduba area on the L/Bank of river Belsiri. Temporary palliative measures in the form of launching of Geo-bag Type-A and Type-B , empty cement bag pitching,launching of Bamboo cribs, Bamboo bundle and tree branches are going on.   0, <b>Tezpur</b> - khulaguti Kachari village   dated: 17/06/2022. Erosion is observed on the R/B of river Dipota at Kholaguti Kachari village. Length 10 m (approx)   0
	Tamulpur	<b>Tamulpur</b> - Village No-1 Paharpur Mouza Kumarikata   Culvert Slab Damage - dated 17/06/2022   0
	Tinsukia	<b>Sadiya</b> - 1. 8th mile 2. kailabast.   1. Erosion at 8th mile by Kundil river under the bridge since 16/06/2022 to 17/06/2022 as per report received from the concerned Gaon Pradhan. Stretch area is 01 m. Location ( 27°52'02"N, 95°45'36"E). 2. Active erosion is reported from Koilabasti area by Kundil river since 16/ 06/2022 to 17/06/2022 by concerned Gaon Pradhan. Stretch area is 3 m. Location (27°50'48.8"N, 95°42'45.2"E).   4
	Udalguri	<b>Khairabari</b> - Mahaliapara Village   Severe erosion by Kalpani River at Mahaliapara village near Umesh Ch. house to Obeswar Baro House. Date of Occurrence: 15.06.2022 Length: 200 m (Approx.)   20
Landslide	<b>District</b>	<b>Details</b>
	Dima-Hasao	<b>Haflong</b> - 1.) Landslide at Dehangi 2.)Kalachand-Koladisa Road (Maibang) blocked due to landslide 3.)Landslide at Gunjung village   Landslide at Dehangi on 17 June 2022, Kalachand-Koladisa Road (Maibang) blocked due to landslide on 17 June 2022, Landslide at Gunjung village on 17 June 2022.   0
	Goalpara	<b>Balijana</b> - Pahartoli village ( ward no. 1 & 2) and Kharmuza   Pahartoli village ( ward no. 1 & 2) and Kharmuza is in the grip of landslide due to on going going rainfall due to which which many families are affected   153
	Kamrup	<b>Boko</b> - Boko-Upper Lampi Road   Roadside partial landslide. Cleared by PWRD, Boko within 30 mins of occurrence. Communication is going on. Date: 16/06/2022. Reported by PWRD, Boko Territorial Road Sub-Division.   0
	Kamrup (M)	<b>Chandrapur</b> - Chandrapur Bagicha(Aranya Nagar)   1)Haren Gogoi,lat : 26.209318 long: 91.870333 2)Bimal Sarkar,lat: 26.236914 long: 91.941804 3)Biju Phukan,Lat : 26.2372 long: 91.941242 Occurred on 17/06/2022 Information received from concerned LM No casualty   0, <b>Guwahati</b> - Jyoti Nagar, Malibagan, Sunsali   Landslide incident occured on 17/06/2022 Major: Jyoti Nagar (26.187722, 91.794975) partially house damaged Minor: Malibagan, Sunsali   12, <b>Sonapur</b> - 10th Mile Hastinapur   Landslide incident occured on 17/06/2022 at 10th Mile Hastinapur. No Casualty   0, <b>Dispur</b> - 8TH Mile Krishna Nagar, BONDAGhulaigaon, Baikunthapur, Kacharibasti   Landslide incident occured on 17/06/2022 . Guard wall collapsed. Paetial Damage. No casualty   13
	Morigaon	<b>Mayong</b> - Gamariguri   Land and Rock Sliding due to continuous rain at Ouguri to Chanaka road as reported by PWD Morigaon district territorial road division on 17/06/22.   0
Urban Flood	<b>District</b>	<b>Details</b>
	Bajali	<b>Bajali</b> - Pathsala   Due to heavy rain fall in different location : Jyoti Nagar, Krishna Nagar, Lachit Nagar, Ward No 1 to 10 Date: 17/06/2022   12000
	Barpeta	<b>Barnagar</b> - Barpeta Road, Ward No-1, 2 & 9   Due to heavy rain fall water logged at some places in the mentioned wards of Barpeta Road town (17-6-2022)   5715
	Darrang	<b>Mangaldoi</b> - Mangaldai town Ward No 1,2,3,4,5,6,7&8   Due to rising water level of river the complete town is flooded dated 17.06.2022   25000
	Goalpara	<b>Balijana</b> - Goalpara Town Ward no. 3,4,5,6,7,8,10,11,12,13,14, & 17   Goalpara Town Ward no. 3,4,5,6,7,8,10,11,12,13,14, & 17 are partially affected due to heavy rain water causing urban flood.   25600, <b>Lakhipur</b> - Lakhipur Town Ward No. 6,8,9&10   Due to Urban Flood in Lakhipur Town Ward No. 6,8,9&10 got affected. The date of occurrence of Urban Flood on 16.06.2022 to till date i.e 17.06.2022   4537
	Kamrup (M)	<b>Guwahati</b> - B.Boruah Road, Maligaon   Partial water logging on 17/06/2022   0, <b>Dispur</b> - Nabin Nagar, Anil Nagar, Narengi, Satgaon, Keraikuchi, Rukminigaon, Hatigaon   waterlogging due to rain on 17/06/2022   0
	Kokrajhar	<b>Kokrajhar</b> - KOKRAJHAR TOWN   URBAN FLOODING   8641, <b>Gossaigaon</b> - Gossaigaon Town   Ward No. 1 and Ward No. 2   314
	Nalbari	<b>Nalbari</b> - Hazo Nalbari Road, Palla Road, Barama Road, NT Road   This places are submerged due to continuous heavy rain on 17/06/2022   2530
Udalguri	<b>Udalguri</b> - Udalguri Town (Ward 01, 02, 04)   Overtopping of drain water to nearby houses in Udalguri Town area on 17.06.2022   342	