

Assam Daily Flood Report as on 21-05-2022 at 4:00 PM

Assam Daily Flood Report as on 21-05-2022 at 4:00 PM			
Particulars	Situation as on 21-05-2022 (in last 24 hours)		
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above danger level	Kopili (Dharamtul), Disang (Nanglamuraghat), Brahmaputra (Neamatighat)	
	Rivers flowing above highest flood level	Kopili (Kampur)	
District Affected	<b>No. of Districts Affected</b>	<b>Name of Flood Affected Districts</b>	<b>Name of Urban Flood Districts</b>
	31	Baksa, Barpeta, Biswanath, Bongaigaon, Cachar, Charaideo, Darrang, Dhemaji, Dhubri, Dibrugarh, Dima-Hasao, Goalpara, Golaghat, Hailakandi, Hojai, Jorhat, Kamrup, Kamrup (M), Karbi Anglong West, Karimganj, Kokrajhar, Lakhimpur, Majuli, Morigaon, Nagaon, Nalbari, Sivasagar, Sonitpur, South Salmara, Tinsukia, Udalguri	
No. Of Revenue Circles Affected	81		
Name Of Revenue Circles Affected	<b>District</b>	<b>Total</b>	<b>Revenue Circle</b>
	Baksa	1	Baksa
	Barpeta	5	Barpeta, Baghbar, Sarthebari, Kalgachia, Chenga
	Biswanath	3	Naduar RC part, Gohpur, Biswanath
	Bongaigaon	2	Manikpur, Srijangram
	Cachar	5	Silchar, Katigorah, Udharbond, Lakhipur, Sonai
	Charaideo	1	Sonari
	Darrang	4	Patharighat, Dalgaon, Mangaldoi, Sipajhar
	Dhemaji	2	Dhemaji, Jonai
	Dhubri	4	Dhubri, Golakganj, Gauripur, South Salmara Part
	Dibrugarh	1	Chabua
	Dima-Hasao	1	Haflong
	Goalpara	4	Balijana, Rongjuli, Lakhipur, Matia
	Golaghat	2	Bokakhat, Khumtai
	Hailakandi	1	Algapur
	Hojai	3	Lanka, Hojai, Doboka
	Jorhat	1	Jorhat East
	Kamrup	9	Goroimari, Hajo, Rangia, Kayan, Chaygaon, Nagarbera, Boko, Chamaria, Kamalpur
	Kamrup (M)	2	Chandrapur, Sonapur
	Karbi Anglong West	1	Donkamokam
	Karimganj	2	Karimganj, Badarpur
	Kokrajhar	1	Bagribari
	Lakhimpur	4	Bihpuria, Subansiri, North Lakhimpur, Narayanpur
	Majuli	2	Majuli, Ujani Majuli
	Morigaon	2	Morigaon, Mayong
	Nagaon	3	Kampur, Raha, Nagaon
	Nalbari	6	Barbhag, Nalbari, Tihu, Barkhetri, Ghograpar, Paschim Nalbari
Sivasagar	1	Sonari RC part	
Sonitpur	4	Dhekiajuli, Naduar, Chariduar, Tezpur	
South	2	Mankachar, South Salmara	

	Salmara							
	Tinsukia	1	Doomdooma					
	Udalguri	1	Udalguri					
	<b>Total</b>	<b>81</b>						
Villages Affected	<b>District</b>	<b>Total</b>	<b>Revenue Circle</b>					
	Baksa	1	(Baksa   1)					
	Barpeta	284	(Sarthebari   55), (Barpeta   62), (Kalgachia   88), (Baghbar   20), (Chenga   59)					
	Biswanath	9	(Naduar RC part   2), (Gohpur   4), (Biswanath   3)					
	Bongaigaon	39	(Srijangram   16), (Manikpur   23)					
	Cachar	447	(Silchar   126), (Katigora   154), (Udharbond   47), (Sonai   58), (Lakhipur   62)					
	Charaideo	1	(Sonari   1)					
	Darrang	154	(Dalgaon   48), (Patharighat   20), (Sipajhar   38), (Mangaldoi   48)					
	Dhemaji	21	(Jonai   19), (Dhemaji   2)					
	Dhubri	141	(Dhubri   43), (Golaganj   33), (Gauripur   49), (South Salmara Part   16)					
	Dibrugarh	2	(Chabua   2)					
	Dima-Hasao	3	(Haflong   3)					
	Goalpara	243	(Balijana   73), (Rongjuli   21), (Lakhipur   106), (Matia   43)					
	Golaghat	4	(Bokakhat   1), (Khumtai   3)					
	Hailakandi	1	(Algapur   1)					
	Hojai	64	(Lanka   11), (Hojai   29), (Doboka   24)					
	Jorhat	1	(Jorhat East   1)					
	Kamrup	110	(Goroimari   8), (Hajo   17), (Kayen   15), (Chaygaon   3), (Nagarbera   16), (Boko   2), (Chamaria   22), (Kamalpur   21), (Rangia   6)					
	Kamrup (M)	23	(Chandrapur   10), (Sonapur   13)					
	Karbi Anglong West	2	(Donkamokam   2)					
	Karimganj	15	(Karimganj   8), (Badarpur   7)					
	Kokrajhar	16	(Bagribari   16)					
	Lakhimpur	59	(Subansiri   1), (North Lakhimpur   1), (Narayanpur   33), (Bihpuria   24)					
	Majuli	12	(Ujani Majuli   4), (Majuli   8)					
	Morigaon	185	(Mayong   106), (Morigaon   79)					
	Nagaon	226	(Nagaon   50), (Kampur   98), (Raha   78)					
	Nalbari	131	(Barbhag   32), (Nalbari   17), (Barkhetri   43), (Ghograpar   19), (Tihu   5), (Paschim Nalbari   15)					
	Sivasagar	2	(Sonari RC part   2)					
	Sonitpur	29	(Dhekiajuli   14), (Naduar   2), (Chariduar   1), (Tezpur   12)					
	South Salmara	17	(Mankachar   12), (South Salmara   5)					
Tinsukia	4	(Doomdooma   4)						
Udalguri	2	(Udalguri   2)						
	<b>Total</b>	<b>2248</b>						
Population And Crop Area Affected	<b>District</b>	<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Total Population</b>	<b>Population Details</b>	<b>Crop Area (in Hect.)</b>	<b>Crop Area Details</b>
	Baksa	0	0	0	0	(Baksa   0)	1.46	(Baksa   1.46)
	Barpeta	1550	736	250	2536	(Barpeta   2536), (Sarthebari   0), (Kalgachia   0), (Chenga   0), (Baghbar   0)	7354.50	(Barpeta   1286.00), (Sarthebari   3102.00), (Kalgachia   1457.00), (Chenga   1153.00), (Baghbar   356.50)
	Biswanath	391	248	104	743	(Naduar RC part   0), (Halem   0), (Gohpur   582), (Biswanath   161)	398.00	(Naduar RC part   41.00), (Halem   0.00), (Gohpur   215.00), (Biswanath   142.00)
	Bongaigaon	0	0	0	0	(Manikpur   0), (Srijangram   0)	431.00	(Manikpur   143.00), (Srijangram   288.00)
	Cachar	83630	39512	54812	177954	(Silchar   37000), (Katigora   77967), (Udharbond   5780), (Lakhipur   37220), (Sonai   19987)	4116.75	(Silchar   501.00), (Katigora   2015.00), (Udharbond   217.00), (Lakhipur   375.00), (Sonai   1008.75)
	Charaideo	0	0	0	0	(Sonari   0)	1.60	(Sonari   1.60)

Darrang	18032	15906	10444	44382	( Patharighat   18560 ), ( Dalgaon   1270 ), ( Mangaldoi   24417 ), ( Sipajhar   135 )	20195.40	( Patharighat   298.90 ), ( Dalgaon   7441.50 ), ( Mangaldoi   11963.00 ), ( Sipajhar   492.00 )
Dhemaji	315	260	69	644	( Jonai   0 ), ( Dhemaji   644 )	384.20	( Jonai   372.20 ), ( Dhemaji   12.00 )
Dhubri	0	0	0	0	( Dhubri   0 ), ( Golakganj   0 ), ( Gauripur   0 ), ( South Salmara Part   0 )	4574.70	( Dhubri   1236.50 ), ( Golakganj   1215.00 ), ( Gauripur   1137.00 ), ( South Salmara Part   986.20 )
Dibrugarh	1949	1490	1148	4587	( Chabua   4587 )	3.50	( Chabua   3.50 )
Goalpara	0	0	0	0	( Lakhipur   0 ), ( Balijana   0 ), ( Rongjuli   0 ), ( Matia   0 )	13900.00	( Lakhipur   8483.00 ), ( Balijana   2408.00 ), ( Rongjuli   487.00 ), ( Matia   2522.00 )
Golaghat	0	0	0	0	( Bokakhat   0 ), ( Khumtai   0 )	51.00	( Bokakhat   25.00 ), ( Khumtai   26.00 )
Hailakandi	35	37	7	79	( Algapur   79 )	0.00	( Algapur   0.00 )
Hojai	36587	25952	7694	70233	( Lanka   2334 ), ( Hojai   14639 ), ( Doboka   53260 )	3949.00	( Lanka   650.00 ), ( Hojai   2051.00 ), ( Doboka   1248.00 )
Jorhat	0	0	0	0	( Jorhat East   0 )	35.00	( Jorhat East   35.00 )
Kamrup	8	7	4	19	( Chaygaon   0 ), ( Nagarbera   0 ), ( Chamaria   0 ), ( Goroimari   0 ), ( Hajo   0 ), ( Kayan   0 ), ( Boko   0 ), ( Kamalpur   0 ), ( Rangia   19 )	4907.98	( Chaygaon   62.00 ), ( Nagarbera   1209.00 ), ( Chamaria   1829.50 ), ( Goroimari   559.00 ), ( Hajo   988.98 ), ( Kayan   99.00 ), ( Boko   69.00 ), ( Kamalpur   44.00 ), ( Rangia   47.50 )
Kamrup (M)	0	0	0	0	( Chandrapur   0 ), ( Sonapur   0 )	1158.00	( Chandrapur   826.00 ), ( Sonapur   332.00 )
Karbi Anglong West	660	678	761	2099	( Donkamokam   2099 )	0.00	( Donkamokam   0.00 )
Karimganj	7144	5074	4164	16382	( Karimganj   10996 ), ( Badarpur   5386 )	3.30	( Karimganj   0.00 ), ( Badarpur   3.30 )
Kokrajhar	0	0	0	0	( Bagribari   0 )	69.38	( Bagribari   69.38 )
Lakhimpur	1000	658	207	1865	( Subansiri   40 ), ( North Lakhimpur   1825 ), ( Narayanpur   0 ), ( Bihpuria   0 )	1210.40	( Subansiri   227.90 ), ( North Lakhimpur   0.00 ), ( Narayanpur   570.50 ), ( Bihpuria   412.00 )
Majuli	0	0	0	0	( Ujani Majuli   0 ), ( Majuli   0 )	151.43	( Ujani Majuli   33.25 ), ( Majuli   118.18 )
Morigaon	7055	6125	4596	17776	( Morigaon   17776 ), ( Mayong   0 )	11238.63	( Morigaon   3429.63 ), ( Mayong   7809.00 )
Nagaon	146165	132534	60728	339427	( Kampur   237158 ), ( Raha   82164 ), ( Nagaon   20105 )	14263.87	( Kampur   5600.00 ), ( Raha   5354.87 ), ( Nagaon   3309.00 )
Nalbari	270	185	42	497	( Barbhag   0 ), ( Nalbari   0 ), ( Barkhetri   0 ), ( Ghograpar   0 ), ( Tihu   0 ), ( Paschim Nalbari   497 )	3798.60	( Barbhag   270.00 ), ( Nalbari   168.60 ), ( Barkhetri   3075.00 ), ( Ghograpar   88.00 ), ( Tihu   36.00 ), ( Paschim Nalbari   161.00 )
Sivasagar	0	0	0	0	( Sonari RC part   0 )	7.60	( Sonari RC part   7.60 )
Sonitpur	220	195	67	482	( Naduar   332 ), ( Dhekiajuli   0 ), ( Chariduar   150 ), ( Tezpur   0 )	1099.10	( Naduar   92.00 ), ( Dhekiajuli   905.10 ), ( Chariduar   0.00 ), ( Tezpur   102.00 )
South Salmara	0	0	0	0	( Mankachar   0 ), ( South Salmara   0 )	243.00	( Mankachar   140.00 ), ( South Salmara   103.00 )

	Tinsukia	0	0	0	0	( Doomdooma   0 )	15.00	( Doomdooma   15.00 )		
	Udalguri	243	141	29	413	( Harisinga   0 ), ( Kalaigaon   0 ), ( Udalguri   413 )	0.00	( Harisinga   0.00 ), ( Kalaigaon   0.00 ), ( Udalguri   0.00 )		
	<b>Total</b>	<b>305254</b>	<b>229738</b>	<b>145126</b>	<b>680118</b>		<b>93562.40</b>			
Relief Camps / Centres Opened	<b>District</b>	<b>Total</b>	<b>Relief Camp</b>			<b>Relief Distribution Centres</b>				
	Cachar	294	199(Silchar   99, Katigorah   76, Udharbond   1, Sonai   23, Lakhipur   0)			95(Silchar   10, Katigorah   38, Udharbond   6, Sonai   1, Lakhipur   40)				
	Darrang	8	1(Patharighat   1, Mangaldoi   0)			7(Patharighat   5, Mangaldoi   2)				
	Dima-Hasao	8	8(Haflong   8)			0(Haflong   0)				
	Hailakandi	1	1(Algapur   1)			0(Algapur   0)				
	Hojai	34	33(Hojai   22, Doboka   11, Lanka   0)			1(Hojai   0, Doboka   0, Lanka   1)				
	Kamrup	1	0(Rangia   0)			1(Rangia   1)				
	Karbi Anglong West	3	0(Donkamokam   0)			3(Donkamokam   3)				
	Karimganj	19	7(Badarpur   7, Karimganj   0)			12(Badarpur   2, Karimganj   10)				
	Lakhimpur	5	0(North Lakhimpur   0, Narayanpur   0, Bihpuria   0)			5(North Lakhimpur   1, Narayanpur   3, Bihpuria   1)				
	Morigaon	4	1(Morigaon   1)			3(Morigaon   3)				
	Nagaon	110	32(Nagaon   10, Raha   7, Kampur   15)			78(Nagaon   6, Raha   45, Kampur   27)				
	Nalbari	2	0(Tihu   0)			2(Tihu   2)				
	Sonitpur	6	0(Tezpur   0)			6(Tezpur   6)				
	Udalguri	1	0(Udalguri   0)			1(Udalguri   1)				
	<b>Total</b>	<b>496</b>	<b>282</b>			<b>214</b>				
Inmates In Relief Camps	<b>District</b>	<b>Total</b>	<b>Revenue Circlewise</b>			<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Pregnant / Lactating Mother</b>	<b>Person with Disability</b>
	Cachar	42294	(Silchar   13033), (Katigorah   21618), (Udharbond   76), (Sonai   7567)			17161	14538	10567	21	7
	Darrang	72	(Dalgaon   0), (Mangaldoi   0), (Sipajhar   0), (Patharighat   72)			5	46	18	1	2
	Dima-Hasao	1402	(Haflong   1402)			463	503	436	0	0
	Hailakandi	79	(Algapur   79)			35	37	7	0	0
	Hojai	14052	(Lanka   0), (Doboka   7437), (Hojai   6615)			7230	4587	2231	4	0
	Karimganj	614	(Karimganj   0), (Badarpur   614)			334	197	58	25	0
	Morigaon	45	(Mayong   0), (Morigaon   45)			20	15	10	0	0
	Nagaon	16349	(Nagaon   7975), (Raha   1427), (Kampur   6947)			7994	5782	2452	119	2
	<b>Total</b>	<b>74907</b>				<b>33242</b>	<b>25705</b>	<b>15779</b>	<b>170</b>	<b>11</b>
Human Lives Lost - Confirmed	<b>District</b>	<b>Total</b>	<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Revenue Circlewise</b>				
	Cachar	2	2	0	0	(Katigorah   0), (Lakhipur   0), (Silchar   2), (Sonai   0), (Udharbond   0)				
	Hojai	1	1	0	0	(Doboka   1), (Hojai   0), (Lanka   0)				
	Nagaon	1	1	0	0	(Kampur   1), (Nagaon   0), (Raha   0)				
	<b>Total</b>	<b>4</b>	<b>4</b>	<b>0</b>	<b>0</b>					
Human Lives Lost Confirmed - Death Type	<b>District</b>	<b>Total</b>	<b>Flood Death</b>	<b>General Drowning (Non Flood)</b>	<b>Landslide</b>					
	Cachar	2	2	0	0					
	Hojai	1	1	0	0					
	Nagaon	1	1	0	0					
	<b>Total</b>	<b>4</b>	<b>4</b>	<b>0</b>	<b>0</b>					
Human Lives Lost - Missing	<b>District</b>	<b>Total</b>	<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Details</b>				
	Cachar	1	0	0	1	(Katigorah   0), (Lakhipur   0), (Silchar   1), (Sonai   0), (Udharbond   0)				
	<b>Total</b>	<b>1</b>	<b>0</b>	<b>0</b>	<b>1</b>					
Human Lives Lost	<b>District</b>	<b>Total</b>	<b>Flood</b>	<b>Non Flood</b>						
	Cachar	1	1	0						

Missing - Type	Total	1	1	0						
Animals Affected	<b>District</b>	<b>Total</b>	<b>Big</b>	<b>Small</b>	<b>Poultry</b>					
	Barpeta	85033	25246	14508	45279					
	Darrang	121611	60557	25544	35510					
	Dibrugarh	214	189	25	0					
	Goalpara	1298	711	587	0					
	Hojai	7009	1546	332	5131					
	Kamrup	17851	7901	4206	5744					
	Lakhimpur	74	19	15	40					
	Morigaon	45050	15350	10255	19445					
	Nagaon	100084	55413	27369	17302					
	Nalbari	17069	6838	7931	2300					
	Sonitpur	4210	2876	1334	0					
	Total	<b>399503</b>	<b>176646</b>	<b>92106</b>	<b>130751</b>					
Animals Washed Away	Nil									
Houses Damaged	<b>District</b>	<b>Fully Kuccha</b>	<b>Fully Pukka</b>	<b>Fully Total</b>	<b>Partially Kuccha</b>	<b>Partially Pukka</b>	<b>Partially Total</b>	<b>Others Huts</b>	<b>Others Cattle Shed</b>	<b>Others Total</b>
	Biswanath	2	0	2	35	0	35	0	0	0
	Dima-Hasao	57	135	192	0	0	0	90	0	90
	Hojai	4	0	4	0	0	0	0	0	0
	Total	<b>63</b>	<b>135</b>	<b>198</b>	<b>35</b>	<b>0</b>	<b>35</b>	<b>90</b>	<b>0</b>	<b>90</b>
Rescue Operation	<b>District</b>	<b>Agency</b>			<b>Boats Deployed</b>	<b>Person Evacuated By Boats</b>	<b>Animal Evacuated By Boats</b>	<b>Helicopters Deployed</b>	<b>Person Evacuated By Helicopters</b>	<b>Medical Team Deployed</b>
	Cachar	Army/Paramilitary force, Circle Office/Local Administration, Fire & Emergency Services (F&ES), Local People, SDRF, Civil Defence/Trained Volunteers, NDRF, Police			5	334	0	0	0	16
	Darrang				0	0	0	0	0	4
	Hojai	Circle Office/Local Administration, Local People, NDRF, SDRF, Army boat, Fire & Emergency Services (F&ES), Country Boats			55	401	52	0	0	9
	Lakhimpur				0	0	0	0	0	4
	Morigaon	Fire & Emergency Services (F&ES)			2	15	0	0	0	0
	Nagaon	Fire & Emergency Services (F&ES), NDRF, SDRF, Army/Paramilitary force			13	737	0	0	0	9
	Total				<b>75</b>	<b>1487</b>	<b>52</b>	<b>0</b>	<b>0</b>	<b>42</b>
Relief Distributed	<b>District</b>	<b>Rice (in Q)</b>	<b>Dal (in Q)</b>	<b>Salt (in Q)</b>	<b>M. Oil (in L)</b>	<b>Cattle Feed - Green Fooder (in Q)</b>	<b>Cattle Feed - Wheat Bran (in Q)</b>	<b>Cattle Feed - Rice Bran (in Q)</b>		
	Cachar	1217.12	223.93	36.50	6636.70	0.00	2823.00	0.00		
	Darrang	68.37	12.40	3.73	373.00	0.00	0.00	397.20		
	Dima-Hasao	1.65	0.31	0.13	85.26	0.00	0.00	0.00		
	Hailakandi	1.38	0.24	0.80	8.00	0.00	0.00	0.00		
	Hojai	644.81	95.56	278.23	27822.90	0.00	0.00	0.00		
	Kamrup	0.00	0.00	0.00	0.00	0.00	163.44	0.00		
	Karbi Anglong West	83.00	15.62	4.41	441.00	0.00	0.00	0.00		

	Karimganj	73.04	13.54	4.16	337.19	0.00	0.00	0.00
	Lakhimpur	27.75	5.48	1.65	165.00	0.00	0.00	292.00
	Morigaon	20.35	3.37	1.01	0.00	0.00	0.00	0.00
	Nagaon	573.40	103.80	31.14	0.00	0.00	210.00	0.00
	Nalbari	0.00	0.00	0.00	0.00	0.00	296.00	0.00
	Sonitpur	0.00	0.00	0.00	0.00	0.00	115.80	0.00
	Udalguri	1.59	0.31	0.09	9.30	0.00	0.00	0.00
	<b>Total</b>	<b>2712.46</b>	<b>474.56</b>	<b>361.85</b>	<b>35878.35</b>	<b>0.00</b>	<b>3608.24</b>	<b>689.20</b>
Relief Distributed Others	<b>District</b>	<b>Baby Food Liquid</b>		<b>Baby Food Solid</b>		<b>Others</b>		
	Cachar	0.00-Q, 2669.00-Pkt		0.00-Q, 1013.00-Pkt		Mortien-3335.00-Pkt; Candle-3765.00-Pkt; Match Box-3588.00-Pkt; Soyabean-456.75-Kg; Potato -225.00-Kg; Tarpaulin-120.00-Pieces; candle-2840.00-Pkt; Potatos-8617.00-Pkt; Biscuit-2669.00-Pkt; Mortein-253.00-Pkt; Soyabin-37.95-Kg; Potatoes-782.00-Kg; M Coil-3017.00-Pkt; Match box-3017.00-Pkt; Potatos-2790.00-Kg		
	Darrang	0.00-Q		0.00-Q, 8.00-Pkt		Tarpaulin-150.00-Q; Taurpaulin-500.00-Pieces		
	Dima-Hasao	0.00-Q		0.00-Q		Biscuit-190.00-Pkt; candle-70.00-Pkt; Match Box-36.00-Pieces; M Coil-38.00-Pkt; Soap-65.00-Pkt; Tarpalin-33.00-Pieces		
	Hailakandi	0.00-Q		0.00-Q		Phenyle-41000.00-ml; Soap-340.00-Pieces; Harpic-21000.00-ml; Tarpaulin-17.00-Pieces		
	Hojai	6861.00-L, 0.00-Q		0.00-Pkt, 0.00-Q		Water bottle-15405.00-L; Biscuits -6861.00-Pkt; Phynyl-5.00-Pieces; Water Bottle-200.00-Pieces; Bleaching Powder-1.00-Pieces; Amul -50.00-L		
	Kamrup	0.00-Q		0.00-Q				
	Karbi Anglong West	0.00-Q		0.00-Q				
	Karimganj	141.00-Pkt, 0.00-Q		135.00-Pkt, 0.00-Q		0-0.00-Q		
	Lakhimpur	0.00-Q		0.00-Q				
	Morigaon	0.00-Q		0.00-Q		0-0.00-Q		
	Nagaon	0.00-Q, 20000.00-ml		0.00-Q, 45.00-Pkt, 75.00-Kg		Drinking Water-2500.00-Pkt; Bleaching-5.00-Pkt; Halogen Tab-4000.00-Pieces; Tarpaulin-1400.00-Pieces; Biscuit-400.00-Pkt; Milk-45.00-Pkt		
	Nalbari	0.00-Q		0.00-Q				
	Sonitpur	0.00-Q		0.00-Q				
Udalguri	0.00-Q		0.00-Q		Sanitary Pad -31.00-Pkt			
Infrastructure Damaged - Embankment Breached	<b>District</b>	<b>Number</b>	<b>Details</b>					
	Udalguri	1	<b>Harisinga</b> - Breach of Credam Khalengdar   Khalengduar (Jalimukh) of Nonoi river   Breach of credam L/B-210 m at khalengduar (Jalimukh) erosion occurred by river Nonoi. Which is occurred from 15th May 2022 onwards.					
	<b>Total</b>	<b>1</b>						
Infrastructure Damaged - Embankment Affected	<b>District</b>	<b>Number</b>	<b>Details</b>					
	Lakhimpur	1	<b>Nowboicha</b> - Singra River RB embankment   Chamua   Damage due wear and tear during shower, seepage and raincuts (Approximate 10 Meter) has been observed at Chamua gaon of Singra RB Embankment under North Lakhimpur WR Divison on 20/05/2022					
	Udalguri	1	<b>Udalguri</b> - Kathalguri village embankment   Kathalguri, Udalguri   Erosion on left bank from river Golandi at Kathalguri village embankment around 420m on 21.05.2022.					
	<b>Total</b>	<b>2</b>						
Infrastructure Damaged - Road	<b>District</b>	<b>Number</b>	<b>Details</b>					
	Barpeta	46	<b>Barpeta</b> - Phularguri Bamunbari Road   Phularguri   Shoulders damaged in stretches from 2nd to 6th Km. (PWD road barpeta) , B.B Road to Pub Chakirbhita Road   Chakirvitha   Road breached at Ch.615.00 M. (PWD road barpeta), <b>Baghbar</b> - 1. Salimpur Jadavpur Kanchan pur Road   Village Salimpur Jadavpur kanchan pur   Date of damage- 16/5/22 Type of damage- shoulder and H/C damage Damage Length- 2050 m, 2.Mandia GP office to 2no.Bordoloni chariali pkg no. As-01-281   2 no. Bordoloni   Date of damage- 16/5/22 Type of damage- shoulder and H/C damage Damage Length- 0 to 40m, 350m, 550m, 600m, 3.Agmandia chariali to Mandia gaon via E&A&A&D pkg no. As-01-241   Mandia gaon   Date of damage- 16/5/22 Type of damage- shoulder and H/C damage Damage Length- 450 m, 4.Mouripam to Bhoirarpam chariali road Pkg no. As-01-258   Mouripam &Amp;Bhoirarpam village   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 650 m,					

		<p>5. Satrakanara bazaar to Manikpur HS road   Village- satrakanara   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 600m,</p> <p>6. Jadavpur HS to Salimpur MPNA road. Pkg. No. As -01-332   Village- jadavpur   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 250m,</p> <p>7. Chasra no 2 to Tedhera pathar pkg no. As-01-77   Village- Tedhera pathar   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 2000m,</p> <p>8. Pachimsychima Madrassa to Sukhowarjhar road pkg no. As-01-358   Dharampur, pachim chaysimana   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 8500m,</p> <p>9. Majorchar to Khatimari rd. Pkg no. As-01-201   Village- Majorchar Khatimari   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 1050m,</p> <p>10. 1653 no. Satrakanara Barakata LPS to new E&amp;D pkg no. 247   Village- Satrakanara 5 no. Seat   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 400m,</p> <p>11. Baghbar PWD sub Division rd. to Mandia Rowmari road   Mandia   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 50m,</p> <p>12. Mandia Dighirpam road on STP Bridge no. 10/1(sub structure &amp;super Str) and RCC Br no. 11/1 &amp; 12/1 approach   Dighirpam   Date of damage- 17/5/22 Type of damage- App, Sub str &amp;super str. Damage Length- 80m,</p> <p>13 Mandia Dongra road   Village-Mandia   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 150m,</p> <p>14 . Mandia Dongra road on RCC slab-culvert and RCC br app of br no. 1/1&amp; 1/2 approach   Dongra   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 300m,</p> <p>15.Mandia Palhaji road on RCC bridge no 3/1 approach   Agmandia   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 250m,</p> <p>16. Dighirpam road to Mouripam rd.   Village- Mouripam   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 200m,</p> <p>17. Satrakanara 9 no seat to 15 no. Seat   Village_Satrakanara 9 no. Seat   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 350m,</p> <p>18. Mandia dighirpam road 1st km   Village Dighirpam   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 550m,</p> <p>19 Kapoha SCSP road to Kapoha PMGSY road   Village- Kapoha   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 250m,</p> <p>20. Barpeta Mandia PWD road to Kapoha SCSP rd.   Kapoha village   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 400m,</p> <p>21. Barpeta Baghbar road   Baghbar gaon   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 2040m,</p> <p>22. Milijuli bazaar to Rajib nagar via social forest road   Rajib nagar   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length - 675m,</p> <p>23. 1254 no paharpur Lps to Bhairarpam chariali road   Village- Bhairarpam   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 750m,</p> <p>24. Eusufpur via dhakaliapara road pkg no. As-01-337   Dhakaliapara   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 250m,</p> <p>25. Paharpur to Bamundongra kabrastan pkg no. As-01-260   Village-Paharpur   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length-450m,</p> <p>26. Allengipathar LpS to Satrakanara 12 no seat   Allengipathar   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 65m,</p> <p>27. Sukhowarjhar to Bhatnapaity Moishkhuti MEM pkg no. As-01-273   Bhatnapaity   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 7500m,</p> <p>28. Kalaridia to Ino.Baghmara char via Nichanar char   Village- Nichanar char   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 5070m,</p> <p>29. Satrakanara 5 no. seat to 12 no seat   Village Satrakanara 12 no seat   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 1430m,</p> <p>30. Chasra no. 1 to Mandia Bordoloni road   Village chasta no. 1   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 250m,</p> <p>31. Kapoha to Medhitary road   Village Medhitary   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 45000m,</p> <p>32. 4 no Bordoloni to kapoha via dapnasing road pkg no. 267   Village 4 no. Bordoloni   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 950m,</p> <p>33. Mandia Dighirpam to Tedhera pathar road pkg no. 276   Tedhera pathar   Date of damage- 17/5/22 Type of damage- shoulder and H/C damage Damage Length- 350,</p> <p><b>Sarthebari</b> - Kayakuchi Newlarbhita Debaridi Road   Kayakuchi- Neularbhita   Road submerged from 8th to 12th Km. Road surface &amp; Shoulders damaged from 4th to 6th Km &amp; 8th to 12th Km. ( reported by JE, PWD Road, 21.05.2022),</p> <p>Balapara to Batia Road   Balapara- Batia   Road surface damaged at 1st to 6th Km &amp; SPT Br. No. 3/1 damaged ( reported by JE, PWD Road, 21.05.2022),</p> <p>Rajaghat Barsimla Road   Barsimla   Road submerged in stretches and road surface badly damaged at 7th to 15th Km. ( reported by JE, PWD Road,21.05.2022),</p> <p>NKK Road   Chaparbari- Naligaon   Road submerged and road surface with shoulders badly damaged</p>
--	--	---

			<p>from 1st to 6th Km. ( reported by JE, PWD Road, 21.05.2022),  L053- Kawaimari LP Shool to Balapara Road   Kawaimari- Balapara   The road submerged in stretches from 2nd to 4th Km. and surface with shoulders ( 90.00M+70.00M) , reported by JE, PWD Road, 21.05.2022,  Kayakuchi Bhaktardoba PWD Road to Mahanbazar Kayakuchi Gaon PMGSY Road   Kayakuchi- Bhaktardoba   The Road embankment eroded by the river Pahumara at 1st &amp; 2nd Km. in stretches ( 90.00M+70.00M), reported by JE, PWD Road, 21.05.2022,  Beelpar to Uttar Chupa Road   Kayakuchi Goan   Shoulders damaged at 1st &amp; 2nd Km., reported by JE, PWD Road, 21.05.2022,  Helacharpam Nasatra Road   Helacharpam- Nasatra   Road submerged in stretches at 2nd &amp; 3rd Km. Road surface with Shoulder badly damaged(reported by JE, PWD Road, 21.05.2022),  Bhaktardoba Newlarbhita PWD Road to Dakshin Paka High School   Bhaktardoba- Newlarbhita   Road submerged at 1st &amp; 2nd Km. Road surface &amp; Sholuders damaged ( reported by JE, PWD Road, 21.05.2022),  Kaphartari Thakargaon Road to Unnirjan Road   Kaphartari   Road breached at 1st &amp; 2nd Km. with road surface damaged ( reported by JE, PWD Road, 21.05.2022),  <b>Kalgachia</b> - State Highway 2   At various points in SH2 from Manas Bridge approach to Barpeta Medical college.   As per report received from PWD(R) dept. on 21-05-22, Due to continuous heavy rainfall from last several days both side of the road Shoulders Damaged with hard crust of SH2 from Manas Bridge approach to Barpeta Medical College, at chainage 43rd Km (Length = 200 m, average breadth = 2.5m, depth = 2.50 m and location coordinate = 26.329675, 90.81323) and at RCC bridge no 35/1 barpeta side manas Bridge approach (Length = 180 m, average breadth = 2.5m, depth = 3.00 m and location coordinate = 26.306885, 90.757817).</p>
	Bongaigaon	5	<p><b>Dangtol</b> - Fulkumari to Bhitari Chengmari Road   Fulkumari to Bhitari Chengmari   Br. No. 1/1 foundation of abutement is in thread due to soil erosion at Ch. 371.00 m. As per report received from PWRD, Bongaigaon. Date of incident 20.05.2022 ,  <b>Boitamari</b> - Talguri basugaon road   Talguri-Basugaon   Water stagnant at 4th km as per received from EE,PWRD, Bongaigaon. Date of incident: 20/05/2022,  <b>Bongaigaon</b> - Chiponchila to Kahipara road   Chiponchila to Kahipara road   Approach of RCC Br. No. 1/1 damaged at Ch.250.00 m.As per report received from PWRD, Bongaigaon. Date of incident 20.05.2022 ,  Chiponchila to Dakuapara via Monakocha road   Chiponchila to Dakuapara via Monakocha   Approach of RCC Br. No. 1/1 damaged at Ch.780.00 m. As per report received from PWRD, Bongaigaon. Date of incident 20.05.2022 ,  Doulguri Ravapara LP School to Udmari Ravapara road   Doulguri Ravapara LP School to Udmari Ravapara   Bamboo foot bridge over river Dhekijani washed away by flow of river water at Ch. 900.00 m. As per report received from PWRD, Bongaigaon. Date of incident 20.05.2022</p>
	Cachar	7	<p><b>Katigorah</b> - Haritkar-I to Salimabad Road   Haritkar-I   Haritkar-I to Salimabad Road PMGSY Pkg. No AS-03-151 (1st &amp; 2nd Km) submerged, as per the report received from PWD Katigorah (T) Road Division, as on 21.05.2022,  KH.Road   Katigorah   KH.Road (5th 8th &amp; 9th KM) submerged, as per the report received from PWD Katigorah (T) Road Division, as on 21.05.2022,  Katirail T.E to Harinagar -I Road   Katirail T.E   Katirail T.E to Harinagar -I Road (3rd &amp; 4th Km.) Submerged as per the report received from PWD Katigorah (T) Road Division, as on 21.05.2022,  Telitikar to Jagdishpur Road   Telitikar   Telitikar to Jagdishpur Road, PMGSY (Pkg No AS-03-641 4th Km)Submerged as per the report received from PWD Katigorah (T) Road Division, as on 21.05.2022,  NH 44 at Katirail T.E to Jagdishpur-IV via Netaji Road   Jagdishpur-IV   NH 44 at Katirail T.E to Jagdishpur-IV via Netaji Road PMGSY Pkg No AS 03-90 (4th &amp; 5th km] Submerged as per the report received from PWD Katigorah (T) Road Division, as on 21.05.2022,  Sadirkhal to Rajatilla Road   Sadirkhal   Sadirkhal to Rajatilla Road ( 1st,2nd 3rd 6th &amp; 7th Km) Submerged as per the report received from PWD Katigorah (T) Road Division, as on 21.05.2022,  Ganirgram to TRK Road via Dudhpur-1 &amp; Boalipar   Ganirgram   Ganirgram to TRK Road via Dudhpur-1 &amp; Boalipar, PMGSY Pkg No AS-03-256( 4th &amp; 5th Km)Submerged as per the report received from PWD Katigorah (T) Road Division, as on 21.05.2022</p>
	Dhemaji	9	<p><b>Dhemaji</b> - Nagakhelia to Lakhpathar PWD road.   Raichapori bolma   Today on 21/05/2022, erosion of side berm( Depth 2.50 M), Ch.6650.00 M to Ch.6730.00 M=80.00 M, occured at Nagakhelia to Lakhpathar PWD road at Raichapori bolma area. ,  Baruah Block Chariali to Das gaon PWD road.   Baruah Block Chariali to Das gaon   Today on 21/05/2022, Submergence of road surface of 0.30 meter and erosion of side berm( Ch.250.00M to Ch.600.00 M=350 M)occurred at Baruah block to Das gaon road.,  NH-15 at Gowal to No2 Borachira PWD road   NH-15 at Gowal to No2 Borachira PWD road   Today on 21/05/2022, Erosion of side berm and approach( Ch.2060.00 M to Ch.2110.00 M=50.00M) , Br. No 3/2 occurred at Borachira.,  <b>Sissiborgaon</b> - PMGSY road from Kadamtoala to No2 Karengbalipur .Packege No. As04255 damage on 19-05-2022 , length 400 Metres.   Kadamtoala to No2 Karengbalipur   PMGSY road from Kadamtoala to No2 Karengbalipur .Packege No. As04255 damage on 19-05-2022 , length 400 Metres. Approach and side brem erosion. report received from Assistant Executive engineer, PWD Jonai Territorial road sub-division-1 , Silapathar,</p>



			<p>PMGSY road from Sissiborgaon Amguri road to Garmara Chapari .Packege No. As04252 damage on 19-05-2022 , length 600 Metres.   Sissiborgaon Amguri road to Garmara Chapari   PMGSY road from Sissiborgaon Amguri road to Garmara Chapari .Packege No. As04252 damage on 19-05-2022 , length 600 Metres. report received from Assistant Executive engineer, PWD Jonai Territorial road sub-division-1 , Silapathar,</p> <p>PWD road from KULAJAN KEBARANGA to SINGIBIL ROAD . Damage on 19-05-2022 , length 30 Metres.   KULAJAN KEBARANGA to SINGIBIL ROAD   PWD road from KULAJAN KEBARANGA to SINGIBIL ROAD Damage the side sh. Damage on 19-05-2022 , length 30 Metres. report received from Assistant Executive engineer, PWD Jonai Territorial road sub-division-1 , Silapathar,</p> <p>PWD road from Silasuti to Jipu Brahmapur . Damage on 19-05-2022 , length 500 Metres.   Silasuti to Jipu Brahmapur   PWD road from Silasuti to Jipu Brahmapur . Damage on 19-05-2022 , length 500 Metres. report received from Assistant Executive engineer, PWD Jonai Territorial road sub-division-1 , Silapathar,</p> <p><b>Jonai</b> - PWD territorial road NH52 to No.1 Janji under PMGSY Package No. As-04-168 , 110.00 meter bridge approach road got partially eroded on 20/05/2022 due to Pote River   At Ch.1560.00 M to Ch.1670.00 M   As per report received from PWRD, Jonai Territorial Road Sub- Division-II, Jonai, a PWD territorial road NH52 to No.1 Janji Road under PMGSY Package NoAs-04-168 , 110.00 meter bridge approach road got partially eroded on 20/05/2022 due to Pote River,</p> <p>PWD territorial road NH52 to No.1 Janji Road under PMGSY Package No. As-04-168 , 40.00 meter culvert approach road got partially eroded on 20/05/2022 due to Pote River.   At Ch. 1989.00 M to Ch. 2089.00 M   As per report received from PWRD, Jonai Territorial Road Sub- Division-II, Jonai, a PWD territorial road NH52 to No.1 Janji Road under PMGSY Package No. As-04-168 , 40.00 meter culvert approach road got partially eroded on 20/05/2022 due to Pote River.</p>
Goalpara	8		<p><b>Balijana</b> - Hudakona to Bordak Road   Hudakona to Bordak Road   Date of occurrence- 19.05.2022 Length/dimension- Length affected 0.25 KM (From Ch. 2.6 KM to 2.85 KM) Average depth of submergence- 0.500 M Traffic Disrupted Data/Report submitted by : Department - Dudhnoi and Goalpara East Territorial Road Div. Date and time of information received- 20.05.2022 at 6.39 pm, Pancharatna Kharmuza Road   Pancharatna Kharmuza Road   Date of occurrence- 20.05.2022 Length/dimension- Length affected 20.0 m (at Ch.8.4 Km) 15.0 m (at Ch.10.50Km) and 15m ( at Ch.10.90 Km) Eroded Side Berm and 3 nos. Culvert Approaches damaged Traffic not disrupted Data/Report submitted by : Department- Goalpara West and JaleswarTerritorial Road Div. Date and time of information received- 20.05.2022 at 11.30 pm,</p> <p>Bardamal Telipara Road   Bardamal Telipara Road   Date of occurrence- 20.05.2022 Length/dimension- Length affected 15.0 m ( at Ch.0.950.0 Km) Damaged HP Culvert 1 nos. and Culvert Approaches 2 nos. Traffic partially disrupted Data/Report submitted by : Department- Goalpara West and Jaleswar Territorial Road Div. Date and time of information received- 20.05.2022 at 11.30 pm,</p> <p>Karaikhowa Bardamal Road   Karaikhowa Bardamal Road   Date of occurrence- 20.05.2022 Length/dimension- Length of damaged road embankment 50.00 m (From Ch 1.2Km to Ch 1.250 Km) Culvert damaged 1 no. Average depth of Submergence 0.25 m Traffic not disrupted Data/Report submitted by : Department- Goalpara West and JaleswarTerritorial Road Div. Date and time of information received- 20.05.2022 at 11.30 pm,</p> <p><b>Matia</b> - Dubapara to BOC Road (SH-46)   Near Dubapara Market   Total affected length = 2 Km as on 20/05/2022 as received from PWRD, Dudhnoi and Goalpara East Territorial Road Division., Lela to Guwabari Road   Near Barigaon   Total affected length = 2 Km as on 20/05/2022 as received from PWRD, Dudhnoi and Goalpara East Territorial Road Division.,</p> <p>Godharbori to Khalisamari Road   Near Tukura Pt-I   Total affected length = 0.150 Km and avg. submergence = 0.5 m as on 20/05/2022 as received from PWRD, Dudhnoi and Goalpara East Territorial Road Division.,</p> <p>Tukura to Khermohra Road   Near Khermohra   Total affected length = 0.100 Km and avg. submergence = 0.8 m as on 20/05/2022 as received from PWRD, Dudhnoi and Goalpara East Territorial Road Division.</p>
Hailakandi	12		<p><b>Lala</b> - Lalacherra Katlicherra Road under Lala Revenue Circle dtd. 20.05.2022   9 km   Submerged, Tantoo Bilgoan Road under Lala Revenue Circle dtd. 20.05.2022   1st &amp; 2nd km   Submerged,</p> <p><b>Algapur</b> - Trolley Line Road, AS-09-14 under Algapur Revenue Circle dtd. 20.05.2022   5th &amp; 6km   Submerged,</p> <p>01T5 to Bakrihawar Pt-II, As-09-29 under Algapur Revenue Circle dtd. 20.05.2022   3rd km   Submerged,</p> <p>Road starting from 4km to PMGSY Pkg. No. AS-09-18 at Vayarpar (Bakrihawar Pt-IX) to Pola river via Magiarpar L.P. School under Algapur Revenue Circle dtd. 20.05.2022   1st, 2nd &amp; 3rd km   Submerged,</p> <p><b>Katlicherra</b> - Dholai Molai Pt IX to Block boundary to 05T2, AS-09-16, Under Katlicherra Revenue Circle Dtd.-20.052022   Ch. 0.000 Km to 3.750 Km   Submerged,</p> <p>Sultani Durgapur road, Under Katlicherra Revenue Circle Dtd.-20.052022   1st km   Road damage due to Runoff water,</p> <p>Katlicherra Hospital Road, Under Katlicherra Revenue Circle Dtd.-20.052022   1st km   Submerged, Boldaboldi Punjee Pt-II, Pkg. No. AS-09-43, Under Katlicherra Revenue Circle Dtd.-20.052022   1st &amp; 2nd km   Damage due to Runoff water in Hilly Terrain,</p>

			72nd KM of NH-154 Jamira Pt-VII, AS-09-04, Under Katlicherra Revenue Circle Dtd.-20.052022   1st Km   Landslide occurred, Nandagram NC Ch. 0.00m to Ch. 2150 m, Under Katlicherra Revenue Circle Dtd.-20.052022   2nd km   Eroded by Rain water, Basha Bari Road Under Katlicherra Revenue Circle Dtd.-20.052022   2nd km   Landslide occurred
Karimganj	8		<b>Karimganj</b> - LAFASAIL VILLAGE ROAD, WASHED OUT/ERODED ROAD PORTION AR DIFFERENT STRETCHES )   LAFASHAIL   DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS ABOVE ROAD IS ERODED/DAMAGED AT VARIOUS STRETCHES on 21-05-2022 W.T. Message from Asstt. E.E., PWRD, Karimganj., FAKIRABAZAR TO LAKKHIBAZAR VIA SUTARKANDI ,PMGSY PKG NO. AS 13 209,ROAD DEMAGED & SIDE DRAINS COLLAPSED.   FAKIRABAZAR   DUE TO INCESSANT RAIN FOR THE LAST FEW DAYS ABOVE ROAD IS PARTIALLY DAMAGED AT VARIOUS STRETCHES on 19-05-2022 W.T. Message from Asstt. E.E., PWRD, Karimganj., <b>RK Nagar</b> - Poldhor Ratbari Road   Poldhor Ratbari Road   Poldhor Ratbari Road Hard crust damaged on 20-05-2022 (length 300.00m) due to incessant rains and drained out of accumulated rain water from nearby catchment area during last few days as reported by Asstt. Executive Engineer,PWRD , Karimganj South Territorial Road Sub-Division , Nilambazar, K.K. Road to Pallisri   K.K. Road to Pallisri   K.K. Road to Pallisri bridge approach eroded on 20-05-2022 (length 100.00) due to incessant rains and drained out of accumulated rain water from nearby catchment area during last few days as reported by Asstt. Executive Engineer,PWRD , Karimganj South Territorial Road Sub-Division , Nilambazar, K K. Road to Dolu (AS-13-271)   K K. Road to Dolu   K.K. Road to dolu Road breached and bridge approach eroded on 20-05-2022 (length 500.00) due to incessant rains and drained out of accumulated rain water from nearby catchment area during last few days as reported by Asstt. Executive Engineer,PWRD , Karimganj South Territorial Road Sub-Division , Nilambazar, <b>Patherkandi</b> - Balirbond Banglatal to Tilbhum market via BSF camp   Tilbhum (BSF Camp)   Due to incessant rain at chainage 2500.00m to 3000.00m (approx length 500meter) has been damaged on 12/05/2022 as reported by AEE, PWD (T/R) Patharkandi., Kanaibazar to Sonatola Road   Hanifabad   Due to incessant rain on 12/05/2022 at chainage 0.00m to 200.00m (approx length 200meter) has been damaged as reported by AEE, PWD(T/R), Kanaibazar to Sonatola Road   Khasergaon, Tukurbazar Road   Due to incessant rain on 12/05/2022 at chainage 3100.00 meter to 4400.00 meter (approx length 650 meter) has been damaged as reported by AEE, PWD(T/R)
Morigaon	4		<b>Morigaon</b> - ROAD FROM NH-37 TO MATIPARBAT VIA BORKHAL (18-05-2022)   MATIPARBAT, MORIGAON   ROAD FROM NH-37 TO MATIPARBAT VIA BORKHAL HAS BEEN SUBMERGED AND DAMAGED AT 4TH, 5TH, 6TH AND 7TH K.M. BY RECENT WAVE OF FLOOD WATER OF RIVER KOPILI & KILLING. , AHATGURI TO NH-37 (TRIMUTI MANDIR) VIA TELAHI SOMAL MATIPARBAT ROAD (20-05-2022)   AHATGURI, MORIGAON   THE ROAD FROM AHATGURI TO NH-37 (TRIMUTI MANDIR) VIA TELAHI SOMAL MATIPARBAT ROAD HAS BEEN SUBMERGED BY CURRENT WAVE OF FLOOD AT 5TH KM. , MRL04-BASANAGHAT KHANDAJAN TO BORDOIPATHAR VIA AJARBARI ROAD (20-05-2022)   BASANAGHAT, MORIGAON   THE ROAD FROM MRL04-BASANAGHAT KHANDAJAN TO BORDOIPATHAR VIA AJARBARI UNDER PMGSY PKG NO. AS-17-245 HAS BEEN SUBMERGED BY CURRENT WAVE OF FLOOD AT 1ST KM., <b>Mayong</b> - Sildubi -Gagalhari (Pt-1) road   Morisuti Tup   Road Submerged at 3rd Km as reported by PWD Morigaon District Territorial Road Division on 21/05/22
Nagaon	17		<b>Kampur</b> - L046-Tetelisoro to Patiapur via Majorati Rd   Kmapur Rev. Circle   L046-Tetelisoro to Patiapur via Majorati Rd, PMGSY, Package No. AS-19-447 Submerged/damaged, Dtd-20.05.2022 reported by Barhampur Territorial Road Sub-Division, NH 36 to Paschim Khaloi bhanga via Uriagrnt Tubukigrnt   Kmapur Rev. Circle   NH 36 to Paschim Khaloi bhanga via Uriagrnt Tubukigrnt, PMGSY, AS-19-492, Submerged/damaged, Dtd-20.05.2022 reported by Barhampur Territorial Road Sub-Division, L078 KSB road to Dhanchula   Kampur Rev. Circle   L078 KSB road to Dhanchula, PMGSY, AS-19-531 Submerged/damaged, Dtd-20.05.2022 reported by Barhampur Territorial Road Sub-Division, L079-Tetelicharagrnt to Tetelichara Lalungaon   Kampur Rev. Circle   L079-Tetelicharagrnt to Tetelichara Lalungaon, PMGSY, Package No. AS-19-557 Submerged/damaged, Dtd-20.05.2022 reported by Barhampur Territorial Road Sub-Division, L-084 Ujagaon to Tinigurigaon   Kampur Rev. Circle   13. L-084 Ujagaon to Tinigurigaon, PMGSY, Package No. AS-19-358, Submerged/damaged, Dtd-20.05.2022 reported by Barhampur Territorial Road Sub-Division, L083-Lutumari Longjup Rd to Lankagaon   Kampur Rev. Circle   L083-Lutumari Longjup Rd to Lankagaon, PMGSY, Package No. AS-19-359, Submerged/damaged, Dtd-20.05.2022 reported by Barhampur Territorial Road Sub-Division, L082-Lutumari Longjup Rd to Ranipukhuri NC Village   Kampur Rev. Circle   L082-Lutumari Longjup Rd to Ranipukhuri NC Village, PMGSY, Package No. AS-19-364, Submerged/damaged, Dtd-20.05.2022 reported by Barhampur Territorial Road Sub-Division, L081-Lutumari Longjup Rd to Jadupathar   Kampur Rev. Circle   L081-Lutumari Longjup Rd to Jadupathar, PMGSY, Package No. AS-19-365, Submerged/damaged, Dtd-20.05.2022 reported by

		<p>Barhampur Territorial Road Sub-Division,  <b>Raha</b> - NH 37 TO BHATIGAON   BHATIGAON   DATE OF OCCURENCE-20/05/2022 ERODED-200 M (APPROX.) DEPARTMENT-PWRD RAHA TERRITORIAL ROAD SUB DIVISION,  CHAPARMUKH TINIALI TO KACHUAGAON ROAD   CHAPARMUKH   DATE OF OCCURENCE-20/05/2022 SUBMERGED/ERODED-200 M (APPROX.) DEPARTMENT-PWRD RAHA TERRITORIAL ROAD SUB DIVISION,  RAHACHAKI HARIAMUKH METEKA ROAD   DURGAJAN   DATE OF OCCURENCE-20/05/2022 SUBMERGED/ERODED-400 M (APPROX.) DEPARTMENT-PWRD RAHA TERRITORIAL ROAD SUB DIVISION,  PHULAGURI TO UTTAR PETBORHA   GARMUR   DATE OF OCCURENCE-20/05/2022 SUBMERGED/ERODED-300 M (APPROX.) DEPARTMENT-PWRD RAHA TERRITORIAL ROAD SUB DIVISION,  KAMPUR CHAPARMUKH RAHA SH 37 ROAD   CHAPARMUKH   DATE OF OCCURENCE-20/05/2022 SUBMERGED/ERODED-80 TO 82 K M (APPROX.) DEPARTMENT-PWRD RAHA TERRITORIAL ROAD SUB DIVISION,  RAHA KAMPUR ROAD TO ATIGAON   RAHA   DATE OF OCCURENCE-20/05/2022 SUBMERGED/ERODED-400 M (APPROX.) DEPARTMENT-PWRD RAHA TERRITORIAL ROAD SUB DIVISION,  BOGARIGURI TO NUTUN BOGORIGURI   BOGORIGURI   DATE OF OCCURENCE-20/05/2022 SUBMERGED/ERODED-1200M (APPROX.) DEPARTMENT-PWRD RAHA TERRITORIAL ROAD SUB DIVISION,  NH 37 TO AMANISALI DAS CHUBURI   AMANISALI   DATE OF OCCURENCE-20/05/2022 SUBMERGED/ERODED-400 M (APPROX.) DEPARTMENT-PWRD RAHA TERRITORIAL ROAD SUB DIVISION,  GASPARA TO DALIMARI   GASPARA   DATE OF OCCURENCE-20/05/2022 SUBMERGED/ERODED-200 M (APPROX.) DEPARTMENT-PWRD RAHA TERRITORIAL ROAD SUB DIVISION</p>
Nalbari	10	<p><b>Barbhag</b> - Matuhrasala road   Katalkuchi   Over topped, submerged . Length = 2.00 k.m. Height = 0.30 mtr. Surface damaged, road side berm damaged as reported by A.E.E. Barkhetri Territorial Road Suv-Division, Mukalmua dated 21/05/2022,  Sanekuchi Barbukiato to Katalkuchi road   Sanekuchi Barbukiato, kotalkuchi   Length = 2.00 k.m. Height = 0.50 mtr. Submerged, surface damaged, side berm damaged as reported by A.E.E. Barkhetri Territorial Road Suv-Division, Mukalmua dated 21/05/2022. ,  Uttarkuchi Sanekuchi Road   Uttarkuchi   Length = 1.50 K.m. Submerged as reported by A.E.E. Barkhetri Territorial Road Suv-Division, Mukalmua dated 21/05/2022. ,  Barbukia to Athgharia road   Barbukia   Length = 1.50 K.m. Submerged as reported by A.E.E. Barkhetri Territorial Road Suv-Division, Mukalmua dated 21/05/2022. ,  Dokoha Kowarpur road   Dokoha   Length = 2.00 K.m. Submerged as reported by A.E.E. Barkhetri Territorial Road Suv-Division, Mukalmua dated 21/05/2022. ,  <b>Nalbari</b> - Nankarbhoira to kendukuchi road submerged   Nankarbhoira to kendukuchi road   As per the report received from PWRD, Nalbari territorial Road Division, Nalbari via whatsapp group on 21.05.2022 Nankarbhoira to kendukuchi road submerged due to rain water. Approximate length is 6.5 meter,  <b>Barkhetri</b> - hajo mukalmua doulashal road   adabari   due to incessant rain road surface damaged at four spots measuring total length 30m approx. and road side berms damaged, length approx.200 m as reported by AEE, PWRD, Barkhetri sub divon 21/05/2022.,  hajo mukalmua doulashal road   Baraliarpar   Due to incessant rain road damaged creating big pot holes, length approx. 40m and side brms damaged, length approx. 160m as reported by AEE, PWRD, Barkhetri sub Div. on 21/05/2022.,  <b>Ghograpar</b> - Sataibari - Keherua Road   Sataibari   As per information received from PWRD, on 20/05/2022 due to incessant rain the sataibari - keherua road has been damaged. Road Edge erosion has seen at ch-2200.00 M, Length of road - 50 M.,  <b>Paschim Nalbari</b> - Palla road near Aparupa Chowk   Near Aparupa Chowk.   Side beam of culvert damaged. Information received from PWRD on 21/05/2022</p>
Sonitpur	3	<p><b>Thelamara</b> - Naharbari to Khalahubari road.   Village- Naharbari, Date- 21/05/2022   Damage of Naharbari to Khalahubari (length- 3metres approx) road as reported by concerned LM on 21/05/2022.,  1 No. Dhanmara to Dighaldal road.   Village- 1 No. Dhanmara , Date- 21/05/2022   Damage of 1 No. Dhanmara to Dighaldal road(length- 4.5 metres approx)as reported by concerned LM on 21/05/2022.,  <b>Tezpur</b> - Na-Ali to Bahbari Road via Uhani Pathar   Uhani Pathar(Na-Ali)   Dated: 21/05/2022. As reported by PWD Roads road damaged at Na-Ali (village: Uhani Pathar) , Na-Ali to Bahbari Road ( Ch. 50 m to 60 m).</p>
Tamulpur	1	<p><b>Goreswar</b> - Singimari DRDA road   Village Singimari   Dated 18/05/2022 Culvert approach DRDA road was washed away, also damaged the Culvert due to overflow of rain water at Village Singimari as reported by concerned Lot Mandal, on 21/05/2022, approximate width of damage 10 metres.</p>
Udalguri	9	<p><b>Udalguri</b> - Nisamakha Darrangipara to Jerusalem road   Darrangipara   The road eroded at Nisamakha Darrangipara to Jerusalem road around 15m on 20.05.2022.,  Kahibari to Jhargaon road   Kahibari   Depression occured at Kahibari to Jhargaon road at 1st km</p>

			<p>DHPC around 7.5m on 20.05.2022.,  <b>Mazbat</b> - Mowamari to NC Bheluguri road   Mowamari village   Due to incessant rain from last few days, The road connecting Mowamari village to NC Bheluguri has been damaged on 20/5/2022. Length-7.5m(approx),  <b>Kalaigaon</b> - Habibhanga to Naptipara Road (PMGSY PKG AS 16 82)   Habibhanga   The road has breached on 21/05/2022 due to overflow of flood water from river Noa resulting in damage of RCC SLAB culvert at CH 1st km (Breach length 15 meter, Breadth 7.5 meter and road submerged for L=50 m), side berm damaged and Hard crust partially damaged.,  Ranipukhuri to Shyamtila Road   Pub-Bholabari   The road has eroded on 21/05/2022 due to heavy current of flood water from the river Bega covering a length of approximately 180 meters and breadth of 7.5 meters.,  Kadamtala to Uttar Barpukhuri-kabirali Road.   Kadamtala   The road has eroded completely on 21/05/2022 due to heavy current and overflowing of flood water from river Kawadanga covering a length of around 30 meters and breadth of 3 meters.,  Chintagaon to bananguri Road (PMGSY PKG AS 16 197).   Batiamari   The hard crust has damaged at CH 600m, side berm also eroded. Bridge approach existing bridge at CH 3rd Km BR No 3/1 is also damaged on 21/05/2022 due to erosion by the flood water from the river Noa covering a length of around 60 meters and breadth of 2 meters.,  Puthiakhat to Puthimari Road (PMGSY PKG AS 26 60)   Majarchuba   The road has partially damaged on 21/05/2022 due to submergence of flood water from river Noa at CH 2nd km covering a length of around 40 meters and breadth of 3.75 meters,  Tangni kalaigaon road (PMGSY PKG AS 16 193)- Ch 1270.00m   Habibhanga   The road had eroded on 21/05/2022 due to heavy current of flood water from river Noa covering a length of around 120 meters and breadth of 2 meters</p>
	Total	139	
	<b>District</b>	<b>Number</b>	<b>Details</b>
Infrastructure Damaged - Bridge	Barpeta	4	<p><b>Kalgachia</b> - 1. RCC Br. No.1/1 &amp; RCC Br. No.2/1 , 2. RCC Br. No.2/1, 3. RCC Br. 2/1.   1.Khudrakuchi to Bankabhanga road, 2. Rampur to Titapani road, 3. Barbhitha to Muhia road.   As per report received from PWD(R) dept on 21/05/22 the Bridge approach damages as follows- 1. Due to continuous heavy rainfall from last several days RCC bridge No. 1/1 &amp; RCC Bridge No. 2/1 approach damaged at khudrakuchi to Bankabhanga road (PMGSY Package No. AS-01-89) (Length = 300 m, Width = 2.50 m, height = 4.00 m location co- ordinate = 26.320233, 90.826718 &amp; 26.322174, 90.825053). 2. Due to continuous heavy rainfall from last several days RCC Bridge No. 2/1 approach damaged at Rampur to Titapani road (PMGSY Package No. AS-01-113) (Length = 100 m, Width = 2.50 m, height = 4.00 m location co- ordinate = 26.315427, 90.818124). 3. Due to continuous heavy rainfall from last several days RCC Bridge No. 2/1 approach damaged at Barbhitha to Mohia road (PMGSY Package No. AS-01-89) (Length = 100 m, Width = 2.50 m, height = 4.00 m location co- ordinate = 26.277572,90.764856).</p>
	Total	4	
Infrastructure Damaged - Wildlife	Nil		
	<b>District</b>	<b>Other Details</b>	
Infrastructure Damaged - Others	Barpeta	<p><b>Barpeta</b> - Elementary Schools Damaged   1181. NALIR PATHAR L.P.S. floor, plinth protection 91.140883 26.382833 Dated - 20.05.2022,  Elementary Schools Damaged   DAKSHIN FINGUA LPS floor, plinth protection, ramp 91.119867 26.442633 Dated - 20.05.2022,  Elementary Schools Damaged   1952.GARI BHITHA L.P floor, plinth protection, ramp, toilet 91.159717 26.40655 Dated - 20.05.2022,  Elementary Schools Damaged   1465. KAWAIMARI BLOCK 12 L.P floor, plinth protection, ramp 91.149117 26.406 Dated - 20.05.2022,  Elementary Schools Damaged   1610. KAWAIMARI BLOCK12 M. L.P floor, plinth protection, ramp 91.14195 26.411133 Dated - 20.05.2022,  Elementary Schools Damaged   1300. NEWLAR BHITHA L.P floor, plinth protection, ramp 91.1785 26.37945 Dated - 20.05.2022,  Elementary Schools Damaged   1012. NEWLAR BHITHA L.P floor, plinth protection, ramp 91.1785 26.37945 Dated - 20.05.2022,  Elementary Schools Damaged   724.NEWLAR BHITHA L.P floor, plinth protection, ramp 91.1742 26.38225 Dated - 20.05.2022,  Elementary Schools Damaged   MILAN LPS floor, plinth protection, ramp, G. Toilet 91.175217 26.4019 Dated - 20.05.2022,  Elementary Schools Damaged   1604.KAWAIMARI BLOCK 6. L.P floor, plinth protection, ramp 91.18495 26.39525 Dated - 20.05.2022,  Elementary Schools Damaged   1712 KAYA KUCHI PAM BALIKA L.P floor, plinth protection, ramp 91.104217 26.416583 Dated - 20.05.2022,  Elementary Schools Damaged   KAWAIMARI ATIRIKTA GHA BLOCK MAKALI LP floor, plinth protection, ramp 91.16975 26.3875 Dated - 20.05.2022,  Elementary Schools Damaged   BAMUNDI ME SCHOOL floor, plinth protection, ramp 91.078367 26.36845</p>	

	<p>Dated - 20.05.2022, Elementary Schools Damaged   TAPARBORI LPS floor, plinth protection, ramp, B. Toilet 91.0539 26.340783</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   HELOCHA NALIRPAM MEM floor, plinth protection, ramp, toilet 91.118733 26.382767</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1080.PITHADI GAON L.P floor, plinth protection, ramp 91.142617 26.370667</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   10 NO BLOCK M. KAWAIMARI LPS floor, plinth protection, ramp 91.131333 26.398783</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   JALKARA PACHIM SUBA LPS floor, plinth protection, ramp 91.103383 26.373533</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   DAKSHIN JALKARA LPS floor, plinth protection, ramp 91.108317 26.3695</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   KHARDHARA PUB SUPA LPS floor, plinth protection, ramp 91.104467 26.357817</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   THEKA PATHAR LPS floor, plinth protection, ramp, G. Toilet 91.098835 26.36425</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   KAHIKUCHI PASCHIM SUBURI LPS floor, plinth protection, ramp 91.10655 26.345283</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   UTTAR PUB KAHIKUCHI LPS floor, plinth protection, ramp 91.11525 26.3511</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   KAYAKUCHI MILAN ME SCHOOL floor, plinth protection, ramp 91.098467 26.415117</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   11 BLOCK KAWAIMARI J LATA VLPS floor, plinth protection, ramp 91.133717 26.403333</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1463.BAGARITAL JANARPAR L.P floor, plinth protection, ramp, B. Toilet 91.197833 26.431833</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1719.JANATA BHEHARTAL floor, plinth protection, ramp 91.1928 26.430133</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1370.BATHANARTARY L.P floor, plinth protection, ramp 91.223367 26.414667</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   387.PARHAKUCHI L.P floor, plinth protection, ramp 91.234633 26.402633</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1145.KALATOLI L.P floor, plinth protection, ramp 91.231633 26.396833</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   KATHALKUR A. PRE-SENIOR MADRASSA floor, plinth protection, ramp, toilet 90.943133 26.239617</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   HAHCHARA UTTAR SUBURI LPS floor, plinth protection, ramp 91.122 26.330533</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   BAGODI PACHIM PARA LPS floor, plinth protection, ramp 91.121933 26.340183</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1619.PANIMARI CHA PATHER M L.P floor, plinth protection, ramp 91.068217 26.371467</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   KAPAHARTARY LPS floor, plinth protection, ramp 91.079083 26.373583</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   THEKA GAON LPS floor, plinth protection, ramp 91.100083 26.369</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   682.MEDHIRTARY L.P floor, plinth protection, ramp, G. Toilet 91.201883 26.40425</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   607. MARI PUR L.P floor, plinth protection, ramp 91.1938 26.408883</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1950. PARAKUCHI PAM L.P floor, plinth protection, ramp 91.215917 26.412083</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   39.KASHKURI L.P floor, plinth protection, ramp 91.224217 26.430833</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   893.BATIA L.P floor, plinth protection, ramp, Door, Wall 91.21095 26.400633</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   BAHURAM KHERKATARY BODO MEDIUM LPS floor, plinth protection, ramp, B. Toilet 91.212633 26.42495</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1730.ERAKACHARI PARA L.P floor, plinth protection, ramp 91.1565 26.37475</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   DAKSHIN PAKA VLP floor, plinth protection, ramp 91.151783 26.379317</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1464. KAWAIMARI 3 NO. L.P floor, plinth protection, ramp 91.163417 26.401783</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   LACHIT BARPHUKAN MES floor, plinth protection, ramp, toilet 91.163 26.4032</p> <p>Dated - 20.05.2022, Elementary Schools Damaged   1949. NON KE KARAGARI GHK BLOCK floor, plinth protection, ramp 91.178333 26.388033</p>
--	--

	<p>Elementary Schools Damaged   JANAPRIYA MES floor, plinth protection, ramp 91.180717 26.387083 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   PUB -PAKA BODO ME SCHOOL floor, plinth protection, ramp 91.184133 26.412217 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1335.KHAIRATTARY L.P floor, plinth protection, ramp 91.1742 26.412883 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1387.KAWAIMARI 8 NO. BLOCK L.P floor, plinth protection, ramp 91.16055 26.392333 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   DAKSHIN PAKA ME SCHOOL floor, plinth protection, ramp, G. Toilet 91.151617 26.379583 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1037. UTTAR CHAGALCHARI L.P floor, plinth protection, ramp 91.157333 26.451783 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   2NO. PUB BARALA LP SCHOOL floor, plinth protection, ramp 91.164867 26.4365 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   KHARDHARA N.S.S. MEM floor, plinth protection, ramp, B. Toilet ramp 91.091133 26.355333 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   852 CHAGALSARI L.P floor, plinth protection, ramp 91.162967 26.4462 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1351.KAWIMARI BLOCK 7. L.P floor, plinth protection, ramp, B. Toilet 91.171 26.394883 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1944.PANIMARICHA PATHER L.P floor, plinth protection, ramp 91.06755 26.357633 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1608. PANI MARICHA L.P floor, plinth protection, ramp, B. Toilet 91.082883 26.3503 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   MNT ME MADRASSA floor, plinth protection, ramp, G. Toilet 91.005567 26.290283 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   Haniful Uddyan L.P.S floor, plinth protection, ramp, G. Toilet 91.135433 26.40785 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   Kirkira Excess area L.P.S floor, plinth protection, ramp 91.1417 26.4224 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   Uttar Naligaon Balika L.P.S floor, plinth protection, ramp 91.116267 26.415917 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   Uttar Pithadi L.P.S floor, plinth protection, ramp, Wall 91.120683 26.375017 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1446 Kawaimari 10 No L.P.S floor, plinth protection, ramp 91.1368 26.394417 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1973 Kawaimari N Jagaran L.P.S floor, plinth protection, ramp, B. Toilet 91.123033 26.411033 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1945 Karagari 9 No. L.P.S floor, plinth protection, ramp 91.141083 26.399833 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1038 Teleria L.P.S floor, plinth protection, ramp 91.108633 26.388533 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1081 Kayakuchi Pam L.P.S floor, plinth protection, ramp 91.1102 26.41695 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1619 Panimurricha Pather L.P.S floor, plinth protection, ramp, toilet 91.068217 26.371467 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   Pub Rahampur L.P.S floor, plinth protection, ramp 91.04095 26.2467 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   Pub Chakaboushi L.P.S floor, plinth protection, ramp 91.038017 26.249183 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   745 Bhaithabhanga L.P.S floor, plinth protection, ramp 91.14755 26.36805 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   340/2 Kayakuchi L.P.S floor, plinth protection, ramp 91.107867 26.401167 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1946 Kayakuchi Gaon Balika L.P.S floor, plinth protection, ramp 91.09925 26.405 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1618 Pub Kapahartari L.P.S floor, plinth protection, ramp, G. Toilet 91.088667 26.373967 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1607 Kapahartari L.P.S floor, plinth protection, ramp 91.08405 26.36555 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   Madhya Barbaradi L.P.S floor, plinth protection, ramp, Wall 91.0858 26.27025 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1613 Kawaimari 4 No. Block L.P.S floor, plinth protection, ramp, B. Toilet &amp; G. Toilet 91.18975 26.401117 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   1756 Kawaimari G Block L.P.S floor, plinth protection, ramp 91.183783 26.388867 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   Bamundi Rananjay Balika L.P.S floor, plinth protection, ramp, B. Toilet 91.155867 26.367217 Dated - 20.05.2022,</p> <p>Elementary Schools Damaged   Namshala Palarpam L.P.S floor, plinth protection, ramp 91.181733 26.3729</p>
--	--

	<p>Dated - 20.05.2022, Elementary Schools Damaged   1179 Erahara Bhanga L.P.S floor, plinth protection, ramp, B. Toilet 91.154 26.386533 Dated - 20.05.2022, Elementary Schools Damaged   138 Era L.P.S floor, plinth protection, ramp, G. Toilet 91.161417 26.3797 Dated - 20.05.2022, Elementary Schools Damaged   Dakshin Paka M.E.S floor, plinth protection, ramp 91.138333 26.372633 Dated - 20.05.2022, Elementary Schools Damaged   1625 No Pachim Ata LPS submerged 91.0869 26.4157 Dated - 20.05.2022, Elementary Schools Damaged   1729 No Bethari Uttar Colony LPS submerged 91.0704 26.3805 Dated - 20.05.2022, Elementary Schools Damaged   1729 No Pather Ghati LPS submerged 91.0925 26.4132 Dated - 20.05.2022, Elementary Schools Damaged   Pakabetbari Pathar LPS submerged 91.0255 26.4020 Dated - 20.05.2022 , <b>Sarthebari</b> - Power Dept. Poles   HT Pole broken at Balapara- Ghoramara ( reported by,SDE, APDCL, Pathsala Division , 21.05.2022), Anganwadi Centres Affected   144 No. Satra Paka AWC ( reported by CDPO, Pakabetbari, 21.05.2022)</p>
Biswanath	<p><b>Naduar RC part</b> - Fisheries/Pond   As per report received from Fishery Demonstrator Sootea dev. block, Nos. of tank affected 56 nos. at village Bakarapata, water area affected 27.16 Ha and Nos. of tank affected 8nos. at vill. Kotarati , water area affected-7.42 Ha .dtd-21.05.2022, <b>Halem</b> - Anganwadi Centres Affected   As reported by CDPO, Chaiduar ICDS project, Gohpur on 20/05/2022, 16 numbers of Anganwadi centers were affected by flood, PWSS Damaged   As reported by Assistant Executive Engineer (PHE), Gohpur, on 20/05/2022 distribution pipeline of 400m (approx.) of Brahmajan TE piped water supply scheme partially damaged. Long: 93.509508, Lat: 26.899097, Agri Bundh Damaged   As reported by BDO, Chaiduar Development Block on 20/05/2022, Brahmajan river Agri bundh at Amjaroni was driven away by flood water, Washed away Culverts   As reported by BDO, Chaiduar Development Block on 20/05/2022, Box culvert at Silothia Baligaon connecting road was driven away by flood water, Culvert Approach Road Damaged   As reported by BDO, Chaiduar Development Block on 20/05/2022, Brahmajan river connecting culvert approach was damaged by flood water at Amjaroni, Washed away Culverts   As reported by BDO, Chaiduar Development Block on 20/05/2022, Box culvert at Jarabari PHC to Amjaroni connecting road driven away by flood water, Agri Bundh Damaged   As reported by BDO, Chaiduar Development Block on 20/05/2022, Brahmajan river Agri bundh at Khatarbari village was damaged by flood, Agri Bundh Damaged   As reported by BDO, Chaiduar Development Block on 20/05/2022, Brahmajan river Agri bundh at New Hatibandhia village was damaged by flood, Secondary Schools Damaged   As reported by BEEO, Chaiduar on 20/05/2022, Gohpur Collegiate HS was affected by flood., Elementary Schools Damaged   As reported by BEEO, Chaiduar on 20/05/2022, Madhya Chattrang LP School was affected by flood., Elementary Schools Damaged   As reported by BEEO, Chaiduar on 20/05/2022, Bhogpur LP School was affected by flood., <b>Biswanath</b> - Agri Bundh Damaged   4 Agri bunds affected under Sowaguri GP &amp; Panibharal GP as per report of BDO Biswanath on 20th may 2022, Agri Bundh Damaged   140 Agri bunds and fishery affected under Kumalia GP as per report of BDO Biswanath on 20th may 2022, Fisheries/Pond   4 fisheries damaged under Garehagi GP as per report of BDO Biswanath on 20th may 2022, Road Breaches   12 Nos of roads affected and 200 Bighas of paddy land affected under Kumalia GP as per report of BDO Biswanath on 20th may 2022, Agri Bundh Damaged   erosion of 250 m of agri bund affected under Kharasimolu GP on 20th May 2022 as per report of BDO Baghmara., Culvert Approach Road Damaged   as per report of LM, one culvert affected at the Mahjuli basti to Mahjuli Pathar road on village Mahjuli Basti</p>
Bongaigaon	<p><b>Boitamari</b> - Culvert Approach Road Damaged   Raghunandanpur Pochagaon road. Nature of damage: SPT Br. No 1/1 damaged at Ch. 950.00 m. Latitude: 26.338927, Long: 90.494522 as per received from PWRD, Bongaigaon. Date of incident 20/05/2022</p>
Cachar	<p><b>Silchar</b> - Anganwadi Centres Affected   AWC No.4 , Dakbanglow, 10 ,Rengti AWC No. 11, Marua AWC No. 52 ,Kuarpar AWC No. 55 AWC No. 18 , Tambutilla AWC No. 91 , Nadiapur AWC No. 131 ,Sridharpur AWC No. 132 , Ghagrapar Pt – I (West) AWC No. 133 ,Salchakra Pt – III AWC No. 134 ,Berabak Roypara AWC No. 151 ,Salchakra Pt – II AWC No. 152 ,Salchakra Pt – I AWC No. 286 ,Roypara Pt-I AWC No. 148 , Guru Basti Mukamtal AWC No. 135 , Srikona Middle Noya Gram AWC No. 136 ,Srikona Borobazar, (Dinomoni Paul Para) AWC No. 140 ,Srikona Grant AWC No. 141 , Rakhhal Khalarpar Pt – II AWC No. 149 ,Hatirhar Pt – II AWC No. 150 , Indragorh Srikona AWC No. 121 ,Nagar band AWC No. 124 ,Ramnagar Tukargram AWC No. 9 , Patharigram AWC No. 11 , Nichintapur Pt-I AWC No. 14 , South Manikpur AWC No. 143 , Patharigram Pt – II AWC No. 123 ,Tarapur Mazumder Bazar AWC No. 83 ,Tupkhana Pt – I AWC No. 84 , Tupkhana Paschim gram AWC No. 85 ,Dalu Road AWC No. 87 ,Tupkhana Rampur AWC No. 89 ,Tupkhana MES Colony AWC No. 174 , Manikpur AWC No. 47 ,Arunachal AWC No. 62,West Kumarpara AWC No. 155, Nayagram AWC No. 281 , West Kumarpara AWC No. 43 ,Ujan Gram Pt-I AWC No. 45 , Niz – Joy Nagar AWC No. 48 , Niz Joynagar (Dubag) AWC No. 59 , Uzangram Pt – I AWC No. 33 ,Sorail AWC No. 34 , Raipur East AWC No. 35 , Pela Dhar AWC No. 36 ,Krishnapur East AWC No. 37 N,Krishnapur West AWC No. 38</p>

,Bhairabnagar East AWC No. 39 ,Ranighat AWC No. 40 ,Raipur West AWC No. 58 ,Bhairabnagar middle AWC No. 60 ,Krishnapur Middle AWC No. 276 ,Krishnapur Nathpara ,Puberkandi Pt-I AWC No. 74 ,Tikarbasti AWC No. 67 ,Itkholaghat Pt-III AWC No. 70 ,Kalibarichar Pt-III AWC No. 9 ,Boaljurmukh AWC No. 26 ,Rangirkhal Koibhartha Colony AWC No. 170, Kutub Uddin Borbhuiya N.G. II Under Sadar Revenue RC,

**Katigorah** - Anganwadi Centres Affected | AWC No. 1 , Mahadevpur & Gonirgram Pt - III AWC No. 2 , Gonirgram Pt - III AWC No. 22 , Niz Fulbari Pt - I (B) AWC No. 23 , Niz Fulbari Pt - I (C) AWC No. 24 ,Kalinagar AWC No. 26 , Gobindapur Pt - II AWC No. 29 , Gobindapur Pt - III (C) AWC No. 44 , Katigorah Pt - I AWC No. 46 , Katigorah Pt - II (B) AWC No. 47 , Jagadishpur Pt - IV AWC No. 48 , Katigorah Pt - III (A) AWC No. 51 , Lathimara (A) AWC No. 52 , Lathimara (B) AWC No. 55 , Jagadishpur Pt - I AWC No. 56 , East Nazatpur (A) AWC No. 58 , Karaikandi Pt - II AWC No. 65 , Niz Levarputa Pt - II (A) AWC No. 70 , Chandinagar Pt - IV AWC No. 73 , Chandinagar Pt - II (B) AWC No. 78 , Harinagar Pt - II AWC No. 80 , Natanpur Grant AWC No. 85 , Jalalpur Pt - II (A) AWC No. 90 , Boleowar Grant AWC No. 93 , South Tarapur AWC No. 94 , Bishambarpur AWC No. 95 , Kushiarkul AWC No. 100 , Rajeswarpur Pt - III AWC No. 101 , Talkar Grant - A AWC No. 121 , Khelma Pt - III (B) AWC No. 122 ,Khelma Pt-VII AWC No. 127 , Khelma Pt - V AWC No. 129 , Brahaman Gram (A) AWC No. 132 , Brahaman Gram (B) AWC No. 141 , Kunapara T.E AWC No. 147 , Bhairabpur Pt - V (A) AWC No. 149 , Bhairabpur Pt - VI AWC No. 156 , Manipur Pt - I AWC No. 159 , Baraitoli Pt - I AWC No. 160 , Baraitoli Pt - II AWC No. 163 , Bhangarpar AWC No. 170 , Burunga Pt - II AWC No. 171 , Burunga Pt - III AWC No. 173 , Bihara Pt - III (A) AWC No. 174 , Bihara Pt - III (B) AWC No. 176 , Bihara Pt - IV (A) AWC No. 177 , Bihara Pt - IV (B) AWC No. 178 , Bihara Pt - IV (C) AWC No. 179 , Bihara Pt - IV (D) AWC No. 181 , Bihara Pt - V (B) AWC No. 183 , Bihara Pt - VI (B) AWC No. 184 , Sewti Pt - I (A) AWC No. 187 , Sewti Pt - III AWC No. 193 , Bar Nunchuri Punjee AWC No. 198 , Bihara Pt - II (b) AWC No. 217 , Lakhipur pt - I AWC No. 218 , Noor Nagar © AWC No. 231 , Kalinagar AWC No. 259 , Chandinagar - I (Solimabad) AWC No. 332 , Tarinipur Pt - I (kheldarpar) AWC No.123,Niz Bihara East AWC No.20 ,Rajar Digirpar AWC No.82 , Bihara - V Kalacharipur AWC No.12 , South Sarisakuri AWC No.13 , Jasirbad AWC No.14 , Bagmara AWC No.25 , HILARA COLONEY AWC No.38 , MEGENTA T.E. AWC No.97 , KUNAPRA T.E. AWC No.59 , NUTANPALLY AWC No.57 , RAJYESWARPUR PART-1 AWC No.108 , KANDIGRAM AWC No.107 , KHELMA PART-3 AWC No.52 , KHELMA PART-8-A AWC No.90 , Hilara Bagan AWC No.28 , Baraitali IV AWC No.30 , Lakhipur III AWC No.34 , Natanpur A AWC No.93 , Sanpur AWC No.96 , Bhairabpur VI AWC No.35 , Digabor T.E. AWC No.33 , Bhairabpur Pt.V-B AWC No.94 , Ajomara AWC No.103 , West Tarapur AWC No.138 , Kandigram AWC No.67 , North Tarapur AWC No.66 , South Tarapur AWC No.73 , Natanpur Grant AWC No.139 , Karabalagrnt AWC No.112 , Kushiarkool AWC No.61 , Mahadevpur Pt I & ii AWC No.62 , Rajyeswarpur Pt ii AWC No.111 , Sainashikandi AWC No.106 , East Chaligram AWC No.104 ,Dhumkar C AWC No.102 ,Mougram AWC No.46 , Chaligram AWC No.42 , Khoyajani AWC No.43 , Gilutali & Vitorgul AWC No.44 , Dhumkar B AWC No.39 , Bhatgram & Brahmangram, AWC No.48 , Khelma pt-VII B AWC No.49 , Khelma pt III AWC No.50 , Khelma pt I, Under Katigorah RC,

**Udharbond** - Anganwadi Centres Affected | AWC No. 34 ,Madhupur Pt - II AWC No. 101 ,Pangram Pt - II (Dakingram) AWC No. 95,Saibag & Borbond AWC No. 96 ,Kandigram AWC No. 45,Lathigram (Middle) AWC No. 44 ,Lathigram (East) AWC No. 89 ,Uzangram (Thana Road) AWC No. 54 ,Durganagar Pt - IV AWC No. 57 ,Gossaipur Pt - II AWC No. 162,Polantiki AWC No. 148 ,Gossaipur Pt - II AWC No. 188 ,Gossaipur Pt - III AWC No. 282,Rongpur Kadamtola AWC No. 66,Bahadurpur AWC No. 64 ,Rongpur-III (Madurgram) AWC No. 63 ,Rongpur-III (Kandigram) AWC No. 125,Rongpur (Daspara) AWC No. 61 ,Serimkul AWC No. 60,Rongpur Pt - II (Monipuri Basti) AWC No. 73 ,Moidanbil AWC No. 75 ,Arkatipur (North Dayapur) AWC No. 119 ,Badripar Pt - VI AWC No. 118 ,Digar Kashipur Pt - II AWC No. 115,Dayapur (Harintilla) AWC No. 116 ,Dayapur (Ataicherra) AWC No. 93 ,Lakhirbond AWC No. 105,Balighat Dayapur- I Under Udharbond RC as on 21.05.22,

**Lakhipur** - Anganwadi Centres Affected | AWC No. 71,Gangapur South Daspara, AWC No. 72, Gangapur main AWC No. 83, Bagpur pt3 middle AWC No. 219,Berenga pt1 badrighat east AWC No. 220, Berenga pt1 badrighat west AWC No. 221, Berenga pt1 Dhumkar AWC No. 225, Berenga pt2 west AWC No. 226,Berenga pt5 Borjurai west AWC No. 230, Berenga pt4 north nayagram AWC No. 233, Berenga pt3 Sahajeepara AWC No. 236,Berenga pt3 kilogram AWC No. 237,Berenga pt3 AWC No. 239, Berenga pt4 north AWC No. 255, Berenga pt2 Choudhury para AWC No. 235, Berenga pt3 Bethukandi AWC No. 132, Kaptanpur Pt - III (Laikol South) AWC No. 137, Kaptanpur Pt - IX AWC No. 167- Lalang pt-II( south) AWC No. 168-Lalang pt-III( Rajagram north) AWC No. 169- Lalang-III( south) AWC No. 170-Lalang pt-IV AWC No. 171-Sibpur pt-I( west) AWC No. 172- Sibpur I( sribar east) AWC No. 173-Sibpur pt-II AWC No. 174-Sibpur-III AWC No. 434-Boglapar AWC No. 29 BHUBONDHOR AWC No. 12.Lalpani Pt-III, Bagkhal South AWC No. 95.Sibpur Pt-I, Niz Sibpur AWC No. 96Sibpur Pt-I, Nazarpur AWC No. 100.Sibpur Pt-II, North Pt. of Kandigram AWC No. 101, Sibpur Pt-II, North Pt. of Kandigram & Ramsigram AWC No. 106. Anwarpar Pt-II & III, Singerband AWC No. 107. Niz Rupailbali North AWC No. 109, Niz Rupailbali West AWC No. 111, Dungripar Pt-I, West AWC No. 113.Dungripar Pt-II South AWC No. 114, Jarailtola Pt. of Dungripar AWC No.119, Singerbond Pt-IV, Dolugram AWC No. 250.Dungripar Pt-I AWC No. 53.Niz Banskandi Pt-II-South AWC No. 54.Niz Banskandi Pt-II- North AWC No. 473.Kashipur Nobapally AWC No. 475Kashipur Daspara Under Lakhipur RC dated 21.05.2022,

**Sonai** - Anganwadi Centres Affected | AWC No. 01-Rangighat pt-1North AWC No. 03-Rangighat pt-2 East AWC No. 29-Natun Ramanagar pt-2 East AWC No. 100-sonabarighat pt-1 south AWC No. 103- Dhanehori pt-1North AWC No. 180-Hawar bosti Natun Ramnagar pt-2 AWC No. 179-22no bosti Natun Ramnagar pt-4 AWC No. 145- selurpar swadhin bazar AWC No. 75-uttar Krishnapur pt-1south AWC No. 140-uttar krishnapur pt1&2 middle AWC No. 47-Dakhin Mohanpur pt-9 gobindanagar AWC No. 42-dakhin Mohanpur pt-2 AWC No. 37-



		gobindanagar pt-1 AWC No. 67- kachudaram pt-1 west AWC No. 190-Daramtilla kachudaram pt-1, Under Sonai RC
Darrang		<b>Patharighat</b> - Handloom & Textile Deptt   7 nos. of families affected (yarn damaged) as reported by Handloom &Textile Deptt. on 20/5/2022, Anganwadi Centres Affected   Tuk para AWC at Bisnupur village affected as reported by CDPO On 20/5/2022, <b>Dalgaon</b> - Fisheries/Pond   as per report received from Fishery Development Officer, Darrang, as on 20/05/2022 25 nos villages, 726nos fish farmers and 145.78 Ha water area affected under Dalgaon Revenue Circle, <b>Mangaldoi</b> - Fisheries/Pond   As reported by Fishery Department a total of 1508 Nos. (Approx.) of fish farmers and 132.31 Ha.(Approx.) Water area are affected. Dated 21/05/2022., <b>Sipajhar</b> - Fisheries/Pond   14 nos. of villages, 277 nos. of Fishermers and 18.12 Hactre of water area affected as reported by Fishery Deptt. reported on 21/05/2022, occurred on 20/05/2022. villages are : Kabeichuba, Pakabangi, Gopalpur, Patgirichuba, Satgharia, Basachuba, Solpam, Khassonapur, Haldha, Malibari, Maijeli, Nayakpara, Badiasicha, Uparkuraa
Dibrugarh		<b>Chabua</b> - Anganwadi Centres Affected   DODHIA AWC SUBMERGED AS INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 21/5/2022, Anganwadi Centres Affected   DODHIA TENGABARI AWC SUBMERGED AS INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 21/5/2022, Health Sub-Centre   DODHIA KULIGAON HEALTH SUB CENTRE SUBMERGED AS INFORMATION RECEIVED FROM HEALTH DEPT. ON 21/5/2022, Elementary Schools Damaged   DODHIA ME SCHOOL SUBMERGED AS INFORMATION RECEIVED FROM EDUCATION DEPT. ON 21/5/2022, Elementary Schools Damaged   DODHIA KULIGAON LPS SUBMERGED AS INFORMATION RECEIVED FROM EDUCATION DEPT. ON 21/5/2022, Elementary Schools Damaged   DODHIA KARMI LPS SUBMERGED AS INFORMATION RECEIVED FROM EDUCATION DEPT. ON 21/5/2022, Elementary Schools Damaged   DODHIA KARMI LPS SUBMERGED AS INFORMATION RECEIVED FROM EDUCATION DEPT. ON 21/5/2022
Hojai		<b>Hojai</b> - PWSS Damaged   Village - Kumurakata, Kumurakata PWSS of Hojai PHE Division is submerged and distribution pipeline etc damaged due to raising of flood water on dated 21/05/2022 with GPS Coordinates 25.9884 N and 92.796836 E, PWSS Damaged   Vill- Warregeding ,Warregeding PWSS of Hojai PHE division is submerged and distribution pipeline is damaged due to flood water on dated 21/05/2022 with GPS Coordinates 26.0567 N and 92.76120 E, PWSS Damaged   Vill- Hayong Goan , Hayong PWSS of Hojai PHE Division is submerged and distribution lines are damaged due to flood on dated 21/05/2022 with GPS Coordinates 26.0743 N and 92.7568 E, Fisheries/Pond   Vill- Kenduguri , No of fish farm family affected- 87 , no of ponds-96 and total water area in hect. is - 13.60 hect. dated 21/05/2022 with GPS Coordinates 26.091 N and 92.7437 E
Karbi Anglong West		<b>Donkamokam</b> - Road Breaches   Due to incessant rain Donkamokam to Tumpreng Road was submerged/affect on 17/05/2022 and caused damaged to Shoulder and BT surface from Ch. 3900.00m to 4100.00 at the geographical Location of latitude:25.99 & longitude:92.73, Road Breaches   Due to incessant rain Kolonga to Sildubi Road was submerged/affect on 17/05/2022 and caused damaged to Shoulder and BT surface from Ch. 8400.00m to 8700.00 at the geographical Location of latitude:25.54 & longitude:92.48
Karimganj		<b>Karimganj</b> - Bridge Approach Road Damaged   NH 151 TO BARPURAHURIA,PMGSY PKG AS13 222,BRIDGE APPROACH DEMEGED(l=200.00M) on 19-05-2022 W.T. Message from Asstt. E.E., PWRD, Karimganj
Lakhimpur		<b>Subansiri</b> - Bamboo Foot Bridge   The existing Bamboo Bridge No. 2/1 on Mohbal to Bangkelleng road is washed away (Bridge Length- 35M) reported by PWRD Dhakuakhana Territorial road Division, Ghilamara on 20/05/2022, Bamboo Foot Bridge   The Bamboo Bridge collapsed at Ch. 250M on Bolahi to Balipukhuri road ( Bridge Length- 75M) reported by PWRD Dhakuakhana Territorial road Division, Ghilamara on 20/05/2022, Bamboo Foot Bridge   The Bamboo Bridge No. 1/1 on Mahanibari to Chenimari road is damaged ( Damaged Length- 20M) reported by PWRD Dhakuakhana Territorial road Division, Ghilamara on 20/05/2022
Morigaon		<b>Morigaon</b> - Protection Bundh Damaged   Patrabori Sluice Middle Shutter Failed leading to Flood Water entering Country side at around 09:00AM today on 21-05-2022
Nagaon		<b>Kampur</b> - PWSS Damaged   1 no. PWSS under PHE Kathiatoli Sub-division Dtd-20.05.2022, PWSS Damaged   1 no. PWSS under PHE Kathiatoli Sub-division Dtd-20.05.2022, Irrigation Canal/Scheme Damaged   Bricked lined canal submerged barge and Pump house, at Dewrigaon, kampur, reported by Irrigation Raha Sub-division Dtd-20.05.2022, Irrigation Canal/Scheme Damaged   Bricked lined canal submerged barge and Pump house, at Saraihagi, kampur, reported by Irrigation Raha Sub-division Dtd-20.05.2022, <b>Raha</b> - Irrigation Canal/Scheme Damaged   Scheme- IIS from SRB KRB Phuloguri (R/B) ILP unit lift point scheme was Submerged under Raha Batadrava Division (Irrigation)Dtd-20.05.2022, Irrigation Canal/Scheme Damaged   Scheme- Raha Part No. 3 and 4 Lift Irrigation Scheme under Raha Batadrava Division (Irrigation) was Submerged Transformer Sub Station and; Control room Dtd-20.05.2022, Irrigation Canal/Scheme Damaged   Scheme- Raha Part No. 2 Lift Irrigation Scheme under Raha Batadrava Division (Irrigation) was Submerged Control room Dtd-20.05.2022, Irrigation Canal/Scheme Damaged   Scheme- Basundhari Lift Irrigation Scheme under Raha Batadrava Division (Irrigation) was damaged main and branch canal submerged Transformer Sub Station, Barge Control room Dtd-

		<p>20.05.2022, Fisheries/Pond   Total submerged village- 32, Total Pond/Tank-579 nos., Total Hectare-128.2 ha, Deptt.- Fishery Dtd-20.05.2022, <b>Nagaon</b> - Fisheries/Pond   10no. of fisheries submerged due to flood under Nagaon sadar Rev. Circle, reported by Fishery department Dtd-20.05.2022</p>
Nalbari		<p><b>Banekuchi</b> - Damaged SPT Bridge   As per report of PWD (Road) department on 20/5/2022 Mohan Bazar Auhati Road SPT Br. No.1/1 damaged .Lat 26.434334 and Long 91.370183 .Location Village: Kharsitha (Raisha ghat), <b>Ghograpar</b> - Culvert Approach Road Damaged   As per PWRD report, on 20/05/2022 one culvert 1/1 approach road damage. Length - 50 M, <b>Paschim Nalbari</b> - Handloom &amp; Textile Deptt   Looms , accessories and weaven cloth of 1 no. numbers of weavers in Lokhopur (Gandhibasti) area are affected. Information received from Handloom and Textile department On 21/05/2022</p>
Sonitpur		<p><b>Chariduar</b> - Fisheries/Pond   Gudamghat 26.768707 N 92.830903 E REPORTED BY DEPT OF FISHERY DTD 21/05/2022 18 nos, Fisheries/Pond   GUDAMGHAT MIRI 26.778292 N 92.826149 E REPORTED BY DEPT OF FISHERY DTD 21/05/2022 21 nos, Fisheries/Pond   KEKOALI MIRI 26.790695 N , 92.825004E REPORTED BY DEPT OF FISHERY DTD 21/05/2022 19 nos , Fisheries/Pond   AKABASTI MIRI 26.829025N , 92.828654 E REPORTED BY DEPT OF FISHERY DTD 21/05/2022 20 nos, Fisheries/Pond   RANGAJAN MIRI 26.7888603N, 92.8502302E REPORTED BY DEPT OF FISHERY DTD 21/05/2022 21 nos, Fisheries/Pond   ROUMARI 26.768522E, 92.831846E REPORTED BY DEPT OF FISHERY DTD 21/05/2022 18 nos, Fisheries/Pond   BERAJAN 26.742351N, 92.8390699E REPORTED BY DEPT OF FISHERY DTD 21/05/2022 18nos, Fisheries/Pond   MANSIRI 26.78011N, 92.8390699E REPORTED BY DEPT OF FISHERY DTD 21/05/2022 19 nos, Fisheries/Pond   GUDHAMGHAT KACHARI 26.792515N, 92.8253324E REPORTED BY DEPT OF FISHERY DTD 21/05/2022 17 nos</p>
Udalguri		<p><b>Udalguri</b> - Culvert Approach Road Damaged   The 3 Row HPC damaged at No. 1 Goroibari to Daifam road around 15m on 20.05.2022. GPS - Lat - 26.747149 Long - 92.095215., Washed away SPT Bridge   The SPT bridge washed away over Sapkhaity river at Bhairaguri bazar around 30m on 20.05.2022. GPS - Lat - 26.659791 Long - 92.065788., Bamboo Foot Bridge   The Bamboo foot bridge wash away over river Sapkhaity river at Dakhin Bhairaguri around 20m on 20.05.2022. GPS - Lat - 26.659354 Long - 92.061144 ., Bamboo Foot Bridge   The Bamboo foot bridge wash away over river Sapkhaity river at No. 2 Sonaripara (Santhakpara) around 30m on 20.05.2022. GPS - Lat - 26.654905 Long - 92.057549., Culvert Approach Road Damaged   The 3 Row HPC Damaged and road eroded at lowdong to daifam connecting road at Bhutniduba Dakhin Chuba around 20m on 20.05.2022. GPS- Lat - 26.656839 Long - 92.1133422, <b>Khairabari</b> - Power Dept. Conductors   Due to haeavy rarin along with wind occured on 13/05/2022, at around 11.35pm, 02nos. of HT &amp; LT poles &amp; conductors were snapped at various places, namely, Bhergaon Chowk, Khoirabari, Jhargaon, Kuhierkuchi, Barnadijhar, Ghogapara, Suwanipara, Nonaikhuti, Kathalbari, Khagra, Jamuguri, Purani Tangla, Dewaguri, Charanpara, Dhoppuri, Gurihati, Kacharidag, Khagrabari, Nalbari &amp; Panisheli. As a result the power supply to various locations have been hampered., Power Dept. Poles   Due to haeavy rarin along with wind occured on 15/05/2022, at around 9.10 am, 07 nos. of LT poles were damaged at villages namely Shyamabari &amp; Chewani. As a result the power supply have been hampered. , Power Dept. Conductors   Due to haeavy rarin along with wind occured on 15/05/2022, at around 9.10 am , HT &amp; LT conductors were snapped at various places, namely, Dewaguri, Chewni, Shyamabari, Latakhat, Atelia, Bartangla, Batabari, Bholaguri, Dingdongpara, Hasrapara, Hatibandha, Khagrabari, Malmura, Nichilamari, Rupakhat, Sukuliapara, Umananda &amp; Batabari. As a result the power supply to various locations have been hampered., Power Dept. Poles   Due to haeavy rarin along with wind occured on 19/05/2022 at around 6.45pm, 8nos. of L.T Poles were damaged at Village, Satgiri (Bogpuri) &amp; Bholaguri. As a result the power supply to various locations have been hampered., Power Dept. Conductors   Due to haeavy rarin along with wind occured on 19/05/2022 at around 6.45pm., HT &amp; LT conductors were snapped at various places namely, Daulchuba, Dhuppuri, Dingdongpara, Garangpara, Gurihati, Hatibandha, Jhargaon, Khagrabari, Malmura, Nalbari, Rangagaon, Sareng, Sukuliapara, Thakuriapara, Udmari &amp; Atelia. As a result the power supply to various locations have been hampered., Fisheries/Pond   As per reported by the Department of Fishery, 14 nos of villages namely: Khagra, Jamuguri, Mohilapara, Singimari, BorJamuguri, Khoirabari, Chinakona, Kuhiarkuchi, Jhargaon, Jabanga Habi, Buduragaon, Dongpara &amp; Kathalbari were affected, where 222 (approx.) farmers and a total of 45 (approx.) Ha. of water area is affcted., Bridge Approach Road Damaged   Approach of Bridge No. 1/1 on Ramgaon Bhergaon road at Chewni (location) was damaged on 19.05.2022, Length: 8 M GPS- Coordinates : Lat: 26.634619 &amp; Long: 91.815008., Culvert Approach Road Damaged   Damage of culvert along with the approach road, HPC No- 1/1 on</p>

		<p>Arrengpara to Gurihati Nichilamari road at Arrengpara (location) was damaged on 16.05.2022, Length: 12 M GPS- Coordinates : Lat: 26.616934, Long: 91.806832.,</p> <p><b>Mazbat</b> - Washed away Culverts   Due to incessant rain, the slab culvert connecting No.2 Kadabil to bahipookri village has been damaged on 20/5/2022. The road communication has been disrupted.(26.857933, 92.288173), Length- 3.45m(approx),</p> <p>Washed away Culverts   One slab culvert has been damaged on Hatipota to Bombay centre on 20/5/2022 due to incessant rain. The road communication has been disrupted.(26.859715,92.313255). Length- 3m(approx),</p> <p>Washed away Culverts   One slab culvert has been damaged on Deochani to Kadabil village on 20/5/2022. The road communication has been disrupted.(26.871421, 92.321819). Length- 3m(approx),</p> <p><b>Kalaigaon</b> - Bamboo Foot Bridge   The bridge over the river Noa connecting No 2 Amguri to Makenzi road at village No 2 Amguri has washed away on 21/05/2022 due to heavy current of river Noa. Bridge length 100 meters. Longitude:91.971017, Latitude: 91.971017,</p> <p>Bridge Approach Road Damaged   The bridge approach on the Khas Bokrajhar to Ojhagaon road (PMGSY PKG AS 16 145) at village Uttar Bokrajhar has damaged on 21/05/2022 due to flood water from river Kulshi. Length: 300 meters, Breadth 7.5 meters, longitude: 91.94609, Latitude: 26.560948,</p> <p>Damaged RCC Bridge   The RCC SLAB culvert on Habibhanga Naptipara road (PMGSY PKG AS 16 82) has damaged at village Habibhanga on 21/05/2022 due to overflow of flood water from river Noa at CH 1st Km. Longitude: 91.99096, Latitude: 26.564755,</p> <p>Fisheries/Pond   Around 325 fish farmers have been affected of 29 villages under kalaigaon Revenue Circle covering a water area of around 62 hectares</p>
	<b>District</b>	<b>Details</b>
Erosion	Baksa	<p><b>Jalah</b> - At Gobardhana ,Khagrabari ,Alengmari   On 20 May 2022, during a field visit by SDO,Civil Salabri,CO,FO(DM),Jalah Rev Circle along with concerned LM and GB and observed 1. at Gobardhana ,approximately 350 meter of left bank of river Beki at the southern part ,adjacent to Gobardhana Satra has been eroding by the River Beki 2. At Khagrabari,approximately 750 meter of left bank of river Beki at Khagrabari Nepali Basti has been eroding by the River Beki. 3. At Alengamari,approximately 550 meter of left bank of river Beki at alengamari has been eroding by the River Beki, at which three numbers of households are shifted due to erosion. The Water Resource Division ,Chirang assured for immediate protection of works for aforesaid erosion.   0,</p> <p><b>Baksa</b> - 2 No. Lokpala   River bank erosion at the right bank of river Mora-Pagladia at village 2 No. Lokpala on 21-05-2022. Erosion site is 10 meters from PWD village road. Total erosion: 5 Lesa   0</p>
	Barpeta	<b>Chenga</b> - Roumari Gaon   1 no. house damaged due to severe erosion at Roumari Gaon village reported by Gaon Pradhan on 21/5/22   7
	Biswanath	<b>Biswanath</b> - Mijika, Ghoramara   Bank erosion observed at Mijika on Right Bank of River Burhigang. Also as per LM report one earthen road near river burhigang about 8ft wide and 500 ft long at village Ghoramara was damaged on 17th May 2022: Lat=26.812877, long=93.198404. Also as per report of BDO Baghmara, 50 m of embankment erosion occurred near tinisuti weekly market by river Burigang and 130m of embankment erosion occurred by river Burigang at forest gate, tinisuti on 20th may 2022.   0
	Bongaigaon	<b>Boitamari</b> - Chatpara   One Mosque fully damaged and one katcha house shifted for gully erosion. Date of incident 20.05.2022   6
	Darrang	<b>Mangaldoi</b> - Gerimari Village   Erosion at the banks of Mangaldai River has occurred at village Gerimari under Mangaldai Rev. Circle. The stretch of erosion is approximately 1Km along the river bank. Dated 21/05/2022.   40
	Dhubri	<p><b>Bilasipara</b> - At village:- Dubachuri Pt-ii and Saltari   the Erosion occurred due to rising of water level of river Mara Gaurang at Dubachuri Pt-ii and also erosion happened for river Sankosh at village Saltari. Date of incident:- 19-05-2022 and 20-05-2022 GPS co-ordinates:- Lat:- 26. 203876 N &amp; Longitude:- 90.17813 E Lat:- 26.16904 N &amp; Longitude:- 90.10141E Land eroded:- Land measuring around 05 Bigha 04 Katha 10 Lessa Population:- 16 nos   16,</p> <p><b>Athani</b> - Kaunbari   Erosion is going on at village kaunbari under Panbari GP from 17.5.2022 to till date. A total land measuring 2B-2K-10L(Approx.) already been eroded Longitude 90.083657 &amp; Latitude 26.14655   0,</p> <p><b>South Salmara Part</b> - Borkalia Surjomoni, Char Katdanga pt-i   As per information received from concerned Lot Mondal erosion occurred on 19/05/22 and 20/05/22. At following Villages 1. Borkalia Surjomoni, 105 nos family has been eroded due to erosion by river Brahmaputra. Area lenth 2 km and breath 100 m. Lat-25.95 Long-90.03 2. Char Katdanga pt-i, 112 nos family has been eroded due to erosion by river Brahmaputra. Area lenth 2.5 km breath 125 m. Lat - 25.85 Long-89.96 All affected families has been shifted to the safe place.   816</p>
	Dibrugarh	<p><b>Dibrugarh East</b> - 1. Maijan Borsaikia Gaon near DTP dyke 2. Dongorpathar 3. UPSTREAM OF STONE SPUR NO - 01 NEAR DTP DYKE AT MAIJAN   1. SEVERE BANK DAMAGE DUE TO RISE OF WATER LEVEL OBSERVED AT WARD NO -03 OF MAIJAN BORSAIKIA GAON AT DOWNSTREAM OF 1 KM OF DTP DYKE ON LEFT SIDE OF THE RIVER BANK FROM 17-05-2022. LAT-27.30.14.66;N. and LONG-94.56.35.92; E.as per information received from Water Resource Department. 2. BANK DAMAGE DUE TO RISE IN WATER LEVEL. Length- 300m DAMAGED AND IS OCCURING FROM 18-05-2022. LAT 27.22.39;44.69;N AND LONG - 95.30.39;25.25; E. as per information received from WRD. 3. UPSTREAM OF STONE SPUR NO - 01 NEAR DTP DYKE AT MAIJAN DAMAGE IS SEEN. 250M AREA IS BEING WASHED AWAY. as on 21.05.2022 LAT - 27.30.39;15.95;N/94.56.39;51.43 ;E TO LONG 27.30.39;15.26;N/94.56.39;42.62;E. as per information received from WRD.   0,</p> <p><b>Dibrugarh West</b> - Lezai Gaon   As per report received from Executive Engineer, WR Division on 20.05.2022 that damage has been observed at Lezai area on the right bank of Sessa river just upstream of Lezai Bridge, affecting a reach length of 300mtrs.   0</p>
	Goalpara	<b>Matia</b> - Baladmari Char Pt-IV   Left bank erosion of river Jaljali at Baladmari Char Pt-IV. Total Reach length =

		300 m (approx.)and Average Width = 3 m as on 21/05/2022 as received from Water Resources Department, Goalpara   0
Golaghat		<b>Bokakhat</b> - Opeswari Ghat (Karonihula Gaon) under Bokakhat Rev. Circle   Erosion occurred at river bank of Dhansiri river of approx 300 M. on 20-05-2022.   0
Hailakandi		<b>Katlicherra</b> - Rangabak Pt. I under Katlicherra Revenue Circle dtd. 20.05.2022   Severe erosion occurred at Rangabak Pt. I. Area of erosion- Length - 50 meter, Breadth - 25 meter   0
Kamrup		<b>Kayan</b> - Dodetia,Nona river bank   Nona river erosion reported by Water Resource Dept. Nalbari Division near dodetia area area under Kayan Revenue Circle on 20/05/2022. Erosion length - 270 m Time- 12:57 & 13:11 Area- River Nona, vill- Dodetia   0, <b>Chaygaon</b> - pub Makeli   On field visit by FO Chhaygaon, it was seen that an active erosion of 10m span on 20/5/2022 around 11:00 AM at kotohi road.   0
Kamrup (M)		<b>Chandrapur</b> - 1)hatisila near ganesh mandir 2) tatimara   Erosion occurred 17.05.2022   information received from water Resource department   Hatisila coordinate:- 91.887997 , 26.219384 Tatimara coordinate:- 91.917294, 26.243107   Area:- 1.5 km approx both.   0
Lakhimpur		<b>Bihpuria</b> - Dhunaguri-Chenimora ghat embankment   Mild Erosion observed at CH. 1790 for a length of 100m on 20th May 2022 as reported by AEE, WRD, Bihpuria SD   0
Morigaon		<b>Laharighat</b> - Bhajaikhaiti   Erosion observed on 21-5-22 at Bhojaikhaiti area at 64th k.M.of Brahmaputra dyke.Minimum offset aprox 220m. Temporary measure taken up like lurching of Bamboo bundle.   0
Nalbari		<b>Tihu</b> - 1.Dahkauniya(3rd km R/B ,Mora Pagoldia) , 2. Gobaradal(6th R/B ,Mora Pagoldia), 3.Gobaradal (7thR/B ,Mora Pagoldia), 4. Dahkauniya(8th R/B ,Mora Pagoldia), 5. Sialmali(Bali),(11th R/B ,Mora Pagoldia), 6.Lanka(Sathikuchi/Gobaradal)(7th L/B ,Mora Pagoldia), 7.Uttar Bali(10th L/B ,Mora Pagoldia), 8.Suradi (Road Erosion)   1.Erosion Point Length:250mts,Lat/Long:26.502723/91.351893, Date of occurrence:19/05/2022 as per information received from JE,WR Dept Nalbari 2.Erosion Point Length:120mts,Lat/Long:26.486586/91.348175 Date of occurrence:19/05/2022 as per information received from JE,WR Dept Nalbari 3.Erosion Point Length:120mts,Lat/Long:26.482205/91.334053 Date of occurrence:19/05/2022 as per information received from JE,WR Dept Nalbari, 4.Erosion Point Length:150mts,Lat/Long:26.48996/91.334053 Date of occurrence:19/05/2022 as per information received from JE,WR Dept Nalbari, 5.Erosion Point Length:300mts,Lat/Long:26.474434/91.31458 Date of occurrence:19/05/2022 as per information received from JE,WR Dept Nalbari, 6.Erosion Point Length:300mts,Lat/Long:26.481441/91.335952 Date of occurrence:19/05/2022 as per information received from JE,WR Dept Nalbari, 7.Erosion Point Length:100mts,Lat/Long:26.47864/91.320975 Date of occurrence:19/05/2022 as per information received from JE,WR Dept Nalbari 8. Village road eroded due to incessant rain near the Haihaira Jaan at Chamaitiyapara(Suradi,near 31 no NH),Date of erosion 18/05/2022 as per information received from GB.   0, <b>Barkhetri</b> - Bhangnamri   river bank erosion of Brahmaptra at Bhangnamri. length 50 m approx. Date 21/05/2022. 14 nos. of houses shifted due to erosion.   0, <b>Ghograpar</b> - Barjabrihati   As per information received from W.R department, Erosion have seen at the R/B of river Noona on 20/05/2022 at village Barjabrihati. Length - 230 M approx   0
Sonitpur		<b>Thelamara</b> - Meghajarani, Ghatua and Nabeel   Date- 21/05/2022, Heavy bank erosion occurred at Meghajarani( Length-200m), Borbeel to Ghatua( 600m)and Nabeel(200m) area on R/Bank of river Gabharu as reported by Water Resource deptt. Co-ordinates of Meghajarani- 92.622171 E, 26.720523N, Nabeel- 92.624336E, 26.648978N, Ghatua-92.61804E, 26.690546N   0, <b>Dhekiajuli</b> - Keherukhanda Pathar   Severe erosion ongoing along the bank of the Belsiri river at Keherukhanda Pathar village. aprox length 550mtr. date 20.5.22   0
South Salmara		<b>Mankachar</b> - Berabhanga Pt-I And Fattapara   As per report submit water resource department of Brahmaputra river site erosion at Revenue village Berabhanga Pt-I and Fattapara. Berabhanga erosion distance Appx-400 M and Fattapara erosion distance Appx-300 M. date: 21-05-2022   0, <b>South Salmara</b> - Tumni Silmlakandi   As per report received from water resource erosion occurred at village Tumni Simlakandi due river Jinjiram on 20/05/22. area lenth 100 m and breath 2 m   0
Tinsukia		<b>Sadiya</b> - 1. Majgaon (amarpur). 2. Koilabasti 3. Gurungbasti.   1. River Bank erosion is being observed at Majgaon (Amarpur) on the North Bank of River Datung since 12/05/2022 till 21/05/2022. As per information received from concerned Gaon Pradhan , the affected stretch is about 280m. 2. Active erosion is reported from Koilabasti area by Kundil river since 12/05/2022 till 21/05/2022. . As per report received from the WR department and concerned Gaon Pradhan , the stretch area is 50m. ( Lati 27.84688889, Long 95.71255556 ) 3. River bank erosion at Gurung Basti area reported by WR department since 15/05/2022 till 21/05/2022. the stretch area is 50m. ( Lati 27.89750000, Long 95.77833333 )   0, <b>Doomdooma</b> - 1. Village: Phelai NC ( Nawkata NC), 2. Village : No. 3 Kordoiguri ( Goriyating ), 3. Village: No. 1 Kordoiguri   1. Severe erosion is being observed at Phelai( Nawkata) area on the left Bank of River Brahmaputra since 5/04/2022 till 21/05/2022. The affected stretch is about 1500 m. 10 m offset remains as of now from the Brahmaputra Embankment.( Long: 95.523457, Lati:27.745786 ) 2. River Bank erosion is being observed at No. 3 Kordoiguri on the left Bank of River Brahmaputra (Ananta Nallah)since 2/04/2022 till 21/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 200 m in length.( Long: 95.468184, Lati: 27.650410), population affected 122. 3. River Bank erosion is being observed at No. 1 Kordoiguri (Dorzijan)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 21/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 300 m in length.( Long: 95.450531, Lati: 27.651217), population affected 37. 4. River Bank erosion is being observed at No.2 Kordoiguri (Simoluguri Satra)on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 21/05/2022. As per information received from concerned Lot Mandal and WR department officials, the affected stretch is about 400 m in length.( Long: 95.4505 , Lati:

		27.65196)   0
	Udalguri	<b>Udalguri</b> - 1. Kathalguri 2. Sapkhaity   1. Erosion on right bank from river Golandi at Kathalguri village around 300m on 21.05.2022. GPS - Lat - 26.740097 Long - 92.120697, 2. Erosion on both bank from river Sapkhaity at Sapkhaity village around 190m on 21.05.2022. GPS - Lat - 26.730195 Long - 92.081763   0, <b>Khairabari</b> - Jhargaon   Erosion is continuing at Jhargaon (L/B- 80M) by Kalpani River, immediate measure is to be taken to eradicate loss of land & properties. Dated: 18.05.2022   200
Landslide	<b>District</b>	<b>Details</b>
	Dima-Hasao	<b>Haflong</b> - 1.Topodisa 2. Moulhoi   1. Due to landslide on 21.05.2022 at Topodisa morning one house was several damaged and 5 members of the family affect. 2. Due to landslide more then 25 house were severely damaged due to landslide at Moulhoi on 21.05.22 and the road between moulhoi and mahadev tilla is completely blocked   5
	Kamrup (M)	<b>Dispur</b> - Bonda Colony   A landslide incident took place on 20/05/2022 at Bonda Colony at Modhu Hazong residents and no casualties during field investigations. To avoid any unforeseen incidents residents Modhu Hazong, Anjima Hajong were instructed to go to a secure location. information Received- Gaonbura Bonda Circle Casualty- Nil Longitude- 91.847714 Latitude- 26.189132 Date of Occurence- 20/05/2022   0
Urban Flood	Nil	