

Assam Daily Flood Report as on 22-06-2022 at 4:00 PM

Assam Daily Flood Report as on 22-06-2022 at 4:00 PM			
Particulars	Situation as on 22-06-2022 (in last 24 hours)		
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above danger level	Kopili (Dharamtul), Disang (Nanglamuraghat), Brahmaputra (Dhubri; Goalpara; Tezpur; Neamatighat)	
	Rivers flowing above highest flood level	Kopili (Kampur)	
District Affected	<b>No. of Districts Affected</b>	<b>Name of Flood Affected Districts</b>	<b>Name of Urban Flood Districts</b>
	32	Bajali, Baksa, Barpeta, Biswanath, Bongaigaon, Cachar, Chirang, Darrang, Dhemaji, Dhubri, Dibrugarh, Dima-Hasao, Goalpara, Golaghat, Hailakandi, Hojai, Kamrup, Kamrup (M), Karbi Anglong West, Karimganj, Kokrajhar, Lakhimpur, Majuli, Morigaon, Nagaon, Nalbari, Sivasagar, Sonitpur, South Salmara, Tamulpur, Tinsukia, Udalguri	Cachar, Darrang, Goalpara, Karimganj, Morigaon
No. Of Revenue Circles Affected	112		
Name Of Revenue Circles Affected	<b>District</b>	<b>Total</b>	<b>Revenue Circle</b>
	Bajali	2	Sarupeta, Bajali
	Baksa	3	Barnagar RC part, Barama, Baganpara
	Barpeta	6	Baghbar, Barpeta, Sarthebari, Kalgachia, Barnagar, Chenga
	Biswanath	1	Halem
	Bongaigaon	3	Boitamari, Manikpur, Srijangram
	Cachar	5	Katigora, Lakhimpur, Silchar, Sonai, Udharbond
	Chirang	2	Bijni, Bengtal
	Darrang	4	Dalgaon, Patharighat, Sipajhar, Mangaldoi
	Dhemaji	3	Jonai, Dhemaji, Sissiborgaon
	Dhubri	7	Dhubri, Bilasipara, Golakganj, South Salmara Part, Athani, Gauripur, Chapar
	Dibrugarh	1	Chabua
	Dima-Hasao	1	Haflong
	Goalpara	4	Matia, Lakhimpur, Balijana, Dudhnoi
	Golaghat	2	Bokakhat, Khumtai
	Hailakandi	4	Algapur, Hailakandi, Lala, Katlicherra
	Hojai	3	Hojai, Lanka, Doboka
	Kamrup	10	Rangia, North Ghy, Kamalpur, Kayan, Chaygaon, Nagarbera, Chamaria, Hajo, Palashbari, Goroimari
	Kamrup (M)	2	Chandrapur, Sonapur
	Karbi Anglong West	1	Donkamokam
	Karimganj	5	Nilambazar, Badarpur, Karimganj, Patherkandi, RK Nagar
Kokrajhar	1	Gossaigaon	
Lakhimpur	6	Subansiri, Bihpuria, Dhakuakhana, Narayanpur, Nowboicha, North Lakhimpur	
Majuli	2	Majuli, Ujani Majuli	
Morigaon	5	Mayong, Bhuragaon, Laharighat, Morigaon, Mikirbheta	
Nagaon	7	Nagaon, Kampur, Kaliabor, Rupahi, Dhing, Samaguri, Raha	
Nalbari	7	Tihu, Paschim Nalbari, Ghograpar, Barbhag, Banekuchi, Barkhetri, Nalbari	
Sivasagar	1	Sivsagar	

	Sonitpur	4	Dhekiajuli, Thelamara, Chariduar, Tezpur					
	South Salmara	2	South Salmara, Mankachar					
	Tamulpur	2	Goreswar, Tamulpur					
	Tinsukia	1	Doomdooma					
	Udalguri	5	Harisinga, Udalguri, Mazbat, Khairabari, Kalaigaon					
	<b>Total</b>	<b>112</b>						
Villages Affected	<b>District</b>	<b>Total</b>	<b>Revenue Circle</b>					
	Bajali	145	( Sarupeta   51 ), ( Bajali   94 )					
	Baksa	28	( Barnagar RC part   20 ), ( Barama   1 ), ( Baganpara   7 )					
	Barpeta	606	( Baghbar   141 ), ( Barpeta   145 ), ( Sarthebari   135 ), ( Kalgachia   100 ), ( Barnagar   16 ), ( Chenga   69 )					
	Biswanath	10	( Halem   10 )					
	Bongaigaon	80	( Boitamari   56 ), ( Srijangram   24 )					
	Cachar	565	( Katigorah   159 ), ( Lakhipur   113 ), ( Silchar   163 ), ( Sonai   87 ), ( Udharbond   43 )					
	Chirang	7	( Bijni   4 ), ( Bengtal   3 )					
	Darrang	381	( Dalgaon   61 ), ( Patharighat   75 ), ( Sipajhar   80 ), ( Mangaldoi   165 )					
	Dhemaji	50	( Jonai   23 ), ( Dhemaji   2 ), ( Sissiborgaon   25 )					
	Dhubri	510	( Dhubri   74 ), ( Bilasipara   51 ), ( Golakganj   23 ), ( South Salmara Part   164 ), ( Athani   118 ), ( Gauripur   56 ), ( Chapar   20 ), ( Agamoni   4 )					
	Dibrugarh	1	( Chabua   1 )					
	Dima-Hasao	2	( Haflong   2 )					
	Goalpara	283	( Matia   52 ), ( Lakhipur   102 ), ( Rongjuli   9 ), ( Balijana   119 ), ( Dudhnoi   1 )					
	Golaghat	38	( Bokakhat   34 ), ( Khumtai   4 )					
	Hailakandi	98	( Algapur   42 ), ( Hailakandi   24 ), ( Lala   32 )					
	Hojai	79	( Hojai   27 ), ( Lanka   16 ), ( Doboka   36 )					
	Kamrup	440	( Rangia   86 ), ( North Ghy   31 ), ( Kamalpur   104 ), ( Kayan   28 ), ( Chaygaon   5 ), ( Nagarbera   23 ), ( Chamaria   60 ), ( Hajo   55 ), ( Palashbari   15 ), ( Goroimari   33 )					
	Kamrup (M)	31	( Azara   1 ), ( Chandrapur   16 ), ( Sonapur   14 )					
	Karbi Anglong West	3	( Donkamokam   3 )					
	Karimganj	469	( Nilambazar   187 ), ( Badarpur   62 ), ( Karimganj   43 ), ( Patherkandi   27 ), ( RK Nagar   150 )					
	Lakhimpur	37	( Subansiri   3 ), ( Bihpuria   3 ), ( Dhakuakhana   12 ), ( Narayanpur   6 ), ( Nowboicha   11 ), ( North Lakhimpur   2 )					
	Majuli	18	( Majuli   14 ), ( Ujani Majuli   4 )					
	Morigaon	283	( Mayong   131 ), ( Bhuragaon   56 ), ( Laharighat   2 ), ( Morigaon   91 ), ( Mikirbheta   3 )					
	Nagaon	321	( Nagaon   72 ), ( Kampur   109 ), ( Kaliabor   2 ), ( Rupahi   5 ), ( Dhing   15 ), ( Samaguri   9 ), ( Raha   109 )					
	Nalbari	258	( Tihu   16 ), ( Paschim Nalbari   18 ), ( Ghograpar   7 ), ( Barbhag   34 ), ( Banekuchi   1 ), ( Barkhetri   118 ), ( Nalbari   64 )					
	Sivasagar	2	( Sivsagar   2 )					
	Sonitpur	53	( Dhekiajuli   24 ), ( Thelamara   2 ), ( Chariduar   2 ), ( Tezpur   25 )					
	South Salmara	85	( South Salmara   37 ), ( Mankachar   48 )					
	Tamulpur	15	( Goreswar   14 ), ( Tamulpur   1 )					
Tinsukia	8	( Doomdooma   8 )						
Udalguri	35	( Harisinga   3 ), ( Udalguri   15 ), ( Mazbat   11 ), ( Khairabari   4 ), ( Kalaigaon   2 )						
	<b>Total</b>	<b>4941</b>						
Population And Crop Area Affected	<b>District</b>	<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Total Population</b>	<b>Population Details</b>	<b>Crop Area ( in Hect. )</b>	<b>Crop Area Details</b>
	Bajali	124221	111379	24100	259700	( Sarupeta   98700 ), ( Bajali   161000 )	412.00	( Sarupeta   412.00 ), ( Bajali   0.00 )
	Baksa	8638	6624	5930	21192	( Barnagar RC part   20957 ), ( Barama   56 ), ( Baganpara   179 )	410.00	( Barnagar RC part   410.00 ), ( Barama   0.00 ), ( Baganpara   0.00 )
	Barpeta	464384	420819	244187	1129390	( Baghbar   310212 ), ( Barpeta   145377 ), ( Sarthebari   335837 ), ( Kalgachia   173378 ), ( Barnagar   10103 ), (	27229.00	( Baghbar   18983.00 ), ( Barpeta   869.00 ), ( Sarthebari   2080.00 ), ( Kalgachia   1823.50 ), ( Barnagar   780.50 ), (

						Chenga   154483 )		Chenga   2693.00 )
Biswanath	0	0	0	0	0	( Gohpur   0 ), ( Halem   0 )	167.00	( Gohpur   0.00 ), ( Halem   167.00 )
Bongaigaon	26071	20813	27658	74542		( Manikpur   0 ), ( Srijangram   7570 ), ( Boitamari   66972 )	0.00	( Manikpur   0.00 ), ( Srijangram   0.00 ), ( Boitamari   0.00 )
Cachar	91611	85154	55237	232002		( Katigorah   89156 ), ( Lakhipur   20361 ), ( Silchar   52850 ), ( Sonai   64200 ), ( Udharbond   5435 )	0.00	( Katigorah   0.00 ), ( Lakhipur   0.00 ), ( Silchar   0.00 ), ( Sonai   0.00 ), ( Udharbond   0.00 )
Chirang	716	734	966	2416		( Sidli   0 ), ( Bijni   622 ), ( Bengtal   1794 )	0.00	( Sidli   0.00 ), ( Bijni   0.00 ), ( Bengtal   0.00 )
Darrang	194038	159344	62594	415976		( Dalgaon   77400 ), ( Patharighat   75359 ), ( Sipajhar   138210 ), ( Mangaldoi   125007 )	9687.50	( Dalgaon   3795.50 ), ( Patharighat   1400.00 ), ( Sipajhar   1654.00 ), ( Mangaldoi   2838.00 )
Dhemaji	14764	11578	9177	35519		( Jonai   17982 ), ( Sissiborgaon   17078 ), ( Dhemaji   459 )	6602.50	( Jonai   5685.50 ), ( Sissiborgaon   910.00 ), ( Dhemaji   7.00 )
Dhubri	215063	198574	183516	597153		( Dhubri   63237 ), ( Bilasipara   125503 ), ( Golakganj   0 ), ( South Salmara Part   265395 ), ( Athani   143018 ), ( Gauripur   0 ), ( Chapar   0 ), ( Agamoni   0 )	6376.70	( Dhubri   711.00 ), ( Bilasipara   0.00 ), ( Golakganj   189.00 ), ( South Salmara Part   3769.00 ), ( Athani   0.00 ), ( Gauripur   695.10 ), ( Chapar   1012.60 ), ( Agamoni   0.00 )
Dibrugarh	1567	1240	1050	3857		( Chabua   3857 )	2.50	( Chabua   2.50 )
Goalpara	111409	93266	36161	240836		( Matia   11286 ), ( Lakhipur   140349 ), ( Balijana   89160 ), ( Rongjuli   0 ), ( Dudhnoi   41 )	944.40	( Matia   321.00 ), ( Lakhipur   0.00 ), ( Balijana   623.40 ), ( Rongjuli   0.00 ), ( Dudhnoi   0.00 )
Golaghat	9522	8952	2955	21429		( Bokakhat   21429 ), ( Khumtai   0 )	124.50	( Bokakhat   108.50 ), ( Khumtai   16.00 )
Hailakandi	19025	19537	12837	51399		( Algapur   27555 ), ( Hailakandi   13044 ), ( Lala   10800 ), ( Katlicherra   0 )	95.00	( Algapur   45.00 ), ( Hailakandi   19.00 ), ( Lala   31.00 ), ( Katlicherra   0.00 )
Hojai	26242	19487	7781	53510		( Hojai   19036 ), ( Lanka   6832 ), ( Doboka   27642 )	1800.00	( Hojai   539.00 ), ( Lanka   815.00 ), ( Doboka   446.00 )
Kamrup	199419	515011	75066	789496		( Rangia   48700 ), ( Kamalpur   146310 ), ( Kayan   38122 ), ( Chaygaon   0 ), ( Nagarbera   0 ), ( Chamaria   0 ), ( Hajo   532240 ), ( Goroimari   0 ), ( North Ghy   21625 ), ( Palashbari   2499 )	4238.50	( Rangia   798.50 ), ( Kamalpur   694.00 ), ( Kayan   407.00 ), ( Chaygaon   144.00 ), ( Nagarbera   245.00 ), ( Chamaria   117.50 ), ( Hajo   690.00 ), ( Goroimari   700.00 ), ( North Ghy   175.00 ), ( Palashbari   267.50 )
Kamrup (M)	3095	2501	50	5646		( Azara   0 ), ( Chandrapur   0 ), ( Sonapur   5646 )	860.00	( Azara   0.00 ), ( Chandrapur   173.00 ), ( Sonapur   687.00 )
Karbi Anglong West	1225	1225	1334	3784		( Donkamokam   3784 )	0.00	( Donkamokam   0.00 )
Karimganj	137561	107947	35763	281271		( Nilambazar   62368 ), ( Badarpur   42960 ), ( Patherkandi   4732 ), ( RK Nagar   51140 ), ( Karimganj   120071 )	1562.50	( Nilambazar   914.00 ), ( Badarpur   0.00 ), ( Patherkandi   348.50 ), ( RK Nagar   300.00 ), ( Karimganj   0.00 )
Lakhimpur	15663	12609	11570	39842		( Narayanpur   0 ), ( Nowboicha   30000 ), (	833.60	( Narayanpur   0.00 ), ( Nowboicha   239.60 ), (

						North Lakhimpur   2789 ), ( Subansiri   844 ), ( Bihpuria   5475 ), ( Dhakuakhana   734 )		North Lakhimpur   0.00 ), ( Subansiri   207.00 ), ( Bihpuria   0.00 ), ( Dhakuakhana   387.00 )
	Majuli	2942	2468	3569	8979	( Majuli   8979 ), ( Ujani Majuli   0 )	184.45	( Majuli   169.26 ), ( Ujani Majuli   15.19 )
	Morigaon	43684	41529	28106	113319	( Mayong   3774 ), ( Bhuragaon   39292 ), ( Morigaon   68391 ), ( Mikirbheta   1862 ), ( Laharighat   0 )	15792.50	( Mayong   14000.00 ), ( Bhuragaon   832.00 ), ( Morigaon   952.00 ), ( Mikirbheta   0.00 ), ( Laharighat   8.50 )
	Nagaon	178456	167646	157348	503450	( Nagaon   97767 ), ( Kampur   259500 ), ( Samaguri   5287 ), ( Raha   140715 ), ( Kaliabor   181 ), ( Rupahi   0 ), ( Dhing   0 )	16872.51	( Nagaon   218.00 ), ( Kampur   8320.00 ), ( Samaguri   225.00 ), ( Raha   7941.51 ), ( Kaliabor   18.00 ), ( Rupahi   43.00 ), ( Dhing   107.00 )
	Nalbari	128247	118674	106815	353736	( Tihu   3570 ), ( Paschim Nalbari   47429 ), ( Ghograpar   4180 ), ( Barbhag   21000 ), ( Banekuchi   480 ), ( Nalbari   12500 ), ( Barkhetri   264577 )	2061.50	( Tihu   200.00 ), ( Paschim Nalbari   554.00 ), ( Ghograpar   718.00 ), ( Barbhag   200.00 ), ( Banekuchi   8.00 ), ( Nalbari   381.50 ), ( Barkhetri   0.00 )
	Sivasagar	230	210	47	487	( Sivsagar   487 )	20.00	( Sivsagar   20.00 )
	Sonitpur	7963	11047	7419	26429	( Dhekiajuli   21140 ), ( Thelamara   336 ), ( Chariduar   4300 ), ( Tezpur   653 )	1619.00	( Dhekiajuli   1424.00 ), ( Thelamara   0.00 ), ( Chariduar   0.00 ), ( Tezpur   195.00 )
	South Salmara	56230	51232	62745	170207	( South Salmara   139183 ), ( Mankachar   31024 )	891.00	( South Salmara   692.00 ), ( Mankachar   199.00 )
	Tamulpur	5722	5449	1540	12711	( Goreswar   12571 ), ( Tamulpur   140 )	200.00	( Goreswar   0.00 ), ( Tamulpur   200.00 )
	Tinsukia	620	429	289	1338	( Doomdooma   1338 )	28.00	( Doomdooma   28.00 )
	Udalguri	3860	2716	1409	7985	( Udalguri   1742 ), ( Harisinga   2 ), ( Mazbat   6050 ), ( Khairabari   154 ), ( Kalaigaon   37 )	11.34	( Udalguri   0.00 ), ( Harisinga   1.34 ), ( Mazbat   0.00 ), ( Khairabari   0.00 ), ( Kalaigaon   10.00 )
	<b>Total</b>	<b>2092188</b>	<b>2198194</b>	<b>1167219</b>	<b>5457601</b>		<b>99026.00</b>	

Relief Camps / Centres Opened	District	Total	Relief Camp		Relief Distribution Centres	
	Bajali	109	13(Sarupeta   10, Bajali   3)		96(Sarupeta   1, Bajali   95)	
	Baksa	3	1(Barama   1, Barnagar RC part   0)		2(Barama   0, Barnagar RC part   2)	
	Barpeta	175	142(Baghbar   15, Barpeta   79, Sarthebari   11, Chenga   37, Kalgachia   0)		33(Baghbar   1, Barpeta   0, Sarthebari   11, Chenga   16, Kalgachia   5)	
	Bongaigaon	31	15(Boitamari   2, Manikpur   3, Srijangram   10)		16(Boitamari   3, Manikpur   1, Srijangram   12)	
	Cachar	258	175(Katigora   45, Lakhipur   22, Silchar   63, Sonai   44, Udharbond   1)		83(Katigora   0, Lakhipur   0, Silchar   83, Sonai   0, Udharbond   0)	
	Chirang	8	8(Bijni   4, Bengtal   4)		0(Bijni   0, Bengtal   0)	
	Darrang	119	10(Dalgaon   1, Sipajhar   5, Mangaldoi   4, Patharighat   0)		109(Dalgaon   0, Sipajhar   38, Mangaldoi   55, Patharighat   16)	
	Dhubri	65	21(Dhubri   4, Bilasipara   15, Athani   2, South Salmara Part   0)		44(Dhubri   0, Bilasipara   21, Athani   0, South Salmara Part   23)	
	Dibrugarh	1	0(Chabua   0)		1(Chabua   1)	
	Dima-Hasao	37	28(Haflong   28)		9(Haflong   9)	
	Goalpara	161	81(Matia   4, Lakhipur   50, Balijana   27)		80(Matia   3, Lakhipur   50, Balijana   27)	
	Golaghat	4	0(Bokakhat   0)		4(Bokakhat   4)	
	Hailakandi	36	9(Hailakandi   7, Lala   2, Algapur   0, Katlicherra   0)		27(Hailakandi   11, Lala   2, Algapur   10, Katlicherra   4)	
	Hojai	64	33(Hojai   19, Doboka   14, Lanka   0)		31(Hojai   19, Doboka   11, Lanka   1)	

Kamrup	108	77(Rangia   18, North Ghy   14, Kamalpur   25, Kayan   19, Hajo   1)	31(Rangia   2, North Ghy   4, Kamalpur   25, Kayan   0, Hajo   0)
Kamrup (M)	5	0(Sonapur   0)	5(Sonapur   5)
Karbi Anglong West	3	0(Donkamokam   0)	3(Donkamokam   3)
Karimganj	103	65(Badarpur   23, Karimganj   37, Patherkandi   5, Nilambazar   0, RK Nagar   0)	38(Badarpur   5, Karimganj   3, Patherkandi   0, Nilambazar   5, RK Nagar   25)
Lakhimpur	24	0(Subansiri   0, Bihpuria   0, Dhakuakhana   0, Narayanpur   0, Nowboicha   0)	24(Subansiri   4, Bihpuria   9, Dhakuakhana   1, Narayanpur   3, Nowboicha   7)
Majuli	5	0(Majuli   0)	5(Majuli   5)
Morigaon	24	1(Morigaon   1, Mayong   0)	23(Morigaon   12, Mayong   11)
Nagaon	300	63(Nagaon   33, Kampur   17, Raha   13, Kaliabor   0)	237(Nagaon   48, Kampur   109, Raha   78, Kaliabor   2)
Nalbari	130	69(Tihu   20, Paschim Nalbari   18, Barbhag   20, Banekuchi   3, Barkhetri   4, Nalbari   4, Ghograpar   0)	61(Tihu   23, Paschim Nalbari   21, Barbhag   0, Banekuchi   0, Barkhetri   4, Nalbari   0, Ghograpar   13)
Sonitpur	8	1(Dhekiajuli   1, Thelamara   0, Chariduar   0, Tezpur   0)	7(Dhekiajuli   1, Thelamara   2, Chariduar   2, Tezpur   2)
South Salmara	45	10(Mankachar   10, South Salmara   0)	35(Mankachar   27, South Salmara   8)
Tamulpur	21	10(Goreswar   6, Tamulpur   4)	11(Goreswar   7, Tamulpur   4)
Udalguri	24	13(Harisinga   2, Udalguri   3, Mazbat   6, Kalaigaon   2)	11(Harisinga   0, Udalguri   11, Mazbat   0, Kalaigaon   0)
<b>Total</b>	<b>1871</b>	<b>845</b>	<b>1026</b>

Inmates In Relief Camps	District	Total	Revenue Circlewise	Male	Female	Children	Pregnant / Lactating Mother	Person with Disability
	Bajali	1853	(Sarupeta   1788), (Bajali   65)	761	775	260	52	5
	Baksa	56	(Barnagar RC part   0), (Baganpara   0), (Barama   56)	24	29	3	0	0
	Barpeta	107532	(Baghbar   2594), (Barpeta   101244), (Sarthebari   2514), (Kalgachia   0), (Barnagar   0), (Chenga   1180)	34717	35817	36905	90	3
	Bongaigaon	4479	(Srijangram   2526), (Boitamari   656), (Manikpur   1297)	1660	1519	1223	77	0
	Cachar	33766	(Katigora   8615), (Lakhipur   3415), (Silchar   19704), (Sonai   1938), (Udharbond   94)	14059	11775	7928	0	4
	Chirang	1363	(Sidli   0), (Bijni   622), (Bengtal   741)	466	507	322	63	5
	Darrang	3568	(Patharighat   0), (Sipajhar   865), (Mangaldoi   1056), (Dalgaon   1647)	1308	1236	1016	4	4
	Dhubri	5483	(Dhubri   1887), (Bilasipara   3292), (Golakganj   0), (South Salmara Part   0), (Athani   304), (Gauripur   0), (Chapar   0), (Agamoni   0)	1767	2333	1383	0	0
	Dima-Hasao	1905	(Haflong   1905)	679	725	436	57	8
	Goalpara	33363	(Matia   1708), (Lakhipur   14048), (Rongjuli   0), (Balijana   17607), (Dudhnoi   0)	13447	10936	8796	169	15
	Hailakandi	1051	(Algapur   0), (Katlicherra   0), (Hailakandi   716), (Lala   335)	351	360	335	5	0
	Hojai	13536	(Hojai   10117), (Lanka   0), (Doboka   3419)	8151	4530	851	4	0
	Kamrup	9313	(Rangia   2421), (Kamalpur   3053), (Kayan   1597), (Chaygaon   0), (Nagarbera   0), (Chamaria   0), (Palashbari   0), (Goroimari   0), (North Ghy   2192), (Hajo   50)	3996	3412	1843	59	3
	Karimganj	20595	(Badarpur   2522), (RK Nagar   0),	7764	6653	6165	13	0

			(Karimganj   17888), (Patherkandi   185)						
	Morigaon	175	(Mayong   0), (Bhuragaon   0), (Laharighat   0), (Mikirbheta   0), (Morigaon   175)			67	75	33	0
	Nagaon	16422	(Kaliabor   0), (Rupahi   0), (Dhing   0), (Samaguri   0), (Nagaon   9744), (Kampur   4980), (Raha   1698)			6280	5750	4241	140
	Nalbari	13615	(Tihu   565), (Paschim Nalbari   10177), (Barbhag   1800), (Banekuchi   643), (Nalbari   220), (Barkhetri   210)			6302	5585	1608	105
	Sonitpur	170	(Thelamara   0), (Tezpur   0), (Dhekiajuli   170)			46	78	40	6
	South Salmara	472	(South Salmara   0), (Mankachar   472)			182	124	141	25
	Tamulpur	518	(Goreswar   212), (Tamulpur   306)			190	162	162	4
	Udalguri	1890	(Mazbat   820), (Khairabari   0), (Harisinga   408), (Udalguri   625), (Kalaigaon   37)			855	741	287	7
	<b>Total</b>	<b>271125</b>				<b>103072</b>	<b>93122</b>	<b>73978</b>	<b>880</b>
Human Lives Lost - Confirmed	<b>District</b>	<b>Total</b>	<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Revenue Circlewise</b>			
	Barpeta	3	2	0	1	(Baghbar   1), (Barnagar   0), (Barpeta   0), (Chenga   0), (Kalgachia   1), (Sarthebari   1)			
	Hojai	4	1	0	3	(Doboka   1), (Hojai   3), (Lanka   0)			
	Kamrup	2	2	0	0	(Chamaria   0), (Chaygaon   0), (Goroimari   0), (Hajo   0), (Kamalpur   0), (Kayan   1), (Nagarbera   0), (North Ghy   1), (Palashbari   0), (Rangia   0)			
	Nalbari	3	3	0	0	(Banekuchi   0), (Barbhag   3), (Barkhetri   0), (Ghograpar   0), (Nalbari   0), (Paschim Nalbari   0), (Tihu   0)			
	<b>Total</b>	<b>12</b>	<b>8</b>	<b>0</b>	<b>4</b>				
Human Lives Lost Confirmed - Death Type	<b>District</b>	<b>Total</b>	<b>Flood Death</b>	<b>General Drownin g (Non Flood)</b>	<b>Landslide</b>				
	Barpeta	3	3	0	0				
	Hojai	4	4	0	0				
	Kamrup	2	2	0	0				
	Nalbari	3	3	0	0				
	<b>Total</b>	<b>12</b>	<b>12</b>	<b>0</b>	<b>0</b>				
Human Lives Lost - Missing	Nil								
Human Lives Lost Missing - Type	Nil								
Animals Affected	<b>District</b>	<b>Total</b>	<b>Big</b>	<b>Small</b>	<b>Poultry</b>				
	Bajali	109896	73449	33367	3080				
	Baksa	7621	4291	2818	512				
	Barpeta	1020185	351346	195258	473581				
	Biswanath	12094	8810	3284	0				
	Darrang	398038	206273	133831	57934				
	Dhemaji	5886	4415	1471	0				
	Dhubri	227232	134820	92412	0				
	Dibrugarh	450	355	95	0				
	Goalpara	105949	75121	24323	6505				
	Hailakandi	13657	4575	3154	5928				
	Hojai	60258	21111	11987	27160				
	Kamrup	469609	404306	50303	15000				
Kamrup (M)	28853	14575	7902	6376					
Karimganj	42180	23939	7231	11010					

	Lakhimpur	25025	12572	6231	6222					
	Morigaon	120717	41838	19372	59507					
	Nagaon	106546	54772	37481	14293					
	Nalbari	231723	101653	94629	35441					
	Sonitpur	33627	22846	10781	0					
	South Salmara	285808	114287	79000	92521					
	Tamulpur	11732	2566	3500	5666					
	<b>Total</b>	<b>3317086</b>	<b>1677920</b>	<b>818430</b>	<b>820736</b>					
Animals Washed Away	Nil									
Houses Damaged	<b>District</b>	<b>Fully Kuccha</b>	<b>Fully Pukka</b>	<b>Fully Total</b>	<b>Partially Kuccha</b>	<b>Partially Pukka</b>	<b>Partially Total</b>	<b>Others Huts</b>	<b>Others Cattle Shed</b>	<b>Others Total</b>
	Baksa	0	0	0	45	0	45	0	0	0
	Chirang	40	5	45	18	0	18	0	0	0
	Kamrup (M)	0	0	0	0	1	1	0	0	0
	Lakhimpur	0	0	0	0	0	0	1	0	1
	Sonitpur	0	0	0	6	0	6	5	0	5
	South Salmara	71	0	71	0	0	0	0	0	0
	Udalguri	14	0	14	9	0	9	0	0	0
	<b>Total</b>	<b>125</b>	<b>5</b>	<b>130</b>	<b>78</b>	<b>1</b>	<b>79</b>	<b>6</b>	<b>0</b>	<b>6</b>
Rescue Operation	<b>District</b>	<b>Agency</b>		<b>Boats Deployed</b>	<b>Person Evacuated By Boats</b>	<b>Animal Evacuated By Boats</b>	<b>Helicopters Deployed</b>	<b>Person Evacuated By Helicopters</b>	<b>Medical Team Deployed</b>	
	Bajali			0	0	0	0	0	36	
	Barpeta	Army/Paramilitary force, Circle Office/Local Administration, Fire & Emergency Services (F&ES), NDRF, SDRF, Vety camp organised 2 nos, Haldhia Gaon, Haldhia Pather		44	1071	112	0	0	4	
	Bongaigaon	Circle Office/Local Administration, Local People, Engine Boat		21	0	0	0	0	16	
	Cachar	Circle Office/Local Administration, Fire & Emergency Services (F&ES), Local People, Civil Defence/Trained Volunteers, SDRF, Army/Paramilitary force, NDRF		22	1013	0	0	0	9	
	Chirang			3	0	0	0	0	4	
	Darrang	Civil Defence/Trained Volunteers, Army/Paramilitary force, Circle Office/Local Administration, NDRF, SDRF		11	450	0	0	0	7	
	Dhubri	Circle Office/Local Administration		63	121	143	0	0	9	
	Dibrugarh			0	0	0	0	0	1	
	Dima-Hasao	Civil Defence/Trained Volunteers, Police, Water Resources Department, NHAI, PWRD		0	0	0	0	0	15	
	Goalpara			0	0	0	0	0	19	
	Hailakandi			0	0	0	0	0	2	
	Hojai	Local People, Fire & Emergency Services (F&ES), Country Boats		18	3	0	0	0	15	
Kamrup	SDRF, Army/Paramilitary force, NDRF		16	250	25	0	0	39		

	Karimganj	Civil Defence/Trained Volunteers, SDRF			10	245	0	0	0	5
	Lakhimpur				0	0	0	0	0	7
	Morigaon	10 Machine Boat for relief distribution., Fire & Emergency Services (F&ES)			12	0	0	0	0	19
	Nagaon	Fire & Emergency Services (F&ES), SDRF, NDRF, Circle Office/Local Administration, Local People			24	420	0	0	0	30
	Nalbari	Circle Office/Local Administration			3	0	65	0	0	43
	Sonitpur				0	0	0	0	0	3
	South Salmara	Circle Office/Local Administration			31	85	123	0	0	4
	Udalguri				0	0	0	0	0	4
	<b>Total</b>				<b>278</b>	<b>3658</b>	<b>468</b>	<b>0</b>	<b>0</b>	<b>291</b>
Relief Distributed	<b>District</b>	<b>Rice (in Q)</b>	<b>Dal (in Q)</b>	<b>Salt (in Q)</b>	<b>M. Oil (in L)</b>	<b>Cattle Feed - Green Fooder (in Q)</b>	<b>Cattle Feed - Wheat Bran (in Q)</b>	<b>Cattle Feed - Rice Bran (in Q)</b>		
	Bajali	2648.47	800.00	273.47	1000.00	0.00	772.24	0.00		
	Baksa	36.02	6.61	1.98	198.18	0.00	0.00	0.00		
	Barpeta	3069.16	506.64	126.00	0.00	0.00	2976.00	1220.00		
	Bongaigaon	164.04	31.52	9.44	320.10	0.00	0.00	0.00		
	Cachar	750.83	248.61	79.42	5961.15	0.00	0.00	0.00		
	Chirang	51.04	10.12	3.04	303.66	20.00	0.00	0.00		
	Darrang	3722.30	636.97	212.40	20940.83	0.00	0.00	1744.50		
	Dhubri	2842.75	538.32	161.47	16145.94	0.00	2130.63	0.00		
	Dibrugarh	0.00	0.00	0.00	0.00	0.00	33.25	0.00		
	Dima-Hasao	50.65	8.45	1.00	108.00	0.00	0.00	0.00		
	Goalpara	1168.25	220.06	66.01	6601.68	0.00	166.00	0.00		
	Golaghat	0.00	0.00	0.00	0.00	0.00	0.00	16.80		
	Hailakandi	698.90	128.57	39.21	3919.37	0.00	0.81	0.00		
	Hojai	312.00	51.20	9.45	384.00	0.00	0.00	37.50		
	Kamrup	585.34	123.30	36.99	4698.91	0.00	900.00	0.00		
	Kamrup (M)	0.00	0.00	0.00	0.00	0.00	100.00	0.00		
	Karbi Anglong West	63.19	12.03	3.61	360.81	0.00	0.00	0.00		
	Karimganj	1055.19	189.99	70.82	185.00	0.00	45.00	0.00		
	Lakhimpur	498.06	92.55	27.76	2776.41	0.00	0.00	881.90		
	Morigaon	310.43	55.55	16.66	750.00	0.00	726.40	0.00		
Nagaon	3060.25	795.87	238.76	10838.33	0.00	912.25	1500.00			
Nalbari	0.00	965.97	289.79	28978.94	0.00	6592.08	0.00			
Sonitpur	57.88	10.78	3.23	0.00	0.00	422.96	13.60			
South Salmara	7.70	1.42	0.43	0.43	0.00	0.00	0.00			
Tamulpur	275.11	51.16	15.40	16.10	0.00	0.00	515.20			
Udalguri	98.72	25.20	4.56	456.00	0.00	32.80	0.00			
	<b>Total</b>	<b>21526.28</b>	<b>5510.89</b>	<b>1690.90</b>	<b>104943.84</b>	<b>20.00</b>	<b>15810.42</b>	<b>5929.50</b>		
Relief Distributed Others	<b>District</b>	<b>Baby Food Liquid</b>		<b>Baby Food Solid</b>		<b>Others</b>				
	Bajali	0.00-Q		564.00-Pkt		tarpaulin-10970.00-Pieces				
	Baksa	0.00-Q		0.00-Q						
	Barpeta	0.00-Q		0.00-Q, 486.00-Pieces		1. Candle Stick -3000.00-Pkt; 2. Mosquito Coil-3000.00-Pkt; Candle-502.00-Pkt; Tarpulin-1500.00-Pieces; Water Bottle-4800.00-ml; Mosquito Coil-1502.00-Pkt; Matches Box-1102.00-Pkt; Biscuit -960.00-Pkt; Mosquito coil -3460.00-Pkt; Candle -1500.00-Pkt; Water bottle -9000.00-Pieces; Tarpaulin -2500.00-Pieces				
	Bongaigaon	0.00-Q, 1842.00-		0.00-Q, 3762.00-Pkt		Bleaching Powder-29.00-Kg; Halogen Tablets-2015.00-Pkt;				



n	Pkt		Phenyl-8.00-Pkt; Temp. HTW-13.00-Pieces; Toilet-11.00-Pieces; Biscuit-765.00-Pkt; Amul Taza-765.00-Pkt; Sanitary Pad-180.00-Pkt; Mother Horlicks-22.00-Pkt; Halogen Tablet-1150.00-Pkt; Mobile Plant/ Pouches-6500.00-Pieces; Dustbin-2.00-Pieces; Sanitary Pads-172.00-Pkt; Horlicks-363.00-Pkt; Tarpoline-460.00-Pieces; phenyl -5.00-Pkt; Mosquito Coil-20.00-Pkt; Match Box-90.00-Pieces
Cachar	0.00-Q	0.00-Q	
Chirang	0.00-Q	0.00-Q	Tarpaulin-300.00-Pieces; Candle-150.00-Pkt; Match Box-15.00-Pkt; Mosquito Net-150.00-Pieces; Sanitary Pads-75.00-Pkt
Darrang	0.00-Pkt, 0.00-Q	68.00-Kg, 0.00-Q	tarpaulin-5000.00-Pieces; candles-800.00-Pkt; 0-0.00-Q
Dhubri	93.00-Pkt, 0.00-Q	0.00-Q, 65.00-Pkt	colour pencil-33.00-Pkt; Art Paper-25.00-Pkt; Wooden Pencil; Box-37.00-Pkt; Eraser-37.00-Pkt; Number Block-15.00-Pkt; Scissor-16.00-Pkt; Colour Paper-15.00-Pieces; Horlicks-67.00-Pkt; Biscuit-20.00-Pkt; sanitary napkin-20.00-Pkt; Gum-15.00-Pieces; Letter Block-5.00-Pkt; HTW-16.00-Pieces; Water Pouches Distributed-19000.00-Pkt; Bleaching Packet Distributed-4200.00-Pkt; Halogen tablet-4200.00-Pieces; Temporary Toilet-14.00-Pieces; Tarpoulin-8.00-Pieces; sanitary nepkin-8.00-Pkt; Horlics-60.00-Pkt; 0-0.00-Q
Dibrugarh	0.00-Q	0.00-Q	Tarpaulin sheets-956.00-Q
Dima-Hasao	0.00-Q	0.00-Q	Turmeric-100.00-Pkt; Milk-100.00-L; Potato-580.00-Kg; Onion-140.00-Kg; Biscuit-700.00-Pkt; Candle-300.00-Pkt; Match Box-108.00-Pkt; Mosquito Repellent-100.00-Pkt
Goalpara	98.00-Pieces, 0.00-Q, 734.00-Pkt	2496.00-Pkt, 0.00-Q	Mosquito Coil-116.00-Pkt; Candle-116.00-Pkt; Match Box-116.00-Pkt; Chira-0.43-Q; Gur-0.04-Q; Gur (Jaggery)-0.17-Q
Golaghat	0.00-Q	0.00-Q	Tarpaulin-75.00-Pieces
Hailakandi	0.00-Q, 546.00-Pkt	0.00-Q, 273.00-Pkt	Sanitary Napkin-262.00-Pkt; Match Box-57.00-Pkt; Disposal Plate-700.00-Pieces; Disposal Glass-700.00-Pieces; Soap-405.00-Pieces; Tarpaulin-333.00-Pieces; Hand Sanitizer-2.00-Pieces; Candle-113.00-Pkt; Mosquito Coil-20.00-Pkt
Hojai	0.00-Q	0.00-Q	Water bottle-3084.00-L; Candles-98.00-Pkt; Sanitary pads-170.00-Pkt; Amul Taza-658.00-L; Phenyl-186.00-Pieces; Bleaching Powder-186.00-Pkt; Chira-15.00-Q; Gur -3.50-Q; Sanitary Napkin-20.00-Pkt; Water-384.00-L; Candle-72.00-Pkt; Phenyl-12.00-Pkt; Belching Powder-12.00-Pkt; Water Bottle-2568.00-L; Sanitary Pads-110.00-Pkt
Kamrup	89.00-Pkt, 0.00-Q	89.00-Pkt, 0.00-Q	Water Pouch-30000.00-Pkt; Tarpaulin-3000.00-Pieces; Chira-13.77-Q; Gur-2.56-Q; Candle-20.00-Pkt; Broom & Floor Wiper-2.00-Pieces; Mosquito Coil-20.00-Pkt; Phenyl-10.00-L; 0-0.00-Q
Kamrup (M)	0.00-Q	0.00-Q	0-0.00-Q
Karbi Anglong West	0.00-Q	0.00-Q	
Karimganj	100.00-Q, 100.00-Pkt	0.00-Q	0-0.00-Q; CANDLE-50.00-Pkt; MOSQUITO COIL-50.00-Pkt
Kokrajhar	6.40-L	0.00-Q	Horlicks-11.00-Kg
Lakhimpur	0.00-Q	0.00-Q	Tarpaulin-113.00-Pieces
Majuli	0.00-Q	0.00-Q	Jaggery (baby food)-556.50-Kg; Flattered rice (baby food)-2226.00-Kg; Toned milk-5565.00-Pkt; Halogen tab.-4700.00-Pieces; Water Pouch-2000.00-Pkt
Morigaon	330.00-ml, 0.00-Q	330.00-Pkt, 0.00-Q	TARPAULIN-6500.00-Pieces; MOSQUITO COIL-3200.00-Pieces; MATCH BOX-3200.00-Q; HAND TUBE WELL-2.00-Q; CHEMICAL PACKETS-1550.00-Q; HALOGEN TABLETS -1640.00-Q
Nagaon	0.00-Q	0.00-Q	Tarpaulin -276.00-Pieces; HTW-13.00-Pieces; Toilet-19.00-Pieces; 0-0.00-Q; Tarpulin-5000.00-Pieces; Poha (Chira)-70.00-Q; Jaggery (Gur)(50 Gram)-22905.00-Pkt
Nalbari	0.00-Q	23.00-Q, 160.00-Pkt	Tarpaulin -985.00-Pkt; Tarpaulin-1775.00-Pkt; M. Coil-720.00-Pkt; Candle-1440.00-Pkt; Match Box-1200.00-Pkt; Phenyl-500.00-L; Bleaching Powder-500.00-Pkt; CONCENTRATE CATTLE FEED-145.00-Q
Sivasagar	0.00-Q	0.00-Q	Chemical Pkt-350.00-Pkt; Halogen /NADDC tablet -500.00-Pieces
Sonitpur	0.00-Q	0.00-Q	

	South Salmara	0.00-Q	0.00-Q	Candle-62.00-Pkt; Hand Tuebwell-66.00-Pieces; Tarpaulin-3019.00-Pieces
	Tamulpur	0.00-Q	0.00-Q, 50.00-Kg	Tarpaulin -5625.00-Pieces; 0-0.00-Q
	Udalguri	0.00-Q, 600.00-Pkt	200.00-Q	Sanitary Pad-344.00-Pkt; Tarpaulin -200.00-Pieces; Daipers-500.00-Pieces; candles-1250.00-Pkt; match box-1250.00-Pkt; milk-600.00-Pkt; biscuits-4000.00-Pkt; Hair oil-1000.00-Pkt; Mineral water-4500.00-ml; tooth paste-1500.00-Pieces; sanitary pad-700.00-Pieces; baby diapers-600.00-Pieces; mosquito net-1000.00-Pieces; Blanket-720.00-Pieces; dettol soap-4000.00-Pieces
Infrastructure Damaged - Embankment Breached	<b>District</b>	<b>Number</b>	<b>Details</b>	
	Baksa	9	<p><b>Baska</b> - 1 No. Katligaon Loihabari Embankment breached on 18/6/2022   1 No. Katligaon   Date of occurrence: 18/6/2022   (Long - 91.356646, Lat - 26.663722),  Embankment breach at Golding river at village Sripurdeor.   Sripurdeor   Date of occurrence: 18/6/2022   (Long - 91.339878, Lat - 26.610664),  Embankment breached at Golding river at village Adalbari   Adalbari   Date of occurrence: 18/6/2022   (Long - 91.323948, Lat - 26.597496),  Embankment breached at Bennabari Barband   Village Bennabari   Date of occurrence: 18/6/2022   (Long - 91.355240, Lat - 26.588988),  Jorthan Nizara Bandh- Embankment Breached   Palashguri (Nathsupa)   Damaged on 18/06/2022   (Long - 26.692116, Lat - 91.317392),  Dangar Dong (Jakhang Dong) on 18/6/2022   Ahopa Pub Suburi near Kamaykha Das house   (Long - 26.698016, Lat - 91.318241),  Dangar Dong on 18/6/2022   Ahopa Pub Suburi near back side of Madan Das house   (Long - 26.698364, Lat - 91.315732)</p>	
	Barpeta	1	<b>Barpeta</b> - Morachowlkhua (Kadong Extension)   Barpeta   damage 10 m approx Water Resource barpeta DOO 19.06.2022   (Long - 90.093500, Lat - 26.332000)	
	Total	<b>10</b>		
Infrastructure Damaged - Embankment Affected	<b>District</b>	<b>Number</b>	<b>Details</b>	
	Kamrup	2	<p><b>North Ghy</b> - 1. R/B embankment of River Barnadi   Kalitapara, Lenga   As reported by Asstt. Executive Engineer, WR Division. 21/06/2022   (Long - 0.000000, Lat - 0.000000),  2. Lenga Ring bund   Lenga   As reported by Asstt. Executive Engineer, WR Division on 21/06/2011   (Long - 0.000000, Lat - 0.000000)</p>	
	Total	<b>2</b>		
Infrastructure Damaged - Road	<b>District</b>	<b>Number</b>	<b>Details</b>	
	Bajali	5	<p><b>Bajali</b> - Pub Rehabari to Belona Road breached   Pub Rehabari   Road breached . Approx length- 18 m and depth-4 m. This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),  Tihu Bongaon Road to Bezkuhi, Affected length . 1000 m   Borsahan   Affected length . 1000 m This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),  Balipara to Bhadrapiha, 800 m. Road embankment damaged   Balipara to Bhadrapiha   Affected length- 800 m. Road embankment damaged . This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),  Bongaon to Kaskuri road, 500 to 2000 m. Road embankment damaged   Bongaon to Kaskuri road   Affected length- 500 to 2000 m. Road embankment damaged. This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),  Kuchdigha to Maguri, Affected length- 2000 m.   Kuchdigha to Maguri   Affected length- 2000 m. This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000)</p>	
	Baksa	8	<p><b>Baska</b> - Goldingpara to Ulubari Village Road on 18/6/2022   Goldingpara   (Long - 26.587033, Lat - 91.299769),  <b>Barnagar RC part</b> - 1. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous heavy rainfall the road Barua House Tiniali to Upen Das House at Udaynagar village Simlaguri has been submerged and damaged on 16/06/2022.   Simlaguri   1. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous heavy rainfall the road Barua House Tiniali to Upen Das House at Udaynagar village Simlaguri has been submerged and damaged on 16/06/2022.   (Long - 0.000000, Lat - 0.000000),  2. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall on Gohekhanda to Kaurpara Road has been submerged and damaged the road surface from CH-0.00M to 800.00 M by the flood water   Gahekhanda   2. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall on Gohekhanda to Kaurpara Road has been submerged and damaged the road surface from CH-0.00M to 800.00 M by the flood water   (Long - 0.000000, Lat - 0.000000),</p>	

			<p>3. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the Gohekhanda to Helonar Pam Road has been submerged and damaged the gravel road from surface CH-0.00M to 1200.00 M by the flood water   Gahekhanda   3. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the Gohekhanda to Helonar Pam Road has been submerged and damaged the gravel road from surface CH-0.00M to 1200.00 M by the flood water   (Long - 0.000000, Lat - 0.000000),</p> <p>4. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the Parabharal Gohekhanda PWD Road has been submerged and damaged the road surface from CH-0.00M to 400.00 M by the flood water   Gahekhanda   4. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the Parabharal Gohekhanda PWD Road has been submerged and damaged the road surface from CH-0.00M to 400.00 M by the flood water   (Long - 0.000000, Lat - 0.000000),</p> <p>5. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the RAngdia Tiniali to Rangdia village Road has been submerged and damaged from CH-0.00M to 1000.00 M by the flood water.   Rangdia   5. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the RAngdia Tiniali to Rangdia village Road has been submerged and damaged from CH-0.00M to 1000.00 M by the flood water.   (Long - 0.000000, Lat - 0.000000),</p> <p>6. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the Road Subash Das House to Madhu Swargiary House has been submerged and damaged from CH-0.00M to 250.00 M by the flood water.   Simlaguri   6. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the Road Subash Das House to Madhu Swargiary House has been submerged and damaged from CH-0.00M to 250.00 M by the flood water.   (Long - 0.000000, Lat - 0.000000),</p> <p>8. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the KhatalparaRangdia PWD Road has been submerged and damaged from CH-0.00M to 19250.00 M by the flood water.   Khatalpara Rangdia   8. As per report received from Asst. Exe. Engineer, PWD Salbari (R&amp;B) divn, Salbari on 21/06/2022 Due to continuous Heavy Rainfall the road portion of the KhatalparaRangdia PWD Road has been submerged and damaged from CH-0.00M to 19250.00 M by the flood water.   (Long - 0.000000, Lat - 0.000000)</p>
	Barpeta	7	<p><b>Barpeta</b> - Howly Ambari Fulkipara road   Howly   Road submerged, Side berm and hard crust damage 2500.00 PWRD Barpeta DOO 17.06.2022   (Long - 90.968231, Lat - 26.426725), Moiramara Fulkipara road   Moiramara   Road submerged, Side berm and hard crust damage 2500.00 PWRD Barpeta DOO 17.06.2022   (Long - 90.972952, Lat - 26.419195), <b>Sarthebari</b> - Burikhamar Bazar to Kaljahi PWD Road   Burikhamar   Reported By JE PWD Road on 21.06.2022   (Long - 0.000000, Lat - 0.000000), Tihu Lachima Road to Dr. Jinaram Das Road Via Kalatali   Kalatali   Reported by JE, PWD Road on 21.06.2022   (Long - 0.000000, Lat - 0.000000), Naligaon to Bhaktardoba PMGSY Road   Naligaon   Naligaon   (Long - 91.398580, Lat - 26.387887), Hatirtari to Kharma Bazar Road via Kahinoor MEM under PMGSY   Hatirtari   Reported by JE, PWD Road on 21.06.2022   (Long - 0.000000, Lat - 0.000000), <b>Barnagar</b> - Const. of earthen field bundh start from PMGSY road to Mozibar Rahman house at village Dharmapur .   Dharmapur   As per report received from Rupshi Dev Block Const. of earthen field bundh start from PMGSY road to Mozibar Rahman house at village Dharmapur .L=440m, B=2.5m, H=1.3m Date-22-6-2022   (Long - 90.856368, Lat - 26.421168)</p>
	Bongaigaon	43	<p><b>Dangtol</b> - Mulagaon Chengmari PWD road to Majhigaon road   Majhigaon   Embankment with hard crust damaged at Ch. 98.00m, 156.00m, 290.00m, 455.00 m. as per report received from PWRD, Bongaigaon date- 22.06.2022   (Long - 90.484323, Lat - 26.394889), Paltan Bazar to Hollaguri road   Hollaguri   Embankment damaged at 4th km. as per report received from PWRD, Bongaigaon date- 22.06.2022   (Long - 90.423472, Lat - 26.396392), Rabhpara Kakragaon Road   Kakragaon   SPT Br. No 2/1 has been threaten..as per report received from PWRD, Bongaigaon date- 22.06.2022   (Long - 90.463049, Lat - 26.433398), East Bhadrugaon to Digdari Road   Digdari   Approach of CD no 2/1 damaged at ch. 1420.00 M.as per report received from PWRD, Bongaigaon date- 22.06.2022   (Long - 90.445647, Lat - 26.440425), <b>Boitamari</b> - Nitya Bazar to Kayetpara road   Kayetpara   Nature of damage : Side shoulder damaged at 1st km. As per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.480715, Lat - 26.311909), <b>Bongaigaon</b> - Baghpara Baptist Missionary to Nigamghola road   Nigamghola   Land slide occurred and side shoulder damaged at 2nd km. as per report received from PWRD, Bongaigaon Date- 22.06.22   (Long - 90.335700, Lat - 26.233300), Ulubari Betbari Road.   Ulubari   Side shoulder damaged at ch. 250.00 m.as per report received from PWRD, Bongaigaon Date- 22.06.22   (Long - 90.905875, Lat - 26.437890), Chiponchila Ghondol Road.   Ghondol   Culvert damaged at ch. 200.00 m.as per report received from PWRD, Bongaigaon Date- 22.06.22   (Long - 90.605637, Lat - 26.553500),</p>

		<p><b>Manikpur</b> - Chakla Kirtanpara road   Kirtanpara   Road embankment erosion at various stretches at Ch. 5th to 7th Km. as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.773223, Lat - 26.376378),</p> <p>Dhupuri No.2 to Bhatipara road.   Bhatipara   Road submerged and breached out from ch 150.00 to 162.00m. Submergence depth 40 cm.as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.793945, Lat - 26.481245),</p> <p>Dangaigaon kirtanpara road.   Dangaigaon   Erosion of side slopes including damage of hard crust occurred from Ch 1650.00m to Ch 2100.00 m..as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.742584, Lat - 26.435906),</p> <p>Bijni Subhajhar road to Mazrabari Pt.II.   Mazrabari Pt.II.   Damage of hard crust including culvert approaches at ch 500.00m.as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.653527, Lat - 26.523806),</p> <p>Jhawbari to Solmari road   Solmari   Road submergence from ch 0.300Km to 2.80 km and SPT Br.No 3/1 approach damage..as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.401481, Lat - 26.416021),</p> <p>Manashghat Sakisali road   Manashghat   Road submergence occurred and road embankment and surface damaged from Ch 0.00km to 4.00 km.as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.457613, Lat - 26.429281),</p> <p>Moukhuwa to NH-31 via Barbila PMGSY Road.   Moukhuwa   Road submergence occurred and road embankment and surface damaged at ch 2nd and 4th km.as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.803532, Lat - 26.486329),</p> <p>Raha Chakla Kokila Road.   Kokila   Road embankment damaged from ch 0.00km to 1.50km..as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.850469, Lat - 26.431137),</p> <p>Chakla Kirtanpara Road.   Chakla   Road embankment damaged at 2nd and 3rd km and existing footbridge washed way at 3rd km..as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.824201, Lat - 26.386238),</p> <p>Manikpur Bashbari Road.   Bashbari   Road embankment damaged and submergence at various stretches of 1st to 3rd km of the road.as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.793017, Lat - 26.343289),</p> <p>Chakla Kirtanpara Road.   Chakla   Road embankment damaged and submergence at 4th km, Breach occurred at 4th km.as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.814485, Lat - 26.388385),</p> <p>Chakla Kirtanpara Road.   Kirtanpara   Road embankment eroded at various stretches of ch from 5th to 7th km.as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.773223, Lat - 26.376478),</p> <p>Dangaigaon Kirtanpara Road.   Dangaigaon   Road embankment and hard crust damaged at Ch. 1720.00 M..as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.742584, Lat - 26.435906),</p> <p>NH 31 to Nagarjhar Saradio LP school Road.   Nagarjha   Breach occurred at 0.500km of the road .Affected length 30.00 m and embankment damaged at various stretches from ch 0.200km to 1.20 km.as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.747035, Lat - 26.467452),</p> <p>Manikpur Bashbari Road.   Bashbari   SPT Br. No. 3/1 partially damaged along with approach damaged..as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.800377, Lat - 26.441855),</p> <p>Manikpur Bashbari Road.   Manikpur   SPT Br. No. 4/1 approach damaged.as per report received from PWRD, Bongaigaon as per report received from PWRD, Bongaigaon date 22.06.2022   (Long - 90.791692, Lat - 26.431624),</p> <p><b>Srijangram</b> - Besimari Tinkonia road   Tinkonia   Water hyacinth block Bridge No. 1/1 at 1st km. as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.604127, Lat - 26.277538),</p> <p>Nayagaon Ghilaguri road   Ghilaguri   Water hyacinth block Bridge No. 1/1 at 1st km.as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.593478, Lat - 26.305329),</p> <p>Behulapara Kuchbari road   Kuchbari   Bridge approach partially damaged at 1st km.as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.705516, Lat - 26.318733),</p> <p>SH2 road   Srijangram   Road surface damaged at 25th km.as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.678670, Lat - 26.334581),</p> <p>MG road   Srijangram   Road surface damaged at 1st km. as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.679346, Lat - 26.331250),</p> <p>Malegarh Gandhibasti road   Gandhibasti   Road embankment partially damaged at 1st km. as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.630892, Lat - 26.253207),</p> <p>Kabaitary Abhayapuri road   Kabaitary   Landslide occurred at 11th km.as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.647621, Lat - 26.262093),</p> <p>Gobindapur Tinkonia road   Tinkonia   Side shoulder damaged at 2nd km.as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.647054, Lat - 26.241630),</p> <p>Kuchbari Balargudam road   alargudam   Side shoulder damaged at 1st km .as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.723484, Lat - 26.292486),</p> <p>Haripur to Malegarh pahar via amguri road (PMGSY Package No.AS-02-177)   Haripur   Road submerged at 5th &amp; 6th km .as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.649578, Lat - 26.282268),</p>
--	--	---

		<p>Nowagaon Rangapani road   Nowagaon   Breached ocured at 8th&amp; 9th KM, Road embankment erosion at various streatches.as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.812568, Lat - 26.364995),</p> <p>Tulungia Borghola road   Tulungia   Culvert approach damaged at ch 4000.00 M..as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.669268, Lat - 26.384106),</p> <p>Borghola Kirtanpara road   Kirtanpara   Approach damaged of RCC Box cell culvert at ch 600.00 M.as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.729942, Lat - 26.383686),</p> <p>Borghola Kirtanpara road   Borghola   Approach damaged of Aie Bridge on Borghola side in stretches from Ch 1150.00 to 1250.00 m including damage of protection work (Boulder pitching).as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.734363, Lat - 26.381044),</p> <p>Tilapara Ambari Kacharipeti road   Tilapara   Damage of road embankment fromCh 1280.00m to 180000m with depression and side slope damage.as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.716903, Lat - 26.349765),</p> <p>Nowagaon Rangapani Road.   Rangapani   Road embankment damaged and breach occurred at 6th &amp; 7th km (Ch 6.00 km to Ch 7.95Km).as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.814076, Lat - 26.375956),</p> <p>Nowagaon Rangapani Road   Rangapani   Road embankment damaged and SPT Br. No 10/1 and approach damaged..as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.797440, Lat - 26.346487),</p> <p>Nowagaon Rangapani Road.   Rangapani   Breach occurred 8th km &amp; 9th Km of the road embankment, erosion at various stretches. At ch 8th &amp; 9th Km..as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.812568, Lat - 26.364995),</p> <p>Chakla Amtola Kokila Road.   Kokila   A massive erosion of side slope &amp; road embankment including hardcrust damaged at 1st km of the road in various stretches.as per report received from PWRD, Bongaigaon date-22.06.2022   (Long - 90.844601, Lat - 26.386454)</p>
Dhemaji	1	<p><b>Dhemaji</b> - PWD Jorkata road to Ujani Chuk (PMGSY package No- As-04-218)   Jorkata road to Ujani Chuk   Today on 22/06/2022, Erosion occurred on both sides of culvert approach connecting L040-jorkata road (T03) to Ujani Chuk (PMGSY package No- As-04-218) at Ch.620.00m. around 8 m.   (Long - 94.583154, Lat - 27.311940)</p>
Dhubri	11	<p><b>Bilasipara</b> - KRISHNAGAR TO HUDURCHAR ROAD, APPROACH OF R.C.C BRIDGE NO. ½ AND ROAD CH.4500.00M TO CH. 5500.00M SIDE BERM AND WBM GRADE-II &amp; III WASH OUT BY GAURANG RIVER FLOOD WATER dated 17-06-22 to 19-06-22   KRISHNAGAR TO HUDURCHAR ROAD,     (Long - 90.205422, Lat - 26.196758),</p> <p><b>Golakganj</b> - KANURI DIMAKURI TO BINNACHARA PWD ROAD FROM CH. 5.00 KM TO 9.00 KM (16-6-2022)   KANURI DIMAKURI TO BINNACHARA PWD ROAD     (Long - 26.108400, Lat - 89.827600),</p> <p>5TH KM DK ROAD GOHAIN KAMAL ALI GARH VIA MANDIR MOTERJHAR FROM 300M TO 1500M (16-6-2022)   5TH KM DK ROAD GOHAIN KAMAL ALI GARH VIA MANDIR MOTERJHAR     (Long - 26.132000, Lat - 89.868200),</p> <p>NALIA BAZAR TO BERBHANGI VIA NALIA PT-1 AT 1ST, 2ND &amp; 4TH KM (21-6-2022)   NALIA BAZAR TO BERBHANGI VIA NALIA PT-1     (Long - 26.057900, Lat - 89.803900),</p> <p>BRIDGE APPROACHES OF BRIDGE NO 1/1 ON 6TH KM DK ROAD TO DUKHISUKHI PMGSY ROAD (21-6-2022)   BRIDGE APPROACHES OF BRIDGE NO 1/1 ON 6TH KM DK ROAD TO DUKHISUKHI PMGSY ROAD     (Long - 26.147200, Lat - 89.871300),</p> <p><b>Chapar</b> - 1) BAHALPUR KOKRAJHAR ROAD (.) ROAD SURFACE DAMAGED AT 1ST AND 2ND KM DUE TO HAVEY RAIN (Latitude 26.319104, Longitude 90.462798)(.)   Bahalpur   From dated 14/06/2022 to 18/06/2022   (Long - 26.319104, Lat - 90.462798),</p> <p>8) NH-31 AT TILAPARA NOONMATI ROAD (.) PMGSY- 1 PKG NO. AS- 05-116 BRIDGE BOTH APPROCH DAMAGED OF R.C.C BRIDGE NO. 2/1 BY THE FLOOD WATER OF RIVER BRAHMAPUTRA9 Latitude 26.229001, Longitude 90.234414 (.)   Tilapara   From dated 14/06/2022 to 18/06/2022   (Long - 90.234414, Lat - 26.229001),</p> <p>12) NH-31 AT DHIRGHAT TO PUTHIMARI ROAD (.) RCC Br. NO 1/1 BOTH APPROACH DAMAGED AND SIDE BERM ERRODED DUE TO HEAVY RAIN (Latitude 26.24458, Longitude 90.395964) (.)   Dhirghat   From dated 14/06/2022 to 18/06/2022   (Long - 90.395964, Lat - 26.244580),</p> <p>13) CHOIBARI TO SASLARKANDA LP SCHOOL ROAD (.) WASHED WAY AT CH 30.00M DUE TO FLOOD WATER OF CHAMPABATI (Latitude 26. 342626, Longitude 90.43058) (.)   Choibari   From dated 14/06/2022 to 18/06/2022   (Long - 90.430580, Lat - 26.342620),</p> <p>NH-31 AT BAHALPUR TO PATALPUR SIDHA ASHRAM ROAD (.) CULVERT NO. 1/1 AND CULVERT NO. 1/2 DAMAGED DUE TO HEAVY RAIN (Latitude 26. 32058, Longitude 90.467786) (.)   Bahalpur   From dated 14/06/2022 to 18/06/2022   (Long - 90.467780, Lat - 26.320580),</p> <p>NH-31 TO TARANGAPUR PT-II VIA CHAMPABARTI ROAD (.) SIDE BERM ERRODED AND ROAD SURFACE DAMAGED DUE TO FLOOD WATER OF CHAMPABARTI (Latitude 26,259181, Longitude 90.425038)(.)   Tarangapur   From dated 14/06/2022 to 18/06/2022   (Long - 90.425038, Lat - 26.259181)</p>
Hailakandi	28	<p><b>Algapur</b> - Construction of road starting from 3rd KM of PMGSY Pkg AS-09-21 at Bakrihawar Pt- II Bakrihawar Pt-VII under Algapur Revenue Circle on dtd. 22.06.2022.   1st KM   Fully submerged  </p>

		<p>(Long - 92.620590, Lat - 24.826065), NH-6 to Mirapin Mukam Road under Algapur Revenue Circle on dtd. 22.06.2022.   Ch. 0.00 m to Ch. 1400.00 m   Fully submerged   (Long - 92.596135, Lat - 24.845968), 01T5- Chandipur Pt-I under Algapur Revenue Circle on dtd. 22.06.2022.   2 nd KM   submerged   (Long - 92.593718, Lat - 24.807140), Dakhin Badarpur- Chandipur RA under Algapur Revenue Circle on dtd. 22.06.2022.   1st &amp; 3rd KM   Partially submerged   (Long - 92.591694, Lat - 24.849570), North Narainpur Pt-I to Block Boundary Mohanpur under Algapur Revenue Circle on dtd. 22.06.2022.   1st KM   Submerged and eroded   (Long - 92.649629, Lat - 24.789602), Algapur Mohanpur Road under Algapur Revenue Circle on dtd. 22.06.2022.   1st and 3rd KM     (Long - 0.000000, Lat - 0.000000), Assam Darshan Mohanpur under Algapur Revenue Circle on dtd. 22.06.2022.   1st KM   Submerged   (Long - 92.646325, Lat - 24.741772), Saddam Para under Algapur Revenue Circle on dtd. 22.06.2022.   1st KM   Fully Submerged   (Long - 92.644440, Lat - 24.808730), Improvement of road starting from Mazumder para road to Panchgram Eddgah via Union Industry under Algapur Revenue Circle on dtd. 22.06.2022.   Ch. 350.00m to 600.00m   Submerged   (Long - 92.602844, Lat - 24.861659), Hafiza Balika Madrassa Road under Algapur Revenue Circle dtd, 22.06.2022   Ch. 0.00m to 600.00m   Submerged   (Long - 0.000000, Lat - 0.000000), <b>Hailakandi</b> - MRL07-Hailakandi Ratanpur road to Lakshinagar via bilpar Dhumkar under Hailakandi Revenue Circle dtd. 22.06.2022   3620.00m to 3990.00m 1700.00m to 2150.00m   Inundated   (Long - 92.578673, Lat - 24.698031), Matijuri Nityanandapur road to rongpur under Hailakandi Revenue Circle dtd. 22.06.2022   ch.0.00m to 200.00 m   Inundated and one HP culvert Damaged   (Long - 92.600582, Lat - 24.632806), 21st km of NH-6 to lala town via Novodaya Vidyalaya under Hailakandi Revenue Circle dtd. 22.06.2022   2nd km &amp; 3 rd Km   Inundated   (Long - 92.573619, Lat - 24.616824), Serlipur to koiya factory under Hailakandi Revenue Circle dtd. 22.06.2022   2nd km &amp; 3 rd Km   Inundated   (Long - 92.576313, Lat - 24.548288), Borhailakandi pt 3 to 430 no. LP school under Hailakandi Revenue Circle dtd. 22.06.2022   1 st &amp; 2 nd km   Inundated   (Long - 92.629411, Lat - 24.652147), Narainpur pt 4 to Narainpur TE under Hailakandi Revenue Circle dtd. 22.06.2022   1st km   Inundated   (Long - 92.535663, Lat - 24.669817), <b>Katlicherra</b> - 05T2 to Dholcherra FV, AS-09-30 under Katlicherra Revenue Circle dtd. 22.06.2022   1st, 2nd &amp; 3rd Km   Road damaged due to heavy runoff water   (Long - 92.492838, Lat - 24.840190), T3 Boldaboldi Pt-II to Krishnapur NC, AS-09-70 under Katlicherra Revenue Circle dtd. 22.06.2022   1st, 2nd &amp; 3rd Km   Road damaged due to heavy runoff water   (Long - 92.518806, Lat - 24.423332), Abdullahpur vernerpur Road under Katlicherra Revenue Circle dtd. 22.06.2022   1st, 2nd &amp; 3rd Km   Road damaged due to heavy runoff water   (Long - 92.607673, Lat - 24.532614), Latakandi Ayenakhil PWD Road to Rongpur Pt-II via Sabbishali under Katlicherra Revenue Circle dtd. 22.06.2022   1st Km   Road damaged due to heavy runoff water   (Long - 92.563161, Lat - 24.501670), NH-6 at Katlicherra Bypass to Bonogram under Katlicherra Revenue Circle dtd. 22.06.2022   1st Km   Road damaged due to heavy runoff water   (Long - 92.569665, Lat - 24.486388), NH-6 at Krishnapur Bazar to Mahmmmedpur Pt-I under Katlicherra Revenue Circle dtd. 22.06.2022   1st km   Road damaged due to heavy runoff water   (Long - 92.602371, Lat - 24.516518), NH-6 at Sorarpar to Rongpur Pt-VI under Katlicherra Revenue Circle dtd. 22.06.2022   1st &amp; 2nd Km   Road damaged due to heavy runoff water   (Long - 92.583116, Lat - 24.509502), O5T2 to Bhagabanpur Punjee Pt-II under Katlicherra Revenue Circle dtd. 22.06.2022   1st, 2nd &amp; 3rd Km   Road damaged due to heavy runoff water   (Long - 92.521495, Lat - 24.382902), T2 at Rangabak Pt-II to Block Boundary at Ramsantipur, AS-09-61 under Katlicherra Revenue Circle dtd. 22.06.2022   1st, 2nd, 3rd &amp; 4th Km   Road damaged due to heavy runoff water   (Long - 92.513450, Lat - 24.349262), 01T5 to Boruncherra FV under Katlicherra Revenue Circle dtd. 22.06.2022   1st &amp; 2nd Km   Landslide occured   (Long - 92.585070, Lat - 24.393349), Apin Grant to Rongpur Pt-I via Digar Apin under Katlicherra Revenue Circle dtd. 22.06.2022   3rd &amp; 4th Km   Submerged   (Long - 92.560307, Lat - 24.502121), 73rd Km of NH-154 to Jamira Pt-VI, AS-09-64 under Katlicherra Revenue Circle dtd. 22.06.2022   1st Km   Landslide occured   (Long - 92.522403, Lat - 24.318559)</p>
Kamrup	22	<p><b>Rangia</b> - Rangia Dhamdhama Road   Vill- Bhatkuchi   Rangia Dhamdhama Road partially washed away and damaged in several intervals as per report of AEE, PWD, NKT, Roads, Rangia on 20.06.2022   (Long - 0.000000, Lat - 0.000000), Danish Ali Road   Vill- Barkukuria   Danish Ali Road partially washed away and damaged in several intervals as per report of AEE, PWD, NKT, Roads, Rangia on 20.06.2022   (Long - 0.000000, Lat - 0.000000), NH37 to Dipteshari Mandir Road at RCC bridge approach   Vill- Nakul   NH37 to Dipteshari Mandir Road at RCC bridge approach was damaged as per report of AEE, PWD, NKT, Roads, Rangia on 20.6.2022.   (Long - 0.000000, Lat - 0.000000), Murara to Chirakhundi Road (Rangia Nagrijuli Road)   Vill- Kachari Solmari   A portion of the</p>

		<p>Murara to Chirakhundi Road was completely washed away on 19.06.2022 as per report of AEE, PWD, NKT, Roads, Rangia   (Long - 0.000000, Lat - 0.000000),</p> <p><b>Kamalpur</b> - Baihata MLA Office   Village-Baihata   Length of Submergence 80 M, Depth of submergence .45 M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.347179, Lat - 91.689580),</p> <p>Old NT Road   Baihata Chariali   Length of Submergence 200 M, Depth of submergence .45 M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.346435, Lat - 91.672766),</p> <p>Gasbari Gurmou Road   Gasbari   Total Length of road 4 KM, Depth of submergence .50 M Length of damage 30M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.486629, Lat - 91.727049),</p> <p>Karara Bathan Road   Karara   Total Length of road 10 KM, damage of culvert at ch 4050 as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.368185, Lat - 91.788620),</p> <p>NH 31 to Moinasundari road   Moinasundari   Total Length of road 850 M, Depth of submergence .45 M Length of submergence 300M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.305688, Lat - 91.716326),</p> <p>2 No Kharikot LPS   2 No Kharikot   Total Length of road 1400 M, Depth of submergence .90 M Length of submergence 1400M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.302357, Lat - 91.688463),</p> <p>Kendukuna Hahara road   Kendukuna   Total Length of road 3.3 KM, Depth of submergence .30 M Length of submergence 3 KM as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.390545, Lat - 91.652685),</p> <p>Baihata Chariali Police point &amp; Old NH 31 Baihata Chariali   Baihata Chariali   Damage of road by pot holes area 1500 MM, Depth of submergence .30 M Length of submergence 100 M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.344443, Lat - 91.726629),</p> <p>Kendukuna panitema road   panitema   Total Length of road 12 KM, Depth of submergence .45 M Length of submergence 300 M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.292077, Lat - 91.640858),</p> <p>Borka dallang road   Borka   Total Length of road 2.5 KM, Depth of submergence .450 M TO .60 M Length of submergence 2.5 KM as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.290366, Lat - 91.641832),</p> <p>Karara Bathan road   Bathan   Total Length of road 10 KM, Depth of submergence .50 M Length of submergence 7 KM as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.369762, Lat - 91.766204),</p> <p>Kendukuna to Bagals road   Kendukuna   Total Length of road 5 KM, Depth of submergence .30 M to .45 M Length of submergence 300 M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.373835, Lat - 91.639710),</p> <p>Singrapara Maroi road   Singrapara   Total Length of road 5.80 KM, Depth of submergence .45 M Length of submergence 1300 M damage of slab culvert 2/1 approach &amp; damage of side beam as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.394107, Lat - 91.764101),</p> <p>Karara Pingleswar road   Pingleswar   Total Length of road 4.744 KM, Depth of submergence .60 M Length of submergence 4 KM as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.372232, Lat - 91.734776),</p> <p>Jalimura Chargsari road   Jalimura   Total Length of road 7.9 KM, Depth of submergence .40 M Length of submergence 7 KM as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.301610, Lat - 91.689628),</p> <p>RCC bridge no 1/1 approach settlement at Kamalpur morowa road   Kamalpur   as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.347256, Lat - 91.669126),</p> <p>NH 31 to Moinasundari road   Moinasundari   Total Length of road 850 M, Depth of submergence .45 M Length of submergence 300 M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.305687, Lat - 91.716325),</p> <p>Guiya singra athgaon   singra   Total Length of road 6 KM, Depth of submergence .30 M Length of submergence 400 M as per report of Asstt. Executive Engineer PWD Kamalpur Territorial Road Sub Division Kamalpur on 21-06-2022   (Long - 26.308383, Lat - 91.621218)</p>
Karimganj	2	<p><b>Badarpur</b> - RAILWAY KALIBARI COLONY TO JUMBASTI ROAD   RAILWAY KALIBARI   THE SAID ROAD HAS BEEN DAMAGED DUE TO FLOOD WATER AS REPORT SUBMITTED BY BADARPUR MUNICIPAL BOARD Dtd. 20-06-2022.   (Long - 24.861315, Lat - 92.564592),</p> <p><b>Patherkandi</b> - PM Road to Paschim Defolala   Bhubrighat   As reported by AEE PWD T/R, Patharkandi a road has been damaged due to flood water on 19/06/22. approx length is 200 meter.   (Long - 92.282603, Lat - 24.615151)</p>
Kokrajhar	3	<p><b>Bagribari</b> - Lalmati to Tumbagan village via Tamarhat DK Road   LALMATI   As reported by, EE, PWRD, Dhubru Civil Sub Div. on 21.6.22., due to heavy rainfalling we.f. 15.6.22 to 19.06.22 the road has been submerged and badly damaged.   (Long - 89.888201, Lat - 26.287372),</p> <p>Kurshakati Bazar to Daldali village   Kurshakati   As reported by, EE, PWRD, Dhubru Civil Sub Div. on 21.6.22., due to heavy rain fall we.f. 15.6.22 to 19.06.22 the road has been submerged and badly</p>

			<p>damaged.   (Long - 89.884230, Lat - 26.268260),</p> <p><b>Gossaigaon</b> - PANBARI SAIALMARI ROAD   PANBARI   AS PER REPORT RECIVED FROM PWD RR KACHUGAON ON 20.06.2022 DUE TO HEAVY RAIN IMMEDIATE RESTORATION OF BADLY ERODED IN STRETCHES FROM 1 KM TO 2 KM ON PANBARI SIALMARI ROAD   (Long - 0.000000, Lat - 0.000000)</p>
Lakhimpur	1		<p><b>Subansiri</b> - Gogamukh Majuli E &amp; D to Ubhatachampara road   As reported by the Dhakuakhana Territorial Road Division, Ghilamara the Gogamukh Majuli E &amp; D to Ubhatachampara road is submerged at 1st KM (L= 50M) on 21/06/2022     (Long - 0.000000, Lat - 0.000000)</p>
Morigaon	12		<p><b>Mayong</b> - Kopoujari PWD road to Old Jame Masjid via Rangapara NRP road   rangapara   As reported by PWD Morigaon district territorial road division on 21/06/22   (Long - 92.177000, Lat - 26.294000),</p> <p>T10 to Kariguri road   kariguri   as reported by PWD Morigaon district territorial road division on 21/06/22   (Long - 92.146000, Lat - 26.282000),</p> <p>Garmari Bangalpara Sukutiputa Road   3rd and 4th km submerged   As reported by PWD Morigaon district territorial road division on 21/06/22   (Long - 92.223000, Lat - 26.284000),</p> <p>DK Road Submerged at several stretches   1st to 23rd km   As reported by PWD Morigaon district territorial road division on 21/06/22   (Long - 92.166000, Lat - 26.170000),</p> <p><b>Morigaon</b> - NH-37 to Mulankata Adarsha gaon road. (21-06-2022)   Mulankata, Morigaon   As per PWD Roads, NH-37 to Mulankata Adarsha gaon road submerged almost entire road length of 1.40 KM avg depth of submergence = 0.70m   (Long - 92.301291, Lat - 26.154138),</p> <p>Baghara Domal Ahatguri road to 1 no Gunamara (21-06-2022)   Baghara, Morigaon   As per PWD (Roads), Baghara Domal Ahatguri road to 1 no Gunamara under submergence from ch.400 to 1150m with average depth 0.35m   (Long - 92.317347, Lat - 26.207014),</p> <p>Khandajan Bakori Chapari road (21-06-2022)   Khandajan, Morigaon   As per PWD (Roads), Khandajan Bakori Chapari AS-17-88 almost entire road length is under submergence avg depth 0.9m.   (Long - 92.305967, Lat - 26.232804),</p> <p>NH-37/SH-3 to Charan beel to Tarani kalbari (21-06-2022)   1 no Morakolong, Morigaon   As per PWD (Roads), road from NH-37/SH-3 adjacent to Charan beel to Tarani Kolbari (SOPD-G). Approx entire road length is under submergence and avg depth = 0.65M   (Long - 92.287452, Lat - 26.230483),</p> <p>1no Morakolong to Tarani kalbari (21-06-2022)   1no Morakolong   As per PWD (Roads), PMGSY ROAD 1 no Morakolong to Tarani Kalbari (AS_17-174) is under submergence and avg depth=0.85m   (Long - 92.291133, Lat - 26.213004),</p> <p>T18 Karaiguri to Jurgaon road (21-06-2022)   Karaiguri   As per PWD (Roads), PMGSY PKG NO. AS-17-178 (T18 Karaiguri to Jurgaon road) is under submergence at 2nd KM.   (Long - 92.289297, Lat - 26.179982),</p> <p>Nabheti to Gasarguri via Bhairaguri (21-06-2022)   Nabheti, Morigaon   As per PWD(Roads), PMGSY PKG NO.AS-17-244 (MRL-08 Nabheti to Gasarguri via Bhairaguri) road is under submergence at 1st KM. Avg Depth = 0.15M   (Long - 92.329559, Lat - 26.257744),</p> <p>Tetelia Tiniali to Jerengagaon Shyam Nagar PWD Road (21-06-2022)   Tetelia, Morigaon   As per PWD (Roads), road from Tetelia to Jerengagaon Shyam Nagar PWD Road is under submergence at different stretches. Avg depth = 0.6m   (Long - 92.266221, Lat - 26.185312)</p>
Nagaon	20		<p><b>Nagaon</b> - Nagaon Dakhinpat Kampur Road   Dakhinpat Kampur Road   Nagaon Dakhinpat Kampur Road ,Submerged/damaged,Length-10th Km-18th Km, and depth of water 6000m depth 500mm to 1000m reported by Nagaon Territorial Road Sub-Division Nagaon, Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Nagaon Morikolong Nonoi Road   Morikolong   Nagaon Morikolong Nonoi Road ,Submerged/damaged,Length-5th Km-11th Km, and depth of depth 400mm to 800m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Nonoi Dakhinpat Road to Burguhainthan Pachim AS19 234   Dakhinpat Road to Burguhainthan Pachim   Dakhinpat Road to Burguhainthan Pachim , Submerged/damaged,Length- 1300m, and depth of depth 400mm to 600m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Pakhimoria Muslimgaon East NS36 AS19287   Pakhimoria Muslimgaon East   Pakhimoria Muslimgaon East, Submerged/damaged,Length- 1500m, and depth of depth 200mm to 400m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Nonoi Uriagaon to Ghagarial   Nonoi Uriagaon to Ghagarial   Nonoi Uriagaon to Ghagarial,Submerged/damaged,Length- 6700m, and depth of depth 500mm to 900m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Anandaram Baruah Road (Cow Path)   Anandaram Baruah Road   Anandaram Baruah Road (Cow Path),Submerged/damaged,Length- 550m, and depth of depth 200mm to 400m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Rudra Ram Bordoloi Road   ADP College   Rudra Ram Bordoloi Road ,Submerged/damaged,Length-300m, and depth of depth 300mm to 400m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>NH-36 to Uparujaragaon AS-19 133   NH-36 to Uparujaragaon   NH-36 to Uparujaragaon</p>



		<p>,Submerged/damaged,Length- 3000m, and depth of depth 400mm to 800m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000), Deodhar ranthali Jalah Road   Deodhar ranthali Jalah Road   Deodhar ranthali Jalah Road</p> <p>,Submerged/damaged,Length- 4000m, and depth of depth 400mm to 800m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000), Borpathari to Dhepajan Muslim gaon AS--19 551   Borpathari to Dhepajan Muslim gaon   Borpathari to Dhepajan Muslim gaon ,Submerged/damaged,Length- 800m, and depth of depth 300mm to 500m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Ghuriagaon to Borpanigaon AS-19 133   Ghuriagaon to Borpanigaon   Ghuriagaon to Borpanigaon ,Submerged/damaged,Length- 2500m, and depth of depth 300mm to 500m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000), Nagaon Morikolong Nonoi Road to Upar Ujaragaon AS 19 234   Nagaon Morikolong Nonoi Road to Upar Ujaragaon   Nagaon Morikolong Nonoi Road to Upar Ujaragaon,Submerged/damaged,Length- 850m, and depth of depth 300mm to 700m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Uparuriagaon to Jalah Bebejia AS19 550   Uparuriagaon to Jalah Bebejia   Uparuriagaon to Jalah Bebejia ,Submerged/damaged,Length- 800m, and depth of depth 300mm to 600m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000), NAGAON MORIKOLONG NONOI ROAD TO uAJARAPANIGAON ,AS19 2930   NAGAON MORIKOLONG NONOI ROAD TO uAJARAPANIGAON   NAGAON MORIKOLONG NONOI ROAD TO uAJARAPANIGAON,Submerged/damaged,Length- 800m, and depth of depth 300mm to 700m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Morikolong Dhepajan to Tetilatal road via kotayani   Morikolong Dhepajan to Tetilatal road via kotayani   Morikolong Dhepajan to Tetilatal road via kotayani ,submerged/ damaged,Length- 11100m, and depth of depth 300mm to 700m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Nagaon Morikolong Nonoi Road to Pathari Chariali via sutargaon   Nagaon Morikolong Nonoi Road to Pathari Chariali via sutargaon   Nagaon Morikolong Nonoi Road to Pathari Chariali via sutargaon ,Submerged/damaged,Length- 2000m, and depth 300mm to 600m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Shivanagar bylane No-01 (infront of Nabarup jtya Vidyalaya)Nagaon   Shivanagar bylane No-01 (infront of Nabarup jtya Vidyalaya)Nagaon   Shivanagar bylane No-01 (infront of Nabarup jtya Vidyalaya)Nagaon ,Submerged/damaged,Length- 75m, and depth 300mm to 400m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Jogeswar Sarmah Road   Jogeswar Sarmah Road   Jogeswar Sarmah Road ,Submerged/damaged,Length- 100m, and depth 200mm to 400m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Dhepajan Muslimgaon Raod   Dhepajan Muslimgaon   Dhepajan Muslimgaon Raod ,Submerged/damaged,Length- 1100m, and depth 3200mm to 400m reported by Nagaon Territorial Road Sub-Division Nagaon,Dated-22/06/2022   (Long - 0.000000, Lat - 0.000000)</p>
Nalbari	41	<p><b>Tihu</b> - MAKHIBAHA GIRLS HS TO BALAPARA VIA KUKURMARA ROAD   MAKHIBAHA   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :750M (APPROX),DATE OF SUBMERGED :18/06/2022.CULVERT NO 1/1 DAMAGED   (Long - 0.000000, Lat - 0.000000),</p> <p>KAUREHAGI -NAMSALA ROAD   JALKHANA   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :4.2KM (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),</p> <p>TIHU-BARAMA ROAD   TIHU   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :600MTS TO 1200MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),</p> <p>KAUREHAGI TO KATHALMURA ROAD   JALKHANA   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :0.5MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),</p> <p>TIHU TO MAKHIBAHA ROAD   MAKHIBAHA   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :4.27 MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),</p> <p>RATANPUR TO PAKRITAL   RATANPUR   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :1 KMS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),</p> <p>SD COLLEGE TO BHADRAKUCHI   BARBARI   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :1.20K.MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),</p> <p>FCI GODOWN TO PARMANKHOWA ROAD   PARMANKHOWA   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :0.8 K.MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),</p> <p>RATANPUR TO DIGHELI HOSPITAL ROAD   RATANPUR   INFORMATION RECEIVED</p>

		<p>FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :12.5MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),  JALKHANA TO RUPDIGA ROAD   JALKHANA   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :2 K.MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),  TIHU GIRLS HS ROAD   TIHU   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :800MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),  TIHU HS TO BIDYANAGAR ROAD   TIHU   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :700MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),  GHOPA TO KAUREHAGI ROAD   JALKHANA   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :750MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),  NIZKHANA TO BALIPARA VIA BHADRABHITHA ROAD   NIZKHANA   INFORMATION RECEIVED FROM JE,PWD(R),PATACHARKUCHI DIV. LENGTH :1.5 K.MTS (APPROX),DATE OF SUBMERGED :17/06/2022.   (Long - 0.000000, Lat - 0.000000),  <b>Paschim Nalbari</b> - Tihu Harbhanga Sandheli Sahnur road   Sandheli Sahnur   Side berm damage of ch 0.00 m ch 2300.00 m with depth 70 cm. Information received from PWRD on 19/06/2022.   (Long - 0.000000, Lat - 0.000000),  Jagara Gopalthan LP School to Khakhrishal Road   Jagara   Submerged. Information received from PWRD on 19/06/2022.   (Long - 0.000000, Lat - 0.000000),  Balapara- Bihampur Road   Balapara   HPC damaged. Information received from PWRD on 19/06/2022.   (Long - 0.000000, Lat - 0.000000),  Khakhrishal Kasuapara Road   Khakhrishal   Submerged. Information received from PWRD on 19/06/2022.   (Long - 0.000000, Lat - 0.000000),  Bhatta Chowk to Larakuchi road   Larakuchi   Submerged. Information received from PWRD on 19/06/2022.   (Long - 0.000000, Lat - 0.000000),  Larakuchi- Bhoiraghol Road   Larakuchi   Submerged. Information received from PWRD on 19/06/2022.   (Long - 0.000000, Lat - 0.000000),  Kutnikuchi Road   Kutnikuchi   Submerged. Information received from PWRD on 19/06/2022.   (Long - 0.000000, Lat - 0.000000),  Bori Pub Chariarpar Namghar to Khetri Dharmapur College via Kakatipara   Bori   Submerged 0.00-1500.00 ch. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000),  Khetri Dharmapur College to Tengabari   Tengabari   Submerged 0.00-2500.00 ch. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000),  L/B of River Burhadia from Kulbilghat Shiv Mandir to Lakhopur   Amoni &amp; Hatiputa   Breached at two places namely Amoni and Hatiputa. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000),  Bori Gopalthan to Kakatipara   Bori   Submerged ch 0.00 to 800.00 m. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000),  Jagara Barnibari road   Jagara   Submerged. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000),  Jagara Mukalmua Road   Jagara   Submerged. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000),  Dakshin Jagara to Shiva Mandir Road   Jagara   Submerged. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000),  Basudev Mandir to Bilpar Supa Road   Bilpar   Submerged. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000),  Sanimandal road to Gangapur PMGSY Pkg No. AS-20/107   Gangapur   Submerged. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000),  <b>Barbhag</b> - Uttam Chandra Barua Road   Malopara to Kamarkuchi   As per report submitted by dept on 22/06/2022   (Long - 0.000000, Lat - 0.000000),  Arikuchi to Bala via Bhagyadevi Sibir   Verious part of the road   As per report submitted by dept on 22/06/2022   (Long - 0.000000, Lat - 0.000000),  Karia Legta Gosai than road   Verious part of the road   As per report submitted by dept on 22/06/2022   (Long - 0.000000, Lat - 0.000000),  <b>Banekuchi</b> - Madhupur to Bihampur road   Madhupur   Ae reported by Gaon Pradhan on 18/06/2022 the road is submerged and damaged due to flood. length - 70 ft.   (Long - 0.000000, Lat - 0.000000),  Madhupur to Jawarddi PWD Road   Besimari   Ae reported by Gaon Pradhan on 18/06/2022 the road is submerged and damaged due to flood.   (Long - 0.000000, Lat - 0.000000),  Basanti Khola to Kalia Gosai Mandir Road   Kaithalkuchi   As per report of PWRD Department on 18/06/2022 the road is submerged and damaged due to flood. length - 2500 Mtr.   (Long - 0.000000, Lat - 0.000000),  BBT to Majgaon to Majgaon road   Banekuchi   As per report of PWRD Department on 18/06/2022 the road side berm and surface damaged due to flood. length - 1 KM   (Long - 0.000000, Lat - 0.000000),  <b>Barkhetri</b> - GALDIGHLA SC SUPA TO KUROBORI VILLAGE VIA MAJA MANDAL SUPA ROAD   GALDIGHLA   SUBMERGED LENGTH 900M as reported by AEE, PWRD, barkhetri</p>
--	--	--

			<p>Territorial Sub Div. on 22/06/2022   (Long - 0.000000, Lat - 0.000000), road from mukalmua jagra at darmon chowk to No1 Naptipara basic school   darmon chowk   submerged length 850m as reported by AEE, PWRD, barkhetri Territorial Sub Div. on 22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p>road from naptipara darmon namghar nayapuri than   darmon   submerged length 450 m as reported by AEE, PWRD, barkhetri Territorial Sub Div. on 22/06/2022   (Long - 0.000000, Lat - 0.000000),</p> <p><b>Nalbari</b> - sariyahtali to NH-31 road   sariyahtali   as per the report from PWRD, Division on 21.06.2022 above road are submerged   (Long - 0.000000, Lat - 0.000000)</p>
	Tamulpur	11	<p><b>Tamulpur</b> - Kekrikuchi to Niz-Kaurbaha Road.As Report Recieved from P.W.D Dept. on dated 22-06-2022.   Vill-Gopalpur   Road Hard Crust &amp; shoulded washed by 150m.   (Long - 91.644591, Lat - 26.548364),</p> <p>Singramari Road Pkg.no.AS2496..As Report Recieved from P.W.D Dept. on dated 22-06-2022.   Vill-Singramari   Road Washedout by 80m.   (Long - 91.598481, Lat - 26.744096),</p> <p>MRL07-Katahbari to Assamese Muslim Suba via Sapatol..As Report Recieved from P.W.D Dept. on dated 22-06-2022.   Vill-Katahbari.     (Long - 91.529276, Lat - 26.621621),</p> <p>MRL17-RD Road to Tamulpur Ghograpar PMGSY road via GhograparAs Report Recieved from P.W.D Dept. on dated 22-06-2022..   Vill-Ghograpar   Road Washedout by 50m.   (Long - 91.567478, Lat - 26.584490),</p> <p>RD Road to Namasudra LP School(Goodwill) ..As Report Recieved from P.W.D Dept. on dated 22-06-2022.   Vill-Ghograpar   Road Washedout by 700m.   (Long - 91.574715, Lat - 26.584490),</p> <p>T09 to Kalazar (PMGSY)..As Report Recieved from P.W.D Dept. on dated 22-06-2022.   Vill-Kalazar.   Road Washedout by 390m.   (Long - 91.503206, Lat - 26.730656),</p> <p>Angarkata -Darrangapar Road (PMGSY).As Report Recieved from P.W.D Dept. on dated 22-06-2022.   Vill-Angarkata   Road Washedout by 20m.   (Long - 91.536959, Lat - 26.724927),</p> <p>RD Road to 1 No Banguri(Goodwill) .As Report Recieved from P.W.D Dept. on dated 22-06-2022.   Vill-Banguri   Road Washedout by 20m.   (Long - 91.580102, Lat - 26.663632),</p> <p>Tamulpur -Goreswar Road to Sontala.As Report Recieved from P.W.D Dept. on dated 22-06-2022.   Vill-Sontala   Road Washedout by 20m.   (Long - 91.633306, Lat - 26.594928),</p> <p>BDT Road (PMGSY).As Report Recieved from P.W.D Dept. on dated 22-06-2022.   Vill-Tamulpur   Road Washedout by 4.5km.   (Long - 91.561010, Lat - 26.605720)</p>
	Udalguri	3	<p><b>Harisinga</b> - Chenipara Village road   Chenipara   The village road eroded due to overtopping of river Kulshi on 17/06/2022. (5m damaged)   (Long - 91.942200, Lat - 26.686500),</p> <p><b>Khairabari</b> - RUPAKHAT-CHARANPARA ROAD   At Latakhat   The RCC Slab culvert was damaged on 21.06.2022, due to the pressure exerted by the overflowing water. Length: 08 M (approx.)   (Long - 91.542000, Lat - 26.392100),</p> <p><b>Kalaigaon</b> - Sujal to Sujal Chouhans house via Garubandha Gomtha PMGSY link road   Khas Bokrajhar and Bokrajhar Bagisha   The road surface has completely damaged on 22/06/2022 due to erosion caused by overflowing of flood water from river Noa covering a length of 500 meters and breadth of 10 meters.   (Long - 91.951857, Lat - 26.546727)</p>
	Total	218	
Infrastructure Damaged - Bridge	District	Number	Details
	Bajali	12	<p><b>Bajali</b> - RCC Bridge no. 1/1. . Affected length is 10 m.   Ratanpur Bamakhata Road   This report is received from the AEE, PWD, Patacharkuchi TR Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),</p> <p>SPT BR no.2/1 Damaged   Bongaon to Kaskuri road   This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),</p> <p>RCC BR no.2/1, Approach damaged   Kucdigha to Maguri   Approach damaged by tihu river. This report is received rfrom the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),</p> <p>SCC BR no.2/2, Approach damaged   Kuchdigha to Maguri   Approach damaged by tihu river. This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),</p> <p>HPC Culvert no.3/1, has been damaged   Patcharcuchi Rampur road   This culvert has been damaged. This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Bridge app 6/1, has been damaged   Upar Noi Ulua   This bridge has been damaged. This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Culvert no. 3/2 app, has been damaged   Soibari Manikpur   This culvert has been damaged. This report is received rfrom the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),</p> <p>HPC Culvert no. 3/1, has been damaged   Soibari Manikpur   This culvert has been damaged. This report is received rfrom the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Bridge app 2/1, 5/1,6/1, has been damaged   Original Bamakhata Kenduguri road   This bridge has been damaged. This report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000),</p> <p>Bridge app 3/2 has been damaged   Bamakhata Kenduguri   This bridge has been damaged. This</p>

			report is received from the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000), Bridge app 1/1,1/2, 2/1, 2/2 has been damaged   Kuara to 3rd Km of Tihu Dumuni Road   These bridge has been damaged. This report is received rfrom the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000), RCC Bridge of Borola ghat has been damaged   Borola Ghat   This bridge has been damaged. This report is received rfrom the AE, PWD, Patacharcuchi TR, Sub-Division, Patshala on 21.06.2022   (Long - 0.000000, Lat - 0.000000)
	Dhemaji	2	<b>Dhemaji</b> - PWD Bamboo foot bridge connecting Gohain gaon to E&D Dyke   Gohain gaon to E&D Dyke   Today on 22/06/2022, Bamboo foot bridge connecting Gohain gaon to E&D Dyke, damaged at Ch. 3012.00m (Length-75.00m).   (Long - 94.606209, Lat - 27.487460), PWD Bamboo foot bridge connecting No1 Simaluguri to No 2 Borachira   No1 Simaluguri to No 2 Borachira   Today on 22/06/2022, Bamboo foot bridge connecting No1 Simaluguri to No 2 Borachira , damaged at Ch. 3012.00m (Length-75.00m).   (Long - 94.608412, Lat - 27.513200)
	Kamrup	2	<b>Kamalpur</b> - BLJC road Bridge no 2/1 at ch. 1600 M   BLJC road   Damage of 6 M spam RCC Bridge needs permanent restoration as per report of Asstt. Executive Engineer PWD Kamalpur Teritorrial road sub division Kamalpur on 21-06-2022   (Long - 26.441339, Lat - 91.755255), Muktapur Mornoipar Bridge   Muktapur   Settlement at one side & both side approach damaged. this was done by Muktapur panchyat.This is not under PWD R as per report of Asstt. Executive Engineer PWD Kamalpur Teritorrial road sub division Kamalpur on 21-06-2022   (Long - 26.423821, Lat - 91.749857)
	Nalbari	3	<b>Paschim Nalbari</b> - RCC Br. No. 1/1 on Chamata Kaithalkuchi road over Burhadia River at Sahpur.   Sahpur   Approach damage. Information received from PWRD on 20/06/2022   (Long - 0.000000, Lat - 0.000000), SRT at Bhoiraghol   Bhoiraghol   Damaged. Information received from PWRD on 20/06/2022.   (Long - 0.000000, Lat - 0.000000), <b>Banekuchi</b> - Ambari Supa To BBNG road   Burinagar   As per report of PWRD Department on 18/06/2022 the Wooden Bridge is damaged due to flood.   (Long - 91.432495, Lat - 26.484210)
	Udalguri	1	<b>Harisinga</b> - Dimakuchi Bogoritol RCC bridge   Dimakuchi   RCC bridge Dimakuchi Donbosco bridge breached around 3m on 18/06/2022   (Long - 91.832100, Lat - 26.774800)
	Total	<b>20</b>	
Infrastructure Damaged - Wildlife	<b>District</b>	<b>Wildlife affected under protected areas description</b>	
	Golaghat	<b>(Golaghat) At District</b> - Inundated Camps as on date: Agorotoli Range (out of 34 camps 8 are inundated), Kaziranga Range (out of 49 camps 8 are inundated). As per report received from the Eastern Assam Wildlife Divn., Bokakhat on 22-06-2022.	
	Morigaon	<b>Mayong</b> - Pobitora WLS out of a total 25nos of camps 17 camps are affected and 14 inundated aa reported by Range Officer PWLS on 22/06/22	
Infrastructure Damaged - Others	<b>District</b>	<b>Other Details</b>	
	Bajali	<b>Bajali</b> - Fisheries/Pond   Total nos of ponds affected 91 nos and total nos of water area (ha) affected 15.2 ha in 11 nos villages as on 21/06/2022	
	Baksa	<b>Baska</b> - Culvert Approach Road Damaged   Amarabati Doukhola slab culvert broken, at village Amarabati, on 18/6/2022, Coordinate: 26.663824, 91.355816, Irrigation Canal/Scheme Damaged   Garamdew FIS- D/S right bank with inlet structure (measuring 15 metres) is completely washed away and the U/S left side afflux bund (measuring 185 metres) of Garamdew FIS ,on 18/6/2022 Coordinate: 26.667582, 91.308555), Culvert Approach Road Damaged   Medhaghat to Choudhuritup Village approach Road slab culvert damage. 18/06/2022, Coordinate: 26.572458, 91.307666, Culvert Approach Road Damaged   Goldingpara (Ulubari supa) Village Road approach road slab culvert damage. 18.06.2022 Coordinate: 26.5877186, 91.298186, Culvert Approach Road Damaged   Palashguri Nathsupa Village Road - Slab culvert broken on 18/06/2022, Coordinate: 26.692122, 91.319418, Irrigation Canal/Scheme Damaged   Irrigation canal, Ahopa Mushlim Supa to PaniMudri Switch gate broken, 18/06/2022, Coordinate: 26.69378, 91.293401, Culvert Approach Road Damaged   Slab culvert approach road damaged near Garamdeo Buragohain house at village Garamdeo, date: 18/06/2022 , Coordinate: 26.672568, 91.31876., Culvert Approach Road Damaged   Garamdew to Bhehbari road near Garamdew High School slab culvert approach road damage at village Garamdew on 18/6/2022 Cordinate: 26.66918, 91.313838, Power Dept. Poles   Total LT Pole: 4, Total HT Pole: 1 , damaged on 21/06/2022 at village Pakhamara, Pamuapathar, and C Block., Power Dept. Transformers   2 nos of 25 KVA Transformer damaged at village Amarabati and Kolachawk on 21/06/2022 , <b>Barnagar RC part</b> - Culvert Approach Road Damaged   As per report received from Asst. Exe. Engineer, PWD Salbari (R&B) divn, Salbari on 21/06/2022Due to continuous Heavy Rainfall on Luasur to Bahbari road the 1 No HPC Culvert has been washed the approach both side is submerged and damaged and the road survice by the flood water, <b>Baganpara</b> - Culvert Approach Road Damaged   Dakhin Kolloipar to nizbarsiral connecting road has been breached approx 8m on dated 20/06/2022, latitude: 26.54038, longitude: 91.50316	
	Barpeta	<b>Sarthebari</b> - Anganwadi Centres Affected   20 1.107 kayakuchi pam-1 , 2.157 kayakuchi pam- 2, 3.109	

		<p>kayakuchi gaon -2, 4.155 kayakuchi gaon-4, 5.111 kayakuchi pathar -1, 6.113 kayakuchi pathar- 3 7.123 kapohartari -1, 8.177 kapahortari -3, 9. 211 kapohartari-4,10.121 gumirpathar -1,11.116 jalkara-1 ,12.-117 jalkara-2, 13.118 jalkara -3, 14.119 morichapathar -1, 15. 156 pub moricha pathar-2, 16. 120.panimoricha pathar -1, 17. 153 panimoricha pathar -2, 18. 125 Thakarpathar -1, 19. 131 thakar gaon -1, 20. 154 bhara gaon ,reported by CDPO pakabetbari .DATE-22-6-2022, Fisheries/Pond   6164 Nos. Date-22-6-2022, <b>Kalgachia</b> - Fisheries/Pond   As per report received frm Fishery dept on 22/06/22, total 1102 nos of ponds are submerged as on today within the circle, total Water area submerged-235.5 Ha., <b>Chenga</b> - Elementary Schools Damaged   Salmara Lahara Sar VLP school Village -Salmara,under Chenga Revenue Circle Washed away , report by BEEO,Chenga on 22/6/2022, Fisheries/Pond   Approx 170 nos. Tank affected reported by fishery deptt. On 22/6/2022</p>
	Bongaigaon	<p><b>Manikpur</b> - Fisheries/Pond   2 Nos of Pond. (1) 2 No Dhupuri- 2, <b>Srijangram</b> - Fisheries/Pond   Total 25 Nos of Pond. 1) Shimalbari Pt I-5 Nos, 2) Nasatra- 1 No, 3) Kokila -2 Nos, 4) Balarchar- 17 Nos. as per report received from DFDO, Bongaigaon adte 22.06.2022</p>
	Chirang	<p><b>Bijni</b> - Bridge Approach Road Damaged   As reported by PWD, Bijni(R&amp;B) Sub Division, bridge approaches eroded at RCC Bridge No 1/1 at 1st KM of Mongolian Bazar to Kathalguri road on 18-06-2022. Length=15 mtr, Breadth=5.00 mtr, Depth= 6.00 mtr. Longitude=90.629121 Latitude=26.54171, Bridge Approach Road Damaged   As reported by PWD, Bijni(R&amp;B) Sub Division, bridge approaches eroded at RCC Bridge No 1/1 at 1st KM of Mongolian Bazar to Kathalguri road on 18-06-2022. Length=5 mtr, Breadth=3.00 mtr, Depth= 5.00 mtr. Longitude=90.629121 Latitude=26.54171, Culvert Approach Road Damaged   As reported by PWD, Bijni(R&amp;B) Sub Division, approaches eroded at Box culvert No 1/1 (Culvert Size 4.00mx4.00m, 2-cell) at 1st KM of Noapara Katalguri Road on 18-06-2022. Length= 7.00 mtr Breadth=4.00 mtr Depth=5.00 mtr. Longitude=90.621078 Latitude=26.538065., Irrigation Canal/Scheme Damaged   As reported by Bijni Sub Division Irrigation, left side of embankment of Silbari-Ulubari FIS damaged at Bamunijhora on 15-06-2022. Length=30 mtr Breadth=5 mtr Depth= 2 mtr. Longitude=90.776862 Latitude=26.59427, Irrigation Canal/Scheme Damaged   As reported by Bijni Sub Division Irrigation, right side of canal of Panbari-Boulajhar damaged at No-2 Burisuta on 15-06-2022. Length=20 mtr Breadth=2 mtr Depth= 1.8 mtr. Longitude=90.838432 Latitude=26.60724, Irrigation Canal/Scheme Damaged   As reported by Bijni Sub Division Irrigation, left side canal damage at Bhatopara of No. 1 Deokumar FIS on 15-06-2022. Length=7 mtr Breadth=5 mtr Depth=2.6 mtr. Longitude=90.830794 Latitude=26.61475, Irrigation Canal/Scheme Damaged   As reported by Bijni Sub Division Irrigation, earthen canal damage at Bhatopara of No 2 Deokumar FIS on 15-06-2022. Length= 30 mtr, Breadth= 2 mtr Depth= 2 mtr. Longitude=90.813533 Latitude=26.59042, Irrigation Canal/Scheme Damaged   As reported by Bijni Sub Division Irrigation, up stream afflux bund damage at Asrabari of Bhawraguri Thaichobeel FIS on 15-06-2022. Length= 20 mtr Breadth=5 mtr Depth= 2.5 mtr. Longitude=90.664751 Latitude=26.56883.</p>
	Darrang	<p><b>Dalgaon</b> - Fisheries/Pond   as per report received from fishery department, fish farmers affected - 1780, water area - 428.9Ha, <b>Sipajhar</b> - Power Dept. Poles   4 Nos. pole Damage as on 22-06-2022, Power Dept. Conductors   4 Km Appox as on 22-06-2022, Fisheries/Pond   Fish farmers affected 2291 nos. and total area affected approx 123.4 Hect. as on 22-06-2022</p>
	Dibrugarh	<p><b>Chabua</b> - Elementary Schools Damaged   DODHIA KULIGAON LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 22/6/2022 N27 35.845 E95 13.227, Elementary Schools Damaged   DODHIA KARMI LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 22/6/2022 N 27 36.032 E95 14.787, Elementary Schools Damaged   DODHIA TENGABARI LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT. ON 22/6/2022 N27 36.652 E95 14.237, Elementary Schools Damaged   DODHIA CHALBIL LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT ON 22/6/2022 N27 36.462 E95 14.673, Elementary Schools Damaged   DODHIA CHALBIL LPS SUBMERGED AS PER INFORMATION RECEIVED FROM EDUCATION DEPT ON 22/6/2022 N27 36.462 E95 14.673, Anganwadi Centres Affected   DODHIA KULIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 22/6/2022 N27 35.845 E 95 13.227, Anganwadi Centres Affected   DODHIA TENGABARI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27 36.652 E95 14.237, Anganwadi Centres Affected   DODHIA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27 36.390 E95 13.651, Anganwadi Centres Affected   UPPER GEREKI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 22/6/2022 N27 33.942 E95 15.125, Anganwadi Centres Affected   DODHIA CHALBIL AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27. 5714 E95. 2346, Anganwadi Centres Affected   RONGMOLA AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27 33'33.40" E95 11'47.26", Anganwadi Centres Affected   UPPER GEREKI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT. ON 22/6/2022, Anganwadi Centres Affected   2 NO. MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27 33' 50.38" E95 13' 16.90",</p>

	<p>Anganwadi Centres Affected   MULUKGHAT MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27 33'52.36" E95 13'15.74",</p> <p>Anganwadi Centres Affected   TENGABARI-MIRIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27 33'52.88" E95 13' 14.42",</p> <p>Anganwadi Centres Affected   GEREKI NEPALI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27 33'50.76" E95 15'26.01",</p> <p>Anganwadi Centres Affected   KULIGAON AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/22 N27 35.860 E95 13.460,</p> <p>Anganwadi Centres Affected   DODHIA ROMAI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27 36.450 E95 13.782,</p> <p>Anganwadi Centres Affected   CHALBIL AISUNG CHAPORI AWC SUBMERGED AS PER INFORMATION RECEIVED FROM SOCIAL WELFARE DEPT ON 22/6/2022 N27 34.890 E95 13.563</p>
Dima-Hasao	<p><b>Haflong</b> - Power Dept. Poles   4 Pole structure damaged in between P.Leikul and Boljang village as per info received from APDCL dated 21/06/2022,</p> <p>Power Dept. Transformers   11 KV Laisong feeder charged upto P.Leikul as per info received from APDCL dated 21/06/2022</p>
Goalpara	<p><b>Rongjuli</b> - Fisheries/Pond   AS PER REPORT RECEIVED FROM FISHERIES DEVELOPMENT OFFICER, RANGJULI TD BLOCK 11 NOS. (APPRX) POND HAS BEEN SUBMERGED. INFORMATION RECEIVED DATE: 22/06/2022 TIME : 01:29 PM IST</p>
Hojai	<p><b>Lanka</b> - Road Breaches   (10800m of Kharikhana to Jugimukh dyke of kopili right Bank due to sudden slump down) on 17/06/2022</p>
Kamrup	<p><b>Rangia</b> - Elementary Schools Damaged   Baidyagarh MES &amp; Balagaon Arimatta LPS was damaged as per report of BEEO, Rangia on 21.06.2022,</p> <p><b>North Ghy</b> - Fisheries/Pond   Total water area= 263.7 Ha, Nos. of Pond Affected= 1552 No. as reported as reported by FDO, Bezera Fish dated 21/06/2022 on dated 21/06/2022ary Block,</p> <p><b>Kamalpur</b> - Fisheries/Pond   Due to incessant rainfall 345 ha as per report of Fisher Development officer under Kamalpur Block area on 21-06-2022</p>
Karimganj	<p><b>Patherkandi</b> - Washed away Culverts   As reported by AEE, PWD (T/R) on 19/06/22 a HP double barrel culvert on Bhubrighat road to Adamtilla washed away due to flood water. approx length of damage is 200 meter. gps coordinates are lat-24.61562, long-92. 277918</p>
Kokrajhar	<p><b>Bhawraguri</b> - Elementary Schools Damaged   AS REPORTED BY BLOCK ELEMENTARY EDUCATION OFFICER, GOSSAIGAON ON 22-06-2022 THAT DUE THE HEAVY RAINFALL AND FLOOD SINCE 14TH JUNE TO TILL DATE PASCHIM ASHARIKANDI LPS WAS PARTIALLY DAMAGED,</p> <p>Elementary Schools Damaged   AS REPORTED BY BLOCK ELEMENTARY EDUCATION OFFICER, GOSSAIGAON ON 22-06-2022 THAT DUE THE HEAVY RAINFALL AND FLOOD SINCE 14TH JUNE TO TILL DATE HONGSHOBIL M E S WAS PARTIALLY DAMAGED,</p> <p>Elementary Schools Damaged   AS REPORTED BY BLOCK ELEMENTARY EDUCATION OFFICER, KACHUGAON ON 22-06-2022 THAT DUE THE HEAVY RAINFALL AND FLOOD SINCE 14TH JUNE TO TILL DATE NO. 2 D. MUSALMANPARA MES (NP)WAS PARTIALLY DAMAGED</p>
Lakhimpur	<p><b>Subansiri</b> - Bamboo Foot Bridge   As reported by the Dhakuakhana Territorial Road Division, Ghilamara, the Bamboo Bridge at 1st KM on Kaligaon to Napam Kaligaon Road is damaged (L= 150M) on 21/06/2022,</p> <p>Fisheries/Pond   Fishery affected at Mohbol, Bordoibam, Gadangarchuk and Bangkeleng area. Total Farm family affected 27 nos and area- 6.09 Ha as reported by FDO, Dhakuakhana on 21/06/2022,</p> <p><b>Dhakuakhana</b> - Fisheries/Pond   0.28 Hectare Ponds/Tanks affected on 22nd June, 2022 (1 number family)  Report submitted by Fishery Development Officer, Dhakuakhana.</p>
Morigaon	<p><b>Mayong</b> - PWSS Damaged   Baha pahar PWSS dtw gr4 quater submerged as reported by PHE , Morigaon on 21/06/22,</p> <p>PWSS Damaged   Thengbhanga PWSS submerged as reported by PHED Morigaon on 21/06/2022,</p> <p><b>Morigaon</b> - Fisheries/Pond   (21-06-2022) As per Fishery Dev Officer (Mayong), 10 nos. of pond affected due to flood.</p>
Nagaon	<p><b>Nagaon</b> - Irrigation Canal/Scheme Damaged   Dakargaht (Rt), Alengi satra Kolonpar,Submeged/damaged-Pumhouse reported by Nagaon Sub-Division (Irrigation ) Nagaon, dated-22/06/2022,</p> <p>Irrigation Canal/Scheme Damaged   Dakargaht (Left)hatigargaon,bamungaon, Fatachuk, Submeged/damaged-Pumhouse &amp; Command area reported by Nagaon Sub-Division (Irrigation ) Nagaon, dated-22/06/2022 ,</p> <p>Irrigation Canal/Scheme Damaged   Majulipathar, 1 &amp; 2No. jalah, Submeged/damaged- Pumhouse &amp; Command area reported by Nagaon Sub-Division (Irrigation ) Nagaon, dated-22/06/2022 ,</p> <p>Irrigation Canal/Scheme Damaged   Jalah DTWS,Alapia Bebejia,Submeged/damaged- Pumhouse &amp; Command area reported by Nagaon Sub-Division (Irrigation ) Nagaon, dated-22/06/2022 ,</p> <p>Irrigation Canal/Scheme Damaged   Dewdhar DTWS, ranthali Rajabheti,Submeged/damaged- Pumhouse &amp; Command area reported by Nagaon Sub-Division (Irrigation ) Nagaon, dated-22/06/2022 ,</p> <p>Irrigation Canal/Scheme Damaged   Bebejia to Mohmoria DTWS2 points, Sukatiputa Lumati,Submeged/damaged- Pumhouse &amp; Command area reported by Nagaon Sub-Division (Irrigation ) Nagaon, dated-22/06/2022 ,</p> <p>Irrigation Canal/Scheme Damaged   Solar Powered MDTW schme at Dakhinpat,dakhinpat, kampur,Submeged/damaged- Pumhouse &amp; Command area reported by Nagaon Sub-Division (Irrigation ) Nagaon, dated-22/06/2022 ,</p> <p>Irrigation Canal/Scheme Damaged   Tulshimukh DTWS , Tulshimukh Kuchgaon ,Submeged/damaged-Pumhouse &amp; Command area reported by Nagaon Sub-Division (Irrigation ) Nagaon, dated-22/06/2022 ,</p>

		Irrigation Canal/Scheme Damaged   TW Points under PMKSY HKKP, Phase-1, Submerged/damaged-Total Points-930 reported by Nagaon Sub-Division (Irrigation ) Nagaon, dated-22/06/2022
Nalbari		<p><b>Tihu</b> - Anganwadi Centres Affected   42 AWC CENTER SUBMERGED .THE DATE OF SUBMERGED :17/06/2022.INFORMATATION RECEIVED FROM CDPO,TIHU ICDS PROJECT.,</p> <p><b>Paschim Nalbari</b> - Handloom &amp; Textile Dept   18 nos. weavers family affected. Damage of loom accessories, woven cloths etc. Information received from handloom and textile dept. on 22/06/2022,</p> <p>Irrigation Canal/Scheme Damaged   Solmara DTWI Point No. 3, Niz Tapa DTWIS point No. 1 &amp; 2, Uttar Amoni MDTWS, Chamata Belsor DTWIS Point No. 1, 2,7 &amp; 8 are affected badly by flood water from 14/06/2022 to 21/06/2022. Information received from Irrigation department on 21/06/2022.,</p> <p>Power Dept. Poles   5 nos. of pole damaged due to heavy rainfall at Gangapur, Goalpara and Bhattasupa. Information received from APDCL Department on 16/06/2022.,</p> <p><b>Ghograpar</b> - Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Chatma Chamarkuchi DTWIS(Point No. 1) at Village Poichara has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Chatma Chamarkuchi DTWIS(Point No. 2) at Village Patkata has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Chatma Chamarkuchi DTWIS(Point No. 3 &amp; 7) at Village Kundargaon has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Chatma Chamarkuchi DTWIS(Point No. 4) at Village Datarra has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Chatma Chamarkuchi DTWIS(Point No. 5) at Village Dhurkuchi has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Chatma Chamarkuchi DTWIS(Point No. 8) at Village Nimua Latima has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Dalbari koniha FIS at Village Dalbari koniha has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Pub Barsiral DTWIS Village Pub Barsiral has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Namati MDTWIS at Village Namati has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Balitara MDTWIS at Village Balitara has been affected,</p> <p>Irrigation Canal/Scheme Damaged   As per report received from Irrigation Department, on 21/06/2022 Barlechakona FIS at Village Sonkuriha has been affected,</p> <p><b>Barbhag</b> - Irrigation Canal/Scheme Damaged   Chatama Chamarkuchi DTWIS ( Point No 6) Dated: 21/06/2022, Irrigation Canal/Scheme Damaged   Chatma FIS, Dated: 21/06/2022,</p> <p>Irrigation Canal/Scheme Damaged   Baharghat ELIS ( Garakhia than oint),Dated: 21/06/2022 ,</p> <p>Irrigation Canal/Scheme Damaged   Baharghat ELIS ( Hatimari point), Dated: 21/06/2022,</p> <p>Irrigation Canal/Scheme Damaged   Deharkuchi DTWIS, Dated: 21/06/2022,</p> <p>Irrigation Canal/Scheme Damaged   Deharkuchi MDTWIS, Dated: 21/06/2022,</p> <p><b>Banekuchi</b> - Culvert Approach Road Damaged   Ae Per Report of PDRD Department, Kashimpur to Burinagar Culvert approach, Side berm damaged dated: 18/06/2022 ,</p> <p>Culvert Approach Road Damaged   Ae Per Report of PDRD Department, Kendukuchi to Haripur Culvert approach damaged dated 18/06/2022 ,</p> <p>Culvert Approach Road Damaged   Ae Per Report of PDRD Department, Sariahtalitoli to Chaplekuchi Culvert approach road damaged Dated : 18/06/2022,</p> <p>Culvert Approach Road Damaged   Ae Per Report of PDRD Department, Banekuchi Kathalbari Road Surface Side Berm Damaged Dated: 18/06/2022,</p> <p>Culvert Approach Road Damaged   Ae Per Report of PDRD Department, Jayanta Path to Janopar Road Surface Side Berm Damaged Dated: 18/06/2022,</p> <p>Culvert Approach Road Damaged   Ae Per Report of PDRD Department, Kashimpur to Merkuchi Culvert No 6/1 Damaged ,</p> <p><b>Barkhetri</b> - Damaged SPT Bridge   no 1/1 at sapkata petrolpump to kandhbari via kuror par road, length 18 m as reported by AEE, PWRD, barkhetri Territorial Sub Div. on 22/06/2022,</p> <p>Sericulture Deptt. Damaged   26 nos rearing families affected, eri food plants farm 0.5 acre with green fenching, rearing crops of eri silk worm Date: 22/06/2022,</p> <p><b>Nalbari</b> - Culvert Approach Road Damaged   Sariahtali to NH-31 culvert damaged as per the report of PWRD received on 21.06.2022</p>
Sonitpur		<p><b>Dhekiajuli</b> - Washed away Culverts   As reported by PWD, Dhekiajuli div. surging water of canal have washed away HP Culvert no 4/2 along Batashipur to Abhoi Centre road at Hijuguri. date 18/6/22,</p> <p>Fisheries/Pond   As reported by Fishery Borsola, 6.40ha in Sirajuli Pathar, 7.60ha in Goroimari Pathar, 6.13ha in Molanpukhuri and 5.73ha in Ino Bosasimalu affected. date 22/6/22,</p> <p><b>Tezpur</b> - Fisheries/Pond   Dated: 22/06/2022. As reported by Dist. Fishery Dev. Officer, Tezpur, 5.10 Ha. approx W/A Fish ponds inundated in Rajbharal &amp; Da-Parbatia.</p>
South Salmara		<b>Mankachar</b> - Elementary Schools Damaged   As per report received from BEEO,Mankachar, floor of 144No. Charbari Pt-II LP School has been partially damaged due to erosion on 22/06/2022
Tamulpur		<p><b>Goreswar</b> - Irrigation Canal/Scheme Damaged   1. FIS from Puthimari river at Deosunga affected as reported by Irrigation department on 22/06/2022.,</p> <p>Irrigation Canal/Scheme Damaged   Pub Gayabari FIS as reported on 22/06/2022, by irrigation department guide bund and afflux bund damaged due to flood water,</p>

		Irrigation Canal/Scheme Damaged   Suklai irrigation project, as reported by irrigation department on 22/06/2022 breaching and breaking of left afflux bund at Village Bholajhar
	Udalguri	<b>Harisinga</b> - Power Dept. Poles   LT and HT poles at village Rajagarh SSB camp, NC Bhutiachang damaged and 33kv pole washed away Kachubil on 21/06/2022. under Tangla electrical sub-division, Power Dept. Conductors   Conductors were snapped at Rajagarh SSB camp on 21/06/2022 under Tangla electrical sub-division, Irrigation Canal/Scheme Damaged   1. Khatowalpara FIS canal totally submerged and full siltation at canal from river kulshi on 20-06-2022, (Long- 91.9317, Lat- 26.6991) (2)Kulshi FIS is totally submerged at Chamuapara village on 20-06-2022. (Long- 91.9395, Lat- 26.6799) (3) Dayalu burha FIS canal embankment breached about 80m at ch,150 m on 20-06-2022, (Long- 91.9685, Lat- 26.7034)
Erosion	<b>District</b>	<b>Details</b>
	Baksa	<b>Baska</b> - Saru Manikpur Major Supa   Erosion at Sarumanikpur Majorsupa village, approx 5 meter on 18/06/2022   0, <b>Jalah</b> - Dangrigoan   At Dangrigoan village ,approx 800 meter of river bank of Kaldia river is under erosion seen on 21-06-2022.   0
	Biswanath	<b>Biswanath</b> - Rowmari   Severe bank erosion is observed at Rowmari area on the R/ bank of the river Buroi of length 1000.00m on 22-06-2022   0
	Bongaigaon	<b>Manikpur</b> - Nagarjhar Agril Bundh Approach road 40 mtr,(26.45589/90.752835)Erosion to place in Bashbari no 2 approach road 5 mtr. & Agril bundh 50 mtr .erosion continues. date-22.06.2022   Erosion atook Place due to River Aie 39 ft. Date-22.06.2022/ Erosion Due to Aie River 200 mtr. Date -22.06.2022   2200, <b>Srijangram</b> - Santoshpur Part II, Santoshpur part III, Balachar Part III   Santoshpur part II: occurred on 21.06.22 in lenth of 700 m on river bank of Aie -Manas. Family affected 8 nos. (Pop:52) Lat- 26.317688, Long- 90.747889, Erosion: occurred on 21.06.22 in length of 1000 m approx on river Bank of Aie-Manas.Family affected :10 nos.(58 population) Long- 26.747884 Lat- 26.317688 .Erosion Balarchar Part III families affected 5 nos. (Pop :27) occurred on 21.06.22 . Length: 250 m.   137
	Chirang	<b>Bijni</b> - No-1 Malipara, Pub Khamarpara(Bagorgaon Bazar), Alengmari   As reported by LM, erosion of agriculture land observed at No 1 Malipara due to Naodraguri canal (tributary of Khanamakra river). Length=1200 mtr(Approx) Breadth=100 mtr(Approx) Depth=10 mtr(Approx). Date of occurrence=20-06-2022. As reported by LM, erosion going on at Pub Khamarpara(Bagorgaon Bazar). Length= 25 mtr(approx), Breadth=15 mtr(approx) Depth=4 mtr. Longitude=90.746573 Latitude= 26.533309 Date of Occurrence=22-06-2022. As reported by LM, erosion occurred on 22-06-2022 at Alengmari. Length=12 mtr(approx) Breadth=8 mtr (approx) Depth= 3 mtr (Approx). Length= mtr(Approx), Breadth= mtr(Approx) Depth= mtr(Approx). Longitude= 90.746549 Latitude= 26.533148.   0
	Dhubri	<b>Golakganj</b> - North Tokrerchara Pt-I   Erosion took place at North Tokrerchara Pt-I under Golakganj Revenue Circle on 20-6-2022. In this incident 2 number of houses shifted to another place. Land eroded 1 Bigha-2.5 Katha-0Lessa   10, <b>Agamoni</b> - village Baghdokra Under Kamandanga GP   • Name of the village: Baghdokra Under Kamandanga GP. • Date of Incident: 16/06/2022 to 21/06/2022. • Time: 3.00 PM. • GPS Co-ordinates: Lat: 26.351746, Long: 89.815013 • Land: 0B-2K-10L. • Population and household damage: No damage till date.   0
	Kokrajhar	<b>Bhawraguri</b> - Rimijhimighop, Tazpur, Asharikandi, Panijani Pt I   AS REPORTED BY IN CHARGE CONTROL ROOM GOSSAIGAON WATER RESOURCE SUB-DIVISION, GOSSAIGAON ON DATED 22/06/2022 1. SEVERE BANK EROSION OBSERVED AT VILLAGE RIMIJHIMIGHOP OF RIVER GONGIA ON L/B LENGTH 400M. 2. SEVERE BANK EROSION OBSERVED AT VILLAGE TAZPUR OF RIVER MODATI ON R/B LENGTH 250M. 3. SEVERE BANK EROSION OBSERVED AT VILLAGE ASHARIKANDI OF RIVER JOYMA ON L/B LENGTH 400M. 4. SEVERE BANK EROSION OBSERVED AT VILLAGE PANIJANIGHOP OF RIVER JOYMA.   0, <b>Gossaigaon</b> - No.2 Khokshaguri, Simlabari   1. As report received from WRD Gossaigaon on 22.06.2022 Due to Heavy rain severe Bank Erosion observed at Village No.2 Khokshaguri of River Sankosh on L/B Length 500M(.) 2. As report received from WRD Gossaigaon on 22.06.2022 Due to Heavy rain severe Bank Erosion observed at Village Simlabari of Rive Sonkosh on L/B Length 550M (.)   0
	Lakhimpur	<b>Bihpuria</b> - 1)Dikrong L/B embankment of Bongalmora PGR, 2) Bongali Gaon near Dikrong R/B embankment   1)Active erosion observed at 14th KM of Dikrong L/B embankment of Bongalmora PGR since 21/06/2022 as reported by WRD, Bihpuria SD.(Long-93.926657, Lat- 27.056568) 2) Erosion occurring near Dikrong R/B embankment at Bongali gaon since 21/06/2022. As reported by concerned LM on about 15 Bigha of land has been eroded. (Long-93.94143, Lat-26.99793)   0, <b>North Lakhimpur</b> - Joyhing morasali and Ghunasuti area   Old agriculture bund at Joyhing was damaged (L-800 Mtr) and Balibheta AWC washed away due to erosion by river Subansiri as reported by WR, NLP on 22/06/2022   0
	Majuli	<b>Ujani Majuli</b> - Jaborchuk Kathani, Maj Gejera, Namoni Gejera   Erosion occurred at Jaborchuk Kathani gaon on 21/06/2022. Latitude- 27.135847, Longitute- 94.492791 Erosion occurred at Maj Gejera on 21/06/2022. Latitude-27.123845, Longitute- 94.45581 Erosion occurred at Namoni Gejera on 21/06/2022. Latitude-27.118456, Longitute- 94.442865   0
	Morigaon	<b>Laharighat</b> - Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori   As per report received from the Water Resources dept on 22-06-2022, erosion is observed in areas like Leruamukh, Goroimari , Bhajaikhati gaon & Barchapori with maximum erosion of 1 m in Leruamukh, 1 m in Goroimari , 4 m in Bhajaikhati gaon & 7 m in Barchapori   0, <b>Morigaon</b> - 1) 2 no Gunamara, 2) Mulankata (21-06-2022)   1) As per PWD (Roads), The bridge approaches of road Morigaon Fire Station to Azarbari via Morakolong road Br.No.4/1 near 2 no Gunamara is under severe



		erosion, disturbing the protection work of the approaches. 2) As per PWD (Roads), severe erosion and damages of both shoulder and Hard crust of the Road from NH-37 to Mulankata Adarsha gaon from 750 to 1400 M approx.   0
	Nalbari	<b>Ghograpar</b> - Pub Barsiral   As per information received from W.R Department, heavy erosion have seen at L/B of river Pagladiya on 22/06/2022 at Village Pub Barsiral (Nakhat), Length- 250M   0
	Udalguri	<b>Harisinga</b> - 1.Kukurakata (2)ward no2, (3)Pub Paneri (4) Bhergaon village (5) Uttar Naobandha (6) Ward No.2 (house of Anjali Basumatary)   1.erosion occurred at kukurata village due to current of the river Nonoi. immediate restoration needed. approximate erosion 300m, long-91.9018, Lat-26.6568 on 21/06/2022. (2)Erosion occurred at Ward no2, due to Nyka river on 19/06/2022. (100m eroded) Lat-26.3937 Long-91.5436. (3) Due to heavy rainfall and overtopping of river Kulshi erosion occurred at Pu-panery village around 71m on 19/06/2022. Lat-26.7312 Long-91.9295. (4) Erosion at Bhergaon village due to overflow of river Kulshi on 19/06/2022. 7.9m eroded. Lat-26.7304 Long-91.9325 (5)Due to heavy rainfall at Uttar Naobandha caused the damaged of brick canal and guide bundh of the existing work. "Land developement Project at uttar Naobandha paddy field" on 20/06/2022. ( 35m Brick canal, 30m earthen embankment) lat-26.7179 long-91.7406. (6) erosion occurred at Ward No.2 due to overflow of Pub Nalbari Dong house at the Anjali basumatary. on 21/06/2022. (30/50ft) Lat-26.3944 Long-91.5445   0, <b>Udalguri</b> - Khusurabari   Severe gully erosion at Khusurabari village around 70m on 21.06.2022.   0, <b>Khairabari</b> - Buduragaon (Near Jogen Rava's Paddy field)   Sever erosion is seen at Buduragaon due to broken earthen embankment near Jogen Rava's Paddy field. Length & Breadth: 300 & 25 M (approx.) Date : 20.06.2022   25
Landslide	<b>District</b>	<b>Details</b>
	Dima-Hasao	<b>Haflong</b> - Bethany, Haflong   Landslide at Bethany village, Haflong due to heavy rainfall as per info received from local dated 22/06/2022   0
	Karimganj	<b>Badarpur</b> - BARTHAL, TAJURTHAL, ANGLAR BAZAR   ON 19/06/2022 DUE TO INCESSANT RAINFALL MULTIPLE LANDSLIDE REPORTED AT VARIOUS LOCATIONS OF BARTHAL, TAJURTHAL, ANGLAR BAZAR RESULTING 40 NOS. OF HOUSES WERE SEVERELY AFFECTED   210
Urban Flood	<b>District</b>	<b>Details</b>
	Cachar	<b>Silchar</b> - Linkroad, National Highway road point, Ambicapatty, Church Road, Chandicharan Road, Bilpar, Public School Road, Subhas Nagar, Sonai Road, N.S. Avenue, Premtala, Chengkuri Rood, Malugram, Kanakpur, Tarapur , Itkhola, Ghoniala, Meherpur, Public School Road,   Due to incessant rainfall, the closure of sluice gates, and over-topping of Embankments in many areas in and around Silchar Town on dated 22.06.2022   15501
	Darrang	<b>Mangaldoi</b> - Ward No-2 Ward No-4   The water logging due to river Bega is receding dated as on 22-06-2022   8000
	Goalpara	<b>Lakhipur</b> - Lakhipur Town Ward No. 1,2,3,4,5,6,8,9&10   Due to urban flood in Lakhipur Town Ward No. 1,2,3,4,5,6,8,9&10 got affected. The Date Of occurrence of urban flood on 16.06.2022 to till date i.e 22.06.2022   5127
	Karimganj	<b>RK Nagar</b> - Ward No.1,2,3,4,6,7   Total 306 Nos families affected from date 18-06-2022 to 22-06-2022   1560
	Morigaon	<b>Morigaon</b> - NABHETI, WARD NO 9   On dtd. 21-06-2022, as per Lot Mondol overflow of floodwater has reached Nabheti Ward no 9 of Morigaon Revenue Town.   1320