

Assam Daily Flood Report as on 24-05-2022 at 4:00 PM

Assam Daily Flood Report as on 24-05-2022 at 4:00 PM			
Particulars	Situation as on 24-05-2022 (in last 24 hours)		
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above danger level	Kopili (Dharamtul/Kampur)	
	Rivers flowing above highest flood level	Nil	
District Affected	<b>No. of Districts Affected</b>	<b>Name of Flood Affected Districts</b>	<b>Name of Urban Flood Districts</b>
	18	Barpeta, Cachar, Darrang, Dima-Hasao, Goalpara, Golaghat, Hailakandi, Hojai, Jorhat, Kamrup, Kamrup (M), Karbi Anglong West, Karimganj, Lakhimpur, Morigaon, Nagaon, Nalbari, Sonitpur	
No. Of Revenue Circles Affected	45		
Name Of Revenue Circles Affected	<b>District</b>	<b>Total</b>	<b>Revenue Circle</b>
	Barpeta	4	Sarthebari, Kalgachia, Baghbar, Chenga
	Cachar	5	Katigora, Silchar, Lakhipur, Udharbond, Sonai
	Darrang	3	Patharighat, Mangaldoi, Dalgaon
	Dima-Hasao	1	Haflong
	Goalpara	5	Matia, Lakhipur, Dudhnoi, Balijana, Rongjuli
	Golaghat	2	Bokakhat, Khumtai
	Hailakandi	1	Algapur
	Hojai	3	Hojai, Doboka, Lanka
	Jorhat	1	Jorhat West
	Kamrup	7	Hajo, Rangia, Chaygaon, Kamalpur, Nagarbera, Chamaria, Boko
	Kamrup (M)	2	Chandrapur, Sonapur
	Karbi Anglong West	1	Donkamokam
	Karimganj	2	Karimganj, Badarpur
	Lakhimpur	1	Bihpuria
	Morigaon	2	Mayong, Morigaon
	Nagaon	3	Kampur, Nagaon, Raha
	Nalbari	1	Barkhetri
	Sonitpur	1	Dhekiajuli
		<b>Total</b>	<b>45</b>
Villages Affected	<b>District</b>	<b>Total</b>	<b>Revenue Circle</b>
	Barpeta	113	( Sarthebari   28 ), ( Kalgachia   25 ), ( Baghbar   43 ), ( Chenga   17 )
	Cachar	328	( Udharbond   20 ), ( Katigora   142 ), ( Lakhipur   48 ), ( Sonai   35 ), ( Silchar   83 )
	Darrang	8	( Patharighat   4 ), ( Dalgaon   1 ), ( Mangaldoi   3 )
	Dima-Hasao	50	( Haflong   50 )
	Goalpara	253	( Matia   39 ), ( Dudhnoi   1 ), ( Rongjuli   15 ), ( Balijana   75 ), ( Lakhipur   123 )
	Golaghat	4	( Bokakhat   1 ), ( Khumtai   3 )
Hailakandi	2	( Algapur   2 )	

Hojai	7	(Hojai   3 ), ( Doboka   2 ), ( Lanka   2 )
Jorhat	1	( Jorhat West   1 )
Kamrup	93	( Rangia   4 ), ( Hajo   23 ), ( Chaygaon   3 ), ( Kamalpur   24 ), ( Nagarbera   18 ), ( Chamaria   19 ), ( Boko   2 )
Kamrup (M)	24	( Chandrapur   13 ), ( Sonapur   11 )
Karbi Anglong West	1	( Donkamokam   1 )
Karimganj	5	( Karimganj   3 ), ( Badarpur   2 )
Lakhimpur	12	( Bihpuria   12 )
Morigaon	220	( Mayong   124 ), ( Morigaon   96 )
Nagaon	247	( Nagaon   66 ), ( Kampur   96 ), ( Raha   85 )
Nalbari	1	( Barkhetri   1 )
Sonitpur	5	( Dhekiajuli   5 )
<b>Total</b>	<b>1374</b>	

Population And Crop Area Affected	District	Male	Female	Children	Total Population	Population Details	Crop Area ( in Hect. )	Crop Area Details
	Barpeta	0	0	0	0	( Sarthebari   0 ), ( Kalgachia   0 ), ( Chenga   0 ), ( Baghbar   0 )	1238.50	( Sarthebari   44.50 ), ( Kalgachia   196.00 ), ( Chenga   135.00 ), ( Baghbar   863.00 )
	Cachar	77233	59855	40866	177954	( Katigora   85724 ), ( Silchar   31931 ), ( Lakhipur   33526 ), ( Udharbond   6102 ), ( Sonai   20671 )	5915.00	( Katigora   3125.00 ), ( Silchar   1268.00 ), ( Lakhipur   223.00 ), ( Udharbond   146.00 ), ( Sonai   1153.00 )
	Darrang	2105	1614	1407	5126	( Patharighat   644 ), ( Mangaldoi   4482 ), ( Dalgaon   0 )	2618.50	( Patharighat   149.50 ), ( Mangaldoi   2469.00 ), ( Dalgaon   0.00 )
	Dima-Hasao	1396	1582	1826	4804	( Haflong   4804 )	0.00	( Haflong   0.00 )
	Goalpara	0	0	0	0	( Lakhipur   0 ), ( Balijana   0 ), ( Matia   0 ), ( Dudhnoi   0 ), ( Rongjuli   0 )	15413.00	( Lakhipur   10060.00 ), ( Balijana   2270.00 ), ( Matia   2259.00 ), ( Dudhnoi   86.00 ), ( Rongjuli   738.00 )
	Golaghat	0	0	0	0	( Bokakhat   0 ), ( Khumtai   0 )	32.00	( Bokakhat   15.00 ), ( Khumtai   17.00 )
	Hojai	675	430	269	1374	( Hojai   555 ), ( Doboka   198 ), ( Lanka   621 )	267.00	( Hojai   46.00 ), ( Doboka   0.00 ), ( Lanka   221.00 )
	Jorhat	0	0	0	0	( Jorhat West   0 )	18.00	( Jorhat West   18.00 )
	Kamrup	130	46	40	216	( Chaygaon   0 ), ( Nagarbera   0 ), ( Chamaria   0 ), ( Rangia   0 ), ( Hajo   0 ), ( Kamalpur   216 ), ( Boko   0 )	4598.35	( Chaygaon   50.00 ), ( Nagarbera   1496.00 ), ( Chamaria   1680.00 ), ( Rangia   16.00 ), ( Hajo   1235.25 ), ( Kamalpur   52.10 ), ( Boko   69.00 )
	Kamrup (M)	0	0	0	0	( Chandrapur   0 ), ( Sonapur   0 )	1154.50	( Chandrapur   948.00 ), ( Sonapur   206.50 )
	Karbi Anglong West	250	268	291	809	( Donkamokam   809 )	0.00	( Donkamokam   0.00 )
	Karimganj	1098	1119	413	2630	( Karimganj   2420 ), ( Badarpur   210 )	0.00	( Karimganj   0.00 ), ( Badarpur   0.00 )
	Lakhimpur	0	0	0	0	( Narayanpur   0 ), ( Bihpuria   0 )	211.00	( Narayanpur   0.00 ), ( Bihpuria   211.00 )
	Morigaon	16052	15588	9301	40941	( Mayong   0 ), ( Morigaon   40941 )	14429.83	( Mayong   10179.00 ), ( Morigaon   4250.83 )
	Nagaon	149573	135923	60795	346291	( Kampur   231211 ), ( Nagaon   30370 ), ( Raha   84710 )	17473.24	( Kampur   7691.00 ), ( Nagaon   3681.00 ), ( Raha   6101.24 )

	Nalbari	0	0	0	0	( Barkhetri   0 ), ( Paschim Nalbari   0 )	673.00	( Barkhetri   673.00 ), ( Paschim Nalbari   0.00 )		
	Sonitpur	0	0	0	0	( Dhekiajuli   0 )	57.00	( Dhekiajuli   57.00 )		
	<b>Total</b>	<b>248512</b>	<b>216425</b>	<b>115208</b>	<b>580145</b>		<b>64098.92</b>			
Relief Camps / Centres Opened	<b>District</b>	<b>Total</b>	<b>Relief Camp</b>			<b>Relief Distribution Centres</b>				
	Barpeta	1	0(Sarthebari   0)			1(Sarthebari   1)				
	Cachar	407	284(Katigora h   100, Sonai   23, Silchar   161, Udharbond   0, Lakhipur   0)			123(Katigora h   65, Sonai   27, Silchar   9, Udharbond   6, Lakhipur   16)				
	Darrang	6	0(Mangaldoi   0, Dalgaon   0)			6(Mangaldoi   3, Dalgaon   3)				
	Dima-Hasao	25	11(Haflong   11)			14(Haflong   14)				
	Goalpara	2	0(Balijana   0, Lakhipur   0)			2(Balijana   1, Lakhipur   1)				
	Hailakandi	1	1(Algapur   1)			0(Algapur   0)				
	Hojai	4	4(Hojai   2, Doboka   2)			0(Hojai   0, Doboka   0)				
	Kamrup	1	0(Kamalpur   0)			1(Kamalpur   1)				
	Karbi Anglong West	1	0(Donkamokam   0)			1(Donkamokam   1)				
	Karimganj	11	2(Badarpur   2, Karimganj   0)			9(Badarpur   0, Karimganj   9)				
	Morigaon	15	3(Morigaon   3)			12(Morigaon   12)				
	Nagaon	54	41(Nagaon   25, Kampur   9, Raha   7)			13(Nagaon   13, Kampur   0, Raha   0)				
<b>Total</b>	<b>528</b>	<b>346</b>			<b>182</b>					
Inmates In Relief Camps	<b>District</b>	<b>Total</b>	<b>Revenue Circlewise</b>			<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Pregnant / Lactating Mother</b>	<b>Person with Disability</b>
	Cachar	62478	(Katigora h   33475), (Silchar   18694), (Udharbond   0), (Sonai   10309)			26372	21169	14869	47	21
	Dima-Hasao	621	(Haflong   621)			213	244	164	0	0
	Hailakandi	238	(Algapur   238)			90	78	70	0	0
	Hojai	434	(Doboka   198), (Lanka   0), (Hojai   236)			231	150	52	1	0
	Karimganj	24	(Karimganj   0), (Badarpur   24)			7	4	10	3	0
	Morigaon	105	(Mayong   0), (Morigaon   105)			47	38	20	0	0
	Nagaon	17812	(Nagaon   10865), (Kampur   5387), (Raha   1560)			8314	6389	2922	184	3
	<b>Total</b>	<b>81712</b>				<b>35274</b>	<b>28072</b>	<b>18107</b>	<b>235</b>	<b>24</b>
Human Lives Lost - Confirmed	<b>District</b>	<b>Total</b>	<b>Male</b>	<b>Female</b>	<b>Children</b>	<b>Revenue Circlewise</b>				
	Cachar	1	1	0	0	(Katigora h   0), (Lakhipur   0), (Silchar   0), (Sonai   0), (Udharbond   1)				
	Nagaon	1	1	0	0	(Kampur   1), (Nagaon   0), (Raha   0)				
	<b>Total</b>	<b>2</b>	<b>2</b>	<b>0</b>	<b>0</b>					
Human Lives Lost Confirmed - Death Type	<b>District</b>	<b>Total</b>	<b>Flood Death</b>	<b>General Drowning (Non Flood)</b>	<b>Landslide</b>					
	Cachar	1	1	0	0					
	Nagaon	1	1	0	0					
	<b>Total</b>	<b>2</b>	<b>2</b>	<b>0</b>	<b>0</b>					
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
Animals Affected	<b>District</b>	<b>Total</b>	<b>Big</b>	<b>Small</b>	<b>Poultry</b>					
	Barpeta	18905	9929	5476	3500					

	Cachar	98469	82679	15790	0					
	Darrang	2430	1500	700	230					
	Goalpara	1250	720	530	0					
	Morigaon	79331	29063	18127	32141					
	Nagaon	108927	60365	30879	17683					
	Nalbari	94	24	30	40					
	<b>Total</b>	<b>309406</b>	<b>184280</b>	<b>71532</b>	<b>53594</b>					
Animals Washed Away	<b>District</b>	<b>Total</b>	<b>Big</b>	<b>Small</b>	<b>Poultry</b>					
	Cachar	7	7	0	0					
	<b>Total</b>	<b>7</b>	<b>7</b>	<b>0</b>	<b>0</b>					
Houses Damaged	<b>District</b>	<b>Fully Kuccha</b>	<b>Fully Pukka</b>	<b>Fully Total</b>	<b>Partially Kuccha</b>	<b>Partially Pukka</b>	<b>Partially Total</b>	<b>Others Huts</b>	<b>Others Cattle Shed</b>	<b>Others Total</b>
	Cachar	2197	990	3187	25507	12540	38047	0	0	0
	Hojai	18	0	18	7	0	7	0	3	3
	<b>Total</b>	<b>2215</b>	<b>990</b>	<b>3205</b>	<b>25514</b>	<b>12540</b>	<b>38054</b>	<b>0</b>	<b>3</b>	<b>3</b>
Rescue Operation	<b>District</b>	<b>Agency</b>			<b>Boats Deployed</b>	<b>Person Evacuated By Boats</b>	<b>Animal Evacuated By Boats</b>	<b>Helicopters Deployed</b>	<b>Person Evacuated By Helicopters</b>	<b>Medical Team Deployed</b>
	Cachar				0	0	0	0	0	9
	Lakhimpur				0	0	0	0	0	1
	Morigaon				0	0	0	0	0	4
	Nagaon	SDRF			2	0	0	0	0	17
	Nalbari	Circle Office/Local Administration			11	0	94	0	0	0
	<b>Total</b>				<b>13</b>	<b>0</b>	<b>94</b>	<b>0</b>	<b>0</b>	<b>31</b>
Relief Distributed	<b>District</b>	<b>Rice (in Q)</b>	<b>Dal (in Q)</b>	<b>Salt (in Q)</b>	<b>M. Oil (in L)</b>	<b>Cattle Feed - Green Fooder (in Q)</b>	<b>Cattle Feed - Wheat Bran (in Q)</b>	<b>Cattle Feed - Rice Bran (in Q)</b>		
	Barpeta	0.00	0.00	0.00	0.00	0.00	37.95	0.00		
	Cachar	760.00	279.90	112.77	6051.95	0.00	7819.14	0.00		
	Darrang	0.00	0.00	0.00	0.00	0.00	0.00	404.30		
	Dima-Hasao	54.77	0.00	0.30	336.00	0.00	0.00	0.00		
	Goalpara	0.00	0.00	0.00	0.00	0.00	93.41	0.00		
	Hailakandi	1.29	0.24	0.07	7.00	0.00	0.00	0.00		
	Hojai	13.00	1.95	0.60	38.00	0.00	0.00	52.00		
	Kamrup	3.65	0.65	0.20	20.00	0.00	0.00	0.00		
	Karbi Anglong West	12.81	2.43	0.73	72.81	0.00	0.00	0.00		
	Karimganj	41.09	7.38	2.21	221.31	0.00	0.00	0.00		
	Morigaon	45.37	8.10	2.43	0.00	0.00	250.00	0.00		
	Nagaon	85.71	15.20	4.56	0.00	0.00	505.00	0.00		
	<b>Total</b>	<b>1017.69</b>	<b>315.85</b>	<b>123.87</b>	<b>6747.07</b>	<b>0.00</b>	<b>8705.50</b>	<b>456.30</b>		
Relief Distributed Others	<b>District</b>	<b>Baby Food Liquid</b>		<b>Baby Food Solid</b>		<b>Others</b>				
	Barpeta	0.00-Q		0.00-Q						
	Cachar	0.00-Q		0.00-Q		Soybean -1593.55-Kg; Candle-920.00-Pkt; Match Box-920.00-Pkt; Potato -2251.00-Kg; Mortien -445.00-Pkt; 0-0.00-Q; Mortien-475.00-Pkt				
	Darrang	0.00-Q		0.00-Q						
	Dima-Hasao	0.00-Q		0.00-Q		0-0.00-Q				
	Goalpara	0.00-Q		0.00-Q						
	Hailakandi	0.00-Q		0.00-Q						
	Hojai	0.00-Q, 48.00-L		0.00-Q		Tarpaulin -300.00-Pieces; Chira -7.50-Q; Tarpaulin-540.00-				

				Pieces; Water -1020.00-L; Biscuits -1080.00-Pkt; Bleaching Powder -35.00-Pkt; Phenyl-35.00-Pieces; Candle-4.00-Pkt; Gur-1.00-Q
	Kamrup	0.00-Q	0.00-Q	
	Karbi Anglong West	0.00-Q	0.00-Q	
	Karimganj	217.00-Pkt	0.00-Q	0-0.00-Q
	Morigaon	0.00-Q	0.00-Q	
	Nagaon	0.00-Q	0.00-Q, 83.00-Kg	TARPULIN-780.00-Pieces; TUBE WELL-13.00-Pieces; TOILET-4.00-Pieces; BATH ROOM-1.00-Pieces
Infrastructure Damaged - Embankment Breached	<b>District</b>	<b>Number</b>	<b>Details</b>	
	Barpeta	2	<b>Sarthebari</b> - Panchyat Bundh of Burhadia river   Kalatali Pathar   Damaged at near Tanuram Deka 39 house approx. 10 m. and in front of Manab Deka 39, Kiran Kalita, Bhumidhar Deka, Pabitar Deka and Ratan Kalita house approx. 30 m. ( reported by LM 24.05.2022), Panchayat Bundh of Burhadia river   Kalatali Pathar   Damaged approx. 12 Ft. near PWD road ( reported by LM, 24.05.2022)	
	Total	2		
Infrastructure Damaged - Embankment Affected	<b>District</b>	<b>Number</b>	<b>Details</b>	
	Dibrugarh	1	<b>Dibrugarh East</b> - GUIDE BANDH AT BEHEI CHETIA - 6 AT DOWNSTREAM MOHONAGHAT   THE BANK IS DAMAGED DUE TO RAIN WATER REPORTED MOHONAGHAT UNDER EAST REV CIRCLE AS ON 21-05-2022. DAMAGED LENGTH - 500M. GPS CO-ORDINATE:- 27°28'25.13" N/ 94°53'8.48" E to 27°28'12.91"N/ 94°52'57.64E. AS PER REPORT RECEIVED FROM ASSISTANT EXECUTIVE ENGINEER DIBRUGARH EAST W.R. SUB-DIVISION.	
	Nalbari	1	<b>Barbhag</b> - L/B of river Pagaldaia from N.T. road to Bijulighat   At Ch. 27 k.m. L/B at village Dhaniagog   Due to incessant rainfall the water level of river Pagladia was rising , as a result erosion occurs. Dated: 24/05/2022	
Total	2			
Infrastructure Damaged - Road	<b>District</b>	<b>Number</b>	<b>Details</b>	
	Barpeta	10	<b>Barpeta</b> - T-09 to Khandarpar PMGSY Road.   khandarpar   Road surface &amp; Shoulders damaged at 1st &amp; 2nd Km Reported by PWDR, Date-23/05/2022 , Kayakuchi Village Road   kayakuchi   Road surface with Shoulders damaged at 1st to 6th Km &amp; approaches of RCC Br.No.1/1,2/2,3/1 &amp; 4/1) damaged Reported by PWDR, Date-23/05/2022, Pohumara RCC Bridge to Bhokamari Road   Pahumara   The Road shoulders damaged at 1st Km Reported by PWDR, Date-23/05/2022, Jarabari Kamalpur Pam PMGSY Road   jarabari   Shoulders damaged in stretches at 1st &amp; 2nd Km Reported by PWDR, Date-23/05/2022, <b>Sarthebari</b> - Tihu Lachima Road to Dr. Jinaram Das Road   Kalatali   Road submerged and breached at different locations(5nos. stretches), Reported by JE, PWD Road on 24.05.2022, Naligaon to Bhaktardoba PMGSY Road   Naligaon-Bhaktardoba   Road surface with shoulders badly damaged (Reported by JE, PWD Road on 24.05.2022), Village Road of Kapahartari Tiniali to Jalkara   Kapahartari   damaged at near Kutub Ali house to Sarbesh Ali House approx. 10 ft ( reported by LM, 24.05.2022), Kawaimari 9 No. Block and 8 No. Block connecting Village road   Kawaimari 9 No. Block   Damaged the culvert at near Anowar Hussain house to Fakirsan house approx. 20 m ( reported by LM,24.05.2022), Hatirtari to Kharma Road via Kohinoor MEM under PMGSY Pkg. No. AS-010195   Hatirtari   Shoulder damaged from 1st to 3rd Km. (reported by JE, PWD Road,24.05.2022), <b>Chenga</b> - 1. Roumari Pathar to Nodir par Road submerged   Roumari Pathar   Side berm eroded, a portion of the road at end point washed away by the river Brahmaputra ( approx length 10.00m ) occurred on 23/5/2022 reported by PWD deptt.	
	Cachar	2	<b>Silchar</b> - Chincoorie Nayagram Road   Nayagram   Chincoorie Nayagram Road from CH.0.00M to CH.900.00 M (In Stretches) average Depth 120.00 CM as per report received from AEE PWD Silchar T Road Division, Silchar on 24.05.2022, Mother Terressa Road   Mother Terressa Road   Mother Terressa Road from CH.280.00 CH to CH 2100.00 M Average Depth 90.00 CM as per report received from AEE PWD Silchar T Road Division, Silchar on 24.05.2022	
Dima-Hasao	28	<b>Haflong</b> - Haflong Jating Road   Haflong   Subsidence of Road (i) at 4th Km, L= 200.00m (ii) at 5th Km, L=130, (Total L=330.00m) Land slide, R/wall washed away, culvert damaged, Road Surface washed away, as per the information received from PWD (R&B) on 22-05-2022, Haflong Lower haflong Road   Lower Haflong   Subsidence of Road at 3rd Km, L=200.00m, Land slide R/wall culvert washed away, Road surface damaged as per the information received from PWD (R&B) on 22-05-2022,		

		<p>PGHJ By-Pass Road   Near Junu Nalla   Subsidence of Road stretch, L=200.00m, Land slide, Culvert washed out, Surface damaged, as per the information received from PWD (R&amp;B) on 22-05-2022, Lower Haflong to Wari Road (PGHJ Road)   Near Dayang Bridge   Subsidence of Road (i) Near Dayang Br, L= 50.00m, (ii) Near Junu Nalla, L=250.00m, Sontila to Gurubari L= 6000m (Total L= 6300.00m) Land slide, Culvert damaged, Road surface washed away, as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Dibarai to Lower Haflong via Jaikang   Dibarai to Lower Haflong via Jaikang, Haflong   Road embankment subsided 200 m, Heavy landslide at different stretches, settlement of surface &amp; Bituminous surface damage, as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Wari to Dehangi (PGHJ Road)   Wari to Dehangi (PGHJ Road)   Landslide, felling of trees, drain blockage, culvert damage, as per the information received from PWD (R&amp;B) on 22-05-2022, Dehangi to Umrangso (PGHJ Road)   Dehangi to Umrangso (PGHJ Road)   Dehangi to Umrangso (PGHJ Road), as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Natun Gunjung North Bagetar New Hospital Road   Natun Gunjung North Bagetar New Hospital Road,   Natun Gunjung North Bagetar New Hospital Road, as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Ram Nagar Natun Basti Road   Ram Nagar Natun Basti Road   Land slide, Road surface damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Devasthan Mandir Road   Devasthan Mandir Road, Haflong   Land slide, R/wall washed away, Road surface damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Kalibari Approach Road   Kalibari Approach Road, Haflong   Land slide, Drain blocked, Road surface damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>DPLH Road   DPLH Road   Land slide, Drain blocked, Road surface washed away, R/wall &amp; Culvert damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Civil Hospital Road   Civil Hospital Road, Haflong   Land slide, R/wall washed away, Road surface damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>HJMB Road   HJMB Road   Land slide, Culvert damaged, Road surface washed away, R/wall damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Old Kubing to Mongon Road   Old Kubing to Mongon Road   Heavy landslide, Damage of Breast wall, Box Culvert, Bituminous Surface as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Haflong Mission Road   Haflong Mission Road, Haflong   Land slide, R/wall &amp; Road surface damaged, culvert damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>T05 to Hokai HC Road   T05 to Hokai HC Road   Land slide, Road surface damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Bagetar New Hospital Road   Bagetar New Hospital Road, Haflong   Culvert damaged, Road surface washed away as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Songpijang Village Road   Songpijang Village Road, Haflong   Land slide, Road surface damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Natun Gunjung Bagetar Road   Natun Gunjung Bagetar Road, Haflong   Land slide, Drain damaged, Road surface damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Natun Kunjung Dibarai Road   Natun Kunjung Dibarai Road, Haflong   Natun Kunjung Dibarai Road as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>KK Hojai Approach Road   KK Hojai Approach Road, Haflong   Land slide, surface damaged as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Topodisa village Approach Road   Topodisa village Approach Road, Haflong   Stretch of road washed away, Land slide as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Dimalik Village Approach Road   Dimalik Village Approach Road, Haflong   Landslide, Culvert damage slide as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>PWD 3rd Colony Approach Road   PWD 3rd Colony Approach Road, Haflong   Complete damage of Road surface as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Kalibari Muolhoi Road   Kalibari Muolhoi Road, Haflong   Kalibari Muolhoi Road as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Gunjung Maibang Road   Gunjung Maibang Road   Gunjung Maibang Road as per the information received from PWD (R&amp;B) on 22-05-2022,</p> <p>Sangbar Thingdol Dimainu Road   Sangbar Thingdol Dimainu Road   Landslide, erosion as per the information received from PWD (R&amp;B) on 22-05-2022</p>
	Goalpara	<p>5</p> <p><b>Lakhipur</b> - Silapani to Takimari (Bamboo Bridge)   Near Takimari   The approach Bamboo Bridge of PWD Department Silapani to Takimari affected 0.35 KM by overflowing of Rain Water as on 23.05.2022 to till date i.e. 24.05.2022. Report received from PWD (Roads),</p> <p>Dhumerghat to Garojan Road   Near Dhumerghat Chariali   The approach Road of PWD Department Dhumerghat to Garojan affected 0.30 KM by overflowing of Rain Water as on 23.05.2022 to till date i.e. 24.05.2022. Report received from PWD (Roads),</p> <p>Gossaidubi Shialkanda Road   Near Gossaidubi   The approach Road of PWD Department Gossaidubi Shialkanda road affected 0.30 KM by overflowing of Rain Water as on 23.05.2022 to till date i.e. 24.05.2022. Report received from PWD (Roads),</p> <p>Khakilamari To Dhamor Road   Near Dhamor From CH. 0.00 M To CH. 700.00 M   The approach Road of PWD Department Khakilamari to Dhamor Road affected 0.70 KM by overflowing of Rain</p>

			Water as on 23.05.2022 to till date i.e. 24.05.2022. Report received from PWD (Roads), <b>Balijana</b> - Lower Chotipara to Bodahapur   Lower Chotipara   Date of occurrence- 21.05.2022 Length/dimension- Length affected 0.080 KM Average depth of submergence- nil Traffic not disrupted 2 nos. of culver app. damaged Report received from Department- Dudhnoi and Goalpara Territorial Road Div. Date and time of information received- 23.05.2022 at 07.09 pm
Hailakandi	3		<b>Katlicherra</b> - Katlicherra Veterbond under Katlicherra Rev. Circle dtd. 22.05.2022   2nd   Damage due to over tapping of Runoff water, Harisnagar Boldaboldi under Katlicherra Rev. Circle dtd. 22.05.2022   1st,2nd,3rd,4th,5th,6th,7th,&8th, km   Damage due to Runoff water, Jhalnacherra to Gharmura Road under Katlicherra Revenue Circle dtd. 22.05.2022   1st & 2nd km   Submerged
Hojai	26		<b>Hojai</b> - NH-54 to Sildubi road at 9th km affected due to flood water on dated 16/05/2022   Vill- Komorakata forest village   As per report received from PWD Department, Hojai Division, Raikata Islampur road affected on dated 16/05/2022   Vill- Raikata Islampur   As per report received from PWD Department, Hojai Division, Amtola to Dighalbal road affected on dated 16/05/2022   Vill- Pachim Amtola   As per report received from PWD Department, Hojai Division, Brajapur to Barafuti Road affected on dated 16/05/2022   Vill- Barafuti   As per report received from PWD Department, Hojai Division, T-08 Solmarijan to Ashinagar road affected on dated 16/05/2022   Vill- Solmarijan   As per report received from PWD Department, Hojai Division, Uttar Bidyanagar to Rajbari road affected on dated 16/05/2022   Rajbari   As per report received from PWD Department, Hojai Division, Rajbari to kenduguri road affected on dated 16/05/2022   Kenduguri   As per report received from PWD Department, Hojai Division, Kenduguri to Hayong Gaon road affected on dated 16/05/2022   vill- Hayong Gaon   As per report received from PWD Department, Hojai Division, Radhanagar to Kumurakata road is affected on dated 16/05/2022   Vill- Radhanagar   As per report received from PWD Department, Hojai Division, Hojai tumpreng road to Dighalbal road is affected on dated 16/05/2022   Vill- dighalbal   As per report received from PWD Department, Hojai Division, Borhula to Nahar gaon road is affected on dated 16/05/2022   Borhula   As per report received from PWD Department, Hojai Division, Jugijan Bazar to borhula road is affected on 16/05/2022   Jugijan Bajar   As per report received from PWD Department, Hojai Division, Kenduguri to west hatimara road is affected on 16/05/2022   Hatimara   As per report received from PWD Department, Hojai Division, Kenduguri RN part 2 road is affected on 16/05/2022   kenduguri part 2   As per report received from PWD Department, Hojai Division, Kenduguri to Toradubi road is affected on 16/05/2022   Toradubi   As per report received from PWD Department, Hojai Division, Shivpur village road is affected on 16/05/2022   Shivpur   As per report received from PWD Department, Hojai Division, Nabhanga Kalimandir road is affected on 16/05/2022   Nabhanga   As per report received from PWD Department, Hojai Division, Rajbari to Sangkha devi road is affected on 16/05/2022   Rajbari   As per report received from PWD Department, Hojai Division, Hojai Tumpreng to 1 no kumurakata road is affected on 16/05/2022   kumurakata   As per report received from PWD Department, Hojai Division, Rajbari to nabhanga road is affected on 16/05/2022   Nabhanga   As per report received from PWD Department, Hojai Division, Hojai Tumpreng road to 2 no kumurakata road is affected on 16/05/2022   2 no kumurakata   As per report received from PWD Department, Hojai Division, Hojai Tumpreng road to Kumurakata forest village road is affected on 16/05/2022   Kumurakata forest village   As per report received from PWD Department, Hojai Division, Pub bogori to Pachim bogori road is affected on 16/05/2022   Pachim bogori   As per report received from PWD Department, Hojai Division, Hojai Mubarak basti to pachim nilbagan road is affected on 16/05/2022   Nilbagan   As per report received from PWD Department, Hojai Division, Amtola to dighalbal road is affected on 16/05/2022   Dighalbal   As per report received from PWD Department, Hojai Division, Singimari to bishnupur road is affected on 16/05/2022   Bishnupur   As per report received from PWD Department, Hojai Division
Karimganj	1		<b>Badarpur</b> - Badarpur Adarkuna Road PKG No--13-331   Adarkuna   On 19-05-2022, Asstt Executive Engineer, PWRD, Badarpur Territorial Road Sub Division, Badarpur reported damaged to the said road at Ch- 17060 m where the culvert No 18/1 has been breached subway
Morigaon	8		<b>Mayong</b> - Road Submerged 04M35 to Gabhura Tup Pather   5th km   As reported by PWD District Territorial Road Division on 23/05/22, Hatibhangi to Barmuri Pather   Package number AS 17-38   length ch-30.00m to ch 1200.00m

			<p>submerged as reported by PWD District Territorial Road Division on 24/05/22,  <b>Morigaon</b> - NH-37 to Mulankata Adarsha Gaon Road (24-05-2022)   Mulankata Adarsha Gaon   Received from PWD TERRITORIAL ROAD DIVISION, Temporary Restoration and Road Safety measures taken at erosion on NH-37 to Mulankata Adarsha Gaon Road.,  Pachatia to Azarbari via Morakolong road (24-05-2022)   Pachatia, Morigaon   Received from PWD TERRITORIAL ROAD DIVISION, Pachatia to Azarbari via Morakolong road under submergence,  Baghara to Damal road (24-05-2022)   Baghara-Damal, Morigaon   Baghara to Damal road under submergence at different stretches.,  Ino Morakolong to Tarani Kalbari road (24-05-2022)   Baghara pathar   Ino Morakolong to Tarani Kalbari road submerged by flood water.,  Pachim Meruagaon Koroibari Road (24-05-2022)   Pachim Meruagaon   Pachim Meruagaon Koroibari Road under submergence by flood water.,  Fire station- Azarbari Road (24-05-2022)   Azarbari   Fire station- Azarbari Road under submergence at different stretches.</p>
	Nagaon	11	<p><b>Kampur</b> - singimari to sitalmari Road   Kampur   Bridge approached of RCC bridge No.1/1 on singimari to sitalmari Road L-75 m submerged/eroded, reported by PWD Raha Territorial Road Sub-division Dtd-23.05.2022,  Kachua PWD Road to Alitangani   Kachua   Bridge approached of RCC bridge No.1/1 on Alitangani jan on road from Kachua PWD Road to Alitangani Vill L-50 m submerged/eroded, reported by PWD Raha Territorial Road Sub-division Dtd-23.05.2022,  Rajaali to Alitangani   Kampur   Road from Rajaali to Alitangani submerged/damaged L-2000 M reported by PWD Raha Territorial Road Sub-division Dtd-23.05.2022,  Borchila to Udmari   Kampur   Road from Borchila to Udmari submerged/damaged L-3500 M reported by PWD Raha Territorial Road Sub-division Dtd-23.05.2022,  Jhungthung No 1 to uttar Ameri   Kampur   Road from hungthung No 1 to uttar Ameri submerged/damaged L-1000 M reported by PWD Raha Territorial Road Sub-division Dtd-23.05.2022,  Kathiatoli to kampur Road (SH-17)   Kampur   Breach occurred at 6th KM of Kathiatoli Amlokhi Road (Kathiatoli to kampur Road (SH-17)) L-40M, Reported by Barhampur Territorial Road sub-division Dtd-23.05.2022,  <b>Nagaon</b> - Nagaon, Dakhinpat, Kampur road   Nagaon Sadar   The read Nagaon, Dakhinpat, Kampur,(SH-18), CH-13.00KM to CH-16.00KM Submerged/damaged reported by PWD Nagaon Territorial Road Sub-Division Dtd-22.05.2022,  <b>Raha</b> - DIGHALI ATI TO CHAPARMUKH   DIGHALI ATI   DATE OF OCCURENCE- 23/05/2022 SUBMERGED/ERODED- 1800 M (APPROX) DEPTT-RAHA TERRITORIAL ROAD SUB DIVISION,  NH-27 TO DUBARITOLI   DUBARITALI   DATE OF OCCURENCE- 23/05/2022 SUBMERGED- 1500 M (APPROX) DEPTT-RAHA TERRITORIAL ROAD SUB DIVISION,  LAOPANI TO MORTENG PATRHAR   LAOPANI   DATE OF OCCURENCE- 23/05/2022 SUBMERGED/ERODED- 2050 M (APPROX) DEPTT-RAHA TERRITORIAL ROAD SUB DIVISION,  PHULAGURI TO UTTAR PETBORHA   GARMUR   DATE OF OCCURENCE- 23/05/2022 SUBMERGED/ERODED- 15 M (APPROX) DEPTT-RAHA TERRITORIAL ROAD SUB DIVISION</p>
	Udalguri	7	<p><b>Mazbat</b> - Baligaon to Bathabari road   Baligaon   the road connecting Baligaon to Bathabari near Natun Panbari LP School and health centre has been damaged on 22/5/2022. The road communication has been disrupted for all kinds of pedestrians and vehicular traffics. Length- 5m(approx),  Borigaon Digholipar to Chungabudhi road   Borigaon Digholipar   The road connecting Borigaon Digholipar to Chungabudhi has been damaged on 22/5/2022. The road communication has been disrupted for all kinds of pedestrians and vehicular traffics. Length- 5m(approx),  <b>Kalaigaon</b> - Tezialpara to Jhilkapara connecting road.   Napatipara   Two row HPC culvert has damaged resulting in breach of the road on 24/05/2022 due to overflow of flood water from river Noa covering a length of around 12 meters and breadth of 7.5 meters.,  Tezialpara to Jhilkapara connecting road.   Naptipara   One row HPC culvert has damaged resulting in breach of the road on 24/05/2022 due to overflow of flood water from river Noa covering a length of around 8 meters and breadth of 5 meters.,  No 3 Barkola Bagisha to No 2 Barkola Bagisha connecting road.   Barkola Bagisha   The HPC culvert has damaged resulting in breach of the road on 24/05/2022 due to overflow of flood water from river Noa covering a length of 10 meters and breadth of 5 meters.,  Punia Bazar to Kalaigaon connecting road   Bardowaneza   The road has severely eroded due to heavy current of river Laljhora in the R/B of the river on 24/05/2022 covering a length of around 100 meters and breadth of 10 meters,  Doloipara to Bez Bhagati connecting road   Doloipara   The road has breached in the both side of a HPC culvert on 24/05/2022 due to heavy pressure of rain water in the paddy field covering a length of around 6 meters and breadth of 3.5 meters</p>
	Total	<b>101</b>	
Infrastructure Damaged - Bridge	<b>District</b>	<b>Number</b>	<b>Details</b>
	Barpeta	1	<b>Sarthebari</b> - Burikhamar Bazar to Kaljahi   Burikhamar Bazar   Road shoulders and approaches of SPT Br. No.1/1 damaged ( 1st & 2nd Km.) ( reported by JE, PWD, 24.05.2022)
	Total	<b>1</b>	



Infrastructure Damaged - Wildlife	District	Wildlife affected under protected areas description
Infrastructure Damaged - Others	Morigaon	<b>Mayong</b> - Pobitora Wild Life Sanctuary No of Camps Affected - 8nos No of Camp inundated - 1nos as reported by Forest Ranger Pobitora WLS on dtd.24/05/22
	District	<b>Other Details</b>
	Cachar	<p><b>Katigora</b> - Handloom &amp; Textile Deptt   Village : Sewti, Burunga, Lakhipur, Kalain, Mahadevpur, Total 820 No. weaver House Hold, Total 538 No. of Loom and 580.40 Kg Yarn damage, as per the report received from Handloom &amp; Textile department Cachar, as on 24.05.2022, Health Sub-Centre   Gangapur Sc, Lathimara-I Sc, Lathimata-II HWC, Chandinagar HWC, Zabda SC, Baraitali SC, Digabor SC, Khelma HWC, Saidpur HWC, Gumra MSC, Mohadevpur HWC., Nayagram SC, Jalapur BPHC, Digorkhal MPHC, as per thr report received from JDHS Cachar, as on 19.05.2022, <b>Silchar</b> - Power Dept. Poles   46 Nos. of LT Pole damage due to Flood report received from AGM, APDCL, Silchar on 23.05.2022, Power Dept. Poles   27 Nos. of HT Pole damage due to Flood report received from AGM, APDCL, Silchar on 23.05.2022, Power Dept. Transformers   25 KVA Transformers = 4 Nos., 63 KVA Transformers = 4 Nos, 100 KVA Transformer = 4 Nos, 250 KVA Transformer = 2 Nos. of damage due to Flood report received from AGM, APDCL, Silchar on 23.05.2022, Health Sub-Centre   Jaroiltola SC, Durgapur SC, Bhubaneswa Bagar HWC, Hierbond SC, Dudpur SC, Hilara SC, Nayagram SC, Simultola SC, Borkhola BPHC, Srikona FW SC, Chanpur, Kashipur SC as per the report received from JDHS Cachar as on 19.05.22, Handloom &amp; Textile Deptt   Village : Dudpatil, Kalinagar, Bhairabbari, Chengcoorie, Tarapur Total 206 No. weaver House Hold, Total 103 No. of Loom and 301.90 Kg Yarn damage, as per the report received from Handloom &amp; Textile department Cachar, as on 24.05.2022, <b>Lakhipur</b> - Veterinary Deptt Infrastructure   Village : Nayagram, Sriber, Pailapool, Choto Mamda, Dighli, Bahadurpur, Lakhicherra, Lakhipur, Pallorbond, Kaptanpur, Rupaibari Total 545 No. weaver House Hold, Total 308 No. of Loom and 519 Kg Yarn damage, as per the report received from Handloom &amp; Textile department Cachar, as on 24.05.2022, Health Sub-Centre   Digli HWC, Diglang Sc, Dugripur SC, Gangapur SC as per the report received from JDHS Cachar as on 19.05.2022, <b>Udharbond</b> - Veterinary Deptt Infrastructure   Rongpur, Madhugram, Bahadurpur, Gossaipur, Louthai, Total 194 No. weaver House Hold, Total 87 No. of Loom and 237 Kg Yarn damage, as per the report received from Handloom &amp; Textile department Cachar, as on 24.05.2022, Public Health Centre (PHC)   Rongpur PHC as per report received from JDHS Cachar as on 19.05.22, Health Sub-Centre   Rongpur SC, Bahadurpur, Gossaipur, Durganagar SC, Chalitakandi SC, Masughat SC, Dudhpatil-V Sc, Lanjitilla SC as per report received from JDHS Cachar as on 19.05.22, Power Dept. Transformers   11KV line around 1km from Maruacherra to Sabaspur nearer to the bank of Jatinga river completely damaged as on 24.05.22, Power Dept. Poles   20 nos Electric pole damage under Underbond Rc as on 24.05.22, <b>Sonai</b> - Veterinary Deptt Infrastructure   Mongalpur, Gobindapur, Dakhin Krishnapur, Badripur, Boali, Kochudorom Total 250 No. weaver House Hold, Total 85 No. of Loom and 221 Kg Yarn damage, as per the report received from Handloom &amp; Textile department Cachar, as on 24.05.2022, Public Health Centre (PHC)   SONAI PHC NSC as per report received from JDHS, Cachar as on 19.05.22, Health Sub-Centre   Dholai BPHC, Amjurghat SC, Gobindanagar SC, Kaptanpur SC, Boromamda SC, Swadhin Bazar Sc, Natun Ramnagar SD NSC, Jharagoole Sc, Mangalpur SC, Dakhinmohanpur SC, Dhanipur SC, Satkarakandi SC, Jhanjarbali SC, Sonabarighat SHC NSC, Rengti SC, Dhamalia SC, Uttar Krishnapur PT-II, Chandpur SC, Singari SC, Natun Kanchanpur HWC , as per report received from JDHS, Cachar as on 19.05.22</p>
	Hojai	<p><b>Hojai</b> - Anganwadi Centres Affected   Vill- Dankipathar , Biswaspara , AWC centre is damaged on dated 20/05/2022 with GPS Coordinates 26.029 N and 92.862766 E, Elementary Schools Damaged   Vill- Siddeswarpur , Siddeswarpur LP School floor and toilet damaged on 19/05/2022 with GPS Coordinates 26.02455 N and 92.76321 E, Elementary Schools Damaged   Vill- Ashinagar , School-Ashinagar MEM , damaged floor and kitchen on dated 20/05/2022 with GPS Coordinates , Elementary Schools Damaged   Vill- Jugijan Gaon, School- Pcahim Jugijan LPS, damaged partially on dated 19/05/2022 with GPS Coordinates 26.17654 N and 92.6435 E, Elementary Schools Damaged   Vill- Barofuti, Jugirpar LPS, damaged floor and toilets on dated 19/05/2022 with GPS Coordinates 26.4321 N and 92.56743 E, Elementary Schools Damaged   Vill- Borpukhuri, Fakaruddin Ali LPS, damaged floor and office room on dated 19/05/2022 with GPS Coordinates 26.5432 N and 92.77651 E, Elementary Schools Damaged   Vill- Hayong Gaon, School - Hayong Gaon LPS is partially damaged on dated 19/05/2022 with GPS Coordinates 26.6976 N and 92.7854 E, Elementary Schools Damaged   vill- Pub Bogori, Pub Bogori LPS is partially damaged on dated 19/05/2022 with GPS Coordinates 26.075913 N and 92.807604 E, Elementary Schools Damaged   Vill-Shibpur, Shibpur Nanath Singram LPS is damaged partially on dated 20/05/2022 with GPS Coordinates 26.0680 N and 92.7885 E, Elementary Schools Damaged   Vill- Taradubi , 2 no Taradubi LPS is partially damaged on dated 19/05/2022 with GPS Coordinates 26.0751 N and 92.730797 E</p>
Morigaon	<p><b>Morigaon</b> - Health Sub-Centre   (24-05-2022) Santipur HWC partially submerged by flood water., Health Sub-Centre   (24-05-2022) Telahi HWC partially submerged by flood water., Health Sub-Centre   (24-05-2022) Damal Sub Centre partially submerged by flood water.</p>	

	Nagaon	<p><b>Nagaon</b> - Irrigation Canal/Scheme Damaged   Dakarghat (RT), Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022 ,  Irrigation Canal/Scheme Damaged   Dakarghat (Left), Pump House And Command area, Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022 ,  Irrigation Canal/Scheme Damaged   Majuli Pathar DTW, Pump House And Command area, Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022 ,  Irrigation Canal/Scheme Damaged   jalah DTWS,Command area, Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022 ,  Irrigation Canal/Scheme Damaged   Dewdhar, Pump House And Command area, Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022,  Irrigation Canal/Scheme Damaged   Pub Jalah DTWS,Pump House And Command area, Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022,  Irrigation Canal/Scheme Damaged   Bebejia to Mohmorja DTWS2,Pump House And Command area, Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022,  Irrigation Canal/Scheme Damaged   Solar Powered MDTW Scheme at Dakhinpat,,Pump House And Command area, Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022,  Irrigation Canal/Scheme Damaged   Tulsimukh DTWS,Pump House And Command area, Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022,  Irrigation Canal/Scheme Damaged   TW Points under PMKSY HKKP Phase -I., Total-645,Submerged/damage reported by Nagaon Sub-Division (Irrigation) Nagaon Dated-23/05/2022,  Fisheries/Pond   5Nos. of pond affected under Khagarijan Development Block , Dated-23/5/2022, Reported by Fisheries Development Officer, Kahagriajn Development Block , Nagaon</p>
	Udalguri	<p><b>Mazbat</b> - Washed away Culverts   One slab culvert has been washed away at ch 1700.00m on Pauripota to Devpukhuri road on 23/5/2022(26.66135, 92.33063). Length- 5.65m,  <b>Udalguri</b> - Protection Bundh Damaged   Damage of of RTP(River Training Project) under Soil Conservation at Belguri Village around 12m on 23.05.2022. GPS - Lat - 26.68666667 Long - 92.02055556,  Fisheries/Pond   As per report of Fishery Department, 01 nos. of village namely Kuptimari constituting of approximately 06 farmers and 0.90 ha. of water bodies are affected.</p>
Erosion	<b>District</b>	<b>Details</b>
	Barpeta	<b>Sarthebari</b> - Kayakuchi Pathar   Erosion by Turkijan at near Aynal Haque house(Reported by LM 24-05-2022)   0
	Biswanath	<p><b>Gohpur</b> - Erosion observed at Brahmapur and Nalbari   1. Erosion observed at Brahmapur M/E on L/B of river Solengi about length of 150 mtr on 24.05.2022 latitude: 26.947747 Logitude: 93.631378 2. Erosion observed at Nalbari M/E on R/B of river Solengi about length of 120 m on 24.05.2022 latitude:26.5706876 , longitude: 93.3857192   0,  <b>Naduar RC part</b> - No-2 Bhojmari   Active bank erosion at No-2 Bhojmari area on right bank of river Brahmaputra . Length=400m on 24.05.2022   0</p>
	Dhubri	<b>South Salmara Part</b> - Puthia   As per information received from concerned LM Mondal erosion occurred at village Puthia on 23/05/22 to 24/05/22 by the river Brahmaputra. 27 nos family has been eroded due to erosion. Area Aprox 25B-0K-0L. Affected families has been shifted to the safe place.   92
	Karimganj	<b>RK Nagar</b> - 1001 No. B.G.K.P. L.P. School.   Due to raise water level, the high flow of water of Baliachara (channel) eroded the soil on date 20-05-2022 making the 1001 No. B.G.K.P. L.P. School, Village-Kalachara, in vulnerable position   0
	Nalbari	<b>Barkhetri</b> - Bhangnamari   River bank erosion of river Brahmaputra at Bhangnamari. Length 500m approx. Date 24/5/2022. Shifting Bhangnamri Police station, PWD(B) IB and Community Hall Laupara Bhangnamri LPS, Madhyakamrup milan HS, 15 nos. houses, shops from bazar chowk shifting due to erosion.   0
	Sivasagar	<b>Demow</b> - Konwar Gaon   Erosion at right bank of Desang river from Bahgarh to AT Road due to rise of water level for a length of 300 metre . The report has been submitted by Water Resource division under Demow Revenue Circle. Date of occurrence: From 23/5/2022 to 24/5/2022.   0
	Sonitpur	<b>Tezpur</b> - Garsingha Bihya, Tinikhoria Chapori   Dated 24/05/2022. Erosion is observed on the right bank of the Jia- Bharali river at Garsingha Bihya under Mahabhairab mouza. A stretch of 200 m (approx) is in the verge of being wash away. Erosion is also observed today i.e 24/05/2022 at Tinikhoria Chapori under Bihaguri mouza due to the river Brahmaputra. A stretch of 50m (approx) is in verge of being wash away. Lat 26.632061 & Long 92.678742.   0
	Tinsukia	<p><b>Margherita</b> - 1. Rathduba &amp; Borfakiyal   Active erosion is going on the right bank of Buri Dehing river at Rathduba &amp; Borfakiyal since 20/05/2022 till 24/05/2022. As per report received from the Field Officer Margherita , the stretch area is 1000m.   25,  <b>Sadiya</b> - 1. Koilabasti, 2. Gurungbasti, 3. 8th mile, 4. Sunpura Purona Bazaar, 5. Sunpura Nadikinar   1. Active erosion is reported from Koilabasti area by Kundil river since 12/05/2022 till 24/05/2022. As per report received from the WR department and concerned Gaon Pradhan, the stretch area is 50m. ( Lati 27.84688889, Long 95.71255556 ) 2. Active river bank erosion is going on at Gurung Basti area since 15/05/2022 till 24/05/2022. As per report by WR department, the stretch area is 50m. ( Lati 27.89750000, Long 95.77833333 ) 3. Active erosion is going on at Sunpura Purana Bazar by Balijan river since 20/05/2022 till 24/05/2022. As per report by WR department, the stretch area is 70m . Location( Lati 27.84849444 N, Long 95.89472222 E). 4. Active erosion is going on at Sunpura Nadikinar by Balijan river since 19/05/2022 till 24/05/2022 As per report by WR Dept, the stretch area is 100m . Location (Lati 27.84161944 N, Long 95.88021389 E). 5. Active erosion is going on at 8th Mile by Kundil river under the bridge since 18/05/2022 till 24/05/2022. As per report by Gaon Pradhan the stretch area is 30m. . Location (Lati 27.86722222 N, Long 95.76000000 E).   0,</p>

		<p><b>Doomdooma</b> - 1. Village : No. 3 Kordoiguri ( Goriyating ), 2. Village: No. 1 Kordoiguri(Darjijan), 3. Village : No. 2 Kordoiguri ( Simoluguri Satra ).   1. River Bank erosion is being observed at No. 3 Kordoiguri on the left Bank of River Brahmaputra (Ananta Nallah) since 2/04/2022 till 24/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 200 m in length.( Long: 95.468184, Lati: 27.650410), population affected 122. 2. River Bank erosion is being observed at No. 1 Kordoiguri (Dorzijan) on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 24/05/2022. As per information received from concerned Lot Mandal and WR department officials the affected stretch is about 300 m in length.( Long: 95.450531, Lati: 27.651217), population affected 37. 3. River Bank erosion is being observed at No.2 Kordoiguri (Simoluguri Satra) on the left Bank of River Brahmaputra (Ananta Nallah) since 19/05/2022 till 24/05/2022. As per information received from concerned Lot Mandal and WR department officials, the affected stretch is about 400 m in length.( Long: 95.4505 , Lati: 27.65196)   0</p>
	Udalguri	<p><b>Mazbat</b> - 1/Niz Rangapani 2/ Kukurbhuka 3/Chubura Chuburi 4/ Panchnoi Nonke   1/ Erosion occurred on L/B of river Dhansiri at Niz Rangapani on 22/5/2022.(26.486952, 92.131677). Length- 580m 2/ Erosion occurred on L/B of river Dhansiri at Kukurbhuka village on 22/5/2022(26.483652, 92.131634). Length- 720m 3/ Severe erosion occurred on R/B of Pagla river at Chubura Chuburi( Natun Bazar) on 22/5/2022(26.395083, 92.172662). length- 400m 4/ Erosion and avulsion occurred on R/B of river Panchnoi at village Panchnoi Nonke on 22/5/2022(26.373897, 92.20808) Length- 300m   0,</p> <p><b>Kalaigaon</b> - Bardowaneza   Severe Erosion occurred at village Bardowaneza on 24/05/2022 due to heavy current of river Laljhora in the R/B of the river covering a length of around 100 meters.   45</p>
Landslide	Nil	
Urban Flood	Nil	