



# FRIMS Assam

## Flood Reporting And Information Management System



Assam Daily Flood Report as on 21-06-2023 at 4:00 PM

Assam Daily Flood Report as on 21-06-2023 at 4:00 PM			
Particulars	Situation as on 21-06-2023 (in last 24 hours)		
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above danger level		Beki (Road Bridge), Pagladiya (Nt Road Crossing), Puthimari (Nh Road Crossing)
	Rivers flowing above highest flood level		Nil
District/Sub-division Affected	No. of Districts/Sub-divisions* Affected	Name of Flood Affected Districts/Sub-divisions*	Name of Urban Flood Districts/Sub-divisions*
	20	Bajali, Baksa, Barpeta, Biswanath, Chirang, Darrang, Dhemaji, Dhubri, Dibrugarh, Golaghat, Hojai, Kamrup, Kokrajhar, Lakhimpur, Nagaon, Nalbari, Sonitpur, Tamulpur, Udalguri	Bajali, Darrang, Kamrup (M), Kokrajhar, Nalbari
No. Of Revenue Circles Affected	45		
Name Of Revenue Circles Affected	District/Sub-division*	Total	Revenue Circle
	Bajali	2	Sarupeta, Bajali
	Baksa	4	Baska, Barama, Baganpara, Jalah
	Barpeta	1	Barpeta
	Biswanath	2	Halem, Gohpur
	Chirang	1	Bijni
	Darrang	4	Sipajhar, Patharighat, Mangaldoi, Dalgaon
	Dhemaji	2	Dhemaji, Sissiborgaon
	Dhubri	2	Chapar, Agamoni
	Dibrugarh	3	Moran, Dibrugarh West, Chabua
	Golaghat	1	Bokakhat
	Hojai	2	Doboka, Hojai
	Kamrup	1	Hajo
	Kamrup (M)	2	Dispur, Guwahati
	Kokrajhar	4	Gossaigaon, Bhawraguri, Dotma, Kokrajhar
	Lakhimpur	2	Bihpuria, Nowboicha
	Nagaon	2	Kampur, Raha
	Nalbari	6	Paschim Nalbari, Banekuchi, Nalbari, Tihu, Ghograpar, Barbhag
	Sonitpur	1	Dhekiajuli
	Tamulpur	2	Goreswar, Tamulpur
	Udalguri	1	Mazbat
	Total	45	
Villages Affected	District/Sub-division*	Total	Revenue Circle
	Bajali	42	( Sarupeta   32 ), ( Bajali   10 )
	Baksa	63	( Baska   17 ), ( Barama   11 ), ( Baganpara   17 ), ( Jalah   18 )
	Barpeta	2	( Barpeta   2 )
	Biswanath	37	( Halem   18 ), ( Gohpur   19 )
	Chirang	31	( Bijni   31 )
	Darrang	187	( Sipajhar   74 ), ( Patharighat   22 ), ( Mangaldoi   75 ), ( Dalgaon   16 )
	Dhemaji	3	( Dhemaji   2 ), ( Sissiborgaon   1 )
	Dhubri	17	( Chapar   3 ), ( Agamoni   14 )
	Dibrugarh	8	( Moran   1 ), ( Dibrugarh West   6 ), ( Chabua   1 )
	Golaghat	17	( Bokakhat   17 )
	Hojai	11	( Doboka   6 ), ( Hojai   5 )

	Kamrup	24	( Hajo   24 )				
	Kokrajhar	145	( Gossaigaon   29 ), ( Bhawraguri   25 ), ( Dotma   90 ), ( Kokrajhar   1 )				
	Lakhimpur	14	( Bihpuria   1 ), ( Nowboicha   13 )				
	Nagaon	27	( Kampur   10 ), ( Raha   17 )				
	Nalbari	108	( Paschim Nalbari   5 ), ( Banekuchi   3 ), ( Nalbari   11 ), ( Tihu   16 ), ( Ghograpar   40 ), ( Barbhag   33 )				
	Sonitpur	1	( Dhekiajuli   1 )				
	Tamulpur	42	( Goreswar   17 ), ( Tamulpur   25 )				
	Udalguri	1	( Mazbat   1 )				
	Total	<b>780</b>					

Population And Crop Area Affected	District/Sub -division*	Male	Femal e	Childre n	Total Populatio n	Population Details	Crop Area ( in Hect. )	Crop Area Details
	Bajali	401	306	32	739	( Sarupeta   0 ), ( Bajali   739 )	226.30	( Sarupeta   191.30 ), ( Bajali   35.00 )
	Baksa	11738	10647	4186	26571	( Baska   3875 ), ( Barama   1370 ), ( Baganpara   14017 ), ( Jalah   7309 )	3873.60	( Baska   43.60 ), ( Barama   37.00 ), ( Baganpara   159.00 ), ( Jalah   3634.00 )
	Barpeta	1701	1383	756	3840	( Barpeta   3840 )	0.00	( Barpeta   0.00 )
	Biswanath	0	0	0	0	( Halem   0 ), ( Gohpur   0 )	429.50	( Halem   30.50 ), ( Gohpur   399.00 )
	Chirang	0	0	0	0	( Bijni   0 )	61.79	( Bijni   61.79 )
	Darrang	536	549	827	1912	( Sipajhar   0 ), ( Patharighat   316 ), ( Mangaldoi   1596 ), ( Dalgaon   0 )	3333.34	( Sipajhar   1486.50 ), ( Patharighat   761.94 ), ( Mangaldoi   878.90 ), ( Dalgaon   206.00 )
	Dhemaji	136	145	85	366	( Dhemaji   0 ), ( Sissiborgaon   366 )	14.00	( Dhemaji   5.00 ), ( Sissiborgaon   9.00 )
	Dhubri	245	161	170	576	( Agamoni   576 ), ( Chapar   0 )	62.05	( Agamoni   60.00 ), ( Chapar   2.05 )
	Dibrugarh	0	0	0	0	( Moran   0 ), ( Chabua   0 ), ( Dibrugarh West   0 )	181.76	( Moran   0.50 ), ( Chabua   127.26 ), ( Dibrugarh West   54.00 )
	Golaghat	0	0	0	0	( Bokakhat   0 )	200.00	( Bokakhat   200.00 )
	Hojai	0	0	0	0	( Hojai   0 ), ( Doboka   0 )	131.83	( Hojai   67.83 ), ( Doboka   64.00 )
	Kamrup	0	0	0	0	( Hajo   0 )	146.00	( Hajo   146.00 )
	Kokrajhar	125	111	80	316	( Kokrajhar   260 ), ( Gossaigaon   0 ), ( Bhawraguri   0 ), ( Dotma   56 )	359.10	( Kokrajhar   172.12 ), ( Gossaigaon   29.02 ), ( Bhawraguri   47.76 ), ( Dotma   110.20 )
	Lakhimpur	12142	12024	930	25096	( Bihpuria   0 ), ( Nowboicha   25096 )	2.00	( Bihpuria   2.00 ), ( Nowboicha   0.00 )
	Nagaon	0	0	0	0	( Kampur   0 ), ( Raha   0 )	1263.58	( Kampur   106.00 ), ( Raha   1157.58 )
	Nalbari	20018	18113	6576	44707	( Nalbari   330 ), ( Barbhag   7 ), ( Paschim Nalbari   455 ), ( Banekuchi   589 ), ( Tihu   12924 ), ( Ghograpar   30402 )	306.00	( Nalbari   20.00 ), ( Barbhag   38.00 ), ( Paschim Nalbari   22.50 ), ( Banekuchi   47.50 ), ( Tihu   109.00 ), ( Ghograpar   69.00 )
	Sonitpur	29	23	13	65	( Dhekiajuli   65 )	0.00	( Dhekiajuli   0.00 )
	Tamulpur	6125	5496	3989	15610	( Goreswar   4766 ), ( Tamulpur   10844 )	1.00	( Goreswar   0.00 ), ( Tamulpur   1.00 )
	Udalguri	15	9	8	32	( Mazbat   32 )	0.00	( Mazbat   0.00 )
	Total	<b>53211</b>	<b>48967</b>	<b>17652</b>	<b>119830</b>		<b>10591.85</b>	

Relief Camps / Centres Opened	District/Sub -division*	Total	Relief Camp	Relief Distribution Centres
	Baksa	9	5(Baska   3, Barama   1, Baganpara   1)	4(Baska   1, Barama   3, Baganpara   0)
	Biswanath	4	0(Halem   0, Gohpur   0)	4(Halem   3, Gohpur   1)
	Dhubri	1	1(Agamoni   1)	0(Agamoni   0)
	Kokrajhar	1	1(Dotma   1)	0(Dotma   0)
	Nalbari	5	5(Tihu   2, Ghograpar   3)	0(Tihu   0, Ghograpar   0)
	Sonitpur	1	0(Dhekiajuli   0)	1(Dhekiajuli   1)
	Tamulpur	9	2(Goreswar   1, Tamulpur   1)	7(Goreswar   7, Tamulpur   0)

	Udalguri	1	0(Mazbat   0)			1(Mazbat   1)				
	Total	31	14			17				
Inmates In Relief Camps	District/Sub -division*	Total	Revenue Circlewise		Male	Female	Children	Pregnant / Lactating Mother	Person with Disability	
	Baksa	1157	(Baska   660), (Barama   139), (Baganpara   358), (Jalah   0)		423	420	278	16	20	
	Dhubri	193	(Chapar   0), (Agamoni   193)		78	54	61	0	0	
	Kokrajhar	56	(Gossaigaon   0), (Bhawraguri   0), (Kokrajhar   0), (Dotma   56)		15	21	20	0	0	
	Nalbari	614	(Paschim Nalbari   0), (Banekuchi   0), (Nalbari   0), (Tihu   69), (Barbhag   0), (Ghograpar   545)		295	237	57	24	1	
	Tamulpur	71	(Goreswar   55), (Tamulpur   16)		34	25	12	0	0	
	Total	2091			845	757	428	40	21	
Human Lives Lost - Confirmed	Nil									
Human Lives Lost - Confirmed - Death Type	Nil									
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
Animals Affected	District/Sub -division*	Total	Big	Small	Poultry					
	Bajali	1210	720	490	0					
	Baksa	25042	9521	5596	9925					
	Biswanath	5044	3115	1929	0					
	Darrang	9313	5548	3765	0					
	Dibrugarh	5256	4197	1059	0					
	Lakhimpur	7079	5492	1587	0					
	Nalbari	52840	19329	17651	15860					
	Tamulpur	1690	1010	680	0					
	Udalguri	5	3	2	0					
Animals Washed Away	Total	107479	48935	32759	25785					
	District/Sub -division*	Total	Big	Small	Poultry					
	Baksa	1	1	0	0					
Houses Damaged	Total	1	1	0	0					
	District/Sub -division*	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
	Baksa	0	0	0	2	0	2	0	0	0
	Kokrajhar	1	0	1	1	0	1	0	0	0
	Total	1	0	1	3	0	3	0	0	0
Rescue Operation	District/Sub -division*	Agency			Boats Deployed	Person Evacuated By Boats	Animal Evacuated By Boats	Helicopters Deployed	Person Evacuated By Helicopters	Medical Team Deployed
	Bajali	SDRF			0	0	0	0	0	2
	Baksa	Fire & Emergency Services (F&ES), SDRF			6	390	0	0	0	2
	Biswanath				0	0	0	0	0	4
	Dhubri				0	0	0	0	0	1
	Lakhimpur				0	0	0	0	0	3
	Nalbari	SDRF			2	325	0	0	0	0

	Tamulpur	Circle Office/Local Administration, Green Trek Adventure, Sikhar Adventure Club, Army/Paramilitary force, Fire & Emergency Services (F&ES), NDRF, SDRF, GREEN TREK NGO	10	565	0	0	0	2
	Total		18	1280	0	0	0	14
Relief Distributed	District/Sub -division*	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)
	Baksa	10.88	1.99	0.60	0.60	0.00	0.00	0.00
	Biswanath	0.00	0.00	0.00	0.00	110.00	93.90	
	Sonitpur	0.77	0.16	0.05	0.00	0.00	0.00	
	Tamulpur	33.99	6.12	1.84	183.50	0.00	108.60	0.00
	Udalguri	0.53	0.10	0.03	2.88	0.00	0.00	0.00
	Total	46.17	8.37	2.52	186.98	0.00	218.60	93.90
Relief Distributed Others	District/Sub -division*	Baby Food Liquid	Baby Food Solid	Others				
	Baksa	0.00-Q	0.00-Q	Candle-78.00-Pieces; Soaps-78.00-Pieces; Maxo Coil-60.00-Pkt				
	Biswanath	0.00-Q	0.00-Q					
	Sonitpur	0.00-Q	0.00-Q	0-0.00-Q				
	Tamulpur	0.00-Q	0.00-Q					
Infrastructure Damaged - Embankment Breached	District/Sub -division*	Number	Details					
	Baksa	3	<b>Barama</b> - Breach occurred on L/B of Mora Pagladia   Alagjar   Breach occurred on L/B of Mora Pagladia river at village Alagjar near Charanpara supa at a stretch of 200 m dated-21/06/2023   (Long - 91.357248, Lat - 26.540695, Dept - Water Resource Deptt.), Breach occurred on R/B embankment of Kaljhar Village   Kaljhar Village Near B.ed College.   Breach occurred on R/B embankment of Kaljhar Village Near B.ed College at a stretch of 10 m approx. dated-21/06/2023   (Long - 91.362613, Lat - 26.531607, Dept - Water Resource Deptt.), Breach occurred on L/B of Mora Pagladia   Alagjar   Breach occurred on L/B of Mora Pagladia river at village Alagjar near Madhya Alagjar supa of stretch of 25 m approx.dtaed-21/06/2023   (Long - 91.362613, Lat - 26.531608, Dept - Water Resource Deptt.)					
	Nalbari	1	<b>Tihu</b> - ROAD CUM EMBANMENT,R/B MORA PAGOLDIA RIVER   GOBARADAL   LENGTH IS APPROX : 40 MTS, REPORTED BY DEPARTMENTAL OFFICIALS Dated: 21/06/2021   (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.)					
	Total	4						
Infrastructure Damaged - Embankment Affected	District/Sub -division*	Number	Details					
	Bajali	3	<b>Sarupeta</b> - Ringbundh of Pahumara River   Village: Nakuchi Pather   Report received from concerned LM on 21th June,2023 at 9 am   (Long - 91.086815, Lat - 26.437753, Dept - P&RD), <b>Bajali</b> - Embankment of Kaldia at Sariha Chakla   Sariha Chakla   Report received from Chairman Patacharkuchi MB dated 21/06/2023 at 10AM   (Long - 91.238575, Lat - 26.529092, Dept - Municipal Road), Embankment of Kaldia at Golibandha   Golibandha near GP office   Report received from concerned LM dated 21/06/2023 at 8AM   (Long - 91.160469, Lat - 26.443195, Dept - P&RD)					
	Biswanath	1	<b>Gohpur</b> - R/Bank embankment of Sessa   at Auguri area mild Bank Erosion observed of length 50 mtr on 21/06/23    (Long - 93.737047, Lat - 26.952548, Dept - Water Resource Deptt.)					
	Nalbari	2	<b>Nalbari</b> - Nalbari Sonkuriha embankment at Pagaldia river   Sondha   Side Berm damaged at Ch 7300 Dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.), Pagaldia embankment at Doulgobindapur ward no-4, Bolakuchi   ward no-4, Bolakuchi   Dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.)					
	Total	6						
Infrastructure Damaged - Road	District/Sub -division*	Number	Details					
	Bajali	3	<b>Bajali</b> - Patacharkuchi to Nityananda   Kuwara   Report received from AEE, PWD Roads dated 21/06/2023 at 10AM   (Long - 91.227660, Lat - 26.525417, Dept - PWD (NH Roads)), Nityananda to Pipla   Pipla   Report received from AEE, PWD Roads dated 21/06/2023 at 10.30 AM   (Long - 91.256251, Lat - 26.527099, Dept - PWD (NH Roads)), Nityananda to Akaya   Kaharpara   Report received from AEE, PWD Roads dated 21/06/2023 at 10.30 AM   (Long - 91.207493, Lat - 26.599310, Dept - PWD (NH Roads))					
	Baksa	1	<b>Baganpara</b> - Dhamdham to Baganpara main road have been damaged on 21/06/2023 approx 40 mtr   Gorbhitor    (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))					

	Barpeta	1	<b>Barpeta</b> - Kadamguri Charichain Road   Kadamguri   As per report received from PWD Dept. a portion of Kadamguri Charichain Road washed away by Flood sater. Date:21/06/2023   (Long - 90.994956, Lat - 26.389730, Dept - PWD (Roads))
	Bongaigaon	17	<p><b>Manikpur</b> - Dangaigaon kirtanpara Road   Dangaigaon   Water logging from Ch.1000.00m to Ch.1200.00m and Road surface damaged. as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.736267, Lat - 26.441949, Dept - PWD (Roads)),</p> <p>Bhandara pt.I to Bhandara pt.V PMGSY Road   Bhandara   Submerged from Ch.2750.00m to Ch.2950.00m, submeregded depth is 45cm.as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.748306, Lat - 26.424079, Dept - PWD (Roads)),</p> <p><b>Bongaigaon</b> - Kharija Dolaigaon pt-II to SSB camp Road   Kharija   Shoulder and ICBP hard crust damaged at Ch.2nd Km.as per report received from PWRD,Bongaigaon dated- 21.06.2023   (Long - 90.580864, Lat - 26.487310, Dept - PWD (Roads)),</p> <p>SH2 to Kukurmari Sutarpura Road via PWRD office   Sutarpura Road   Erosion and depression occurred at hard crust portion near FCI road at 1st Km.as per report received from PWRD,Bongaigaon dated- 21.06.2023   (Long - 90.544766, Lat - 26.490591, Dept - PWD (Roads)),</p> <p>Bongaigaon Bhakrivita road   Bhakrivita   Hard crust damaged and pot hole occurred at Ch. 2nd Km. as per report received from PWRD,Bongaigaon dated- 21.06.2023   (Long - 90.546857, Lat - 26.498114, Dept - PWD (Roads)),</p> <p>Bongaigaon college to Dolaigaon road   Dolaigaon   Road surface damaged and water stagnant at various surfaces at Ch.0.00 to Ch.200.00m.as per report received from PWRD,Bongaigaon dated- 21.06.2023   (Long - 90.538297, Lat - 26.484983, Dept - PWD (Roads)),</p> <p>Deuripara   Bagheswari temple to Deuripara Road   Hard crust and shoulder damaged and water stagnant at Ch.0.00 to Ch.180.00m.as per report received from PWRD,Bongaigaon dated- 21.06.2023   (Long - 90.563631, Lat - 26.468217, Dept - PWD (Roads)),</p> <p>B.Ed College approach Road   B.Ed College   Hard crust and shoulder damaged and water stagnant at Ch. 1st Km. as per report received from PWRD,Bongaigaon dated- 21.06.2023   (Long - 90.564221, Lat - 26.470926, Dept - PWD (Roads)),</p> <p><b>Srijangram</b> - T01 to Solmara Road   Solmara   Culvert approach damaged at Ch.500.00m. as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.679589, Lat - 26.389664, Dept - PWD (Roads)),</p> <p>Tulungia Borghola Road   Tulungia   Culvert approach damaged at Ch.6500.00m.as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.695414, Lat - 26.387847, Dept - PWD (Roads)),</p> <p>Saripunia-II to Saripunia-I Road   Saripunia   Erosion on embakment at Ch.15th Km.as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.679425, Lat - 26.412231, Dept - PWD (Roads)),</p> <p>Haripur to new Piradhara Road   Piradhara   Shoulder damaged at 1st and 2nd Km. as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.682180, Lat - 26.302310, Dept - PWD (Roads)),</p> <p>Abhayapuri Police station to 8th APBN Road   Abhayapuri   Shoulder and hard cust damaged at 1st Km.as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.659410, Lat - 26.344230, Dept - PWD (Roads)),</p> <p>Kuchbari Bhaghekhaiti to Mererchar(Balargudam) Road   Mererchar   Shoulder damaged at Ch.300.00m Ch. 500.00m and Ch.800.00m.as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.714300, Lat - 26.289520, Dept - PWD (Roads)),</p> <p>Borigaon Bamungaon Road   Bamungaon   Submeregded and Shoulder damaged.as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.673350, Lat - 26.339480, Dept - PWD (Roads)),</p> <p>Abul Kalam Ajad Road   Srijangram   Hard crust damaged at Ch. 300.00 and Ch.500.00m.as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.666830, Lat - 26.330720, Dept - PWD (Roads)),</p> <p>Lal Bahadur Sastri Road   Srijangram   Hard crust damaged at Ch. 1st Km.as per report received from PWRD, Bongaigaon dated- 21.06.2023   (Long - 90.660640, Lat - 26.329320, Dept - PWD (Roads))</p>
	Chirang	2	<p><b>Bijni</b> - Bijni Subhajihar Road to No 1 Sisubari   No 1 Sisubari   As reported by PWD Bijni (R&amp;B) Sub Division, Bijni Subhajihar Road to No 1 Sisubari damaged at No 1 Sisubari. Length=3.50 mtr, Breadth= 2.50 mtr, Depth=2.00 mtr. Date of Occurrence=21-06-2023   (Long - 90.638557, Lat - 26.523069, Dept - PWD (Roads)),</p> <p>Borobazar Bhabanipur Road to No 2 Dogorpara   No 2 Dogorpara   As reported by PWD Bijni (R&amp;B) Sub Division, Borobazar Bhabanipur Road to No 2 Dogorpara road damaged at No 2 Dogorpara. Length=20.00 mtr, Breadth= 2.00 mtr, Depth=3.50 mtr. Date of Occurrence=21-06-2023   (Long - 90.619491, Lat - 26.596530, Dept - PWD (Roads))</p>
	Darrang	4	<p><b>Patharighat</b> - Turai to Taragaon Road   Taragaon   As reported by JE, PWD Road submerged at length 1 km dated.21/06/2023   (Long - 26.424246, Lat - 91.821298, Dept - PWD (Roads)),</p> <p>MPK to Hussainchubri Road   Hussainchubri   Road submerged at length CH. 1 km Length L= 600 mt Depth 0.40 mt.dated.21/06/2023   (Long - 91.816143, Lat - 26.500555, Dept - PWD (Roads)),</p> <p>MPK road at 21st km   MPK Road   As reported ,Submerged length=300m, depth = 0.35m.dated.21/06/2023   (Long - 91.845116, Lat - 26.483933, Dept - PWD (Roads)),</p> <p><b>Dalgaon</b> - Barhabi to Mazgaon road   Barhabi to Mazgaon road   As per report received from</p>

		PWD(R) barhabi to mazgaon PMGSY road shoulder has been damaged at Ch-1650m. immediate restoration is required. Date of occurrence- 20/06/2023   (Long - 92.126601, Lat - 26.637039, Dept - P&RD)
Dhubri	2	<b>Chapar</b> - NH 31 at Chirakuta to Tokrabandha quarry road surface damaged on Dated 20-06-2023   Chirakuta   Road damaged due to over flow of water by the river Gaurang   (Long - 90.242500, Lat - 26.220760, Dept - PWD (Roads)), Road from Chirakuta to Jamduar pt -I submerged due to water on Dated 20-06-2023   Jamduar Pt-I   Road damaged due to over flow of water by the river Gaurang   (Long - 90.242700, Lat - 26.220600, Dept - PWD (Roads))
Goalpara	1	<b>Matia</b> - Garomari to Nabagata Simlitola   Nabagata Simlitola   Road submerged from Ch. 2600 M to 2800 M and from 2900 M to 3100 M and the approch of Bridge No 3/1 has been eroded and subsided, Date - 20/06/2023, reported by AEE, PWRD, Goalpara East Territorial Road Sub-Division, Goalpara   (Long - 90.884238, Lat - 26.078810, Dept - PWD (Roads))
Kamrup	2	<b>Goroimari</b> - Road Submerged length 150 m breadth 6m Tukrapara to Dakhin Choudharypam as reported by AEE, PWRD, Chhayaon, dtd- 20.06.2023   Goroimari    (Long - 91.196227, Lat - 26.090307, Dept - PWD (Roads)), Road Submerged length 100 m breadth 6m Bowrabhitha to Monjuribilar Dhundhuntari as reported by AEE, PWRD, Chhayaon, dtd- 20.06.2023   Goroimari    (Long - 91.210927, Lat - 26.083880, Dept - PWD (Roads))
Kokrajhar	9	<b>Bagribari</b> - BASHBARI MOWAMARI ROAD   Mowamari   As reported by Executive Engineer, PWRD, Dhubri Civil Sub-Division, Territorial Road Division side berm, hard crust have been badly damaged and eroded due to heavy rainfall in last few days. Date-21.06.2023   (Long - 89.997472, Lat - 26.086477, Dept - PWD (Roads)), <b>Gossaigaon</b> - Panbari to Salmari Road   Panbari & Salmari   As reported by AEE PWD RR Kachugaon Sub division Dated 21.06.2023 due to continous rainfall right side of road formation is badly erosion (L-120.00M) by the Salmari River   (Long - 90.053435, Lat - 26.511800, Dept - PWD (Roads)), <b>Bhawraguri</b> - Rupshi Pt II to Rupshi Railway Gate (Kumguri beel to near choutara Railway line PWD Road to Rupshigaon Pt II)   Eroded at Ch 300.00 m   As reported by AEE PWD RR Kachugaon & BDO, Gossaigaon due to incessant heavy rainfall from 16th June, 2023 to 21.06.2023 at Rupshigaon pt ii village rupshi pt ii to rupshi railway gate Road formation eroded at ch 300.00m   (Long - 26.405640, Lat - 90.075860, Dept - P&RD), <b>Dotma</b> - Serfanguri Gossainichina Road   Serfanguri   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Serfanguri Gossainichina Road Br. No.1/1 approaches eroded   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Serfanguri to Kumguri via Laokriguri   Kumguri   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Serfanguri to Kumguri via Laokriguri Br. No.1/1 approach road eroded.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Jogdoi Fakiragram road   Jogdoi   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Jogdoi Fakiragram road bride approach eroded.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Gomobil Anghihara road   Gomobil   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Gomobil Anghihara road bridge approach eroded at Br. No.3/1, 6/1, 6/2.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Gwmwbil to Anthaibari road   Gwmwbil   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Gwmwbil to Anthaibari road culvert no.1/7 collapsed.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Brajakhal road   Brajakhal   As reported by Asstt. Exe. Engineer, PWD (RR) on 21-06-2023 Damage of Brajakhal road near culvert at Brajakhal.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
Lakhimpur	2	<b>Nowboicha</b> - NH-15 at Rajali to Haripur Balitika Road   Balitika   NH-15 at Rajali to Haripur Balitika, overtopped and erosion, breaches at CH:3000M to CH:6500 M, breached at CH:3500 M on 21.06.2023. Report received from PWD (Roads)   (Long - 27.133053, Lat - 94.001978, Dept - PWD (Roads)), NH-15 to Mahghuli Borchala Road   Solmoria   NH-15 to Mahghuli Borchala Road, overtopped from CH:1600 M to CH:4500 M on 21.06.2023. Report received from PWD(Roads)   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
Nagaon	2	<b>Kampur</b> - Road from Chankchaki to Bakulaguri   Chankchaki to Bakulaguri   Road from Chankchaki to Bakulaguri (PMGSY-11, Pkg No. AS-19-715): Embankment erosion took place at Premajaan. Affected length approx. L= 100.00 m. date- 19/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Road from Kumbhirdubi to Chiropathar   Kumbhirdubi to Chiropathar   Road from Kumbhirdubi to Chiropathar (PMGSY-1, Pkg No. AS-19-462): Erosion took place at different stretches. Affected length pprox. L= 400.00m date- 19/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
Nalbari	15	<b>Paschim Nalbari</b> - Tihu Lachima Road to Lakhopur via Kendubari   Kendubari   Submerged due to flood water. Information received from PWD (R) Department on 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Chamaa Kaithalkuchi Road   Chamata   Submerged due to rain water. Information received from

			<p>PWD (R) Department on 20/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p><b>Banekuchi</b> - On 20/06/2023 at 7.00 PM Mohan Bazar Chowk to Banekuchi Chowk PWD road submerged appr.200 mtr. report from Gaon Pradhan   Rajakhat Banekuchi    (Long - 91.395332, Lat - 26.459034, Dept - PWD (Roads)),</p> <p><b>Barkhetri</b> - Loharkatha-Bezkuchi Road   HAMLAKUR   Due to incessant heavy rain for last few days , road side berm eroded and damaged by creating hole at 3rd Km on Loharkatha Bezkuchi Road as reportyed by AEE, PWRD, Barkhetri Teritorial Sub Div. on 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p><b>Ghograpar</b> - Nalbari - Dhamdhama Road   Balitara   Submerged at Nalbari dhamdhama road to Pub Balitara on 21-06-2023   (Long - 91.470000, Lat - 26.510000, Dept - PWD (Roads)),</p> <p>Ghograpar tamulpur Road Nalbari   Arara   Submerged at Ghograpar Tamulpur Road Nalbari on 21-06-2023   (Long - 91.570000, Lat - 26.480000, Dept - PWD (Roads)),</p> <p>Rangia Dhamdhama Road   Dhamdhama   Submerged at Rangia Dhamdhama Road on 21-06-2023   (Long - 91.480000, Lat - 26.550000, Dept - PWD (Roads)),</p> <p>Gohain Kamal Ali Road   Chataibari-Dhamdhama   Gohain Kamal Ali Road submerged due to flood on 21-06-2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>PWD IB Dhamdhama   Dhamdhama   PWD IB Dhamdhama submerged due to flood water on 21-06-2023   (Long - 91.470000, Lat - 26.550000, Dept - PWD (Roads)),</p> <p><b>Barbhag</b> - PMGSY Road Dokoha to Mathura road   Dokoha   Length: 8 km submerged dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>PMGSY Mathura sala road   Khudra Tingtingi   Length: 6 km submerged dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Athgharia Barbukia road under signature project   Athgharia   Length : 7.50km submerged dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Sanekuchi-Bargasha road   Sanekuchi   Length : 3 km. submerged dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Barsimalia Village road   Barsimalia   Length: 2.10km submerged dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>GBD to Barbukia road   Barbukia   Length : 2.10km submerged dated: 21/06/2023   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))</p>
Tamulpur	5		<p><b>Tamulpur</b> - Due to heavy rainfall and flash flood Patkijuli Hatiduba Firing Range culvert and approach road got damaged on 21 June 2023   Hatiduba    (Long - 91.491448, Lat - 26.781797, Dept - PWD (Roads)),</p> <p>Due to heavy rainfall and flash flood Dowamakha village road damaged on dated 21 june 2023   Dowamakha    (Long - 91.655155, Lat - 26.660245, Dept - PWD (Roads)),</p> <p>Due to heavy rainfall and flash flood Hahkata Balabari road Sub-Marge (Ananda Bazar Hahkata Balabari road) damaged on 21/06/2023   Hahkata    (Long - 91.516315, Lat - 26.637378, Dept - PWD (Roads)),</p> <p>Boraliapar Iron Bridge damaged on 21 June 2023   Boraliapar    (Long - 91.655076, Lat - 26.657136, Dept - PWD (Roads)),</p> <p>Daranga Bridge in kumarikata got affacted 21 June 2023   Kumarikata    (Long - 91.514079, Lat - 26.729985, Dept - PWD (Roads))</p>
Udalguri	6		<p><b>Mazbat</b> - Erosion occurred at left side of the Mazbat-Deochani road from Ch- 12500 M to 12850 M due to heavy rainfall on 20/6/2023   Mazbat- Deochani road    (Long - 92.332017, Lat - 26.857267, Dept - PWD (Roads)),</p> <p>Erosion occurred at Ch- 3000 M , approx length 50m, width 4.50m, depth 3m of the Manuhmari to Gariapthar road due to heavy rainfall on 20/6/2023   Manuhmari to Gariapthar road    (Long - 92.369075, Lat - 26.709564, Dept - PWD (Roads)),</p> <p>Damages of both side approaches of RCC slab culvert 4.00m span on Alisinga to Rowmari road due to heavy rainfall on 20/6/2023   Alisinga to Rowmari road    (Long - 92.317950, Lat - 26.675120, Dept - PWD (Roads)),</p> <p>Earthen shoulder eroded at approximately length 100.00m, depth 2.00m on Mazbat-Gelabil road due to heavy rainfall on 20/6/2023   Mazbat-Gelabil road    (Long - 92.282567, Lat - 26.774485, Dept - PWD (Roads)),</p> <p>Damage of both side approches of RCC slab culvert on NH-15 to Simaluguri road near Bathow Mandir due to heavy rainfall on 20/6/2023   NH-15 to Simaluguri road near Bathow Mandir    (Long - 92.258600, Lat - 26.680759, Dept - PWD (Roads)),</p> <p>Damages of HPC culvert on MRL05-Orang Dalgaon road under PMGSY-III due to heavy rainfall on 20/6/2023   Orang Dalgaon road    (Long - 92.182400, Lat - 26.381700, Dept - PWD (Roads))</p>
<b>Total</b>		<b>72</b>	
Infrastructure Damaged - Bridge	<b>District/Sub-division*</b>	<b>Number</b>	<b>Details</b>
	Baksa	1	<b>Baganpara</b> - Thakursupa to Jartaluk connecting rcc bridge damaged on dated 21/06/2023   Thakursupa   Road is completely disconnected   (Long - 91.484416, Lat - 26.576328, Dept - PWD (Roads))
	Barpeta	1	<b>Barpeta</b> - Kujarpith Bonbaha Raod to DK Road   Betbari   As per report received from PWD Dept a Bamboo foot bridge is partially affectedon 21/06/23   (Long - 91.017104, Lat - 26.406384, Dept - PWD (Roads))
	Darrang	1	<b>Dalgaon</b> - RCC Br No.14/1 on Dalgaon to Dhupguri via devpukhuri road   RCC Br No.14/1 on

			Dalgaon to Dhupguri via devpukhuri road   As per report received from PWD(R), due to heavy rain & incessant rainfall the approach of RCC br no.14/1 on Dalgaon to Dhupguri via devpukhuri road under Asom Mala project (package no.CE/AM/SOPD(L1)/35/2020-21/5) has been badly damaged. Immediate restoration is required. Date of occurrence - 20/06/2023   (Long - 92.316065, Lat - 26.613227, Dept - PWD (Roads))
	Kokrajhar	3	<b>Bagribari</b> - Bridge No.4/1   Bongshijhora to Monglajhora Road   As reported by Asstt. Exec. Engineer, PWD (RR) Sub-Division Gossaigaon, Damaged due to the incessant heavy rainfall. Date: 20-06-2023   (Long - 89.973048, Lat - 26.247123, Dept - PWD (Roads)), <b>Bridge No.4/1</b>   Bongshijhora to Monglajhora Road   As reported by Asstt. Exec. Engineer, PWD (RR) Sub-Division Gossaigaon, Damaged due to the incessant heavy rainfall. Date: 20-06-2023   (Long - 89.971291, Lat - 26.247542, Dept - PWD (Roads)), <b>Bridge No.4/3</b>   Bongshijhora to Monglajhora Road   As reported by Asstt. Exec. Engineer, PWD (RR) Sub-Division Gossaigaon, Damaged due to the incessant heavy rainfall. Date: 20-06-2023   (Long - 89.972507, Lat - 26.247179, Dept - PWD (Roads))
	Nalbari	1	<b>Paschim Nalbari</b> - RCC Bridge No.1/1 on Barbila Chowk to Lakhopur via Sarabari   Lakhopur   Approaches badly damaged due to flood water. Information received from PWD (R) Department on 21/06/2023.   (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Total	7	
Infrastructure Damaged - Wildlife	Nil		
Infrastructure Damaged - Others	District/Sub-division*	Other Details	
	Baksa	<b>Baska</b> - Road Breaches   Road breached at Tekelibhang to Doomni village Doomni Coordinate: 26.644772, 91.34704 date: 21/06/2023. , Power Dept. Poles   1 no. HT pole uprooted at village Narayanpur Coordinate: 26.709654, 91.347878 date: 21/06/2023. , Culvert Approach Road Damaged   Chaibari to Panbari connecting road Slab culvert damaged. Cordinate: 26.63336, 91386898, Date: 21/06/2023., Road Breaches   Dhanbil to Chaibari Connecting CC Block Road damaged. Cordinate: 26.640733, 91.390791	
	Chirang	<b>Bijni</b> - Road Breaches   As reported by concerned LM, due to incessant rain village road of village Batabari is reported to be damaged. Length=3.04 mtr, Breadth=3.6mtr, Dept=1.21 mtr. Latitude=26.512399 Longitude=90.69214 Date of Occurrence=21-06-2023., <b>Sidli</b> - Bamboo Foot Bridge   As reported by AE, PWD Chirang (R&B) Division, Kajalgaon, NH-31(C) Athiabari to Dhupguri road , Bamboo foot bridge at Ch.787.00m over river Suthi washed out at Athiabari Location- Latitude-26.556649, Longitude-90.423385, Damage details- Length -30.00m , Breadth-3.50m , Depth-4.50m date of occurrence -21-06-2023, Culvert Approach Road Damaged   As reported by AE, PWD Chirang (R&B) Division, Kajalgaon, Dangshibari village road , Culvert approach road damaged at Dangshibari Location- Latitude-26.593069, Longitude-90.45741, Damage details- Length -5.00m , Breadth-4.00m , Depth-3.00m date of occurrence -21-06-2023, Irrigation Canal/Scheme Damaged   As reported by JE, Sidli Sub-Division (Irrigation), Irrigation Canal Embankment damage from Ch.6829.50m to Ch. 6834.50 at Taktara village of LBC-6 Location- Latitude-26.529336, Longitude-90.430933 , damage details-Length -15.00m , Breadth-3.50m , Depth-2.80m date of occurrence- 21-06-2023, <b>Bengtal</b> - Culvert Approach Road Damaged   As reported by AEE, PWD Chirang (R&B) Division, Kajalgaon, Bamungaon Aujhar road Culvert approach damaged at Garlabari FV Location- Latitude-26.59522, Longitude-90.43821, Damage details- Length -4.50m , Breadth-2.50m , Depth-3.00m and Latitude-26.59532 Longitude-90.4382, Damage details- Length -10.00m , Breadth-3.00m , Depth-3.00m date of occurrence -21-06-2023	
	Darrang	<b>Patharighat</b> - Fisheries/Pond   As reported by Fishery Deptt. 67.47 Hectare area of pond submerged dated.21/06/2023, <b>Mangaldoi</b> - Power Dept. Poles   As per report received from APDCL Mangaldai approx.5 poles are damaged. Dated 21/06/2023, Power Dept. Conductors   As per report received from APDCL Mangaldai approx. 1.5 km conductor are damaged. Dated 21/06/2023, Road Breaches   Baigormari to Magurmari No.1 road breached, breach length 7 M approx. Lat-26.480247, Long-92.145739 under Pub Mangaldai Rev. Circle,dated.21/06/2023, <b>Dalgaon</b> - Fisheries/Pond   as per report received from fishery department, 10 nos of beneficiary,10 nos tank of water area 3.95 Ha at village No.2 Sialmari has been affected under Dalgaon Revenue Circle.Date of occurrence - 20/06/2023 , Power Dept. Conductors   As per report received from SDE,APDCL, kharupetia, 33kv conductor snap due to uprooting of a huge tree.Date of occurrence - 21/06/2023, Power Dept. Poles   As per report received from SDE,APDCL, kharupetia, 1 no of pole due to uprooting of a huge tree has been damaged.Date of occurrence - 21/06/2023	
	Dhemaji	<b>Gogamukh</b> - Bridge Approach Road Damaged   Old NT Road at Padumoni to Deogorbari; At Ch. 200.00m to Ch.230.00m; Longitude:94°24'59", Latitude:27°25'15"N; Dhemaji Territorial Road Division, Length-30 m, Dated: 21/06/2023, Bridge Approach Road Damaged   Bordoloni Chariali to Nagaon Road; At Ch. 150.00m to Ch.200.00m;	

		Longitude:94°25'19", Latitude:27°24'53" N; Dhemaji Territorial Road Division, length- 50 m, Dated: 21/06/2023
	Kokrajhar	<p><b>Gossaigaon</b> - Damaged SPT Bridge   As reported by BDO, Kachugaon Dev Block, Dated 21.06.2023 due to heavy rainfall No.2 Bhomrabil wooden bridge damaged near SSB camp,</p> <p>Damaged SPT Bridge   As reported by BDO, Kachugaon Dev Block, Dated 21.06.2023 due to heavy rainfall Ballamguri to Polashguri Wooden Bridge damaged,</p> <p>Damaged SPT Bridge   As reported by Gossaigaon Municipal Board Dated 20.06.2023 due to heavy rainfall Wooden Bridge damaged near Giridhari Ashram connecting Gossaigaon Ward No.1 and Ward No.4,</p> <p>Damaged SPT Bridge   As reported by Municipal Board Dated 20.06.2023 due to heavy rainfall Wooden Bridge damaged at Samshamkola connecWard No.1 and Ward No.4,</p> <p>Damaged SPT Bridge   As reported by Gossaigaon Municipal Board Dated 20.06.2023 due to heavy rainfall Wooden Bridge damaged near Ananta Kutir L.P. School connecting Gossaigaon Ward No.2 and Ward No.3,</p> <p>Bamboo Foot Bridge   As reported from AEE PWD RR Gossaigaon Sub Division, Dated 21.06.2023 due to Heavy rainfall Bamboo Foot Bridge No. 1/1 has been washout at Dingdinga Mandarkuti Road,</p> <p>Damaged SPT Bridge   As reported from AEE PWD RR Gossaigaon Sub Division, Dated 21.06.2023 due to Heavy rainfall Harafuta to Simultapu Road via Nayagaon Road, Washout Bridge No.2/1 ,</p> <p><b>Bhawraguri</b> - Agri Bundh Damaged   As reported by BDO Kachugaon development block due to incessant heavy rain from 14th June, 2023 to 21.06.2023 dhodhora bund at Dakhin Mukuldang village near Raju's paddy field is badly damaged (Lat: 26.480671, long:90.093411) ,</p> <p>Agri Bundh Damaged   As reported by BDO Kachugaon development block due to incessant heavy rain from 14th June, 2023 to 21.06.2023 North Chekadani bund at Dakhin Mukuldang village near Pradip's paddy field is badly damaged (Lat: 26.485303, long:90.086181) ,</p> <p>Bridge Approach Road Damaged   As reported by AEE PWD RR Kachugaon due to incessant heavy rainfall from 16th June, 2023 to 21.06.2023 at Asharikandi Kartimari village Bhawraguri Sapatgram Road Bridge approach eroded at Br. No. 20/1(Lat: 26.346232, long:90.108015)</p>
	Lakhimpur	<p><b>Subansiri</b> - Bamboo Foot Bridge   As reported by Dhakuakhana Territorial Road Division, Ghilamara the Bamboo Foot Bridge on Kekuri Madhupur to Chelajan Kachari road is damaged (L= 110M) on 21/06/2023,</p> <p>Bamboo Foot Bridge   As reported by Dhakuakhana Territorial Road Division, Ghilamara the Bamboo Foot Bridge on Kekuri Madhupur to Balijan Kachari road is damaged (L= 150M) on 21/06/2023,</p> <p>Bamboo Foot Bridge   As reported by Dhakuakhana Territorial Road Division, Ghilamara the Bamboo Foot Bridge on Balideori to Manordeori road is damaged (L= 125M) on 21/06/2023</p>
	Majuli	<p><b>Ujani Majuli</b> - Bamboo Foot Bridge   Due to rise of Flood water of a tributary of River Brahmaputra communication of the following villages have been cut off 1) Lachon Chapor - Lachon Dhunaguri from 20/6/2023. Reconstruction of the Bamboo Bridge is going on., ,</p> <p>Bamboo Foot Bridge   Due to rise of Flood water of a tributary of River Brahmaputra communication of the following villages have been cut off between Ratanpur Gayan and Bonoriya Chapor from 20/6/2023. Reconstruction of the Bamboo Bridge is going on.</p>
	Nalbari	<p><b>Barkhetri</b> - Damaged RCC Bridge   Due to incessant heavy rain for last few days both the approaches of RCC Br1/1 on Mukalmua Bhangnamri Ferry Ghat road badly eroded and damaged on North side 60m and on Soth side 50m as reportyed by AEE, PWRD, Barkhetri Teritorial Sub Div. on 21/06/2023,</p> <p><b>Tihu</b> - Agri Bundh Damaged   BREACHED NEAR TIHU AKHARA PWD ROAD RCC BRIDGE ,MORAPAGOLDIA (L/B),BOPROSUPA ,SIALMARI,BALI , LENGTH IS APPROX 40FTS ,DAMAGED ON 20/06/2023 AS PER REPORT GP ,</p> <p>Agri Bundh Damaged   BEREACHED NEAR KAIHATIPARA SUPA,BALI OF MORA PAGOLDIA (L/B),LENGTH APPROX 60 FTS ,DAMAGED ON 20/06/2023 REPORTED BY GP ),</p> <p>Agri Bundh Damaged   BREACHED NEAR CREMATION GROUND ,MAHAJANPARA SUPA, BALI ,(R/B)MORA PAGOLDIA RIVER, LENGTH IS APPOX 30 FTS ,DAMAGED ON 20/06/2023 REPORTED BY GP ,</p> <p><b>Ghograpar</b> - Culvert Approach Road Damaged   On 21-06-2023 Culverthas been damaged on ghograpar Tamulpur Road, Lat - 26.48, Long -91.57</p>
	Udalguri	<p><b>Khairabari</b> - Washed away Culverts   Due to overflow of downpour, the HPC measuring 10 × 5 M approx. on the Bhergaon - Tangla road has been eroded at Bar Tangla, disrupting the overall communication on 19.06.2023. Lat: 26.652593 Long: 91.878958,</p> <p><b>Harisinga</b> - Washed away Culverts   Purani Bhergaon to Borhola village road. One HPC wash out at village Jabangahabi due to heavy rainfall on 20th June 2023. LAT 26.6692 LONG 91.8040.,</p> <p>Irrigation Canal/Scheme Damaged   Socha FIS right canal embankment breach for length approximate 100m at different changes and breadth 2.5m at village no.2 bamunjuli due to heavy rainfall on 18th June 2023. LAT 26.8089 LON 92.8322.,</p> <p>Irrigation Canal/Scheme Damaged   Geruapara FIS canal embankment breached for length 100m at different changes and breadth 2.5m along with canal outlets damaged. At village Patala due to heavy rainfall on 18th June 2023.. LAT 26.6990 LON 91.8364</p>
Erosion	District/Sub-division*	Details
	Baksa	<b>Baganpara</b> - Borikadonga Barman supa   As per SDO WR on dated 20/06/2023 at Borikadonga approx 300 meter has been eroded on R/B of river Pagladia.   300   (Long - 91.472415, Lat - 26.699782)
	Barpeta	<p><b>Kalgachia</b> - Showpur   Showpur , Kurakur, nera Beki bridge, SH-2, reported by LM on 20.06.2023   0   (Long - 90.887857, Lat - 26.339905),</p> <p><b>Chenga</b> - Roumari Pathar Bazar (700 m), Balartari (600 m)   B/dyke on R/B of river Brahmaputra from</p>

		Adabari to Kukarjan from ch 5.80 km to 33.232 km Information received from Water Resource department on 21.06.2023   0   (Long - 0.000000, Lat - 0.000000)
Biswanath		<b>Biswanath</b> - 4 No. Kumalia (Forciati)   continuous active ban erosion is observed at Forciati area in between Ch.3rd to 4th Km of Biswanath-Panpur and 6th to 7th Km of Solmari Kalakati area of Biswanath-Panpur Dyke of river Brahmaputra as per report from water resources. 21/06/2023   0   (Long - 93.126548, Lat - 26.685488), <b>Halem</b> - Paken   River Brahmaputra -Mild bank erosion is observed at Paken area of B/Dyke from Jamuguri to Kharoi outfall. 21/06/2023 Length = 10.00m, Latitude : , Longitude:   0   (Long - 93.625317, Lat - 26.799672), <b>Gohpur</b> - At Gopsarguri   Mild bank erosion is observed on marginal embankment on R/Bank of river Sessa of length 50 mtr on 21/06/23   0   (Long - 93.716944, Lat - 26.979166), <b>Naduar RC part</b> - No-2 Bhojmari & Kalakati   Dated 21/06/2023, As reported by Biswanath WR Sub-division, (1) active bank erosion is observed at No-2 Bhojmari area on the R/Bank of river Brahmaputra of Biswanath- Panpur Dyke. Length= 20.00 m, Lat 26.670388 Long 93.089423 (2) Continuous active bank erosion is observed at Kalakati area in between 6th to 7th km of Biswanath-Panpur Dyke of river Brahmaputra. 21/06/2023 Lat 26.67441008 Long 93.09784163 Lat 26.67468932 Long 93.09795485   0   (Long - 0.000000, Lat - 0.000000)
Dhubri		<b>Dhubri</b> - kuntirchar Pt-I, kuntirchar Pt-II, Majerchar   Erosion is going on (by the river Brahmaputra) at village Kuntirchar Pt-I, Kuntirchar Pt-II & Majerchar As per the field verification w.e.f 17/06/23 to 21/06/23 it is seen that till now 47 nos of family has been affected (total area = 64Bigha-1Katha-5Lessa)and they have shifted their houses to another place. No situation has arisen for opening of any relief Camp. (Kinirchar Pt-I Lat- 26.04912778, Long-89.99160278) (Kuntirchar PtII-Lat-26.03223611 Long-89.98838611) (Majerchar- Lat- 26.05064722, Long- 90.13675833)   325   (Long - 26.049128, Lat - 89.991603)
Kamrup		<b>Chaygaon</b> - No 2 Ratanpur village to Jogibari Road.   PWD(R) chhaygaon Sub-Division reported about erosion of about 90 mtr of a PWD road because of the rising water level of Kulsi River. Date: 20/06/2023.   0   (Long - 91.382541, Lat - 26.004431)
Kokrajhar		<b>Dotma</b> - Vill- Nowebhita   Dated: 21/06/2023 Erosion occurred at village Nowerbhita by the river Longa. Around 200metres (Approx.) eroded.   0   (Long - 0.000000, Lat - 0.000000)
Lakhimpur		<b>Bihpuria</b> - Dikrong Ghat area near 80 No. Solmari Grant   Active erosion observed at Dikrong ghat area on R/B of Dikrong river at 80 No. Solmari Grant village due to which one family has been shifted to safe location. Approximately 200 meters of land has been eroded as reported by WRD, Bihpuria Sub-Division on 21/06/2023. 02 nos. Of tarpaulins provided to the erosion affected family.   7   (Long - 93.878200, Lat - 27.081900)
Majuli		<b>Majuli</b> - Kartik Chapor NC   Erosion occurred on 20th June, 2023 and one family have been shifted to a nearby safe place. Approximately 3 katha of land area has been eroded   5   (Long - 94.164901, Lat - 26.841096)
Morigaon		<b>Bhuragaon</b> - Balidunga Pam, Kupatimari   As per Water Resource department, Morigaon, Brahmaputra river erosion eroded 1 meter at a length of 700 meter at Kupatimari and Balidunga Pam revenue village under Bhuragaon Rev. Circle from 20-06-2023 to 21-06-2023."   0   (Long - 26.411003, Lat - 92.251558)
Nagaon		<b>Kaliabor</b> - Hatimura Area   Severe bank erosion of river Brahmaputra due to sudden slump down at Hatimura area length about 100 meters and breadth about 22 metres on 20.06.23 reported by Water Resources Department.   0   (Long - 92.995224, Lat - 26.612052)
Sonitpur		<b>Thelamara</b> - Village- Baligaon Bongaligaon and Garuduba   Date-21/06/2023, As reported by Tezpur Water Resource Tezpur Division on 21/06/2023- 1) Active bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri,Length = 200.00m, Latitude : 26.736022, Longitude: 92.558699 2) Bank erosion is observed at Garuduba area of river Belsiri Length = 150.00m, Latitude :26.642391, Longitude: 92.530572   0   (Long - 92.530572, Lat - 26.642391), <b>Tezpur</b> - Burha chapor (Dhania Sisuati)   Dated: 21/06/2023. As reported by Tezpur Water Resources Division, Tezpur bank erosion of river Brahmaputra is observed at Burha Chapor (Dhania Sisuati). Length: 350.00m   0   (Long - 92.628394, Lat - 26.526149)
South Salmara		<b>Mankachar</b> - Berabhanga Pt-I, II and Jordanga Pt-I.   AS per report received from I/C Control Room Hatisingimari W.R Sub-Division, Hatisingimari, an erosion due to Brahmaputra river at Berabhanga Pt-I, land measuring length-40 M, Breadth- 3 M, Berabhanga Pt-II- length-120 M, Breadth-1 M and Jordanga Pt-I length- Breadth- on 21-06-2023 As per report received from Gaon Pradhan 8 (Eight) nos. house hold shifted to other place due to erosion at Berabhanga Pt-I on 21-06-2023.   43   (Long - 25.773519, Lat - 89.902791)
Tamulpur		<b>Tamulpur</b> - Vill- Kalbari   Severe bank erosion and gully erosion occurred at Gerua and its adjacent paddy area in Kalbari village on 21 June 2023   0   (Long - 91.602460, Lat - 26.590520)
Udalguri		<b>Mazbat</b> - 1/ Swrangjuli 2/ Raidanglow   1/ Erosion occurred on L/B of river Mainajuli for a length of 300m on 20/6/2023 due to heavy rainfall. (Lat: 26.857074 long: 92.344789 2/ erosion occurred on R/B of river Mainajuli for a length of 200m on 20/6/2023 due to heavy rainfall ( Lat: 26.84345, Long: 92.3359)   0   (Long - 0.000000, Lat - 0.000000), <b>Kalaigaon</b> - Pachim Jangalpara   Erosion continues at village Pachim Jangalpara in the R/B of river Nanoi near Pachim Jangalpara LP School covering a length of around 120 meters and depth of 5 meters on 21/06/2023 due to heavy current of the river.   30   (Long - 91.998994, Lat - 26.566631)
Landslide	<b>District/Sub-division*</b>	<b>Details</b>
	Dima-Hasao	<b>Haflong</b> - Mahur, Kalachand, Between Dimruchora and Jolaidisa   1. Landslide at Mahurpura village approach road on 21-06-2023 Lat :- 25.160488, Long :- 93.067072. 2. Landslide near Kalachand electric post on 20-06-2023 Lat :- 25.341306, Long:- 93.133135. 3. Road block in between Dimruchora and Jolaidisa at nH54 due to break down of culvert 21-06-2023.   0   (Long - 0.000000, Lat - 0.000000)

	Kamrup (M)	<b>Guwahati</b> - Devagiri path Kharghuli   A landslide incident occurred at Devagiri path Kharghuli on 21/06/2023, no casualty   0   (Long - 91.766362, Lat - 26.194403)
Urban Flood	<b>District/Sub-division*</b>	<b>Details</b>
	Bajali	<b>Bajali</b> - Pathsala and Patacharkuchi Town   ward No 10 of Pathsala Town and 2,3,4,5,6,8,10 of Patacharkuchi Town dated 21/06/2023 reported by Chairman of Pathsala and Patacharkuchi MB   653   (Long - 0.000000, Lat - 0.000000)
	Darrang	<b>Dalgaon</b> - Kharupetia Town (ward no.1 and 8)   as per report received from lm, waterlogging at kharupetia town (ward no 1 and 8) under dalgaon revenue circle as on 20/06/2023   100   (Long - 92.149805, Lat - 26.519547)
	Kamrup (M)	<b>Dispur</b> - Rukminigaon, Hatigaon, Baghorbori Revenue Village   Waterlogging at Rukminigaon, Hatigaon- Sijubari, Wireless and Baghorbori. Roads are inundated no houses affected on 21/06/2023   0   (Long - 0.000000, Lat - 0.000000), <b>Guwahati</b> - Chandmari, B.Baruah Road, Satipur masjid goli, Boragaon, Maligaon   Partially water logging at Chandmari, B.Baruah Road, Satipur masjid goli, Boragaon, Maligaon on 21/06/2023   0   (Long - 0.000000, Lat - 0.000000)
	Kokrajhar	<b>Dotma</b> - Fakiragram MB   Due to incessant rainfall from 12-06-2023 to till date waterlogging at various wards under Fakiragram MB, Date: 21-06-2023 1. WARD NO.1 2. WARD NO.2   520   (Long - 0.000000, Lat - 0.000000), <b>Kokrajhar</b> - Ward no.1 to 10   DUE TO INCESSANT RAINFALL FROM 12.06.2023, WATER LOGGED AT KOKRAJHAR URBAN AREA VIDE WARD NO. 1 TO 10, dated-21/06/2023   12769   (Long - 0.000000, Lat - 0.000000)
	Nalbari	<b>Nalbari</b> - collage road, forest office road, gopal bazar road, hajo nalbari road   as per the report received from LM, these roads are submerged due to rain water Dated: 21/06/2023   600   (Long - 0.000000, Lat - 0.000000)

\*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)