

Assam Daily Flood Report as on 24-06-2023 at 4:00 PM

Particulars	Situation as on 24-06-2023 (in last 24 hours)		
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above danger level	Brahmaputra (Tezpur; Neamatighat)	
	Rivers flowing above highest flood level	Nil	
District/Sub-division Affected	No. of Districts/Sub-divisions* Affected	Name of Flood Affected Districts/Sub-divisions*	Name of Urban Flood Districts/Sub-divisions*
	15	Bajali, Baksa, Barpeta, Chirang, Darrang, Dhubri, Dibrugarh, Goalpara, Golaghat, Jorhat, Kamrup, Lakhimpur, Nagaon, Nalbari, Tamulpur	Darrang
No. Of Revenue Circles Affected	42		
Name Of Revenue Circles Affected	District/Sub-division*	Total	Revenue Circle
	Bajali	2	Bajali, Sarupeta
	Baksa	4	Baganpara, Barama, Baska, Jalah
	Barpeta	4	Barnagar, Sarthebari, Chenga, Barpeta
	Chirang	1	Sidli
	Darrang	4	Patharighat, Dalgaon, Mangaldoi, Sipajhar
	Dhubri	3	Golakganj, Bilasipara, South Salmara Part
	Dibrugarh	4	Tingkhong, Naharkatia, Dibrugarh West, Chabua
	Goalpara	1	Lakhipur
	Golaghat	1	Bokakhat
	Jorhat	1	Jorhat East
	Kamrup	5	North Ghy, Kamalpur, Rangia, Hajo, Kayan
	Lakhimpur	2	Nowboicha, Bihpuria
	Nagaon	1	Raha
	Nalbari	7	Barkhetri, Paschim Nalbari, Banekuchi, Nalbari, Tihu, Barbhag, Ghograpar
	Tamulpur	2	Goreswar, Tamulpur
	Total	42	
Villages Affected	District/Sub-division*	Total	Revenue Circle
	Bajali	137	(Bajali 57), (Sarupeta 80)
	Baksa	32	(Baganpara 11), (Barama 2), (Baska 16), (Jalah 3)
	Barpeta	112	(Barnagar 1), (Sarthebari 76), (Chenga 9), (Barpeta 26)
	Chirang	4	(Sidli 4)
	Darrang	168	(Patharighat 14), (Dalgaon 7), (Mangaldoi 75), (Sipajhar 72)
	Dhubri	216	(Golakganj 68), (Bilasipara 33), (South Salmara Part 115)
	Dibrugarh	11	(Tingkhong 2), (Naharkatia 2), (Dibrugarh West 6), (Chabua 1)
	Goalpara	5	(Lakhipur 5)
	Golaghat	17	(Bokakhat 17)
	Jorhat	1	(Jorhat East 1)
	Kamrup	174	(North Ghy 8), (Kamalpur 85), (Rangia 16), (Hajo 47), (Kayan 18)
	Lakhimpur	12	(Nowboicha 11), (Bihpuria 1)

	r							
	Nagaon	9	(Raha 9)					
	Nalbari	202	(Barkhetri 64), (Paschim Nalbari 25), (Banekuchi 5), (Nalbari 20), (Tihu 30), (Barbhag 49), (Ghograpar 9)					
	Tamulpur	18	(Goreswar 6), (Tamulpur 12)					
	Total	1118						
Population And Crop Area Affected	District/Sub-division*	Male	Female	Children	Total Population	Population Details	Crop Area (in Hect.)	Crop Area Details
	Bajali	109039	98232	14316	221587	(Bajali 139067), (Sarupeta 82520)	396.10	(Bajali 185.40), (Sarupeta 210.70)
	Baksa	1398	779	266	2443	(Barama 264), (Baska 0), (Jalah 1501), (Baganpara 678)	5.00	(Barama 0.00), (Baska 0.00), (Jalah 5.00), (Baganpara 0.00)
	Barpeta	42456	36308	25232	103996	(Sarthebari 67378), (Chenga 2310), (Barpeta 34268), (Barnagar 40)	361.75	(Sarthebari 63.75), (Chenga 20.00), (Barpeta 278.00), (Barnagar 0.00)
	Darrang	2909	2841	2743	8493	(Patharighat 804), (Dalgaon 0), (Mangaldoi 7334), (Sipajhar 355)	3387.50	(Patharighat 692.20), (Dalgaon 38.00), (Mangaldoi 1182.30), (Sipajhar 1475.00)
	Dhubri	357	333	170	860	(Golakganj 0), (Bilasipara 860), (South Salmara Part 0)	828.90	(Golakganj 205.90), (Bilasipara 28.50), (South Salmara Part 594.50)
	Dibrugarh	0	0	0	0	(Tingkhong 0), (Dibrugarh West 0), (Chabua 0), (Naharkatia 0)	172.03	(Tingkhong 2.00), (Dibrugarh West 49.00), (Chabua 118.50), (Naharkatia 2.53)
	Goalpara	2045	2015	690	4750	(Lakhipur 4750)	0.00	(Lakhipur 0.00)
	Golaghat	0	0	0	0	(Bokakhat 0)	197.00	(Bokakhat 197.00)
	Jorhat	0	0	0	0	(Jorhat East 0)	21.40	(Jorhat East 21.40)
	Kamrup	76	68	20	164	(North Ghy 0), (Kamalpur 0), (Rangia 164), (Hajo 0), (Kayan 0)	1106.64	(North Ghy 10.50), (Kamalpur 226.73), (Rangia 180.91), (Hajo 678.00), (Kayan 10.50)
	Lakhimpur	10562	10683	815	22060	(Nowboicha 22060), (Bihpuria 0)	226.00	(Nowboicha 226.00), (Bihpuria 0.00)
	Nagaon	0	0	0	0	(Raha 0)	548.28	(Raha 548.28)
	Nalbari	16944	15368	8356	40668	(Barkhetri 0), (Nalbari 2263), (Tihu 19780), (Barbhag 8300), (Ghograpar 2464), (Paschim Nalbari 6521), (Banekuchi 1340)	1098.10	(Barkhetri 229.00), (Nalbari 0.00), (Tihu 312.00), (Barbhag 71.60), (Ghograpar 150.00), (Paschim Nalbari 272.00), (Banekuchi 63.50)
Tamulpur	1328	911	511	2750	(Goreswar 2016), (Tamulpur 734)	120.86	(Goreswar 0.00), (Tamulpur 120.86)	
Total	187114	167538	53119	407771		8469.56		
Relief Camps / Centres Opened	District/Sub-division*	Total	Relief Camp			Relief Distribution Centres		
	Bajali	110	53(Bajali 27, Sarupeta 26)			57(Bajali 8, Sarupeta 49)		
	Baksa	2	1(Barama 1, Jalah 0)			1(Barama 0, Jalah 1)		
	Barpeta	36	2(Sarthebari 2, Barpeta 0)			34(Sarthebari 16, Barpeta 18)		
	Chirang	4	0(Sidli 0)			4(Sidli 4)		
	Darrang	7	1(Patharighat 1, Sipajhar 0)			6(Patharighat 1, Sipajhar 5)		
	Dhubri	4	4(Bilasipara 4)			0(Bilasipara 0)		
	Goalpara	3	1(Lakhipur 1)			2(Lakhipur 2)		
	Kamrup	5	4(Rangia 4, Kayan 0)			1(Rangia 0, Kayan 1)		
	Lakhimpur	3	0(Nowboicha 0, Bihpuria 0)			3(Nowboicha 2, Bihpuria 1)		
Nalbari	35	28(Paschim Nalbari 15, Banekuchi 3, Nalbari 2, Barbhag 2, Ghograpar 6)			7(Paschim Nalbari 0, Banekuchi 0, Nalbari 7, Barbhag 0, Ghograpar 0)			

	Tamulpur	11	7(Goreswar 1, Tamulpur 6)			4(Goreswar 4, Tamulpur 0)				
	Total	220	101			119				
Inmates In Relief Camps	District/S ub- division*	Total	Revenue Circlewise			Male	Female	Children	Pregnant / Lactating Mother	Person with Disability
	Bajali	5036	(Bajali 2566), (Sarupeta 2470)			2239	2092	686	11	8
	Baksa	264	(Baganpara 0), (Baska 0), (Jalah 0), (Barama 264)			84	139	40	1	0
	Barpeta	279	(Chenga 0), (Sarthebari 279)			118	128	33	0	0
	Darrang	92	(Dalgaon 0), (Mangaldoi 0), (Sipajhar 0), (Patharighat 92)			30	26	36	0	0
	Dhubri	860	(Golakganj 0), (South Salmara Part 0), (Bilasipara 860)			357	333	170	0	0
	Goalpara	136	(Lakhipur 136)			62	47	24	2	1
	Kamrup	164	(North Ghy 0), (Kamalpur 0), (Rangia 164), (Hajo 0), (Kayan 0)			71	68	20	2	3
	Nalbari	5232	(Barkhetri 0), (Paschim Nalbari 2872), (Nalbari 51), (Tihu 0), (Ghograpar 1542), (Banekuchi 282), (Barbhag 485)			2359	2113	713	30	17
	Tamulpur	607	(Goreswar 71), (Tamulpur 536)			246	221	137	3	0
	Total	12670				5566	5167	1859	49	29
Human Lives Lost - Confirmed	District/S ub- division*	Total	Male	Female	Children	Revenue Circlewise				
	Baksa	1	1	0	0	(Baganpara 1), (Barama 0), (Baska 0), (Jalah 0)				
	Nalbari	1	1	0	0	(Banekuchi 1), (Barbhag 0), (Barkhetri 0), (Ghograpar 0), (Nalbari 0), (Paschim Nalbari 0), (Tihu 0)				
	Total	2	2	0	0					
Human Lives Lost Confirmed - Death Type	District/S ub- division*	Total	Flood Death	General Drowning (Non Flood)	Landslide					
	Baksa	1	1	0	0					
	Nalbari	1	1	0	0					
	Total	2	2	0	0					
Human Lives Lost - Missing	Nil									
Human Lives Lost Missing - Type	Nil									
Animals Affected	District/S ub- division*	Total	Big	Small	Poultry					
	Bajali	149965	80948	55185	13832					
	Barpeta	67030	25644	25476	15910					
	Darrang	9085	5830	3115	140					
	Dibrugarh	5068	4118	950	0					
	Goalpara	643	150	170	323					
	Kamrup	6618	3821	2797	0					
	Lakhimpur	5403	4091	1312	0					
	Nalbari	134093	56546	44467	33080					
	Tamulpur	32150	20732	11418	0					
	Total	410055	201880	144890	63285					
Animals Washed Away	District/S ub- division*	Total	Big	Small	Poultry					
	Bajali	764	0	0	764					
	Nalbari	200	0	0	200					
	Total	964	0	0	964					

Houses Damaged	District/S sub-division*	Fully Kuccha	Fully Pukka	Fully Total	Partially Kuccha	Partially Pukka	Partially Total	Others Huts	Others Cattle Shed	Others Total
	Baksa	3	0	3	183	0	183	0	0	0
	Kamrup	0	0	0	79	0	79	0	0	0
	Tamulpur	0	0	0	28	2	30	0	0	0
	Total	3	0	3	290	2	292	0	0	0
Rescue Operation	District/S sub-division*	Agency			Boats Deployed	Person Evacuated By Boats	Animal Evacuated By Boats	Helicopters Deployed	Person Evacuated By Helicopters	Medical Team Deployed
	Bajali	Circle Office/Local Administration, Local People			3	0	0	0	0	9
	Barpeta	SDRF			1	14	1	0	0	0
	Darrang	Circle Office/Local Administration			0	0	0	0	0	2
	Goalpara				0	0	0	0	0	1
	Kamrup				0	0	0	0	0	2
	Lakhimpur				0	0	0	0	0	4
	Nalbari				1	0	0	0	0	0
	Total				5	14	1	0	0	18
Relief Distributed	District/S sub-division*	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)		
	Bajali	746.22	132.63	93.00	93.00	0.00	704.00	0.00		
	Baksa	0.00	0.00	0.00	0.00	0.00	163.60	0.00		
	Barpeta	44.36	5.87	2.38	185.17	0.00	205.00	0.00		
	Chirang	0.00	0.00	0.00	0.00	0.00	0.00	100.00		
	Darrang	2.25	0.42	0.13	12.50	0.00	0.00	250.50		
	Dhubri	14.46	2.58	0.77	77.40	0.00	0.00	0.00		
	Goalpara	0.00	0.00	0.00	0.00	0.00	0.00	12.23		
	Kamrup	1.96	0.38	0.11	11.34	0.00	60.00	0.00		
	Lakhimpur	0.00	0.00	0.00	0.00	0.00	0.00	100.00		
	Nalbari	106.93	17.99	5.39	539.22	0.00	4489.97	0.00		
	Tamulpur	62.02	11.03	3.31	330.75	0.00	94.71	0.00		
Total	978.20	170.90	105.09	1249.38	0.00	5717.28	462.73			
Relief Distributed Others	District/S sub-division*	Baby Food Liquid		Baby Food Solid		Others				
	Bajali	0.00-ml, 0.00-Q		329.00-Pkt		Candle-600.00-Pkt; Match Box-75.00-Pkt; M.Coil-150.00-Pkt; Tarpaulin-10446.00-Pieces; Wheat bran-1040.40-Q				
	Baksa	0.00-Pkt, 0.00-Q		0.00-Pkt, 0.00-Q		0-0.00-Pkt				
	Barpeta	0.00-Q		0.00-Q						
	Chirang	97.00-L		97.00-Kg		Tarpaulin-15.00-Pieces				
	Darrang	2.00-L, 0.00-Q		2.00-Pkt, 0.00-Q		candles-15.00-Pkt; mosquito repellent coil-10.00-Pkt; matchbox-5.00-Pkt; sanitary napkin-26.00-Pkt; 0-0.00-Q				
	Dhubri	0.00-Q		0.00-Q						
	Goalpara	25.00-Pkt		75.00-Pkt		Cheera-0.34-Q; Gur-0.08-Q				
	Kamrup	10.00-Pkt, 0.00-Q		10.00-Pkt, 0.00-Q		Candle-30.00-Pkt; Mosquito Coil-20.00-Pkt; Sanitary Napkin-20.00-Pkt; Drinking water-2500.00-Pkt; 0-0.00-Q				
	Lakhimpur	0.00-Q		0.00-Q		Tarpaulin-297.00-Pieces				
	Nalbari	0.00-Q		0.00-Q		0-0.00-Q; Masquito Coil-758.00-Pkt; Candle-2358.00-Pkt; Phenyl-431.00-Pkt; Wheat bran -1367.00-Q; Masquito coil-640.00-Pkt; Match -640.00-Pkt; Sanitary Napkin-124.00-Pkt				
Tamulpur	0.00-Q		0.00-Q		Tarpaulin -20.00-Q; Chira-28.19-Q; Gur-39.18-Q; Mosquito coil-323.00-Pkt; Match box-323.00-Pkt; Candle -323.00-Pkt; Water bottle -6460.00-L					
Infrastructure Damaged	District/S sub-division*	Number	Details							

- Embankment Breached	Darrang	4	<p>Mangaldoi - CM Dutta Bund FIS At village Mollapara As reported by Dept. embankment breach occurred at Main Canal of CM Dutta Bund FIS at Ch 8700m. Approx. length of damage is 10-12m. Dated 24/04/2023. (Long - 91.994520, Lat - 26.444710, Dept - Irrigation),</p> <p>CM Dutta Bund FIS At village Bezpara As reported by Dept. embankment breach occurred at Main Canal of CM Dutta Bund FIS at Ch 10500m. Approx. length of damage is 10-11m. Dated 24/04/2023. (Long - 91.994520, Lat - 26.444710, Dept - Irrigation),</p> <p>CM Dutta Bund FIS At village Mollapara As reported by Dept. embankment breach occurred at Main Canal of CM Dutta Bund FIS at Ch 8800m. Approx. length of damage is 5-6m. Dated 24/04/2023. (Long - 91.994500, Lat - 26.444700, Dept - Irrigation),</p> <p>CM Dutta Bund FIS At village Bezpara As reported by Dept. embankment breach occurred at Main Canal of CM Dutta Bund FIS at Ch 10470m. Approx. length of damage is 6-7m. Dated 24/04/2023. (Long - 91.994520, Lat - 26.444710, Dept - Irrigation)</p>
	Total	4	
Infrastructure Damaged - Embankment Affected	District/Sub-division*	Number	Details
	Biswanath	1	Gohpur - Mild bank erosion is observed at R/Bank embankment of Sessa at Auguri area for a length of 30 mtr on 24/06/23 (Long - 93.733716, Lat - 26.951885, Dept - BRO)
	Golaghat	1	Bokakhat - Un embankment portion of Alengmari area at ch. 13000m (Alengmari) Inundation of Berkep,Alengmari village area about 25m that took place on 23.06.2023 was caused by the back water from the river Dhansiri (Long - 93.412223, Lat - 26.412980, Dept - Water Resource Deptt.)
	Kamrup	3	<p>Hajo - Puthimari embankment Hadal manakuchi On 23/06/2023 as per water resource department seepage,boiling, leakage was observed . The restoration work done at L/B embankment of river puthimari of 2.76 km from gallipar to hadal by WRD. (Long - 26.282500, Lat - 91.575000, Dept - Water Resource Deptt.),</p> <p>Puthimari embankment Kaya Jani, boromboi Boiling and seepage reported by water resource department on 23/06/2023 on R/B embankment of puthimari river at kayajoni and ulletia and boromboi for 5.7km (Long - 26.287700, Lat - 91.585000, Dept - Water Resource Deptt.),</p> <p>Brahmaputra dyke Hatimura to adabari B/dyke T tangonmari is a level crossing of the embankment with village road. Was damaged for 25m length by tractor on 23/06/2023 asreported by WRD . (Long - 26.240000, Lat - 91.580000, Dept - Water Resource Deptt.)</p>
	Nalbari	10	<p>Nalbari - Pagaldia embankment Bhadra As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - BRO),</p> <p>Pagaldia embankment Barmurikona As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.),</p> <p>Pagaldia embankment at poila Poila As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.),</p> <p>Pagaldia embankment Balilcha As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.),</p> <p>Pagaldia embankment Digheli As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.),</p> <p>Pagaldia embankment Digeli balajan suburi As per the report of WR department this embankment is affected due to raising of water on 23.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - Water Resource Deptt.),</p> <p>Ghograpar - Noona Embankment Gargari On 22/06/2023 as per WRD, Embankment overtopped occurs near Gargari area on L/B of river noona at Ch 500 m. (Long - 91.570000, Lat - 26.550000, Dept - BRO),</p> <p>Noona Embankment Namati On 22/06/2023 as per WRD, Embankment overtopped occurs near Namati area on R/B of river noona at Ch 3500 m. (Long - 26.580000, Lat - 91.560000, Dept - Water Resource Deptt.),</p> <p>Noona Embankment Bilpar On 22/06/2023 as per WRD, Embankment overtopped occurs near Namati area on R/B of river noona at Ch 3500 m. (Long - 91.550000, Lat - 26.440000, Dept - Water Resource Deptt.),</p> <p>Pagladia Embankment Pub-Barsira(Bhadar) On 19/06/2023 as per WRD, Embankment overtopped occurs near Bhadar (Pub-Barsiral) area on L/B of river pagladia ch - 3th KM (Long - 91.530000, Lat - 26.560000, Dept - Water Resource Deptt.)</p>
Total	15		
Infrastructure Damaged - Road	District/Sub-division*	Number	Details
	Bajali	23	<p>Sarupeta - Galia to Tapa via Gathiapara Gathiapara Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Datirbori to Rajakhat Road Rajakhat Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Karagari Bazar area Road Karagari Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept -</p>

		<p>PWD (Roads)), Majgaon Anandapur road Majgaon Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Bhawanipur Gopal Ata Satra Road Bhawanipur Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), BB road to Gathiapara via Dangarpar Gathiapara Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Tihu Palha Simlaguri Road Simlaguri Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), ADP road to Majgaon Majgaon Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Galia Sukmanah Road Sukmanah Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Banglipara Sarupeta road Banglipara Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), ADP Bazar to Gohain Kamal Ali road Pota Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), NH-31 to Banglipara Shivmandir road banglipara Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Majgaon Kaljar road Kaljar Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Majgaon Dulirvitha road Majgaon Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Phulartal Porabharal road Porabharal Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Sukmanah MPNA road Sukmanah Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), MPNA to Galia Sukmanah road Galia Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Sukmanah Bazar road Sukmanah Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), NH-31 to Kahara gaon road Kahara Gaon Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Laogaon Hudukhata road Hudukhata Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Chaulabari to Palla river via Kahlpara road Kahlpara Road submerged as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Gopal Ata Satra road Bhawanipur Road submerged and bridge approaches erroded as per the report received from AEE, PWRD Bhawanipur TR Sub-Division, Bhawanipur dated 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))</p>
Baksa	6	<p>Jalah - Bh College to Bunmajapam road Bunmajapam As per the information received from PWD deptt. Due to continous havy rainfall the road surface and side berm has been damaged and hp culvert washed away at (CH 400.00M & 4050) on 21-06-2023 (Long - 91.000470, Lat - 4000.000000, Dept - PWD (Roads)), Tanagamari to Mushalbari Road Tangamari As per the information received from PWD deptt. Surface has been breached 1500.00 M on 21-06-2023 (Long - 26.631759, Lat - 91.086400, Dept - PWD (Roads)), Kawimari to Borghopa road kawiamri As per the information received from PWD deptt. The HP culvert has been damaged at 500.00 m on 21-06-2023 (Long - 91.045465, Lat - 26.557869, Dept - PWD (Roads)), Samuhathi Market to Baharuddin House Pokalagi As per the information received from PWD deptt.</p>

		<p>Surface and side been damage at (CH 900.00 M, CH 1000.00, Ch1100.00 M and CH 1300.00M) on on 21-06-2023. (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), No 2Dakhin Dumriguri Prathomik Vidyalay Road Santi bazar to sansuma basumatary house kalbari As per the information received from PWD deptt. Approach has been damage at ch 2150 , Dated - 21/06/2023 (Long - 91.053218, Lat - 26.600486, Dept - PWD (Roads)), Hazua Nalbari road hazua nalbari As per the information received from PWD deptt. Surface side beam has been damage 6400.00 M on 21-06-2023 (Long - 91.291314, Lat - 26.732984, Dept - PWD (Roads))</p>
Barpeta	22	<p>Barpeta - BB road to DK road via Madhya Chakirbhitha road Chakirbhitha As per report received from PWD Roads Dept BB road to DK road via Madhya Chakirbhitha road fully submerged, Side berms and road surface damaged in stTetches. Reported by PWD .Date-23-06-2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), BB road at Lakhi bazar to Khablarbhtiha Khablarbhtiha As per report received from PWD Roads Dept BB road at Lakhi bazar to Khablarbhtiha road fully submerged. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Dangarkuchi to Deurikuchi road Deurikuchi As per report received from PWD Roads Dept Dangarkuchi to Deurikuchi road fully submerged. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), NIJ-31 to Pub Kaljhar road Kaljhar As per report received from PWD Roads Dept NIJ-31 to Pub Kaljhar road fully submerged. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), UK road (NI1-31 to Jarabari) PMGS Y road Jarabari As per report received from PWD Roads Dept UK road (NI1-31 to Jarabiiri) PMGS Y road subniergcil iii stretches. Side bcmis and road surfacti damaged in stretches. Reported by PWD .Date-23-06-2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Putlartary Chowk to Bantipiir road Putlartari Bantipur As per report received from PWD Roads Dept Putlartary Chowk to Bantipiir road fully submergetl. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023. (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Putlartary Tini Ali to Bantipur Road Putlartari Bantipur As per report received from PWD Roads Dept Putlartary Tini Ali to Bantipur Road fully submerged. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023. (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), DK road to Bhalukabari Pathar via Bhalukabari Gaon Bhulukabari Gaon- Bhulukabari Pathar As per report received from PWD Roads Dept DK road to Bhalukabari Pathar via Bhalukabari Gaon. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), BAMunbari Kujarpith road Baminbari- Kujarpith As per report received from PWD Roads Dept Bamunbari Kujarpith road fully submerged. Side berms and road surface damaged in stretches. (PMGSY completed Pkg- AS-01-508).Reported by PWD .Date-23-06-2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Kayakuchi Village road Bhakuamari, Maricha As per report received from PWD Roads Dept Kayakuchi Village road fully submerged. Side berms and road surface damaged in stretches. Reported by PWD .Date-23-06-2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Barpeta Patbaushi Keotkuchi Road Patbaushi Keotkuchi As per report received from PWD Roads Dept Side berm eroded & Hard Crust damaged at several stretches .Reported by PWD .Date-23-06-2023 (Long - 91.032534, Lat - 26.298922, Dept - PWD (Roads)), Baradi Tatikuchi Road Baradi Tatikuchi As per report received from PWD Roads Dept Road submerged and breach occurred at several stretches .Reported by PWD .Date-23-06-2023 (Long - 91.038035, Lat - 26.325899, Dept - PWD (Roads)), 918 No. Metuakuchi LPS Road Metuakuchi As per report received from PWD Roads Dept Side berm eroded & Hard Crust damaged at several stretches. Reported by PWD .Date-23-06-2023 (Long - 90.995401, Lat - 26.319517, Dept - PWD (Roads)), arpeta Guwahati PWD road to Keotkuchi Namghar and app. Of RCC Br. No 3/1 on BD Road Keotkuchi As per report received from PWD Roads Dept Barpeta Guwahati PWD road to Keotkuchi Namghar and app. Of RCC Br. No 3/1 on BD Road. Reported by PWD .Date-23-06-2023 (Long - 91.046317, Lat - 26.312914, Dept - PWD (Roads)), Keotkuchi Mailkuchi Road Keotkuchi Mailkuchi As per report received from PWD Roads Dept Road submerged. Reported by PWD . Date-23-06-2023 (Long - 91.054898, Lat - 26.305494, Dept - PWD (Roads)), Pohumara Temura Road Pohumara Temura As per report received from PWD Roads Dept Road submerged and side berm damage in several stretches. Reported by PWD .Date-23-06-2023 (Long - 91.017738, Lat - 26.281450, Dept - PWD (Roads)), Patbaushi Nangalkur Road to Barpeta Baghbar Road via Majorgaon and Nalirpam Patbaushi Nangalkur As per report received from PWD Roads Dept Side berm and hard crust damage in several stretches. Reported by PWD .Date-23-06-2023 (Long - 91.008945, Lat - 26.293674, Dept - PWD (Roads)), Bhella Tatikuchi Road Bhella Tatikuchi As per report received from PWD Roads Dept Approach of RCC Br. No. 2/1 is eroding due to heavy flood of water. Reported by PWD .Date-23-06-2023 (Long - 91.076617, Lat - 26.321520, Dept - PWD (Roads)), Barpeta Howly Road to Barpeta Medical College Road (SH-2). Dabaliapara As per report received from PWD Roads Dept Side berm eroded and hard crust damaged . Reported by PWD .Date-23-06-2023</p>

			<p>(Long - 90.995506, Lat - 26.336415, Dept - PWD (Roads)), Nakhanda E&D Road Nakhanda area As per report received from PWD Roads Dept Side berm eroded. Reported by PWD .Date-23-06-2023 (Long - 91.020083, Lat - 26.302272, Dept - PWD (Roads)), Ganakkuchi to Karertal via Barpeta Polytechnic Institute and Model School at Barpeta Ganakkuchi As per report received from PWD Roads Dept Side berm eroded. Reported by PWD .Date-23-06-2023 (Long - 91.001025, Lat - 26.306051, Dept - PWD (Roads)), Nagaon Sikarvitha Road Nagaon As per report received from PWD Roads Dept Side berm eroded and hard crust damaged .Reported by PWD .Date-23-06-2023 (Long - 91.101908, Lat - 26.329283, Dept - PWD (Roads))</p>
Bongaigaon	43		<p>Bongaigaon - Kashidoba Kakoijana Road Kashidoba Kakoijana Road Road hard crust damaged at various stretches from Ch. 800.00m to 1500.00m and Embankment damaged at 5th Km. as per report received from PWRD, Bongaigaon dated-23.06.2023 (Long - 90.601127, Lat - 26.419829, Dept - PWD (Roads)), Nakkati Hill approach road Nakkati Hill approach road Road submerged from Ch. 2000.00m to Ch. 2160.00m and Bridge approach of Bridge No. 3/1 damaged, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.529457, Lat - 26.398712, Dept - PWD (Roads)), Nakkati Hill approach road Nakkati Hill approach road Bridge approach of Br. No. 3/2 damaged completely. As per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.533769, Lat - 26.398341, Dept - PWD (Roads)), Dholagaon Tilapara(Dewangaon) road Dholagaon Tilapara(Dewangaon) road Breached out from Ch.1500.00m to Ch.1535.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.526484, Lat - 26.405792, Dept - PWD (Roads)), Majgaon Nigamghola(Kandulimari Pahar NC) Majgaon Nigamghola(Kandulimari Pahar NC) Embankment damaged at Ch.400.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.572449, Lat - 26.413344, Dept - PWD (Roads)), New Bongaigaon Dhaligaon Road New Bongaigaon Dhaligaon Road Surface damaged, water logged and muddy surface formed from Ch.0.00m to Ch.500.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.523670, Lat - 26.490165, Dept - PWD (Roads)), New Bongaigaon Dhaligaon Road New Bongaigaon Dhaligaon Road Surface damaged and water logged from Ch.500.00m to Ch.900.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.523272, Lat - 26.490535, Dept - PWD (Roads)), Bagheswari temple to Chitkagaon Road Bagheswari temple to Chitkagaon Road Side slope eroded and hard crust damaged, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.565225, Lat - 26.469981, Dept - PWD (Roads)), NH-31C Popragaon PMGSY Road to Korebari NH-31C Popragaon PMGSY Road to Korebari Side slope eroded at Ch.1st Km, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.619676, Lat - 26.489413, Dept - PWD (Roads)), Boitamari - Sankarghola kherpuji road Kherpuji Hard crust & shoulder damage at ch 6th km on 23/06/2023 (Long - 90.547499, Lat - 26.280913, Dept - PWD (Roads)), Sankarghola kherpuji road Kherpuji Landslide at ch 6th km submitted on 23/06/2023 by pwdr (Long - 90.517716, Lat - 26.289992, Dept - PWD (Roads)), Sankarghola to kherpuji road Kherpuji Landslide at ch 1st km and ch 2nd km submitted on 23/06/2023 by PWDR (Long - 90.519196, Lat - 26.264915, Dept - PWD (Roads)), Dangtol - Talguri Basugaon Road Talguri Basugaon Road Embankment Damaged at Ch. 13050.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.437166, Lat - 26.425305, Dept - PWD (Roads)), Fulkumari to Durgamandir road Fulkumari to Durgamandir road Embankment damaged at various stretches from 800.00m to 2100.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.431975, Lat - 26.360219, Dept - PWD (Roads)), Paltanbazar to Hollaguri road Paltanbazar to Hollaguri road Embankment damaged at various stretches from 2000.00m to 3000.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.423056, Lat - 26.383126, Dept - PWD (Roads)), Manikpur - Gerukabari to Kirtanpara road Kirtanpara Road submerged from Ch.9300.00m to Ch.9400.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.754335, Lat - 26.410217, Dept - PWD (Roads)), Hapachara Barbila to Nachanguri Road Nachanguri Hard crust, side slope and shoulder got damaged, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.662334, Lat - 26.433170, Dept - PWD (Roads)), Patiladaha Monakoch to Baobari Road Baobari Breached out for about 20m at Ch.970.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.797627, Lat - 26.494121, Dept - PWD (Roads)), Gerukabari Jamdoha PMGSY Road Jamdoha Breached out at Ch.752.00m to Ch.970.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.701968, Lat - 26.451735, Dept - PWD (Roads)), NH-31 to Dankinamari village Road Dankinamari Submerged for a length of 200.00m at Ch.720.00m to Ch.920.00m(Depth is 30cm), as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.641590, Lat - 26.493949, Dept - PWD (Roads)), Manasghat Sakisali Road Sakisali Road shoulder damaged/eroded from Ch.1st Km to Ch.9th Km, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.755204, Lat - 26.462392,</p>

		<p>Dept - PWD (Roads)), Roha Chakla Kokila Road Kokila Road surface damaged at Ch.10th Km, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.840281, Lat - 26.358849, Dept - PWD (Roads)), Dhupuri Garoleti road Garoleti Submarged from Ch. 100.00 to Ch. 150.00m and Ch.250.00m to Ch. 300.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.795634, Lat - 26.485596, Dept - PWD (Roads)), Purana Bijni to Patiladaha road Patiladaha Bridge approach of SPT Br. No. 8/1 partially damaged, clearing of water hyacinth on urgent basis, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.788278, Lat - 26.489028, Dept - PWD (Roads)), Gerukabari Jamdoha PMGSY road Jamdoha Approaches of culvert No. 1/2 and culvert No. 1/3 damaged, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.704193, Lat - 26.453973, Dept - PWD (Roads)), Patiladaha Lungijhar road Lingijhar Submarged from Ch. 900.00 to Ch. 9400.00m (depth of submargenece=45cm), as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.795054, Lat - 26.497138, Dept - PWD (Roads)), Sialmari Salmara road to Lungijhar village road Salmara Shoulder damaged from Ch.0.00 to Ch.600.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.777098, Lat - 26.490723, Dept - PWD (Roads)), Dhupuri No.2 to Bhatipara road Bhatipara Submarged from Ch.0.00 to Ch.300.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.793977, Lat - 26.481545, Dept - PWD (Roads)), Siamari Salmara road Salmara Submarged at Ch. 1st ,2nd and 3rd Km at a depth of 45cm, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.773557, Lat - 26.487288, Dept - PWD (Roads)), Patiladaha Monakocha to Baobari road Baobari Submarged from Ch. 200.00 to Ch. 300.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.797646, Lat - 26.493940, Dept - PWD (Roads)), Patiladaha to Dhupuri road Dhupuri Submarged from Ch. 200.00 to Ch. 220.00m, Ch.2800.00 to Ch.2830.00m and Ch.2900.00m to Ch. 2925.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.798906, Lat - 26.489634, Dept - PWD (Roads)), Srijangram - Ujanpara Ambari Road Ujanpara Ambari Submarged at Ch.2600.00m to Ch.2630.00m(Depth is 10cm), as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.705871, Lat - 26.356202, Dept - PWD (Roads)), Tilapara to Ambari Kacharipety Road Tilapara to Ambari Kacharipety Embankment erosion at Ch.200.00m, Ch. 250.00m and Ch.400.00m, as per report received from PWRD, Bongaigaon, dated- 23.06.2023 (Long - 90.704720, Lat - 26.343670, Dept - PWD (Roads)), Tilapara to Ambari Kacharipety Road Tilapara to Ambari Kacharipety Road surface damaged at different stretches from Ch.630.00m, Ch. 2600.00m. As per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.710783, Lat - 26.344962, Dept - PWD (Roads)), Tulungia Borghola Road Tulungia Borghola Aproach of Br No.6/1 damaged at one End at Ch. 5400.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.680562, Lat - 26.389148, Dept - PWD (Roads)), Ambari PWD road to Gauranga mandir Road Ambari PWD road to Gauranga mandir Shoulder and hard crust damaged at 1st Km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.723220, Lat - 26.337210, Dept - PWD (Roads)), SH-2 to Anganbadi centre Road SH-2 to Anganbadi centre Shoulder and hard crust damaged at 1st Km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.709410, Lat - 26.330510, Dept - PWD (Roads)), Abhayapuri to Malegarh road. Abhayapuri to Malegarh Land slide & shoulder eroded at Ch. 12th km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.647675, Lat - 26.271010, Dept - PWD (Roads)), Abhayapuri to Malegarh road Abhayapuri to Malegarh Shoulder damaged at Ch. 11th km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.647620, Lat - 26.270745, Dept - PWD (Roads)), Abhayapuri to Malegarh road Abhayapuri to Malegarh Shoulder damaged at Ch. 10th km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.645970, Lat - 26.268709, Dept - PWD (Roads)), Tulungia Borghola road Tulungia Borghola Hill land slide disrupted drain water flow and damaged hard crust at three places of hill portion Ch. 5th & 4th Km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.671399, Lat - 26.386708, Dept - PWD (Roads)), Sidalsuti Mererchar road cum embankment. Sidalsuti Mererchar Shoulder and brick drain damaged at Ch.9th , 10th and 11th Km, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.730473, Lat - 26.389184, Dept - PWD (Roads)), SH2 road SH2 road Shoulder and hard crust damaged at Ch.37940.00m, as per report received from PWRD, Bongaigaon, dated-23.06.2023 (Long - 90.780225, Lat - 26.311685, Dept - PWD (Roads))</p>
Dhubri	22	<p>Chapar - SATYAPUR LAKSHIMANDIR TO SAGALKHUTI ROAD LATITUDE:-26.271719 LONGITUDE -90.428868 (Dated 23-06-2023) Satyapur Due to rain (Long - 90.428868, Lat - 26.271719, Dept - PWD (Roads)), BANIAPARA TO CHIRAKUTA ROAD(.)LATITUDE:-26.231677 LONGITUDE -90.262603, (Dated</p>

		<p>23-06-2023) Baniapara Due to rain (Long - 90.264782, Lat - 26.231677, Dept - PWD (Roads)), TILAPARA TO NOONMATI ROAD(.) UNDER PMGSY –I FOR THE YEAR 2017-18 PACKAGE NO AS -05-116 BOTH SIDE APPROACH DAMAGE AND ERRODED DUE TO HEAVY RAIN WATER(.) LATITUDE:-26.201662, LONGITUDE -90.331209 AND LATITUDE:-26.201935, LONGITUDE -90.330932 (Dated 23-06-2023) Noonmati Pt-I Due to heavy rain (Long - 90.330932, Lat - 26.201935, Dept - PWD (Roads)), NH-31 TO BALOKERKHAL ROAD(.) UNDER PMGSY I AT CH. 3.50 KM ERROSION OF SIDE SLOPE OF ROAD AND DAMAGE OF EXISTING ICBP CARRIAGEWAY DUE TO HEAVY RAIN WATER(.) LATITUDE:-26.197589, LONGITUDE -90.339693 (Dated 23-06-2023) Balokerkhal Due to rain (Long - 90.339693, Lat - 26.197589, Dept - PWD (Roads)), NH-31 TO BALOKERKHAL ROAD(.) UNDER PMGSY I BRIDGE NO. 4/1BOTH SIDE APPROACH DAMAGED DUE TO HEAVY RAIN WATER(.) LATITUDE:-26.20127, LONGITUDE : -90.340139 (Dated 23-06-2023) UNDER PMGSY –I FOR THE YEAR 2017-18 PACKAGE NO AS -05-128 Balokerkhal Due to rain (Long - 90.340139, Lat - 26.201270, Dept - PWD (Roads)), Gauripur - ROAD FROM KENDRIYA VIDYALAYA PANBARI TO ITI ALOMGANG (SIDE BERM ERODED) (Date-22-06-23) ALOMGANG (Long - 90.037335, Lat - 26.135215, Dept - PWD (Roads)), Ghageralga Road BUG Br. To Boraibari Road (.) (HPC DAMAGED AND SIDE BERM DAMAGED) (Date-22-06-23) Ghageralga (Long - 90.027112, Lat - 90.027112, Dept - PWD (Roads)), PANBARI IDGAH TO NOVODOY VIDAYALAYA AT 2ND KM (SIDE BERM DAMAGED) PANBARI (Long - 90.046290, Lat - 26.133457, Dept - PWD (Roads)), Dhubri - SIDE BERM, SIDE SLOPES WITH HARD CRUST FULLY DAMAGED ON KANURI DIMAKURI ROAD AT BINNACHARA AT CH. 12TH ,13TH & 14TH KM (DATE-22-06-23) BINNACHARA (Long - 89.827607, Lat - 25.992487, Dept - PWD (Roads)), Bilasipara - T03-UDMARI SALKOCHA ROAD(.) UNDER PMGSY –III FOR THE YEAR 2020-21 PACKAGE NO AS -05-209 SIDE BERM ERROSION AT CH. 5400.00M , 5300.00M, AT SEVERAL STREATCHES UDMARI SALKOCHA ROAD dated 21-06-23 to 22-06-2023 (Long - 90.318317, Lat - 26.260265, Dept - PWD (Roads)), BAMUNPARA PT-4 TO KAZAIKATA PT-I ROAD BAMUNPARA PT-4 TO KAZAIKATA PT-I ROAD dated 21-06-23 to 22-06-2023 (Long - 90.255290, Lat - 26.226128, Dept - PWD (Roads)), SUAPATA PT-I TO KAZAIKATA PT-I ROAD SUAPATA PT-I TO KAZAIKATA PT-I ROAD dated 21-06-23 to 22-06-2023 (Long - 90.280969, Lat - 26.205678, Dept - PWD (Roads)), KATHALDI PT-III VILLAGE ROAD(.) RCC BRIDGE NO 1/1 KATHALDI PT-III VILLAGE ROAD dated 21-06-23 to 22-06-2023 (Long - 6.902317, Lat - 5.262219, Dept - PWD (Roads)), South Salmara Part - Airkata Jaleswar road to Gunaipani under PMGSY pk AS05153 Airkata As per report recived from EE PWRD Airkata Jaleswar road to Gunaipani under PMGSY pk AS05153 road has been damaged at Ch 1500m to ch 1800 lenth 300 m as on 23.06.23 due to heavy rainfall. (Long - 90.101700, Lat - 25.959000, Dept - PWD (Roads)), Tarangajhar steel bridge to Airkata road Tarangajhar As per report recived from EE PWRD Tarangajhar steel bridge to Airkata road has been damaged at Ch 5th km lenth 50 m as on 23.06.23 due to heavy rainfall. (Long - 90.148000, Lat - 25.985000, Dept - PWD (Roads)), Athani - NH-31 AT MAKRIJHORA TO PIAZBARI 1, SIDE BERM AND SURFACE DAMAGED 2NDKM ADN 3RD KM DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.93654 & LONGITUDE: 90.174300). NH-31 AT MAKRIJHORA TO PIAZBARI 1 AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 (Long - 90.174300, Lat - 26.936540, Dept - PWD (Roads)), NH-31 AT SATAGURI TO DALANERLGA PT-II ROAD, SIDE BERM AND SURFACE DAMAGED 1ST KM 2ND KM DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.160343 & LONGITUDE: 90.054166). NH-31 AT SATAGURI TO DALANERLGA PT-II ROAD, AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 (Long - 90.054166, Lat - 26.160343, Dept - PWD (Roads)), MAHAMAYA IB TO GUTIPARA ROAD, PMGSY, PACKAGE NO. AS-05-43 ROAD SUBMERGED 1ST KM DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.264072 & LONGITUDE: 90.15236). MAHAMAYA IB TO GUTIPARA ROAD AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 (Long - 90.152360, Lat - 26.264072, Dept - PWD (Roads)), NH-31 AT BAGRIBARI TO MAKRIJHORA ROAD, SIDE BERM AND SURFACE DAMAGED AT CH. 2ND KM AND 3RD KM DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.188784 & LONGITUDE: 90.116537). NH-31 AT BAGRIBARI TO MAKRIJHORA ROAD AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 (Long - 90.116537, Lat - 26.188784, Dept - PWD (Roads)), 2ND KM OF BAGRIBARI BANIAMARI ROAD TO SADHUBHASA PT-IROAD SIDE BERM AND SURFACE AT CH.1ST & 2ND KM DUE TO WATER OF GOURANG RIVER (.) (LATITUDE: 26.180808 & LONGITUDE: 90.12114). 2ND KM OF BAGRIBARI BANIAMARI ROAD TO SADHUBHASA PT-IROAD AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 (Long - 90.121140, Lat - 26.180808, Dept - PWD (Roads)), TOPRAJHOWPARA PT-I TO TOPRAJHOWPARA PT-II ROAD ,SIDE BERM AND SURFACE DAMAGED AT CH. 1ST KM DUE TO WATER GOURANG RIVER (.) (LATITUDE: 26.322367 & LONGITUDE: 90.165705). TOPRAJHOWPARA PT-I TO TOPRAJHOWPARA PT-II ROAD AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 (Long - 90.165705, Lat - 26.322367, Dept - PWD (Roads)), NH-31 AT ARIANI TO NOISERDhab ROAD SIDE BERM AND SURFACE DAMAGRED 1ST KM</p>
--	--	---

			, DUE TO WATER OF TIPKAI RIVER (.) (LATITUDE: 26.195951 & LONGITUDE: 90.141323). NH-31 AT ARIANI TO NOISERDHAB ROAD AFFECTED W.E.F. 18/06/2023 TO 22/06/2023 (Long - 90.141323, Lat - 26.195951, Dept - PWD (Roads))
Goalpara	12		<p>Lakhipur - Kurshakati Salmara PMGSY Road Near Kurshakati As per report of PWD Road department, Due to incessant rainfall for several days Kurshakati Salmara PMGSY Road RCC Br. No. 2/1 & 3/1 CH. 2600M to CH. 2900M Av. depth of submergence 45CM and Bridge approach eroded and affected length 300M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.353121, Lat - 26.057240, Dept - PWD (Roads)),</p> <p>Rakhakilla Bazar to To Tikrikilla Shibbari Road Near Rakhakilla As per report of PWD Road department, Due to incessant rainfall for several days Rakhakilla Bazar to To Tikrikilla Shibbari Road at 2nd KM to 3rd KM has been submerged 45 CM and affected length 200M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.217851, Lat - 25.958184, Dept - PWD (Roads)),</p> <p>Chataimari Gumaijhar Road Near Gumaijhar As per report of PWD Road department, Due to incessant rainfall for several days Chataimari Gumaijhar Road SPT Br. No. 1/1 at 1st KM, Av. depth of submergence of flash flood from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.213784, Lat - 25.962286, Dept - PWD (Roads)),</p> <p>Lakhipur Khalisabhita Road Near Khalisabhita As per report of PWD Road department, Due to incessant rainfall for several days Lakhipur Khalisabhita Road at 14th KM to 15th KM , Bridge No. 15/1 road submerged 45CM & Bridge Approach eroded and affected length 45M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.185618, Lat - 25.993028, Dept - PWD (Roads)),</p> <p>Gournagar Chataimari Road Near Gournagar As per report of PWD Road department, Due to incessant rainfall for several days Gournagar Chataimari Road at 5th Km road submergence 45CM and affected length 50M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.208543, Lat - 25.968998, Dept - PWD (Roads)),</p> <p>Morichbari to Bausatary Road Near Bausatary As per report of PWD Road department, Due to incessant rainfall for several days Morichbari to Bausatary Road at 1st KM and road submerged 45CM from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.187013, Lat - 25.994671, Dept - PWD (Roads)),</p> <p>Lakhipur Jaleswar Road Near Jaleswar As per report of PWD Road department, Due to incessant rainfall for several days Lakhipur Jaleswar Road subway at Rajmita road submerged 60CM from 18.06.2023 to till date i.e. 24.06.2023 (Long - 90.244209, Lat - 26.031399, Dept - PWD (Roads)),</p> <p>Sarkarergaon PWD road to Dharai PWD Road Near Dharai As per report of PWD Road department, Due to incessant rainfall for several days Sarkarergaon PWD road to Dharai PWD Road at 1st KM sideberm eroded and affected length 110M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Gumaijhar to NEC Rd Tikrikilla Near Gumaijhar As per report of PWD Road department, Due to incessant rainfall for several days Gumaijhar to NEC Rd Tikrikilla at 1st KM road breached and affected length 90M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Hasdoba to Kolabari Majipara Road Near Kolabari As per report of PWD Road department, Due to incessant rainfall for several days Hasdoba to Kolabari Majipara Road at CH. 40M Box cell culvert Damaged and affected length 3M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Lakhipur Khalisavita Road Near Khalisavita As per report of PWD Road department, Due to incessant rainfall for several days Lakhipur Khalisavita Road at CH. 850M & CH. 10200M sideberm eroded and affected length 30M from 18.06.2023 to till date i.e. 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Gournagar Chataimari Road Near Gournagar As per report of PWD Road department, Due to incessant rainfall for several days Gournagar Chataimari Road at CH. 4th KM HP No 4/1 damage from 18.06.2023 to till date i.e. 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))</p>
Golaghat	3		<p>Golaghat - Sapekhathi cholong pathor road Gomariguri Development Block As per the information received from PWD Deptt. road affected due to flash flood of ghiladhari river on 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>Lakhimipathar road Gomariguri Development Block As per the information received from PWD Deptt. road affected due to flash flood of ghiladhari river on 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)),</p> <p>No1. Lilapur to Indrapur connecting road Gomariguri Development Block As per the information received from PWD Deptt. road affected due to flash flood of ghiladhari river on 24.06.2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))</p>
Kamrup	4		<p>Rangia - Dipteswari Temple Road. Nakul Report given by pwd (R) Rangia of road eroded Length 100m, Breath 6m at ch 2.00 Km. Dated 23/06/23 (Long - 91.640577, Lat - 26.426479, Dept - PWD (Roads)),</p> <p>Rangia Dhamdhama road Gurkuchi Report given by pwd (R) Rangia of road damage Length 30m, Breath 6m at ch 4km Dated 23/06/23 (Long - 91.598102, Lat - 26.454051, Dept - PWD (Roads)),</p> <p>Palashbari - kulshi Garubandha Bangelibia Baregaon Road kulshi Garubandha Bangelibia Baregaon Road Erosion due to rainfall on kulshi Garubandha Bangelibia Baregaon Road under Palashbari Territorial Road Sub-div as reported by PWRD, Mirza on 23/06/2023 (Long - 25.959410, Lat - 91.417585, Dept - PWD (Roads)),</p> <p>Batarhat Jharabori Lengta Loharghat Road Batarhat Jharabori Lengta Loharghat Road Submerge of Road due to Rainfall on Batarhat Jharabori Lengta Loharghat Road under Palashbari Territorial Road</p>

			Sub-div as reported by PWRD, Mirza on dated 23/06/2023 (Long - 26.014321, Lat - 91.474725, Dept - PWD (Roads))
	Karimganj	3	Patherkandi - Adamtilla DLF PWD road Lonagai TE Adamtilla DLF PWD road at Longai TE a portion of road has been eroded on 20/06/2023 due to heavy rainfall. approx stretch is 10 sq/ft. (Long - 24.566113, Lat - 92.293053, Dept - PWD (Roads)), Adamtilla road to Mohangool BSF Camp road Adamtilla On 18/06/2023 due to heavy rainfall Adamtilla road to Mohangool BSF Camp road at Adamtilla due to landslide the road has been damaged . approx stretch is 120 meter. (Long - 24.596248, Lat - 92.266734, Dept - PWD (Roads)), Adamtilla road to Mohangool BSF Camp road. Adamtilla On 18/06/2023 due to heavy rainfall Adamtilla road to Mohangool BSF Camp road at Adamtilla the road has been damaged . approx stretch is 37.3 sq/meter (Long - 24.595505, Lat - 92.267770, Dept - PWD (Roads))
	Kokrajhar	1	Dotma - MONAKOCHA VILLAGE ROAD MONAKOCHA AS PER REPORTED BY VILLAGE MAN ON 24.06.2023, DUE TO WATER LOGGING MONAKOCHA VILLAGE HAS BEEN DAMAGED (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Nalbari	17	Barkhetri - Dagapara to Balitpar Road" : Side-berm erroded & damaged, road surface damaged. Affected length: 4 KM. Dagapara, Lautola, Ghoga, Loharkatha, Sutarkuchi, Adabari As reported by AEE, PWRD, Barkhetri on 24-06-23. (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), hamlakur to kurabori sumberged from ch10.00m to 200.00m and side berm eroded at ch 1.50to 1.80KM. Hamlakur As reported by AEE, PWRD, Barkhetri on 24-06-23. (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Nalbari - Sonamati Katra road Katra As per the report of PWD roads this road is submerged due to rain water dtd 24/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Tihu - TIHU AKHARA LINK ROAD BALI,SATHIKUCHI SUBMERGED ROAD,LENGTH IS APPROX 2KMS AS PER REPORT JE, PWD ROAD , ON 23/06/23 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), PWD ROADS HARIBHANGA HARIBHANGA ,BHOJKUCHI SUBMERGED ROAD,AS PER REPORT JE ,PWD ROADS ,TOTAL LENGTH APPROX 1.5 KMS,REPORTED ON 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), BARAMA KAITHALKUCHI ROADS SATHIKUCHI SUBMERGED ROAD AS PER REPORT JE,PWD ROADS ,LENGTH IS APPROS 500 MTS, REPORTED ON 23/06/23 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Barbhag - Raimadha Village Road Raimadha Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Dokoha Kowarpur Road Dokoha Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Pajipar Deharkuchi Road Pajipar Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Nalbari Kamarkuchi to khudrakulhati namghar kamarkuchi Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Pandula Bausiadapur Road Pandula Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Barsimulia Barbukia Road Barsimulia Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Kamarkuchi to Kotalkuchi Kotalkuchi Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Arangamow village Road Arangamow Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (NH Roads)), Kamalpur Morowa Road Morowa Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Sonkuriha Bhanukuchi Moura village Road Sonkuriha Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads)), Kaharjhar village Road Barkulhati Flood Affected Report Submitted by AEE ,PWD (Roads)dated 23/06/2023 (Long - 0.000000, Lat - 0.000000, Dept - PWD (Roads))
	Tamulpur	1	Goreswar - Barghuli Rangia Road Village Bihapara As per report of AEE PWD Goreswar Rural road subdivision, the road from Barghuli to Rangia Road at 2.20 Km got submerged and breached at village Bihapara date of report received 23/06/23 (Long - 91.624028, Lat - 26.476729, Dept - PWD (Roads))
	Total	157	
Infrastru cture Damaged - Bridge	District/S ub- division*	Numbe r	Details
	Dhubri	1	Dhubri - APPROACHES OF SPT BR. NO. 3/1 AND ROAD SIDE BERM PARTIALLY DAMAGED AT 2nd , 3RD & 4TH KM ON FALIMARI PMGSY ROAD TO FALIMARI PT. – II (Ch. 1.75 km to 3.50km) (Date-22-06-2023) FALIMARI (Long - 89.979187, Lat - 26.054810, Dept - PWD (Roads))
	Total	1	
Infrastru cture Damaged -	Nil		

Wildlife		
	District/Sub-division*	Other Details
Infrastructure Damaged - Others	Bajali	<p>Bajali - Anganwadi Centres Affected 241 No. Daloigaon, Muguria Anganwadi Centre completely damaged, Lat-26.520882 Long- 91.169655. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 235 No. Balattary, Bamunkuchi Anganwadi Centre completely damaged. Lat - 26.507139 Long- 91.220878. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 177 No. Bhatigomura, Tihu Dekhata Anganwadi Centre completely damaged. Lat-26.480514, Long- 91.229286. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 53 No. Panara (M), Tihu Dekhata Anganwadi Centre completely damaged. Lat-26.480562, Long- 91.229313. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 157 No. Kuwara , Patacharkuchi Anganwadi Centre completely damaged. Lat-26.515546, Long- 91.253620. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 170 No. Bezkuchi, Patacharkuchi Anganwadi Centre completely damaged. Lat-26.515601, Long- 91.253702. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 39 No. Dumuria, Dumuria Anganwadi Centre completely damaged. Lat- 26.512110, Long- 91.159410. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 98 No. Panpara, Dhumarpathar Anganwadi Centre completely damaged. Lat-26.669074, Long- 26.669074. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 334 No. Dakhin Batiamari, Dhumarpathar Anganwadi Centre completely damaged. Lat- 26.592718, Long- 91.611099. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 343 No. Chenglimari, Dhumarpathar Anganwadi Centre completely damaged. Lat-26.658012, Long- 92.243033. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 342 No. Uttar Dhumarpathar, Dhumarpathar Anganwadi Centre completely damaged. Lat- 26.661588, Long- 91.126842. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 332 No. Pub Dhumarpathar, Dhumarpathar Anganwadi Centre completely damaged. Lat- 26.661705, Long- 91.126997. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 331 No. Silapatni, Dhumarpathar Anganwadi Centre completely damaged. Lat-26.634768, Long- 91.118912. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 145 No. Silapatni, Dhumarpathar Anganwadi Centre completely damaged. Lat-26.634830, Long- 91.119013. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM, Anganwadi Centres Affected 109 No. Chenglimari, Dhumarpathar Anganwadi Centre completely damaged. Lat-26.658503, Long- 92.243422. Report received from DSW i/c Bajali dated 24/06/2023 at 12 PM</p>
	Baksa	<p>Baganpara - Irrigation Canal/Scheme Damaged As per reported SDO irrigation on dated 22/06/2023 Gerua FIS embankment have been damaged (lat-26.6590974,long- 91.4808644), Power Dept. Poles As per nalbari ESD 1 sde total HT pole 2 nos and LT poles 7 nos have been damaged on 23/06/2023 at villages Odlā, Borikadonga, Gerua and Tupulia. Odlā GPS(lat-26.6823,long-91.4506), Borikadonga (lat-26.6823,long-91.4781),</p> <p>Baska - Culvert Approach Road Damaged Dhanbil to Chaibari Connecting CC Block Road damaged. Cordinate: 26.640733, 91.390791 3)Culvert Breach approach road damaged near Dhira LP School connecting Nikashi Arampur to Nikashi road dated 23/6/2023.(coordinate: 26.745295, 91.373774),</p> <p>Agri Bundh Damaged Agri Bund at Paschim Atiabari dated 23/6/2023 3) Agri Bund at Charaimari dated 23/6/20023 4)Agri bund at village Ahop dated 23/6/2023 5)Agri bund damaged Palashguri Natsupa dated 23/6/2023, Bridge Approach Road Damaged Road breached at Tekelibhanga to Doomni village Doomni Coordinate: 26.644772, 91.34704 date: 21/06/2023. 2)Road – Ahop to palashguri road damaged dated 23/6/2023 3)Bebejia to Chutiapara village road dated 23/6/2023 4)Dihira MV School to Bhutankhuti Road Broken dated 23/6/2023, Washed away Culverts Dihira MV School to Bhutankhuti HPC Culvert washed away at village Arampur on 21/06/2023 Coordinate: 26.644772, 91.347040.,</p> <p>Jalah - Power Dept. Poles As per the information received from APDCL, Vill-Bakua Lat-26.689861 Long-91248368 electric conductor 800m, Dated- 21/06/2023, Power Dept. Poles As per the information received from APDCL, Vill Simla Lat-26.728176 Long-91.204357. LT Pole damage dated- 24/06/2023</p>
	Barpeta	<p>Sarthebari - Fisheries/Pond 53 nos of fish pond (total 14.27 Hect) submerged in singra village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 46 nos of fish pond (total 29.30 Hect) submerged in garartari village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 26 nos of fish pond (total 9.06 Hect) submerged in Agdia pathar village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 29 nos of fish pond (total 4.26 Hect) submerged in Besimari pam village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 125 nos of fish pond (total 24.60 Hect) submerged in joshoda pam village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 30 nos of fish pond (total 8.66 Hect) submerged in Bogchara village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 56 nos of fish pond (total 8.93 Hect) submerged in Kaljahi pathar village, Report submit by fishery deptt on 23/6/2023, Fisheries/Pond 50 nos of fish pond (total 7.27 Hect) submerged in Buri khamar village, Report submit by fishery deptt on 23/6/2023,</p>

	<p>Fisheries/Pond 25 nos of fish pond (total 10.60 Hect) submerged in Rangia gaon village, Report submit by fishery deptt on 23/6/2023,</p> <p>Fisheries/Pond 25 nos of fish pond (total 10.73 Hect) submerged in Rangia nadir pam village, Report submit by fishery deptt on 23/6/2023,</p> <p>Fisheries/Pond 18 nos of fish pond (total 3.40 Hect) submerged in Gohiya nadir pam village, Report submit by fishery deptt on 23/6/2023,</p> <p>Fisheries/Pond 90 nos of fish pond (total 22.80 Hect) submerged in sariyakhuchi village, Report submit by fishery deptt on 23/6/2023,</p> <p>Chenga - Road Breaches Niz Chenga to Bampara Road breach length 7 m. Reported by pwd roads.Date-24-06-2023</p>
Biswanath	Gohpur - Power Dept. Poles 3 nos 8.5 PSC pole uprooted at Chengmora Jaranigaon on 22/06/23
Bongaigaon	<p>Boitamari - Fisheries/Pond 2 no of fisheries damaged at vill- Borghola pt II (2 ha) and Sankarghola Pt-II (0.6 ha) submitted on 23/06/2023 by Fishery Dept. GPS cordination: Lat:26.27479, Long: 90.60014 (Borghola Pt-II) and lat: 26.301541, long: 90.535311 (sankarghola pt-II),</p> <p>Culvert Approach Road Damaged Shankarghola Kherpuji Road, Nature of damage: CD damage at 1st km. Longitude- 90.532007, Latitude- 26.309694. As per report received from PWRD, Bongaigaon. dated- 23/06/2023,</p> <p>Manikpur - Fisheries/Pond 7 nos of fisheries damaged at vill-Nowagaon 2.4 hac. submitted on 23/06/2023 by Fishery Dept. GPS coordinate is- 26.406434/90.827182,26.40647/90.827136,26.407253/90.827217,26.412411/90.84218,26.412742/90.842662,26.407274/90.826512,26.410221/90.844995,</p> <p>Bridge Approach Road Damaged Nowagaon Rangapani road to Numberpara Bazar road, SPT Bridge No. 1/1 over Manas river damaged and road with approach eroded. Latitude : 26.400121 Longitude : 90.813742, as per report received from PWRD, Bongaigaon, dated-23.06.2023,</p> <p>Bridge Approach Road Damaged Bashbari Chalabila Road, SPT Bridge No. 1/1 partially damaged along with both side approach. Latitude : 26.420455 Longitude : 90.7763, as per report received from PWRD, Bongaigaon, dated- 23.06.2023,</p> <p>Culvert Approach Road Damaged Hapachara Barbila to Silghagri road, Submarged at Ch. 2nd, 3rd and 4th Km and slab culvert No. 4/1 partially damaged Latitude : 26.438659 Longitude : 90.744471, as per report received from PWRD, Bongaigaon, dated-23.06.2023,</p> <p>Srijangram - Culvert Approach Road Damaged Narayan Das Thakur Ata Satra road, HP culvert damaged at Ch.1200.00m and road side slope damaged at various point at Ch. 1st k.m. Longitude- 90.7830946, Latitude- 26.315759. As per report received from PWRD, Bongaigaon, dated- 23.06.2023.</p>
Darrang	Mangaldoi - Culvert Approach Road Damaged As reported by Irrigation Dept. damaged road crossing slab culvert in main canal at CH 10000m of CM Dutta Bund FIS at village Bezpara. Approx. length of damage is 4-5m.. Dated 24/06/2023.
Dhubri	<p>Gauripur - Culvert Approach Road Damaged APPROCHES OF CULVERT NO. 1/1 & 2/1 & SIDE BERM ERRODED AT 1ST KM, 2ND KM ON DG ROAD AT RLY. LEVEL CROSSING TO TIAMARI PT. II VIA ROYPARA ,(Location-Tiamari),(Date-22-06-23),(LAT – 26.061613 LONG – 89.962487),</p> <p>Dhubri - Culvert Approach Road Damaged APPROCHES OF CULVERT NO. 1/1 AND ROAD SIDE BERM ERRODED BY HEAVY RAINFALL ON 4TH KM OF DJG ROAD TO 1384 NO JHAGRARPAR PT. IV LP SCHOOL ,(Location-Jhagrapar),(Date-22-06-23),(LAT- 26.054167, LONG- 89.959457),</p> <p>Bilasipara - Power Dept. Poles PSC Pole - 7.5 mtr-6 No's 8.5 mtr-7 No's Damaged Conductor (in KM) HT- 2, LT- 3 Nos. on dated 23-06-23,</p>
Golaghat	<p>Golaghat - Road Breaches As per the information received from BRO (Gomariguri) Breach at Main road section near rupkolia bridge under Chowdang Pathar GP due to flash flood of ghiladhari river on 24.06.2023,</p> <p>Agri Bundh Damaged As per the information received from BRO (Gomariguri) Breach of Agribund at 2 No. chowdandpathar LP school due to flash flood of ghiladhari river on 24.06.2023</p>
Kamrup	<p>North Ghy - Irrigation Canal/Scheme Damaged 5 Nos. of electrical/solar pump(PMKSJ-HKKP) of beneficiary belonging to village Athiabo and Bezera were affected on 23.06.2023 as per report received from AEE, Jalukbari Sub-Div (Irrigation), Amingaon,</p> <p>Palashbari - Culvert Approach Road Damaged Damage culvert due to rainfall on Loharghat Bazar to Bagan via kochpara Road under palashbari Territorial Road sub-div, as reported by PWRD Mirza on Dated: 23-06-2023, GPS Cordinates 25.973052, 91.47445</p>
Lakhimpur	<p>Nowboicha - Power Dept. Conductors 15.20 KM conductor damaged due to Singra River Flood on 17.06.2023 to 22.06.2023. Report received from APDCL, Nowboicha on 23.06.2023. ,</p> <p>Power Dept. Poles 13 Nos. of poles damaged due to Singra River Flood on 17.06.2023 to 22.06.2023. Report received from APDCL, Nowboicha on 23.06.2023. ,</p> <p>Subansiri - Bamboo Foot Bridge As reported by the Dkakuakhana territorial road division, Ghilamara the Bamboo foot Bridge on Napam to Koibatra Gaon is damaged (L=100M) on 23/06/2023</p>
Nalbari	<p>Paschim Nalbari - PWSS Damaged Total 8 nos. of PWSS namely Barhelacha PWSS, Kheluwa- Barbila PWSS, Lakhopur PWSS, Ghilzari PWSS, Jagara PWSS, Kendubari MPWSS, Pahlangpara PWSS, Gamarimuri PWSS are partially submerged by flood and rain water. Information received from PHE Department on 23/06/2023,</p> <p>Banekuchi - PWSS Damaged on 23/06/2023 at 12 PM Distribution of pipe line of Uttar Pub Dharmapur PWSS has been damaged appr. 60 mtr. length near Madhupur to Bihampur road report from Line department .,</p> <p>Fisheries/Pond Tentative ponds & Tanks submerged .Affected water area 22 Ha and approxi.220 nos of farmer affected may be increase or decrease during post flood assessment reported by fishery department on 23/06/2023. ,</p> <p>PWSS Damaged On 22/06/2023 the PWSS Schemes of 1)Nakerbari PWSS,2)Balizar PWSS ,3)Garber PWSS</p>

		.4)Uttar Bausiapara PWSS,5)Uttar Kaithalkuchi PWSS, 6)Kaithalkuchi PWSS and 7)Madhupur PWSS submerged and partially damaged report by Line department, Nalbari - Handloom & Textile Deptt 80 nos of handloom weavers are submerged due to flood as per the report of handloom and textile department on 23.06.23, Tihu - Fisheries/Pond TOTAL SUBMERGED POND LAND 158 HA AS PER REPORT DFDO,FISHERY, ON 23/06/23, Health Sub-Centre AS PER REPORT DY.SUPERINTENDENT, TIHU FRU HWS & JALKHANA MPHC SUBMERGED ,DATE OF REPORTING 23/06/2023, Public Health Engineering (PHE) TOTAL SUBMERGED PWSS 6 NOS UNDER TIHU & GOBARADAL PHE SUB DIVISION AS PER REPORT SUBMITTED BY JE,PHE, ON 23/06/2023, Ghograpar - Power Dept. Poles 7 HT & 5 LT pole has been damaged due to recent flood on 23/06/2023 as per reported APDCL , Power Dept. Conductors 3.94 KM conductor has been damaged due to flood on 23/06/2023 as per reported APDCL , Handloom & Textile Deptt On 23/06/2023, 40-45 nos of weavers has been affected by recent flood as per reported handloom and Textile dept., Anganwadi Centres Affected 19 nos of AWC centre has been damaged on 23/06/2023 due to recent flood as per reported by Social welfare Dept., Secondary Schools Damaged Borajol HS School has been damaged on 22/06/2023 due to flood occurs at village Borajol as per reported Head Master Borajol HS
	Udalguri	Harisinga - Irrigation Canal/Scheme Damaged Geruapara FIS Chainage- 1080 m broken culvert....longitude: 91.83• latitude: 26.63• Village- Patala due to heavy rainfall on 21st June 2023, Irrigation Canal/Scheme Damaged Geruapara FIS. Erosion of embankment of canal due to flood. Chainage 1400 m. Village- Patala on 21stJune2023., Udalguri - Irrigation Canal/Scheme Damaged CC lining damaged at Ch. 7730m of B2M canal (Approx 10 Mtrs.) under DIP of village No.1 Chandana Tea Estate Lat- 26.754808 Long- 92.088783 on 23-06-2023,.
	District/Sub-division*	Details
	Baksa	Baska - River Bank Erosion L/B of Mora Pagladiya river at Village 3 No Lokpala 2) River Bank Erosion R/B of Mora Pagladiya river at Village 2 No Lokpala near Lokpala LP School River Bank Erosion L/B of Mora Pagladiya river at Village 3 No Lokpala 2) River Bank Erosion R/B of Mora Pagladiya river at Village 2 No Lokpala near Lokpala LP School 0 (Long - 26.624869, Lat - 91.404756)
	Barpeta	Chenga - Chatta, Roumari Gaon, Roumari Pathar, Chenimari Near the B/dyke on R/B of river Brahmaputra from Adabari to Kukarjan from ch 5.80 km to 33.232 km.....breach occurred in three stretches 400 m, 550 m and 500 m respectively Report received from water resource department on 24.06.2023 0 (Long - 0.000000, Lat - 0.000000)
	Biswanath	Gohpur - at No 2 Bickrampur area. Mild erosion is observed at R/Bank embankment of river Sessa of 30 mtr on 24/06/23 0 (Long - 93.728440, Lat - 26.964250), Halem - Paken Mild bank erosion is observed by river BRAHAMAPUTRA at Paken area of B-dyke from Jamuguri to Kharoi outfall.Length =10m.(avg.width=0.10m) on 24/06/2023 0 (Long - 93.625660, Lat - 26.798990)
	Dhubri	South Salmara Part - Sundarpara Pt-III, Sundarpara Pt- IV As per field information received fro LM 44 nos families has been eroded due erosion by river Brahmaputra at village Sundarpara PT-III on 19.06.23 to 23.06.23. area aprox leanth 1500 m breadth 500 m. As per field information recived fro LM 62 nos families has been eroded due erosion by river Brahmaputra at Village Sundarpara PT-IV on 19.06.23 to 23.06.23. area aprox leanth 2 km breadth 700 m. 287 (Long - 90.089000, Lat - 25.963300)
Erosion	Kamrup	Kamalpur - Bhehbari area on L/B of Puthimari Embankment. Active erosion found at up stream of Bhehbari of about 150 mtr on L/B of Puthimari Embankment. Reported by Rangia WR Sub-Division on 23.06.2023. 0 (Long - 91.687136, Lat - 26.463514), Rangia - Barlesakona, Madhukuchi, Assam. As per report given by AEE, WR Department , Rangia dated 23/06/2023 river bank erosion at left bank of river puthimari breath-300m approx. 0 (Long - 91.682713, Lat - 26.424333), Hajo - AdhiarpR Erosion of R/B of river bhairatula Jaana at village deharkuria for length of 55m at 23/062023 as reported by WRD 0 (Long - 26.410000, Lat - 91.280000)
	Kokrajhar	Bhawraguri - Rimijhimighop As reported by Executive Engineer, Kokrajhar WRD & Sectional Officer, Gossaigaon WRD on dated 23-06-2023 1. River Bank Erosion observed at village Rimijhimighop Reach Length 200 M on L/B of River Gongia. 0 (Long - 90.118611, Lat - 26.403055)
	Nalbari	Barkhetri - Hanapara, Burlitpar L/B of river pagladia from From dusutimukh to adabari at Burlitpar, length 350m as reported by AEE, WRD, Mukalmua on 24-06-23. Six(6) nos of families shifted their houses due to erosion of river pagaldia at Hanapara & Burlitpar. 25 (Long - 0.000000, Lat - 0.000000), Barbhag - Kamarkuchi, Ganagpar, Sadhnapar,Bihdia, Korla Erosion on L/B of river Pagladia from Sonkuriha to Dusutimukh from ch 28.20 K.M. to 35.50 K.M. as per report submitted by Asst. Executive Engineers, Mukamua W.R. Sub-Division, Mukalmua. Population affected 20000. Longitude : 91.4779 Latitude : 26.3511 Erosion on R/B of river Pagladia from Bijulighat to Adabari from ch 0.00 K.M. to 5.80 K.M. as per report submitted by Asst. Executive Engineers, Mukamua W.R. Sub-Division, Mukalmua on 24/06/2023. Population affected 20000, 15000 Longitude : 91.4480 Latitude : 26.3224 Erosion on R/B of river Pagladia from NT road to Bijulighat from ch 31.00 K.M. to 41.00 K.M. as per report submitted by Asst. Executive Engineers, Mukamua W.R. Sub-Division, Mukalmua on 24/06/2023. Population affected 20000, 15000 Longitude : 91.4553, 91.4722 Latitude : 26.3753, 26.3535 0 (Long - 0.000000, Lat - 0.000000)

	Sonitpur	Thelamara - 1. Baligaon Bangaligaon 2. Kalakuchi Date-24/06/2023, As reported by Tezpur Water Resource Tezpur Division on 24/06/2023- 1) Active bank erosion is observed at Baligaon Bongaligaon area on the left bank area of river Belsiri,Length = 200.00m, Latitude : 26.736022, Longitude: 92.558699 2) Bank erosion is observed at Kalakuchi(Ch 200m to 350m) on the R/Bank of river Gabharu since 22.6.2023. Latitude-26.746466 and Longitude-92.616082 0 (Long - 92.558699, Lat - 26.736022)
	South Salmara	Mankachar - Nepurer Alga As per report received from Gaon Pradhan, erosion is going on in revenue village Nepurer Alga by the river Brahmaputra. 7 Nos. temporary house hold from Nepurer Alga are shifted to safe place, for these purpose 2 Nos. of engine Boat deployed on 24-06-2023. 65 (Long - 25.748368, Lat - 89.844128)
	Tamulpur	Goreswar - Village Bholabatabari As per information received on dated 23/06/2023 from Soil conservation department R/B of subtributary river Naobandha about 60 m of Naobandha Suklai Erosion protection got eroded at village Bholabatabari 0 (Long - 0.000000, Lat - 0.000000), Tamulpur - 1. Hatiduta 2. Kandulimara 1. As per the reports date 22/06/23 from Tamulpur Sub-division (Irrigation Head workI.S. due Division(Irrigation) recieved on 24/06/2023 mentions head work of Daranga I.S. at village Cblock- Tamulpur) due to flash flood. 2. As per report received on date 24/06/2023 from Water Resource Dept. severe erosion have been occured at L/B of Pagladia river at Kandulimara Village. Total length of erosion is 100M. (Long- 91.5030174, Lat-26.6629458) 0 (Long - 91.598244, Lat - 26.590530)
	Udalguri	Mazbat - 1. Mazgaon 2. Kalbari 3. No.1 & No 2 Kadabil village 1. Severe erosion occurred on B/B of river Pagla at Mazgaon village for a length of 500m on 23/6/2023(Lat: 26.731623, Long: 92.304411 2. 1. Severe erosion occurred on R/B of river Dhansiri at Kalbari village for a length of 500m on 23/6/2023(Lat: 26.706159, Long: 92.290079 3. 1. Severe erosion occurred on L/B of river Butiamari at No.1 Kadabil and No.2 Kadabil village for a length of 600m on 23/6/2023. (Lat: 26.861808, long: 92.311488) 0 (Long - 0.000000, Lat - 0.000000)
Landslide	District/Sub-division*	Details
	Karimganj	RK Nagar - kalinagar part 2 feeder name 11kv Bhairab Nagar Feeder 1 no. LT Pole. due to landslide on date 22- 06 2023 as reported Ramkrishnanagar Electrical Sub-division APDCL on date 23-06-203 0 (Long - 92.462114, Lat - 24.568653)
Urban Flood	District/Sub-division*	Details
	Darrang	Dalgaon - Kharupetia Town(Ward No-1) As per report received from LM, water logging at kharupetia town ward no.1 under dalgaon revenue circle as on 24-06-2023 100 (Long - 92.149805, Lat - 26.519547)
*Bajali, Biswanath, Hojai and Tamulpur are sub-divisions (Independent)		